

Smith County Road Department

Repair and Service Summary

Start Date

1/1/2001

End Date

7/15/2022

Dump Truck

93 - 2001 FORD STERLING DUMP TRUCK

Date	Serviced By	NO	Odometer	Serviced	Labor	Stock Parts	Outside Parts	Total Repair	Description	Qty	Rate	Amount	Total
07/11/11		2200704		☐				\$5,806.05	LABOR - WASH ENGINE	1			\$5,806.05
									PUMP GP HYD. - 7F-9108	1			
									CORE DEPOSIT - CORE DEPOSIT	1			
									CORE CREDIT - CORE CREDIT	1			
									LABOR - INSTL. INJECT. PUMP	1			
									F REIGHT - FREIGHT	1			
									LABOR - LABOR	1			
									LABOR - INSTALL ENG. OIL CO	1			
									SENSOR - 224-4536	1			
									F REIGHT - FREIGHT	1			
									LABOR - INSTL. UNIV. JOINT	1			
									UNIVERSAL JOINT - 5-280X	1			
									DRIVE SHAFT - DRIVE SHAFT	1			
									F REIGHT - FREIGHT	1			
									LABOR - INSTL. SPEED/TIME S	1			
									SENSOR GP - 245-4630	1			
									freight - FREIGHT	1			
									LABOR - LABOR	1			
									INJ. GP FUEL - OR-9349	1			
									LABOR - LABOR	1			
									LABOR - LABOR	1			

remove & install unit injector hyd. Pump. Remove & install turbocharger. Remove & install engine oil cooler. Remove & install universal joint. Remove & install eng. speed/timing sensor. Remove & install air compressor, combined repair times for unit injector. Adjust inlet/exhaust valve.

07/11/11				☐				\$1,025.08	PARTS - PARTS	1			\$1,025.08
									LABOR - LABOR	1			
									F REIGHT - FREIGHT	1			
									LABOR - LABOR	1			
									PARTS - PARTS	1			
									LABOR - LABOR	1			

TROUBLESHOOT ENGINE & REMOVE & INSTALL FUEL PRIMING PUMP, FUEL SUPPLY/RETURN LINES.

08/08/11				☐				\$55.78	PANEL DAS - 22-53848-00	1			\$55.78
10/20/11		52231		☐				\$74.20	BEARING - BGS 594-A	1			\$74.20
									OIL BATH SEAL - SLS 370003A	1			
11/01/11		3231		☐				\$12.95	HARNES -	1			\$12.95

Smith County Road Department

Repair and Service Summary

Start Date 1/1/2001
End Date 7/15/2022

Dump Truck

93 - 2001 FORD STERLING DUMP TRUCK

Date	Serviced By	NO	Odometer	Serviced	Labor	Stock Parts	Outside Parts	Total Repair	Description	Qty	Rate	Amount	Total
06/28/13		2201779		☐				\$5,502.14	PARTS - PARTS	1			\$5,502.14
									LABOR - LABOR	1			
									LABOR - LABOR	1			
									PARTS - PARTS	1			
									LABOR - LABOR	1			
									F REIGHT - FREIGHT	1			
instl. Air cleaner & panel, instl new unit injector set, instl exhaust manifold to fix leak													
08/10/13		2201859		☐				\$3,432.56	PARTS - PARTS	1			\$3,432.56
									PARTS - PARTS	1			
									LABOR - LABOR	1			
REMOVE & INSTALL UNIT INJECTOR SET (ALL)													
08/12/13	N	T00525600		☐				\$186.34	SURGE TANK - A05-23573-000	1			\$186.34
									FITTING - 43277	1			
11/29/13		5 031358		☐				\$2,995.41	LABOR - LABOR	1			\$2,995.41
									TCM - 0094701	1			
									ECU ASSEMBLY - 73 29543300	1			
									F REIGHT - FREIGHT	1			
									MISC SUPPLIES - MISC SUPPLI	1			
truck won't shift /repic. TCM													
01/02/14		90930		☐				\$15.42	NYRACORD FLAP LOGO - CPF 1 1				\$15.42
01/03/14		7637		☐				\$120.26	VALVE - 29.554	1			\$120.26
01/07/14		91141		☐				\$68.93	AIR FILTER - CFI 88459	1			\$68.93
05/21/14		19-72011		☐				\$615.05	REMAN FAN CLUTCH - 8801X	1			\$615.05
									CORE - 215-8801XC	1			
									F REIGHT - FREIGHT	1			
08/24/15		T00525600		☐				\$3,259.39	RADIATOR - 46024	1			\$3,259.39
									F REIGHT - FREIGHT	1			
									OIL COOLER ASSY - F6HZ*7A09	1			
									RAD. MOUNT BUSHING - F4HZ*8 4				
10/13/15		121053		☐				\$3.72	MINIATURE LAMP - CLB 3157	4			\$3.72
08/17/17		03938 ?		☐				\$7.29	CONNECTOR - 755-1524	1			\$7.29