

**\*\* Reprint \*\***

Invoice: 040413009  
Date / Hour: 6/9/2021 3:21:15PM  
Repair Order: 13009  
Customer: 00001  
Branch: HUR  
Total Invoice: \$6,332.54  
\*\*\*Cash\*\*\*  
Page 1 of 1

Ship To: Straightline Transportation

, WV

Customer P/O: ebailey House Orig R/O: 0 Completion Date: 06/09/2021

Unit Number: 357

Model Year: 2013

Make/Model: PETERBILT 367

Type: Class 8

VIN: 1XPTP4EX9ED244315

Meter: 373937 Miles

ECM Reading: 21502

Task: 1 45-000000 Engine System

Department: Service

Complaint: Customer states that cel is on

Correction: truck came in with cel , hooked up to truck . it had codes 3376,2754,3225,1921,2639. all for dpf pressures . removed cover from dpf and the DOC is leaking around the end cap , needs new doc , wount know about the dpf until its taken apart  
new doc came in , i removed old doc and inspected the dpf inlet . all looked good . installed new doc and gaskets . started truck and put into regin  
regin finished , no codes found truck ready to go

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
PCR	4353249RXCUM	EPA/MODULE-INLET CATALYST	EA	1.0		
PCR	4353249RXCUM-C	288050000 D-CORE	EA	1.0		
PCU	2871453CUM	GASKET-DPF ASSY	EA	1.0		
PCU	2866337CUM	GASKET-CIRCULAR 5"	EA	1.0		
	EPA	EPA		1.0		

Detail Tax Info:

WEST VIRGINIA EXEMPT TAX

\$0.00

West Virginia Taxable

\$340.84

Total: \$340.84

Total Parts:

Total Core Charge:

Total Labor:

Total Miscellaneous:

Invoice Subtotal:

Total Tax:

Total Invoice:

\$6,332.54

Payment Method

Terms

Due Date

Cash

00 Net 10th

7/10/2021

Paid With: Cash

Amount Due:

Signature:

Date:



# Payment Receipt

Transaction Id: 9FAQEHTFEE

Transaction Date: 10/07/2021

Payment Method: ACH-XXXX6109

Net Payment Amount: USD 27,737.77

Payment Status: Success

## Invoices Paid with This Transaction

S No.	Customer Number	Invoice Number	Invoice Date	Due Date	Open Amount	Paid Amount	Currency
1		J9-48501	09/03/2021	10/03/2021			USD

Net Payment Amount: USD 27,737.77

Total Paid Amount: USD 27,737.77



INVOICE NO

PREVIEW

TO PAY ONLINE LOGON TO  
customerpayment.cummins.com

PAGE 1 OF 5

\*\*\* CHARGE \*\*\*

DATE		CUSTOMER ORDER NO.		DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE	
				09-DEC-2013	ISX15 CM2350 X101		PETERBILT	
CUSTOMER NO.		SHIP VIA		FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL	
210147				17-JUN-2021	79691935		367	
REF. NO.		SALESPERSON		PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.	
74071					375843 / 0		357	
QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION		PRODUCT CODE	UNIT PRICE	AMOUNT

OSN/MSN/VIN 1XPTP4EX9ED244315

## COMPLAINT

REGEN AND SAME FAULTS RETURNING, SEE ALLEN'S EMAIL  
ISX15 PRO OVERHAUL  
NATIONAL OVERHAUL WARRANTY PROMOTION  
NATIONAL OVERHAUL WARRANTY ONLY AVAILABLE ON PRO AND ELITE  
OVERHAUL KITS

## CAUSE

-DIAGNOSED FOR HIGH OIL CONSUMPTION.  
-OVERHAUL ENGINE WITH PRO OVERHAUL SPECIAL WITH NOW WARRANTY.  
OVERHAUL INCLUDES: LINER / PISTON KITS, BEARINGS RECON CYL HEAD, LUBE  
OIL PUMP, WATER PUMP, HP FUEL PUMP BASE AND UPDATED TAPPETS  
-REPLACED 8 BADLY PITTED HEAD BOLTS  
-TIMED NEW FUEL PUMP AND SET GEAR LASH AT NEW .004 SPEC  
-PULLED AFTERTREATMENT, CLEANED DPF AND DOC. DPF WAS 2.2, CLEANED  
DOWN TO .9, WE BAKED IT AND RECLEANED DOWN TO .8.  
-REPLACED PLASTIC COOLANT FITTINGS FOR DEF DOSER VALVE  
-RAN ON DYNO AND REGEN, AFTER REGEN FC 755 CAME ACTIVE. THROUGH T/R  
STEPS AND REPLACED FUEL PSI SENSOR  
-REPLACED CLUTCH BRAKE. CLUTCH BRAKE DIDN'T WORK, CHECKED OVER  
AND INNER TABS BROKEN OFF

## CORRECTION

ADMINISTRATIVE TIME - OPEN AND CLOSE REPAIR ORDER (SHOP REPAIRS)  
INSITE - USE DURING TROUBLESHOOTING SIGNATURE ENGINES  
GUARDIAN INSPECTION  
PERFORM JOB SAFETY ASSESSMENT (JSA) (NON-REIMBURSABLE)  
STEAM CLEAN - COMPLETE ENGINE  
AIR CLEANER ASSEMBLY (INCLUDING BRACKET) - REMOVE AND INSTALL, EACH  
PISTON AND LINER - REMOVE AND INSTALL, ALL  
BEARINGS, MAIN AND THRUST - REMOVE AND INSTALL, ALL (PISTONS  
REMOVED)  
PISTON RING - MEASURE END GAP, ALL SETS  
LUBRICATING OIL PUMP - REMOVE AND INSTALL  
WATER PUMP - REMOVE AND INSTALL (WITH EGR)  
POWER STEERING PUMP - MOVE FOR ACCESS  
POWER STEERING RESERVOIR - MOVE FOR ACCESS  
CONNECTING ROD - INSPECT FOR REUSE, ALL

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS  
DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE  
EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE  
BEEN READ AND FULLY UNDERSTOOD.

AUTHORIZED BY (

DATE 9/3/21



INVOICE NO

PREVIEW

TO PAY ONLINE LOGON TO  
customerpayment.cummins.com

PAGE 2 OF 5

\*\*\* CHARGE \*\*\*

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
		09-DEC-2013	ISX15 CM2350 X101		PETERBILT
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
210147		17-JUN-2021	79691935		367
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
74071			375843 / 0		357

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
			OSN/MSN/VIN	1XPTP4EX9ED244315			

CONNECTING ROD - MEASURE FOR BEND AND TWIST, ALL  
TURBOCHARGER (ALL MODELS) - INSPECT FOR REUSE, EACH  
COOLANT FILTER - REPLACE, ALL, EACH  
INJECTOR - CLEAN EXTERIOR FOR REUSE, EACH TWO, EACH  
LUBRICATING OIL FILTER, SPIN-ON TYPE - REPLACE, EACH  
FUEL FILTER, SPIN-ON TYPE - REPLACE, EACH  
COOLANT THERMOSTAT SEAL - REPLACE, EACH  
COOLANT HEATER HOUSING - REMOVE AND INSTALL  
CAB HEATER SUPPLY / RETURN FITTING - REMOVE AND INSTALL, EACH  
FUEL PUMP - REMOVE AND INSTALL (COMMON RAIL FUEL SYSTEM)  
RADIATOR, CHARGE AIR COOLER, AIR CONDITIONER CONDENSER ASSEMBLY -  
REMOVE AND INSTALL (PART OF ANOTHER REPAIR)  
RADIATOR - CLEAN FOR REUSE  
CHARGE AIR COOLER - PRESSURE TEST  
AIR CONDITIONER SYSTEM - EVACUATE AND RECHARGE  
ENGINE - PAINT  
ENGINE - RUN-IN AND TEST (CHASSIS DYNAMOMETER)  
FUEL RAIL PRESSURE SENSOR - REMOVE AND INSTALL, FRONT OR REAR  
T3-DRIVE TRAIN  
AFTERTREATMENT DIESEL PARTICULATE FILTER, (SWITCHBACK) - REMOVE  
AND INSTALL - ISX15 CM2350 X101  
AFTERTREATMENT DIESEL OXIDATION CATALYST, (SWITCHBACK) - REMOVE  
AND INSTALL - ISX15 CM2350 X101  
AFTERTREATMENT DIESEL PARTICULATE FILTER - CLEAN  
AFTERTREATMENT DIESEL OXIDATION CATALYST CLEANING  
AFTERTREATMENT STATIONARY REGENERATION  
THANK YOU FOR YOUR BUSINESS

## COVERAGE

CUSTOMER BILLABLE  
REPAIRS WILL HAVE A 2 YEAR 200,000MILE NOW WARRANTY

## REMARK

6/17/2021 ESTIMATE FOR CLASSIC OVERHAUL \$18-22,000, ESTIMATE FOR PRO  
OVERHAUL \$28-32,000. GARY AUTHORIZED REPAIRS FOR EITHER KIT  
AVAILABLE.  
8/27/2021 TOTAL FOR REPAIRS \$27,737.77

Billing Inquiries? Call (877) 460-6970 or email [billing@cummins.com](mailto:billing@cummins.com)

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS  
DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE  
EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE  
BEEN READ AND FULLY UNDERSTOOD.

AUTHORIZED BY (print name)

DATE

9/3/21



INVOICE NO

PREVIEW

TO PAY ONLINE LOGON TO  
customerpayment.cummins.com

PAGE 3 OF 5

\*\*\* CHARGE \*\*\*

DATE	CUSTOMER ORDER NO.	DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE
		09-DEC-2013	ISX15 CM2350 X101		PETERBILT
CUSTOMER NO.	SHIP VIA	FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL
210147		17-JUN-2021	79691935		367
REF. NO.	SALESPERSON	PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.
74071			375843 / 0		357

QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT
OSN/MSN/VIN 1XPTP4EX9ED244315							

1		CSSNA ISX15 PRO	ISX15 NOW PRO OVERHAUL				
1		GUARDIAN INSP	GUARDIAN FREE VISUAL INSPECTION				
1		1 FREIGHT	5406130	C1-FREIGHT			
1		1 FREIGHT	FREIGHT CHRGS SERVICE	C1-FREIGHT			
1		1 4374002	TUBE,VENT (REQ 2-4386678)	CECO			
2		2 4386678	UNION,MALE	CECO			
2		2 07158583010FTG	FITTING	C1-NSPART1			
1		1 3163087	LUBRICANT	CECO			
1		1 4918675	SEALANT	CECO			
1		1 3163087	LUBRICANT	CECO			
10		10 3678506	SCREW,HEX FLANGE HEAD CAP	CECO			
1		1 FREIGHT	FREIGHT CHRGS SERVICE	C1-FREIGHT			
1		1 5440813	GASKET,ACC DRIVE SUPPORT	CECO			
2		2 3627695	SEAL,O RING	CECO			
1		1 4988280	GASKET,HYDRAULIC PUMP	CECO			
1		1 3163075	PAINT	CECO			
1		1 4386678	UNION,MALE	CECO			
12		12 4965698	SCREW,HEX FLANGE HEAD CAP	CECO			
1		1 4059172	SEAL,O RING	CECO			
2		2 2871863	CLAMP,V BAND	CECO			

There are additional contract terms on the reverse side of this document, including limitation on warranties and remedies, which are expressly incorporated herein and which purchaser acknowledges have been read and fully understood.

AUTHORIZED BY (print name)

E

9/8/21



INVOICE NO

PREVIEW

TO PAY ONLINE LOGON TO  
customerpayment.cummins.com

PAGE 4 OF 5

\*\*\* CHARGE \*\*\*

DATE		CUSTOMER ORDER NO.		DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE	
CUSTOMER NO.		SHIP VIA		09-DEC-2013	ISX15 CM2350 X101		PETERBILT	
210147				FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL	
				17-JUN-2021	79691935		367	
REF. NO.		SALESPERSON		PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.	
74071					375843 / 0		357	
QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION	PRODUCT CODE	UNIT PRICE	AMOUNT	
OSN/MSNA/M								


OSN/MSN/VIN 1XPTP4EX9ED244315

2	2	2871453	GASKET, AFM DEVICE	CECO			
1	1	2866337	GASKET, AFM DEVICE	CECO			
1	1	FS19765	PAC, FS	FLG			
1	1	2866636	GASKET, AFM DEVICE	CECO			
2	2	24108	CLAMP #4	C2-OTHER			
1	1	3688113	PLUG,GEAR COVER	CECO			
2	2	24144	CLAMP #6	C2-OTHER			
19	19	4GJW3	3/8 FUEL (USE HJ30R9-06)	C2-OTHER			
1	1	24147	CLAMP #16	C2-OTHER			
2	2	CC2746	FLEETCOOL	FLG			
1	1	5299153	CONNECTOR,ELC REPAIR	CECO			
2	2	3926704	CLAMP,SPRING HOSE	CECO			
1	1	503-1872-04	CLAMP-HOSE	ONAN			
1	1	2897581	SENSOR,PRESSURE	CECO			
1	1	FMP-CB537	CLUTCH BRAKE	C1-NSPART1			
1	1	5579457RX	KIT,OVERHAUL	DRC			
1	1	OHK9457D	KIT, OVERHAUL	CLEAN			
-1	-1	OHK9457D	KIT, OVERHAUL	DIRTY			
1	1	CAP	NOW 2 YEAR 200,000 MILES	C1-			
		CERTIFICATES		CERTIFICATES			

PARTS:

PARTS COVERAGE CREDIT:

DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ AND FULLY UNDERSTOOD.

AUTHORIZED BY (print name) 

DATE

9/8/21



INVOICE NO

PREVIEW

TO PAY ONLINE LOGON TO  
customers.payment.cummins.com

PAGE 5 OF 5

\*\*\* CHARGE \*\*\*

DATE		CUSTOMER ORDER NO.		DATE IN SERVICE	ENGINE MODEL	PUMP NO.	EQUIPMENT MAKE	
				09-DEC-2013	ISX15 CM2350 X101		PETERBILT	
CUSTOMER NO.		SHIP VIA		FAIL DATE	ENGINE SERIAL NO.	CPL NO.	EQUIPMENT MODEL	
210147				17-JUN-2021	79691935		367	
REF. NO.	SALESPERSON			PARTS DISP.	MILEAGE/HOURS	PUMP CODE	UNIT NO.	
74071					375843 / 0		357	
QUANTITY ORDERED	BACK ORDERED	QUANTITY SHIPPED	PART NUMBER	DESCRIPTION		PRODUCT CODE	UNIT PRICE	AMOUNT
OSN/MSN/VIN		1XPTP4EX9ED244315						

TOTAL PARTS:

SURCHARGE TOTAL:

LABOR:

LABOR COVERAGE CREDIT:

TOTAL LABOR:

MISC.:

MISC. COVERAGE CREDIT:

TOTAL MISC.:

ELECTRONIC TOOLING FEE

HAZ WASTE DISPOSAL

SHOP SUPPLIES

NOW OVERHAUL SPECIAL

HAZ WASTE DISPOSAL CREDIT

SHOP SUPPLIES CREDIT

CITY  
LOCAL  
STATE

THERE ARE ADDITIONAL CONTRACT TERMS ON THE REVERSE SIDE OF THIS DOCUMENT, INCLUDING LIMITATION ON WARRANTIES AND REMEDIES, WHICH ARE EXPRESSLY INCORPORATED HEREIN AND WHICH PURCHASER ACKNOWLEDGES HAVE BEEN READ AND FULLY UNDERSTOOD.

SUB TOTAL:

TOTAL TAX:

US \$

27,737.77

AUTHORIZED BY (print name)

DATE

9/3/21