IIIVOIV

## Invoice

Date	Invoice #
3/15/2018	1409

			P.O. No.	Terms	Project
uantity		Description		Rate	Amount
1 1 2 1 1 2 1 16 16	Pilot Beari Valve Cover Gasket Kit	or newly rebuilt engines	s		
1	Rate of Work Done pulled the assembled the top end and rep	motor and sent it to mey laced fuel lines water pu	vers engine for rebuild we th mp and rebuilt the carb.	ien	

Date	Invoice #
11/13/2017	1278

		P.O. No.	Terms	Project
Quantity	Description		Rate	Amount
1 1 1 5	U-Joint Drive Shaft Carrier Bearing Valve Cover Gaskets Pass. Rear Brake Drum Rate of Work Done to change the right rear brake drun u-joints, and carrier bearing, replaced the exhaust syste Muffler and tailpipe, replaced the valve cover gaskets, coolant system, removed the choke cable lubed it and a choke cable works better but no change in the speedo o could be greased. Good Used Muffler and Tailpipe Assy.	m with a newer used Ford drained, flushed and re-fille dso did the speedo cable, the	d the	
9 Ford F-150			Total	\$677.