

Invoice: 1
Date / Hour: 5/26/2020 1:19:06PM
Repair Order: 5054
Customer: 4516
Branch: SITC
Total Invoice: \$25,238.99
CHARGE
Page 4 of 5

Bill To:

Ship To:

Work:	Shop:
Customer P/O: 32	Orig R/O: 0
	Completion Date: 5/21/2020

Detail Tax Info:
MO EXEMPT

\$0.00
\$0.00

Total Parts:
Total Core Charge:
Total Core Ret:
Total Labor:
Total Miscellaneous: _____
Invoice Subtotal:
Total Tax: _____
Total Invoice: \$25,238.99

Payment Method	Terms	Due Date
CHARGE	NET 30	6/25/2020

Remit To:

Invoice:
 Date / Hour: 5/26/2020 1:19:06PM
 Repair Order:
 Customer:
 Branch:
 Total Invoice: \$25,238.99
 CHARGE

Page 1 of 5

Ship To:

Customer P/O

Orig R/O: 0

Completion Date: 5/21/2020

Unit Number: QW32

Model Year: 2007

Make/Model: INTERNATIONAL 9200

Type: TRUCK

VIN: 2HSCEAPR57C370721

Meter: 955053 Miles

In-Service Date: 04/01/2006

ECM Reading: 32571

COLOR CODE 9219 WHITE

Task: 1 1200138 OVERHAUL/IN-FRAME

Department: Service

Complaint: OVERHAUL/IN-FRAME

Correction: PERFORM IN-FRAME OVERHAUL WITH NEW CYLINDER HEAD, WATER PUMP, BOTH CAMSHAFTS, ALL INTAKE & EXHAUST VALVE AND INJECTOR ROCKER ARMS.
 REPLACE HOSES, CLAMPS, & HARDWARE AS NEEDED.
 REPAIR SEVERAL WIRES IN ENGINE AND CHASSIS HARNESS THAT HAD RUBBED SPOTS, DOWN TO THE WIRES.
 REPLACE RADIATOR, ALL FILTERS, COOLANT, AND FAN BELT.
 HAD TO R & I TIRES, HOOD, COWL TRAY, WIPERS, AND AIR CLEANER ASSEMBLY AND PIPING, RADIATOR / CIA ASSEMBLY, A/C CONDENSOR, FAN AND HUB ALL FOR ACCESS.
 HAD TO EVACUATE AND RE-CHARGE A/C SYSTEM
 RE-USE INJECTORS, TURBO, AND OIL PUMP

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	105	LUBRPLATE	EA	1.0		
	1517672C81	CLAMP	EA	1.0		
	186780	SEAL	EA	1.0		
	5413782RX-C	CYLINDER HEAD -Core	EA	-1.0		
	5473364RX-C	WATER PUMP -Core	EA	-1.0		
	2000310C1	LOOM HOSE INSLTR 1.25" X 12"	EA	3.0		
	2042165C2	HOSE	EA	1.0		
	212161	O-RING	EA	1.0		
	299407C1	CLAMP	EA	2.0		
	3049221	O-RING	EA	2.0		
	3163075	PAINT - RED	EA	1.0		
	349804	1/4 NUT	EA	1.0		
	3539944C2	HOSE	EA	1.0		
	3554554C1	GUIDE BRK HOSE & CABLE*SWIVEL	EA	1.0		
	3565410C4	BELT FAN*12PK 2310 ISX 14.625"	EA	1.0		
	3582685C1	HOSE RAD OUTLET 2.5" ID FORMED	EA	1.0		
	3678756	SEALO RING	EA	1.0		
	3682826	GROMMET	EA	4.0		
	375804	1/4 LW	EA	2.0		
	377505	WASHER	EA	1.0		
	377904	1/4 FW	EA	2.0		
	3804604C1	GUIDE BRK HOSE & CABLE SPACER	EA	5.0		
	3810406	1/4X3/4	EA	1.0		
	3902662	NUT,HEXAGON FLANGE	EA	1.0		
	4004764	HOSE,PLAIN	EA	1.0		
	4026588	COVER,CAMSHAFT	EA	1.0		

** See Last Page for Invoice Total **

Invoice:
 Date / Hour: 5/26/2020 1:19:06PM
 Repair Order:
 Customer:
 Branch:
 Total Invoice: \$25,238.99
 CHARGE
 Page 3 of 5

Customer P/O:	32	Jloessen	Orig R/O:	0	Completion Date:	5/21/2020
WF2126		FILTER	EA	1.0		
ZSH5001200001Q		15W40Q	EA	47.0		
ZZBE29553		TIESTRAP	EA	10.0		
ZZBE29557		TIESTRAP	EA	43.0		
ZZBE29558		TIE STRA	EA	22.0		
FREIGHT IN		INCOMING FREIGHT		1.0		
SHOP SUP		SHOP SUPPLIES		1.0		
VOL DIS		VOLUME DISCOUNT		-1.0		

Task 1 Subtotals
 Parts:
 Core Chg
 Core Ret
 Labor:
 Miscellaneous:
 Task 1 Subtotals \$23,758.36

Task: 2 1200112 EGR VALVE - R&R

Department: Service

Complaint: CHECK ENGINE LIGHT ON

Cause: FAULTY E.G.R. VALVE.

Correction: FOLLOW DIAGNOSTIC STEPS WHICH LED TO REPLACEMENT OF E.G.R VALVE
 REPLACE E.G.R. VALVE
 REMOVE D.P.F.D.P. SENSOR AND BLOW OUT TUBES. PER INSTALLATION INSTRUCTIONS.
 CLEAR CODES AND TEST DRIVE.

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
	1817812C1	MEX16	EA	1.0		
	4955422RX-C	EGR VAL	EA	-1.0		
	373905	WASHER	EA	1.0		
	4510830	MEX30BOLT	EA	1.0		
	4955422RX	EGR VAL	EA	1.0		
	4955422RX-C	EGR VAL	EA	1.0		
	FREIGHT IN	INCOMING FREIGHT		1.0		
	LAPTOP	HOOKUP COMPUTER FEE		1.0		
	SHOP SUP	SHOP SUPPLIES		1.0		
	VOL DIS	VOLUME DISCOUNT		-1.0		

Task 2 Subtotals
 Parts:
 Core Chg
 Core Ret
 Labor:
 Miscellaneous:
 Task 2 Subtotals \$1,480.83

** See Last Page for Invoice Total **

Invoice:
 Date / Hour: 5/26/2020 1:19:06PM
 Repair Order:
 Customer:
 Branch:
 Total Invoice: \$25,238.99
 CHARGE
 Page 2 of 5

Customer P/O:	32	J/Boessen	Orig R/O:	0	Completion Date:	5/21/2020
4089405		ROD BEARING KIT	EA	6.0		
4101432		CAMSHAFT	EA	1.0		
4101451		SCREW,CAPTIVE WASHER CAP	EA	18.0		
4298626		CAMSHAFT	EA	1.0		
4311990		INJ ROCKER	EA	6.0		
4318947		TSTAT	EA	1.0		
4331263		HARNESS	EA	1.0		
4336706		SCREW,STUDDER FLANGE CAP	EA	1.0		
4376175		OVERHAUL KIT	EA	1.0		
450016C1		CNDT 1FT	EA	6.0		
4510620		M8X20BOLT	EA	1.0		
4510825		M8X25BOLT	EA	2.0		
4510830		M8X30BOLT	EA	1.0		
4511020		M10X20BOLT	EA	1.0		
465008		M8 NUT	EA	1.0		
485794C2		HOSE	EA	2.0		
4985661		SEAL RECTANGULAR RING	EA	1.0		
502607		HOSE CLAMP	EA	3.0		
502644		#44 CLAMP	EA	3.0		
502648		#48 CLAMP	EA	5.0		
5413782RX		CYLINDER HEAD	EA	1.0		
5413782RX-C		CYLINDER HEAD -Core	EA	1.0		
5473364RX		WATER PUMP	EA	1.0		
5473364RX-C		WATER PUMP -Core	EA	1.0		
5484228		ROCKER LEVER	EA	3.0		
5484229		ROCKER LEVER	EA	3.0		
5484230		LEVER,ROCKER	EA	3.0		
5484231		LEVER	EA	3.0		
584067C1		1 1/4 LOOM	EA	7.0		
640057		PERFORMANCE PLUS 50/50 ELC	EA	6.0		
80744CN		LUBRICANT	EA	1.0		
996205R3		TAPE	EA	1.0		
AF25139M		AIR FLTR	EA	1.0		
FLTREL60500		RED 50/50	EA	8.0		
FLTRI92000307		RADIATOR INTERNATIONAL FITS	EA	1.0		
F519729		FILTER	EA	1.0		
JHFK1713		CLAMP	EA	3.0		
L2643493		HOSE 1FT	EA	3.0		
L2643504		HOSE 1FT	EA	5.0		
PASN345		PINK H/S BUTT CONN	EA	10.0		
PTX51813		50ml GSKT MAKER	EA	1.0		

** See Last Page for Invoice Total **

Invoice:
Date / Hour: 5/26/2020 1:19:06PM
Repair Order:
Customer:
Branch:
Total Invoice: \$25,238.99
CHARGE
Page 4 of 5

Customer P/O:

Completion Date: 5/21/2020

Detail Tax Info:

MO EXEMPT

\$0.00

\$0.00

Total Parts:

Total Core Charge:

Total Core Ret:

Total Labor:

Total Miscellaneous:

Invoice Subtotal:

Total Tax:

Total Invoice:

\$25,238.99

Payment Method

Terms

Due Date

6/25/2020

Remit To: