

# INVOICE

BILL TO

INVOICE # 2127  
DATE 02/23/2022  
DUE DATE 03/25/2022  
TERMS Net 30

ACTIVITY	QTY	RATE	AMOUNT
Labor 2001 Sterling Dump Truck (D-14) 249,399mi 1FZXE7EB81AH49773  Transmission was slipping out of gear and the clutch was out of adjustment. Pulled transmission and found the clutch was worn and the flywheel was grooved and burned. Also found the rear main seal leaking. Section of flex pipe was crushed. Replaced with new. Had the transmission rebuilt. Replaced clutch, flywheel, pilot bearing and rear main seal.	18		
Transmission rebuild	1		
Clutch Kit	1		
pilot bearing	1		
Clutch brake	1		
Flywheel	1		
seal	2		
Exhaust clamp TLC500S	1		
flex pipe 2ft	5.50		
Transmission fluid 50wt	1		
Shop supplies Gasket maker, Non-hardening gasket maker, blue loctite, cleaning supplies etc			

SUBTOTAL

TAX

TOTAL

6,127.75

Warranty:

All parts subject to manufacturer warranty only.

Warranty does not cover labor unless we expressly give a warranty in a section above.