

Invoice

Date	Invoice #
12/27/2019	066109



Make, Model, Serial #

P.O. Number

Terms

EQUIP #

9093

Due on receipt

Description

Quantity

Amount

REPLACE ENGINE WITH A REMAN ENGINE. 5600 TOOLCAT
ENGINE
LABOR

1

MACHINE CAME IN WITH ENGINE OVERHEATING AND BLOW BY.
DETERMINED THAT THE ENGINE WAS BAD. CALLED CUSTOMER AND
CREATED ESTIMATE. REMOVED CAB, A/C SYSTEM AND REMOVED
ENGINE AND RELATED PARTS. IT TOOK EXTRA TIME AND PARTS DUE
TO CORROSION, RUST AND SEIZED BOLTS AND FITTINGS. ONCE THE
ENGINE WAS REMOVED, WE FOUND OTHER PARTS THAT WERE
DAMAGED AND NEEDED REPLACED IN ORDER FOR MACHINE TO
OPERATE CORRECTLY. SEE ATTACHED INVOICE.
DEALER DISCOUNT

*PARKS
Carter Serv.*

Subtotal

Sales Tax (0.0%)

Total

\$5,598.93

Phone #

Fax #

Web Site

Balance Due

Payments/Credits

Invoice

Date 12/27/2019 Invoice # 066110



Make, Model, Serial #

P.O. Number

Term

EQUIP #

9093

Due on receipt

Description

Quantity

Amount

REPLACE ENGINE WITH ARIEAN ENGINE, 5600 1000 CCM
THERMOSTAT
GASKET
FILTER, AIR INNER ENGINE
FILTER, AIR OUTER ENGINE
OIL, 15W40
FILTER, ENG OIL
ANTIFREEZE, COOLANT, PG 53 47 PREMIUM GAL
BELT, DRIVE
BELT, ALTERNATOR
BELT, FAN
GASKET
GASKET
GASKET
GASKET
BATTERY, WLT 650 CCM
SWITCH, PRESS OIL ENG
IDLER, BELT DRIVE ASSY
FILTER, OIL HYD
SHOP SUPPLIES
ENVIRONMENTAL FEE

1
1
1
1
8
1
4
1
1
1
1
1
1
1
1
1
1
1
1

Subtotal

Sales Tax (0.0%)

Total

Balance Due

Payments/Credits

Phone #

Fax #

Web Site

Invoice

Date

Invoice #

12/27/2019

066110



Make, Model, Serial #

P.O. Number

Terms

EQUIP #

9093

Due on receipt

Description

Quantity

Amount

LABOR

MACHINE CAME IN WITH ENGINE OVERHEATING AND BLOW BY. REPLACED ENGINE ON SEPARATE INVOICE. NEW BATTERY WAS NECESSARY BECAUSE OLD WOULD NOT HOLD CHARGE. DUE TO DAMAGED PARTS AND RELATED THIS MACHINE REQUIRED ADDITIONAL PARTS WHILE ENGINE WAS OUT OF MACHINE. FOUND THAT THE BELTS WERE DAMAGED AND CRACKED. REPLACED DRIVE ALTERNATOR AND A CLEAN BELT. IDLER INDICATOR FOR BELT TENSION AND BEARINGS WERE BAD ON BELT DRIVE ASSEMBLY. REMOVED AND REPLACED ALL FILTERS WITH NEW. INNER AND OUTER AIR FILTERS, ENGINE OIL FILTER AND ADDED NEW OIL TO SPEC. ADDED FRESH AND PROPER COOLANT TO SPEC. REPLACED HYDRAULIC FILTER BECAUSE THE SYSTEM WAS OPENED. REPLACED ENGINE OIL PRESSURE SWITCH BECAUSE THE OLD WAS LEAKING. INSTALLED ALL RELATED GASKETS.

Subtotal**Sales Tax (0.0%)****Total**

\$3,597.41

Phone #

Fax #

Web Site

Balance Due**Payments/Credits**

Estimate

Date	Estimate #
9/24/2019	4766

Name / Address

Project

Description	Qty	U/M	Cost	Total
REPLACE ENGINE WITH A REMAN ENGINE, 5600				
TOOLCAT				
REPLACE ENGINE	15			
RE-MAN ENGINE				
THERMOSTAT	1			
GASKET	1			
FILTER, AIR INNER ENGINE	1			
FILTER, AIR OUTER ENGINE	1			
OIL, 15W40	8			
FILTER, ENG OIL	1			
ANTIFREEZE/COOLANT, PG 53/47 PREMIX GAL	4			
BELT, DRIVE	1			
BELT, ALTERNATOR	1			
BELT, FAN	1			
MANIFOLD, EXHAUST	1			
GASKET	1			
GASKET	1			
GASKET	1			
GASKET	1			
SHOP SUPPLIES	1			
ENVIRONMENTAL FEE	1			
EVERY EFFORT HAS BEEN MADE TO MAKE THIS ESTIMATE ACCURATE. IT IS ONLY AN ESTIMATE. MORE PARTS OR LESS PARTS MAY BE NEEDED.				
THANK YOU VERNON				
Sales Tax				
Total				\$6,352.74

Customer Signature