		VEHICLE ID		MILES IN	MILES OUT	DATE/TIME IN		DATE OUT	INVOICE NO
		1FDAF5HR7	AEA89908	71244	1244 71244 01/1:		7/23 13:20	02/28/23	67046
		VEHICLE DESCRIPTION TAG NO.					STATUS		
		2010 FORD F550 SUPER						COMPLETE	
CONTROL NO.	LICENSE PLATE NO.	CUST. LABOR RATE	PROD. DATE	IN-SERV DATE	E DELIV DA	TE	DELIV. MILES	GI	ERMS
083864				20072-73-000-007-007-2	THE PERSON	- T 185	discussion of the second	A STATE OF THE PARTY	
CELL	PHONE 2	PHONE 1	erneus.	estanto lobolicación	erny	State of the	SWELL LAND SE		Cash
					CERT		1	ROC	OMMENT

Tech Hours Type A * A64 Customer

Concern Customer states THE VEHICLE IS SMOKING ALOT, THEY TOOK INLET OFF

TURBO AND HAS BLOW BY BLOWING FROM CAP AND HAS OIL BLOWING OUT EXHAUST. VEHICLE SEEM TO RUN OK BUT DID GO INTO REDUCE

POWER NOW, USING OIL. CHECK AND REPORT

Cause FAILED TURBO SEALS.

Correction DIAG FOUND THE C.A.C. PIPING FULL OF OIL, PERFORMED W.S.M FOR OIL CONSUMPTION, REMOVED THE VEHICLE CAB, REMOVED C.A.C PIPES AND CLEANED. REMOVED THE TURBOS AND ASSEMBLED WITH NEW. SWAPPED V.C.T. ACTUATOR, INSTALLED WITH NEW SEALS AND GASKETS. REINSTALLED THE CAB. FILLED THE FLUIDS. TEST DROVE. CHECK THE FLUIDS AND FOR LEAKS, NO C.E.L. HAD ADDED TIME FOR REGEN AFTER TREATMENT SYSTEM REQUIRED A REGEN DUE TO OIL CONTAMINATION. AND TO REPLACE A LEAKING COOLANT HOSE, TEST DROVE, CHECKED FLUIDS.OIL AND COOLANT LEVEL IS GOOD, NO C.E.L

Part Number	Description	Qty.	Unit Price Ext. Price
A,AFTERMARKET TURBO	DALES SUPER STORE	1	
8C3Z 6N640 B	GASKET	2	
W302515	SEAL	4	
W302506	SEAL	4	
388898 S	SEAL	2	
3U2Z 14A088 AB	KIT - TERMINAL	1	
AC3Z 8260 A	HOSE ASY	. 1	
VC 13 G	ANTI-FREEZE	1	

Line Total... \$6,308.19

Parts Total...

Amount

Warranty Claim Type: F

Authorization Code:

Service Cont No:

			VEHICL	EID	MILES IN	MILES OUT	DA	TE/TIME IN	DATE OUT	INVOICE N
			1FDAF5HR7	AEA89908	72453	72453	10/1	7/22 07:0	01 11/03/22	65196
			VEHICLE DESCRIPTION					TAG NO.	ST	ATUS
			2010 FORD F55	50 SUPER					СОМ	PLETE
CONTROL N		ICENSE PLATE NO.	CUST. LABOR PATE	PROD, DATE	IN-SERV DATE	DELIV. DA	ATE	DELIV. MIL	ES	TERMS
083864										Cash
CELL		PHONE 2	PHONE 3	STOCK	10.	SERV	ADV.		RO	COMMENT
ine	Op-Coc	la Eall	Code Tec				007230	000000000000		-
A	0000	rail (Amount	
oncern		er states INSTA	A6	i4	Custor	ner				
	and upp lines, m removin head lig	per hose, lower aster cylinder, ag cab bolts, fro	. 4X4 shifter exte CAC pipes, heate parking brake cab out cab bolt nuts s to gain access to	er hoses, tran ble and chas started to sp	ns cooler lin sis to cab c sin, had to r	es, hydro connectors emoved t	boos s. Wh he fro	ter en ont		
orrection	bottle, barms ar inlet an supply Remove SPEC. torqued lines, al mounted 15qts 18 truck up	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line d HPFP cover, swapped pump pump down, to Il torqued to W d cab, reconnect 5w-40, topped on lowered boom	own, got bolts to er plumbing, remo or safety. Once c ited 3 broken bo	come out, re byed cab fro ab was lifted its from turb sh before put PFP, installed installed co alled parts g/hoses, cha el system, st ve. PASSED	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip emoved to I. GEAR L r supplied gaskets a kets or w ilters and NO CEL.	ASH and for ashe oil fill back	as lift bo oil IN EP, uel irs. er.		
	bottle, barms ar inlet an supply Remove SPEC. torqued lines, al mounted 15qts 18 truck up	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line d HPFP cover, swapped pump pump down, to Il torqued to W d cab, reconnect 5w-40, topped on lowered boom	own, got bolts to er plumbing, remo- or safety. Once co sted 3 broken bol- nes checked gear loa- o gear to new HF rqued pump gear SM specs, reinst sted parts & wiring off fluids, bleed fuel took on test drive	come out, re byed cab fro ab was lifted its from turb sh before put PFP, installed installed co alled parts g/hoses, cha el system, st ve. PASSED	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip emoved to I. GEAR L r supplied gaskets a kets or w ilters and NO CEL.	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN EP, uel irs. er.	Ext. Price	
Part N	bottle, barms ar inlet an supply Remove SPEC. torqued lines, al mounted 15qts 15 truck up leaks, te	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line ed HPFP cover, swapped pump pump down. to Il torqued to W d cab. reconnect 5w-40, topped of topped of lowered boom est drove again	own, got bolts to er plumbing, remotor safety. Once conted 3 broken boltes checked gear load of gear to new HF rqued pump gear SM specs, reinstated parts & wiring off fluids, bleed fue took on test drivand retested good Description	come out, repowed cab from furbilities f	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip emoved to I. GEAR L r supplied gaskets skets or w liters and NO CEL.	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN P, uel irs. er. ed no	Ext. Price	
Part N	bottle, barms ar inlet an supply Remove SPEC. torqued lines, al mounted 15qts 15 truck up leaks, te	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line ed HPFP cover, swapped pump pump down. to Il torqued to W d cab. reconnect 5w-40, topped of topped of lowered boom est drove again	own, got bolts to er plumbing, remote safety. Once cotted 3 broken bothes checked gear load of gear to new HF rqued pump gear SM specs, reinstated parts & wiring off fluids, bleed fuels, took on test drivand retested good	come out, repowed cab from furbilities f	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip emoved to I. GEAR L r supplied gaskets skets or w liters and NO CEL.	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN P, uel irs. er. ed no	Ext. Price	
Part N	bottle, barms ar inlet an supply Remove SPEC. torqued lines, al mounted 15qts 15 truck up leaks, te	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line ed HPFP cover, swapped pump pump down. to Il torqued to W d cab. reconnect 5w-40, topped of topped of lowered boom est drove again	own, got bolts to er plumbing, remotor safety. Once conted 3 broken boltes checked gear load of gear to new HF rqued pump gear SM specs, reinstated parts & wiring off fluids, bleed fue took on test drivand retested good Description	come out, repowed cab from furbilities f	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip emoved to I. GEAR L r supplied gaskets skets or w liters and NO CEL.	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN P, uel irs. er. ed no	Ext. Price	
Part N 8C3Z	bottle, barms ar inlet an supply Remove SPEC. torqued lines, al mounted 15qts 15 truck up leaks, te	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line ed HPFP cover, swapped pump pump down. to Il torqued to W d cab. reconnect 5w-40, topped of topped of lowered boom est drove again	own, got bolts to er plumbing, remo or safety. Once cotted 3 broken bothes checked gear load gear to new HP rqued pump gear SM specs, reinstated parts & wiring off fluids, bleed fuels, took on test drivand retested good Description PUMP ASY - F	come out, re proved cab fro ab was lifted lts from turb sh before pu PFP, installed installed co alled parts g/hoses, cha el system, st we. PASSED ad at this tim	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip moved to I. GEAR L r supplied gaskets of kets or w ilters and NO CEL oak overn Otty. 1	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN P, uel irs. er. ed no	Ext. Price	
Part N 8C3Z	bottle, barms ar inlet an supply Remove SPEC. torqued lines, al mounted 15qts 15 truck up leaks, te Number 9A543 Di	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line ed HPFP cover, swapped pump pump down. to Il torqued to W d cab. reconnect 5w-40, topped of topped of lowered boom est drove again	own, got bolts to er plumbing, remoor safety. Once coted 3 broken bothes checked gear load of gear to new HF rqued pump gear SM specs, reinstated parts & wiring off fluids, bleed fuels, took on test drivand retested good Description PUMP ASY - F CLEAN CORE DIRTY CORE	come out, re proved cab fro ab was lifted lts from furb sh before pu PFP, installed , installed parts g/hoses, cha el system, st ve. PASSED ad at this time FUE	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip moved to I. GEAR L r supplied gaskets of kets or w ilters and NO CEL oak overn Otty. 1	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN P, uel irs. er. ed no	Ext. Price	
Part N 8C3Z	bottle, barms ar inlet an supply Remove SPEC, torqued lines, al mounted 15qts 18 truck up leaks, te Number 9A543 Di 9A332 A 9A332 B	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line ed HPFP cover, swapped pump pump down. to Il torqued to W d cab. reconnect 5w-40, topped of topped of lowered boom est drove again	own, got bolts to er plumbing, remo or safety. Once conted 3 broken bothes checked gear load or gear to new HP rqued pump gear SM specs, reinstated parts & wiring ff fluids, bleed fuels, took on test drivand retested good Description PUMP ASY - FOLEAN CORE DIRTY CORE TUBE - FUEL	come out, re proved cab fro ab was lifted lts from furb sh before pu PFP, installed , installed parts g/hoses, cha el system, st ve. PASSED ad at this time FUE	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip moved to I. GEAR L r supplied gaskets of kets or w ilters and NO CEL oak overn Otty. 1	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN P, uel irs. er. ed no	Ext. Price	
Part N 8C3Z 8C3Z 8C3Z W303	bottle, barms ar inlet an supply Remove SPEC, torqued lines, al mounted 15qts 18 truck up leaks, te Number 9A543 Di 9A332 A 9A332 B	ded cab nuts do patteries, air filte d chained off f d pipes. extract line and fuel line ed HPFP cover, swapped pump pump down. to Il torqued to W d cab. reconnect 5w-40, topped of topped of lowered boom est drove again	own, got bolts to er plumbing, remoor safety. Once conted 3 broken bothes checked gear load gear to new HP rqued pump gear SM specs, reinstated parts & wiring iff fluids, bleed fuels, took on test drivand retested good pescription PUMP ASY - FUEL TUBE - FUEL TUBE - FUEL	come out, re proved cab fro ab was lifted lts from furb sh before pu PFP, installed alled parts g/hoses, cha el system, st ve. PASSED d at this tim FUE SU SU	emoved bat m frame, st d, removed to inlets, re imp removal d customer over w/ new w/ new gas unged fuel fi arted truck, o, let cold se	tery trays trapped of down pip emoved to I. GEAR L r supplied gaskets of skets or w ilters and NO CEL oak overn Qty. 1 1 1 1 1	ASH ASH and fi ashe oil fill back hight,	as lift bo oil IN P, uel irs. er. ed no	Ext. Price	