

REPAIR ORDER # 000002525

PAGE: 2

11/19/18 02:35 pm

VEHICLE: 49 GMC

LICENSE: 131027/KS

MILEAGE: 41718

VIN: A24881696

FLEET:

ENGINE: Cyl -- Disp -

PHONE 1:

PHONE 2:

TERMS: Net 30

LABOR			PARTS		
OP	DESCRIPTION	CHARGE	QUAN	PART # / DESCRIPTION	PRICE BY
	CHANGE ENGINE OIL, GREASE CHASSIS, HOIST & UJOINTS. ALL ZERKS HARD TO TAKE GREASE. CLEAN OUT REMOTE OIL FILTER HOUSING OF DECADES OLD OIL DEPOSITS. ADDED MOLY ENGINE OIL TREATMENT. FILL TRANS & REAR END.		5.0 CQ630	10W-30 MOTOR OIL	
			3.0 780-05	80W-90 GL-5	
06 DS	LIGHTS	292.50	1.0 02742-029	MOLY EP SYN GREASE	
	CUSTOMER WANTED ALL LIGHTS & FUEL GAUGE WORKING. REPLACED RUSTED BOLTS, BAD WIRING, POOR GROUND CONNECTIONS & BAD SWITCHES. REPLACE & WIRE IN TURN SIGNAL ASSEMBLY & DIMMER SWITCH. REPLACE ALL 4 BED CORNER LIGHTS, BRAKE, TURN, PARK LAMP ASSEMBLYS. CLEAN TAG LIGHT & REPLACE BULB. MAKE GROUND WIRE FROM FRAME TO BED. CHECK & R&R BRAKE PRESSURE SWITCH ON FRAME & REWIRE FROM SWITCH TO TURN SIGNAL ASSEMBLY. REWIRE ALL LIGHTS ON BED, REAR PARK, BRAKE, TURN, TAG & FRONT PARK & TURN LIGHTS & HEAD LIGHT SWITCH. CHECK & REPLACE 1 FUSE, 1 FRONT TURN & 1 PARK LIGHT BULBS & MAKE GROUND WIRE, RESEAL 4 FRONT TURN LENSES. CHECK FUEL SENDER & GAUGE, REWIRE FROM FUEL SENDER TO GAUGE.		1.0 0132-023	MOLY EP OIL TREATM	
			2.0 1114102	14 GA WIRE WHITE	
			28.0 1116105	16 GA WIRE BLACK	
			11.0 381844310007	HEAT SHRINK CONNEC	
			3.0 3100SMALL	COTTOR PIN ASSORTM	
			8.0 31WS	5/16 LOCK WASHER	
			7.0 31NF5	5/16-18 NUT	
			3.0 31WUSS	5/16 FLAT WASHER	
			1.0 3124CH50	5/16-18X1-1/2 BOLT	
			5.0 3112CH50	5/16-18X3/4 BOLT	
			13.0 14WUSS	1/4 FLAT WASHER	
			8.0 14WS	1/4 LOCK WASHER	
			6.0 14NF5	1/4-20 NUT	
			2.0 1416CH50	1/4-20X1 BOLT	
			2.0 1408CH50	1/4-20X1/2 BOLT	
			4.0 37WS	3/8 LOCK WASHER	
			2.0 3720CH50	3/8-16X1-1/4 BOLT	
			12.0 STP130	OEM WIRE TERMINAL	
			12.0 STP131	OEM WIRE TERMINAL	
			1.0 W541	WEATHER HEAT SHRIN	
RECOMMENDATIONS:			1.0 AGC20BP	GLASS FUSE	
			5.0 1412CH50	1/4-20X3/4 BOLT	
			2.0 67	MINIATURE LAMP	

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

(Signature) _____

CUSTOMER ACKNOWLEDGEMENT

QUOTES:

SURCHARGE SHOP/MISC SUPPLIES
FREIGHT

SURCHARGE TOTAL: \$
 FREIGHT: \$
 LABOR: \$
 PARTS: \$
 SUBLET: \$
 HAZ WASTE: \$
 SUPPLIES: \$
 DISCOUNT: \$
 NON TAXABLE: \$
 TAX: \$
 TOTAL: \$
 PAYMENTS: \$
 DUE: \$

2533

11/19/18 02:35 pm

VEHICLE: 43 GMC
LICENSE: 131027/KS
MILEAGE: 41718
VIN: A24881696FLEET:
ENGINE: Cyl -- Disp -PHONE 1: [REDACTED]
PHONE 2: [REDACTED]
TERMS: Net 30

LABOR

OP DS DESCRIPTION CHARGE

CARB KIT

REMOVE CARBURATOR, FOUND TO BE VERY RUSTY & THROTTLE
SHAFT WORE OUT. SENT UPPER HALF OF CARB TO HARRYS TO
HAVE BUSHINGS MADE TO TAKE UP 3/4 OF PLAY. HAD TO
SOAK LOWER & CARB INLET FILTER FOR 3 DAYS TO LOOSEN &
CLEAN UP FILTER, CHECK VALVE & ACCELERATOR PUMP TO
GET OUT. FOUND ACCELERATOR PUMP NOT REUSABLE & HAD TO
ORDER A NEW ONE. PUT CARB TOGETHER WITH NEW KIT.
ADDED INLINE FUEL FILTER. INSTALL CARB, CLEAN OIL
BATH OUT. FILL & MAKE NEW GASKET FOR AIR FILTER
HOUSING. RAN ENGINE & ADJUST CARB. TEST DRIVE, NO
PROBLEMS FOUND.

08 DS FILL HOIST

TEST PTO BY RAISING BED, ADDED ONE GALLON HYDRAULIC
OIL & REPLACE WORE OUT FILL PLUG. WORKED BED UP &
DOWN TO CHECK OPERATION, NO PROBLEMS FOUND.

09 DS MISSING BOLTS

FOUND MISSING GENERATOR BOLT, REPLACE & TIGHTEN BELT.
HOOD, FLOOR PANS & ENGINE COVERS WERE MISSING BOLTS &
SCREWS. REPLACE THEM.

* RESURFACE FLYWHEEL

* CARB BUSHINGS

PARTS

QUAN	PART # / DESCRIPTION	PRICE EX
2.0	85432 BULLET TERM FEMALE	
3.0	1035 CARB CLEANER	
1.0	CQ530 30W OIL	
1.0	86032 FUEL FILTER	
3.0	5202 #4 HOSE CLAMP	
1.5	CQ24078 5/16 FUEL HOSE	
8.0	80206 3/16 VAC HOSE	
2.0	M12D125A 12MFW	
1.0	SUS35 303 HYDRAULIC OIL	
1.0	64892 1/2 PIPE PLUG	

RECOMMENDATIONS:

I hereby authorize the above repair work to be done with the necessary material and hereby grant you and/or your employees permission to operate the car, truck or vehicle herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanics lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto. You will not be held responsible for loss or damage to vehicle or articles left in vehicle in case of fire, accident or any other cause beyond your control.

Signature) _____

CUSTOMER ACKNOWLEDGEMENT

NOTES:

SURCHARGE
SHOP/MISC SUPPLIES
FREIGHT

SURCHARGE TOTAL:	\$
FREIGHT:	\$
LABOR:	\$
PARTS:	\$
SUBLET:	\$
HAZ WASTE:	\$
SUPPLIES:	\$
DISCOUNT:	\$
NON TAXABLE:	\$
TAX:	\$
TOTAL:	\$
PAYMENTS:	\$
DUE:	\$

2533.77