

UNIT# HG6000TX HG6000TX VERMEER CHIPPER

REPAIR ORDER SUMMARY DATA

CUST#

RO# C6127

START 7/23/20 14:04

BILLED 2/11/21 08:20

PO#

WRITER

PHC 01

PBC 00

APPROVAL

/SMH

REPAIR ORDER TOTALS BY PAY TYPE

C PRB 1

I PRB 0

W PRB 0

BILLED 2/11/21 08:20 SMH

BILLED

BILLED

LABOR

PARTS

SUBLET

OTHER

MISC EXP

MISC CHARGES

DEDUCTIBLE

TAX

TOTAL DUE

SERVICE UNIT INFORMATION

OWNER 1530 UNIT# HG6000TX HG6000TX VERMEER CHIPPER

CURR HRS

VIN: 1VR2390A491000314 2371955

ENGINE: WJH05105

2ND KEY:

SERIES:

CYLINDERS:

CID:

GVWR:

COLOR:

PROBLEM # 01 DETAILS

PRB# 1 LABOR TYPE 1CRB ENGINE REBUILDING

** BILLED **

COMPLAINT: CHECK ENGINE WILL NOT START

CORRECTION: CHECK FOUND ENGINE WOULD NOT TURN OVER REMOVED ENGINE FROM

CHIPPER REMOVE OIL PAN FOUND BEARING MATERIAL IN PAN

DOWNLOADED HISTORY FROM ECM FOUND USED ENGINE WITH SAME

ARRANGEMENT NUMBER INSTALL CLUTCH AND MISC PARTS TO FIT

APPLICATION REPAIR AIR CLEANER INSTALL UNIT IN CHIPPER ADJUST BELT

REPLACE LEAKING HOSES START AND RUN UNIT

HOLD STATUS: F FINISHED

OPR# 1

SKILL LEVEL:

TECH #: 034

LABOR:

52.00

PARTS:

C18E-U

ENGINE (US

1.00

126-2702

SEAL

1.00

198-6068

SEAL

1.00

4N0699

GSKT

1.00

129-9452

GSK

6.00

117-8801

O-RING

1.00

188-0210

PAN GSK

2.00

159-0926

SEAL WASHE

19.00

227-0838	SEAL	1.00
114-2687	O-RING	1.00
5P8068	SEAL	1.00
5P5846	SEAL O RIN	1.00
1R1808	OIL FILTER	2.00
1R0749	FILTER	1.00
326-1643	FUEL/WATER	1.00
1S4295	GASKET	1.00
101-3125	GSKT	1.00
24073	WATER FILT	1.00
155-5619	GASKET	1.00
6V8969	TRUSSE HEA	9.00
71545-00	SPEED SENS	1.00
3926704	CLAMP,S	2.00
2422	AIR FILTER	2.00
2423	AIR FILTER	2.00
M10TR	THREADED R	1.00
7N3448	OIL SUPPLY	1.00
15W40	GAL OIL	14.00
AF	GAL ANTI F	20.00
AW32	GAL HYD FL	7.00
OTHER:	NEW ESN WJH01688	
	FREIGHT NON-TAX	1.00
1	LABOR	
	PARTS	
	SUBLET	
	OTHER	

REPAIR ORDER TOTALS

LABOR SALE
PARTS SALE
OTHER SALE
REPAIR ORDER SUBTOTAL
TOTAL MISC CHARGES
TOTAL DUE

24,191.28