

PARTS & ACCESSORIES

PART NO. DESCRIPTION
HUBB Sub bearing
1998 Explorer
1998 Explorer
1998 Explorer

REPAIR ORDER NO.
23927

DATE
7-25-17
MECHANIC
Leather
CHARGE

TYPE IDENTIFICATION NO. LICENSE NO. SPEEDOMETER READING
1998 Explorer IFM7U35P0W2B34901 2908

rotational noise LF
replace LF wheel hub & bearing assembly, chain & install x-fer case Labor

pd 468
CK# 202

I HEREBY AUTHORIZE THE ABOVE REPAIR WORK TO BE DONE ALONG WITH NECESSARY MATERIALS. YOU AND YOUR EMPLOYEES MAY OPERATE ABOVE VEHICLE FOR PURPOSES OF TESTING, INSPECTION OR DELIVERY AT MY RISK. AN EXPRESS MECHANIC'S LIEN IS ACKNOWLEDGED ON ABOVE VEHICLE TO SECURE THE AMOUNT OF REPAIRS THERETO. YOU WILL NOT BE HELD RESPONSIBLE FOR LOSS OR DAMAGE TO VEHICLE OR ARTICLES LEFT IN VEHICLE IN CASE OF FIRE, THEFT, ACCIDENT OR ANY OTHER CAUSE BEYOND YOUR CONTROL.

TOTAL LABOR
TOTAL PARTS
OUTSIDE LABOR
TAX
TOTAL 485.87

TOTAL PARTS

SIGNED

CUSTOMER COPY

BUS:	COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
			98 FORD EXPLORER	1FMZU35P0WZB34901		58478/58478	
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
12AUG11	IS		18:30 112AUG11			CASH	16AUG11
12AUG11	DI						
R.O. OPENED	READY	OPTIONS: ENG:5.0_Liter_EFI					

14:04 12AUG11 14:11 16AUG11
 LINE OPCODE TECH TYPE HOURS
 A ABS LIGHT STAYS ON - ADVISE.

LIST	NET	TOTAL
GEN GEN		
518 CF		
2 R515003 CQ BRG HUB ASSY		
LABOR:	0.00	200.00
OTHER:		
TOTAL LINE		

DIAGNOSE AND FOUND FRONT WHEEL SPEED SENSOR AT FAULT.ADVISE
 CUSTOMER FRONT WHEEL SPEED SENSOR ARE PART OF FRONT WHEEL BEARING HUB
 ASSEMBLIES. ESTIMATE AND ADVISED. REPLACED BOTH FRONT WHEEL HUB/BEARING
 ASSEMBLIES.

 CUSTOMER PAY SHOP CHARGE FOR REPAIR ORDER 16.95

We would like to thank you for choosing us
 for your vehicle needs. We aim to provide you
 with excellent service. You may receive a
 Factory Survey, if you cannot answer
 EXCELLENT or if you have any questions,
 please call our Service Center. Thank you for
 your business and we hope to see you again.

Thank you for your business

Your complete satisfaction is our #1 concern. If
 you have any questions, comments, or if we can
 be of further assistance please contact us.



LINCOLN

STATEMENT OF DISCLAIMER

The factory warranty constitutes all of the warranties
 with respect to the sale of this item/items. The Seller
 hereby expressly disclaims all warranties either
 express or implied, including any implied warranty of
 merchantability or fitness for a particular purpose.
 Seller neither assumes nor authorizes any other person
 to assume for it any liability in connection with the
 sale of this item/items. THERE WILL BE A \$30 FEE
 CHARGED ON ALL RETURNED CHECKS.

CUSTOMER SIGNATURE

DESCRIPTION

LABOR AMOUNT
 PARTS AMOUNT
 GAS, OIL, LUBE
 SUBLET AMOUNT
 MISC. CHARGES
 TOTAL CHARGES
 LESS INSURANCE
 SALES TAX

PLEASE PAY
 THIS AMOUNT

732.09

CUSTOMER COPY

	182.95
Subtotal	0.00
Sales Tax	0.00
Discount	182.95
Total	182.95
Total Payment	\$0.00
Change	

Thank you for your business!!