]	Branch					
		4				
		Time	Page			
	08/27/21	20:18:25 (B)	01			
	Account No.		Invoice No.			
			J69926			
1	Ship Via					
	Sales Tax License No.					
		Salesperson				
DESCRIPTION						

STK#/FLEET#

HRS PIN/EIN

WARRANTY DATE

HRS

LU267161

850K C/A WT/LT DOZ 850K

If we can be of further assistance, please contact us at 936-634-8801.

3561 1T0850KXPEE267161

06/07/16

5000

Thank you for choosing Doggett Machinery Services for your service needs.

SEGMENT# 1 C 2407 XTRAVEL

06/03/21 06/03/21 06/11/21

TRAVEL TIME AND MILEAGE

MACHINE IS ON CAFE ROAD BY HIS BARN

LABOR

10401101

SEGMENT TOTAL ==>

```
SEGMENT# 2 C CUST XMISC
                               06/03/21 06/03/21 06/11/21
MACHINE WONT START
 **** TECHNICIANS COMMENTS *******************
*2637 Attempted to spin engine over. Nothing happened,
 *batteries and found a terminal melted. Cleaned the terminal *
 *and I was able to spin engine over. The engine sounded like *
 *it had lost compression and oiling issue. Machine needs to *
 *come to shop.
                                                               LABOR
10401101
                                                    SEGMENT TOTAL ==>
SEGMENT# 3 C CUST XMISC
                               06/03/21 06/03/21 06/11/21
GET MACHINE READY TO LOAD
                                                               LABOR
                                                    SEGMENT TOTAL ==>
 10401101
```

CONTINUED ON PAGE 02

	Branch				
	Date		Time		Page
	Date	08/27/21	20:18:25	(B)	
	Account No.	00/11/11	Ohone No	127	Invoice No.
					J69926
	Ship Vla	•		_	
	Sales Tax Licer	ise No.	F,S,T, ID		
			Salesperson		
I I			Salespeison		018
	DESCRIPTION				
·					
STK#/FLEET# HRS PI	N/EIN	WARRANTY DAY	re Hrs		
	0850KXPEE2671				
850K			5000		
SEGMENT# 5 C CUST XMISC 06/03/21 0	6/03/21 06/11	/21			
REMOVE ENGINE FOR INSPECTION					
**** TECHNICIANS COMMENTS ********	*******	*****			
*		*			
*Pushed machine into shop. remove engine.					
*removed engine and mount on engine stand					
*and rod caps took pics of damage, reinst *7-23-21 Crate up all components and drag					
*outside, clean work area. #2407 7-29-21	machine back	*			
*#2407 7-30-21					
*		*			
**********	******	*****			
		LAB	OR		
10401101	SE	GMENT TOTAL=	=>		
					_
	08/09/21 07/21	./21			
Clean Machine		7.37	on		
10401101	CE	LAB =:GMENT TOTAL			
10401101	SE	GMENI TOTAL	-/		
SEGMENT# 7 C CUST 10-020-068 08/03/21 0	08/03/21 07/21	/21			
ENGINE, R&R					
Drain engine oil and coolant.					
Remove precleaner, hood, muffler, air cle	eaner,				
and radiator.					
Remove engine.					
Replace with new Engine					
Assemble in reverse order.		*****			
**** TECHNICIANS COMMENTS ********					

CONTINUED ON PAGE 03

		Branch					
	1	Date		ílme			Page
	- 1		08/27/21		20:18:25	(B)	03
		Account No.		Phone	P No.		Invoice No.
)	J69926
		Ship Via			Purchase Orde	er	
		Sales Tax License	e No.		F.S.T. ID		
≤					Salesperson		
						018	
DESCRIPTION							

```
STK#/FLEET#
                                 HRS PIN/EIN
                                                      WARRANTY DATE
                                                                       HRS
LU267161
           850K C/A WT/LT DOZ
                                3561 1T0850KXPEE267161
                                                         06/07/16
                                                                      5000
 *Push machine back into shop transfer needed components
 *from old engine onto new engine, start installing engine
 *into
 *machine. #2407 8-6-21
 *install engine. #2407 8-6-21
 *#2407 8-9-21 install engine
 *#2407 8-9-21 install engine and recoonect all componants.
 *#2407 8-10-21 remove cleaned and reassemble all 4 multi
 *function valves.
 *install engine, replaced fuel filter, air filters, install
 *hood, top off hydraulic oil. #2407 8-10-21
 *program ECU tried to start engine, batteries were bad
 *replaced both batteries and cleaned terminals start engine
 *and checked oil pressure and for leaks. #2407 8-11-21
 *run machine, install sheet metal. #2407 8-11-21
 *clean work area, install old engine on return stand for
 *core. #2407 8-13-21
 ****drain hydraulic and transmission resivoirs and changed
 *both filters*** #2407 8-16-21
 **************
                               FILTER ELEMENT
                                                      1
 AT365870
                               FILTER ELEMENT
 AT370279
                                                      1 N
                               Cover
 AT410527
                               CORE
                                                      1-
 CRPE11123
                                                      2
 DRC4223-C
                               BX, SHOP TOWEL
                               FILTER ELEMENT
 F071151
                                                     1 N
                               Diesel Engine
 PE11123
                               FILTER KIT
 RE541746
                               SEALING RING
                                                      1 S
 R300529
                                                      CONTINUED ON PAGE 04
```

,

	Branch						
	Date 08/27/21	08/27/21 Time 20:18:25 (B)					
	Account No.	lo. Phone No.					
	Ship Via	Purchase Order					
	Sales Tax License No.	F.S.T. ID					
N		018					
DESCRIPTION							

STK#/FLEET#	050% 5/2	/- m	202		PIN/EIN		ANTY DATE	HRS	
LU267161	850K C/A	WT/LT	DOZ	3561	1T0850KXPEE	267161	06/07/16		
	850K							5000	
R522690				GASKET		1			
R529509				GASKET		1			
R529510				GASKET		1			
TY26575				COOL-GAR	D 1GAL	12			
T176296				WING SCR	EW	2 N			
19M7572				CAP SCRE	W	6			
24M7239				WASHER		6			
51M7045				O-RING		1			
							PARTS		
							LABOR		
10401101						SEGMENT	TOTAL==>		

```
SEGMENT# 8 C CUST 10012000D 08/03/21 08/12/21 07/21/21
2000 HOUR SERVICE WIT4
**** TECHNICIANS COMMENTS *******************
 *Change cab air and re circulation filters.
 *Change engine air filter(s).
 *Change engine oil and filter.
 *Change final drive oil.
 *Change fuel filter(s).
 *Change hydraulic filter element(s).
 *Change hydraulic oil.
 *Change open crankcase vent filter.
 *Change transmission filter(s) element(s).
 *Change transmission oil.
 *Check air intake system.
 *Check battery electrolyte level and tighten terminals.
 *Check coolant and add conditioner or extender.
 *Check coolant heater.
                                                      CONTINUED ON PAGE 05
```

		LUFKIN TX				
		Date Time				
	!)		05	
		Account No. Friome No.			Invoice No.	
			J69926			
-		Ship Via		Purchase Order	•	
		Sales Tax License No.		F.S.T. ID		
	:					
1 = 1				Salesperson		
					018	
DESCRIPTION						

STK#/FLEET#	HRS	PIN/BIN	WARRA	NTY DATE	HRS
LU267161 850K C/A WT/LT DOZ	3561	1T0850KXPEE2671	61	06/07/16	
850K					5000
*Check coolant level.				*	
*Check track frame pivot oil le	evel.			*	
*Lubricate C-Frame dozer linkag	ge.			*	
*Lubricate push beam dozer link	tage.			*	
*Lubricate push beam lift cylin	nder piv	ots.		*	
*Lubricate right and left end of	crossbar	pivot.		*	
*Lubricate ripper.				*	
*Test coolant.				*	
*Test diesel fuel.				*	
*Test engine oil.				*	
*Test final drive oil.				*	
*Test hydraulic oil.				*	
*Test transmission oil.				*	
*drain both outer final drives.	#2407	8-12-21		*	
*drain both inner final drives,	fill b	oth inner and ou	ter	*	
*final drives with new oil, cha	anged a/	c fresh air filt	ers.	*	
*#2407 8-12-21				*	
*fill hydraulic and hydrostatic	resivo	irs with new oil		*	
*#2407 8-16-21				*	
*				*	
*********	*****	*******	****	***	
AR69444	5 GAL H	YD OIL	3		
AT191102	AIR FIL	TER	2		
AT315957	FILTER	ELE	1		
AT318160	FILTER		2 S		
FRT	SHIP &	HANDLING	1		
TY26682	Plus-50	II Oil 2	67		
Plus-50 II Oil	15W40 C	J4/SN			
TY6354	1GAL HY	GARD	2		

	_	1	Branch						
		Ī	Date	08/2	7/21	Time 2	0:18:25 (B)	Page	06
		Ì	Account No.		,,,,,,	Phone		Invoice	
	-		Ship Via			1	Purchase Order		3320
			Sales Tax Lice	nse No.			F.S.T. ID		
≧							Salesperson	018	
,		DESC	RIPTION						
TK#/FLEET# LU267161 850K C/A WT/LT DOZ		PIN/EIN 1T0850KX			ANTY DATE 06/07/16		HRS		
850K	, 5501	11000011			LABOR		5000		
10401101			SE	GMENT	TOTAL	>			
SEGMENT#10 C CUST NA Install Rear Glass	08/11/21							_	
***** TECHNICIANS COMMENTS ***					*				
*Clean glass surface and insta *motor and wiper arm. #2407 8	-12-21			er	*				
*install new wiper motor on re	ar glass.	#2407	8-13-21		*				
				and the state of the state of					

***** WORK ORDER TOTALS *****

PARTS LABOR

DEDUCTIBLE

HAULING

TOTAL CHARGE

39418.51