Invoice To Account No:		Deliver To:				2EVA	ICE IIAAC	
	1.			inv	oice Numb		12400	
					Invoice D		02/03/	50
					Locati		452	9236
					Order Numb		152	3230
				1 '	Payment Ty	pe:		
					Pa	ge:		1 of 2
Make/Model:		Meter	Serial Number:		2 ld:		leet No:	
JOHN DEERE CP690		1200	1N0C690PE3407	0393 11	IOC690PEJ	4070393		
Service Reminders: TRUCK TRIP 3 Reta	ail							
COMPLAINT:								
01 Trin Fee for Service	e Truck 31-60 miles	from closest UAT loca	tion					
Parts Location:								
Tax Region:ss								
Where From:								
Extra Mileage: Trips Made:								
Trips Made.								
CAUSE:								
CORRECTION:								
7.4.1. 5400.00								
Job Total: \$480.00				-				
Gen- Retail								
COMPLAINT:								
WONT MOVE								
CAUSE:								
CORRECTION:								
		ic pump solenoid to be						
1/9 removed old sole control unit, traced of location, left location	ircuit down to find st	soleriold, tested operat out in wiring to PTP co	ion, machine still no ntroller, repaired wir	t moving due ing and testo	e to commi ed machine	unication is a operation	ssues with tran	smission and
PartNumber	Description			Quantity	List Price	Net Price	Extended Price	Taxed Ind
AXE13473	SOLENOID V							Tausel Inc.
Miscellangous	Description			Quantity	List Price	Net Price	Extended Price	Taxed ind
FREIGHT	FREIGHT							
Labor:	Parts: :	OL&M:	Misc:			Sub-Total:		

Deliver To:

SERVICE INVOICE

Invoice To Account No:	Deliver To:		SERVIC	E INVOIC
		Invoice N	umber:	12400291
		Invoi	ce Date	02/03/2023
		III	ocation:	50
		Work Order N		1529236
		Paymer	nt Type:	
			Page:	2 of 2
Make/Model:	Meter Sedal Number:	EQ ld:	Fleet	No:
JOHN DEERÉ CP690	1200 1N0C690PEJ4070	393 1N0C690	PEJ4070393	
Service Reminders:	Finance Information			
Customer PO No: 1004	Type: Farm Plan Auth	No: 881578	Job Total:	
Tax Exempt No:	Merchant No: 64000842	001070	Sales Tax:	
Advisor:	Card No:			
	Bill Code:		Total:	\$2,194.64
	Credit Plan:			
This purchase(s) is subject to the terms of	the Multi-Use Account, a service of John Deere Fina It, in the goods described.	ncial, f.s.b. Il grent ti	he issuer a purchase	a money security
TERMS AND CONDITIONS This purchase(s) is subject to the terms of interest, except as fimited in that agreemen	the Multi-Use Account, a service of John Deere Fina it, in the goods described.	ncial, f.s.b. Il grent ti	he issuer a purchase	a money security

Work Order Number: 128658: Payment Type;	Invoice To Account No	:	Deliver To:					SER	VICE INV	OICE
Make/Model: Meter Serial Number: EQ Id. Fleet No: JOHN DEERE CP690 156 1NDC690PEJ4070393 1N0C690PEJ4070393 Service Reminders: Trip3 Retail IOMPLAINT: 1 Trip Fee for Service Truck 31-60 miles from closest UAT location arts location: 06 IX region: PARIS AUSE: ORRECTION: De Total: { en- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: UItiple Techs, Multiple trips prected by replacing failed connector, did a patch job to get machine running on second day. Lixthumber Description ELEC. CONN CYASIO1 BRAKE AND PARTS CLEANER							Invoice Lock & Order Nu	e Date cation: imber:	01/1	16/2023 50
JOHN DEERE CP590 155 1NOC690PEJ4070393 1NOC690PEJ4070393 Service Reminders: Trip3 Retail OMPLAINT: 1 Trip Fee for Service Truck 31-60 miles from closest UAT location arts location: 06 tx region: PARIS AUSE: ORRECTION: Db Total: { en- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: Ultiple Techs, Multiple trips orrected by replacing falled connector, did a patch job to get machine running on second day. Bathwinter Describing Index Net Price Extended Price Taxed TM10610 ELEC. CONN TAXABLE PRICE TAXABLE PRICE TAXABLE PRICE TAXABLE PRICE TAXABLE TAXABLE TAXABLE PRICE TAXABLE PRI								Page:		1 of 2
Service Reminders: Trip3 Retail COMPLAINT: 1 Trip Fee for Service Truck 31-80 miles from closest UAT location and location: 06 arts location: 06 ax region: PARIS AUSE: CORRECTION: Db Total: {	Make/Model:			Meter	Serial Number:		EQ ld:		Fleet No:	
Trip3 Retail OMPLAINT: 1 Trip Fee for Service Truck 31-60 miles from closest UAT location arts location: 06 ix region: PARIS AUSE: ORRECTION: Ob Total: { en- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips orrected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Parison State Price Extended Price Taxed M10610 ELEC. CONN SRAKE AND PARTS CLEANER				156	1N0C690PEJ4070	393	1N0C690P	EJ4070393		
1 Trip Fee for Service Truck 31-60 miles from closest UAT location ants location: 06 ax region: PARIS AUSE: ORRECTION: Ob Total: en- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: Token Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips were cled by replacing failed connector, did a patch job to get machine running on second day. were tribumber Description M10610 ELEC. CONN SPAKE AND PARTS CLEANER										
arts location: 06 tx region: PARIS AUSE: ORRECTION: Db Total: { fen- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips orrected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Quantity List Price Net Price Extended Price Taxed 7/10610 ELEC. CONN	OMPLAINT:									
AUSE: ORRECTION: Db Total: en- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips orrected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description TM10610 ELEC. CONN V26101 BRAKE AND PARTS CLEANER	1 Trip Fee for Servic	e Truck 31-60 miles	from closest UA	T locatio	n					
corrected by replacing failed connector, did a patch job to get machine running on second day. arthumber Description Quantity List Price Nat Price Extended Price Taxed 7/26101 BRAKE AND PARTS CLEANER										
cen- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips prected by replacing failed connector, did a patch job to get machine running on second day. arthumber Description Quantity List Price Net Price Extended Price Taxed TM10610 ELEC. CONN 26101 BRAKE AND PARTS CLEANER	AUSE:									
en- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips prected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Quantity List Price Net Price Extended Price Taxed 7/410610 ELEC. CONN 7/26101 BRAKE AND PARTS CLEANER	ORRECTION:									
en- Retail OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips orrected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Quantity List Price Net Price Extended Price Taxed 7M10610 ELEC. CONN Y26101 BRAKE AND PARTS CLEANER										
OMPLAINT: LECTRICAL ISSUES WITH BLOWER FAN AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips prected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Quantity List Price Net Price Extended Price Taxed 7/410610 ELEC. CONN 9/26101 BRAKE AND PARTS CLEANER	ob Total: (
AUSE: Token Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips Perceted by replacing failed connector, did a patch job to get machine running on second day. INTROMOSE THUMBER OBESCRIPTION OUANNITY DESCRIPTION EXTENDED OUANNITY DESCRIPTION OUANNITY DESCRIPTION OUANNITY DESCRIPTION OUANNITY DESCRIPTION OUANNITY DESCRIPTION OUANNITY OUANNITY DESCRIPTION OUANNITY OUA	en- Retail									
AUSE: roken Wire at the HIC connector ORRECTION: ultiple Techs, Multiple trips orrected by replacing failed connector, did a patch job to get machine running on second day. orthweet Description Quantity List Price Not Price Extended Price Taxed TM10610 ELEC. CONN 726101 BRAKE AND PARTS CLEANER	OMPLAINT:									
ORRECTION: ultiple Techs, Multiple trips prected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Quantity List Price Net Price Extended Price Taxed TM10610 ELEC. CONN Y26101 BRAKE AND PARTS CLEANER	LECTRICAL ISSUES	WITH BLOWER FA	AN							
ORRECTION: ultiple Techs, Multiple trips prected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Quantity List Price Net Price Extended Price Taxed TM10610 ELEC. CONN Y26101 BRAKE AND PARTS CLEANER	AUSE:									
ultiple Techs, Multiple trips prected by replacing failed connector, did a patch job to get machine running on second day. artNumber Description Quantity List Price Net Price Extended Price Taxed 7M10610 ELEC. CONN Y26101 BRAKE AND PARTS CLEANER	roken Wire at the HI	Connector								
precised by replacing failed connector, did a patch job to get machine running on second day. Anthumber Description Quantity List Price Net Price Extended Price Taxed	ORRECTION:									
artNumber Description Quantity List Price Net Price Extended Price Taxed 7M10610 ELEC. CONN Y26101 BRAKE AND PARTS CLEANER	ultiple Techs, Multipl	e trips								
7M10610 ELEC. CONN Y26101 BRAKE AND PARTS CLEANER	rrected by replacing	failed connector, die	d a patch job to	get mach	ine running on sec	ond day.				
726101 BRAKE AND PARTS CLEANER	rtNumber	Description				Quantity	List Price	Net Price	Extended Price	Taxed Inc
	M10610	ELEC. CONN								
por: Parts: \$ OL&M: Misc: Sub-Total:		BRAKE AND PARTS	CLEANER							
	or: ff	Parts: \$	OL&M:		Misc:			Sub-Total:		

COMPLAINT:

04 baler electrical issues

Involce To Account No:	Deliver To:				12375478
			Invoice Nur		
			Invoice		01/16/2023
	li .	ll.	Work Order Nu	ation:	1286589
			Payment		120000
		il	,	.,,,	
		1	1	Page:	2 of 2
Aake/Model: 1	Meter	Serial Number:	EQ ld:	Fl	eet No:
JOHN DEERE CP690	156	NDC890PEJ4070393	1N0C690P	EJ4070393	
Service Reminders:					
ORRECTION:	location, customer complains to function improperly, spoke	ed of bater issues, in with customer, cust	spected bater a omer will repair	nd found bear and inform te	ring to be out and cl
ORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler	location, customer complaint to function improperly, spoke OL&M: \$	ed of bater issues, in with customer, cust Misc:	spected bater a omer will repair	nd found bear and inform te Sub-Total:	ring to be out and cl ch of status.
AUSE: CORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts:	to function improperly, spoke	With Customer, Cost	spected bater a omer will repair	una 11110111111	ring to be out and cl ch of status.
ORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts:	OL&M: \$ Finance Information	Misc:	onier war repea	una 11110111111	
ORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts: Customer PO No: 1001	OL&M: \$ Finance Information Type: Farm Plan	Misc:	onier war repea	Sub-Total:	:
ORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts: Customer PO No: 1001 Tax Exempt No:	OL&M: \$ Finance Information Type: Farm Plan Merchant No: 6400084	Misc:	onier war repea	Sub-Total: Job Total: Sales Tax	
ORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts: Customer PO No: 1001 Tax Exempt No:	OL&M: \$ Finance Information Type: Farm Plan Merchant No: 6400084 Card No: Bill Code:	Misc:	onier war repea	Sub-Total:	
ORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts: Customer PO No: 1001 Tax Exempt No:	OL&M: \$ Finance Information Type: Farm Plan Merchant No: 6400084	Misc:	onier war repea	Sub-Total: Job Total: Sales Tax	
CORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts: Customer PO No: 1001 Tax Exempt No:	OL&M: \$ Finance Information Type: Farm Plan Merchant No: 6400084 Card No: Bill Code:	Misc:	onier war repea	Sub-Total: Job Total: Sales Tax	
CORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts:	OL&M: \$ Finance Information Type: Farm Plan Merchant No: 6400084 Card No: Bill Code:	Misc:	onier war repea	Sub-Total: Job Total: Sales Tax	
ORRECTION: 0/2 Spoke with customer and drove to roke on passenger side causing baler abor: Parts: Customer PO No: 1001 Tax Exempt No:	OL&M: \$ Finance Information Type: Farm Plan Merchant No: 6400084 Card No: Bill Code:	Misc:	onier war repea	Sub-Total: Job Total: Sales Tax	

TERMS AND CONDITIONS
This purchase(s) is subject to the terms of the Multi-Use Account, a service of John Deere Financial, f.s.b. I grant the issuer a purchase money security Interest, except as limited in that agreement, in the goods described.

Received by:	Dale:
--------------	-------

invoice To Account No:		Deliver To:			SERVI	CE INVO	ICE
				Invoice Num	ber:		
				Invoice		01/06/2	
				Work Order Nun	ation: aher:	1286	50 6589
				Payment T		77.00	
			İ	P	age:	1	of 2
Make/Model:		Meter	Serial Number:	EQ ld:	Fle	et No:	
JOHN DEERE CP690		156	1N0C690PEJ4070393	1N0C690PE	J4070393		
Service Reminders: FTrip3 Retail							
COMPLAINT:							
11 Trip Fee for Servic	e Truck 31-60 miles fro	om closest UAT locat	ion				
parts location: 06 tax region: PARIS							
CAUSE:							
CORRECTION:							
Job Total:							
Gen- Retail			= -		7		
COMPLAINT:	S WITH BLOWER FAM	4					
COMPLAINT:	S WITH BLOWER FAN	4					
COMPLAINT:		N					
COMPLAINT: ELECTRICAL ISSUES CAUSE: Broken Wire at the HIG		N					
COMPLAINT: ELECTRICAL ISSUES CAUSE: Broken Wire at the HIG	C connector	N					
COMPLAINT: ELECTRICAL ISSUES CAUSE: Broken Wire at the HIG CORRECTION: Multiple Techs, Multip	C connector le trips		chine running on second	1 day.			
COMPLAINT: ELECTRICAL ISSUES CAUSE: Broken Wire at the HIG CORRECTION: Multiple Techs, Multiple corrected by replacing	C connector le trips			1 day.	Net Price Ex	tended Price T.	axed In
COMPLAINT: ELECTRICAL ISSUES CAUSE: Broken Wire at the HIG CORRECTION: Multiple Techs, Multip	C connector le trips failed connector, did a				Net Price Ex	tended Price T.	axed In
COMPLAINT: ELECTRICAL ISSUES CAUSE: Broken Wire at the HIG CORRECTION: Multiple Techs, Multiple orrected by replacing	C connector le trips failed connector, did a	a patch job to get mad			Net Price Ex	stended Price To	axed In

O.f.

COMPLAINT:

04 baler electrical issues

Invoice To Account No: Deliver To: SERVICE INVOICE Invoice Number: Invoice Date 01/88/2023 1/86/2023			Deliver To:		SE	RVICE INVO	ICE
Invoice Date COLORITIONS Invoice Date COLORITIONS Invoice Date COLORITIONS Invoice Date Coloring So Work Order Number: 1286589 Payment Type: 2 of 2 Igake/Model: Meter Serial Number: EQ Id: Fleet No: Page: 2 of 2 Igake/Model: Page:					Invoice Number:		
Leading to the page of the pag						01/06	2023
Page: 2 of 2 Also Model: Meter Serial Number: EQ Id: Fleet No: OHN DEERE'CP890 156 1N0C690PE,J4070393 1N0C690PE,J4070393 INOC690PE,J4070393 1N0C690PE,J4070393 NUSE: DRRECTION: // Spoke with customer and drove to location, customer complained of baler issues, inspected baler and found bearing to be out and choke on passenger side causing baler to function improperly. spoke with customer, customer will repair and inform tech of status. DOT: Parts: OL&M: Misc: Sub-Total: Substomer PO No: Ix Exempt No: Sales Tax: Total: \$874.15					Location:		50
Alse/Model: Meter Serial Number: EQ Id: Fleet No:						128	6589
alke/Model: Meter Serial Number: EQ Id: Fleet No: OHN DEERE'CP890 156 1NOC690PEJ4070393 1NOC690PEJ4070393 NUSE: DRECTION: IZ Spoke with customer and drove to location, customer complained of baler issues, inspected baler and found bearing to be out and choke on passenger side causing baler to function improperly. spoke with customer, customer will repair and inform tech of status. DOT: Parts: QL&M: Misc: Sub-Total: Sustomer PO No: ax Exempt No: Avisor: Total: \$874.15					Payment Type:		
INDICASOPEJAG70393 INDC690PEJAG70393 INDC690PEJAG					Page:		2 of 2
ervice Reminders: AUSE: DRRECTION: 1/2 Spoke with customer and drove to location, customer complained of baler issues, inspected baler and found bearing to be out and choke on passenger side causing baler to function improperly. spoke with customer, customer will repair and inform tech of status. bor: Parts: OL&M: Misc: Sub-Total: Sub-Total: Substomer PO No: ax Exempt No: divisor: Total: \$874.15	łake/Model:		Meter	Serial Number:	EQ ld:	Fleet No:	
AUSE: DRRECTION: IZ Spoke with customer and drove to location, customer complained of baler issues, inspected baler and found bearing to be out and choke on passenger side causing baler to function improperly. Spoke with customer, customer will repair and inform tech of status. bor: Parts: OL&M: Misc: Sub-Total: ustomer PO No: ax Exempt No: divisor: Total: \$874.15 BERMS AND CONDITIONS en umbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use in classified to the terms stated above. Thank you for choosing United Ag & Turt, we appreciate your product tax exempt, implies its use in the classified of the terms stated above. Thank you for choosing United Ag & Turt, we appreciate your product tax exempt.	OHN DEERE'CP690)	156	1N0C690PEJ4070393	1N0C690PEJ407039	93	
DRRECTION: JZ Spoke with customer and drove to location, customer complained of baler issues, inspected baler and found bearing to be out and choke on passenger side causing baler to function improperly. Spoke with customer, customer will repair and inform tech of status. bor: Parts: OL&M: Misc: Sub-Total: Job Total: ustomer PO No: ax Exempt No: dvisor: Total: \$874.15 ERMS AND CONDITIONS ERMS AND CONDITIONS ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use in classification of the form of the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your contents and the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your contents are contents.	Service Reminders:						
DRRECTION: JZ Spoke with customer and drove to location, customer complained of balar issues, inspected balar and found bearing to be out and choke on passenger side causing balar to function improperly, spoke with customer, customer will repair and inform tech of status. bor: Parts: OL&M: Misc: Sub-Total: Job Total: ax Exempt No: Advisor: Sales Tax: Total: \$874.15	ALISE:						
IZ Spoke with customer and drove to location, customer complained of baler issues, inspected baler and found bearing to be out and choke on passenger side causing baler to function improperly, spoke with customer, customer will repair and inform tech of status. Description	NOSE.						
ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its exclusively for affect hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its exclusively for affect hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its classified and the content of the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your	DRRECTION:						
erms and conditions ERMS AND CONDITIONS en unibers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its clustering function. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its clustering for affection. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your contents and the contents and the contents and the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your contents are contents.							
ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its classified by a gradual renders and product tax exempt, implies its use its classified and product tax exempt. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its classified and product tax exempt. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its classified and product tax exempt. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its classified and product tax exempt.	1/2 Spoke with cust	omer and drove to loo	ation, customer comple	ained of baler issues, ins	spected baler and found	bearing to be out a	nd ch
ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use in actualished for agriculture pspospection. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your descriptions.	oke on passenger	side causing baler to	function improperly, spo	oke with customer, custo	mer will repair and info	m tech of status.	
ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is exclusively for agriculture psposportion. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate you	har	Parte	OLSM:	Misc	Sub-To	tal:	
ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its classively for agriculture pydSpction. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your	DOT:	Parts.	OLAM.	misc.			
ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use its classively for agriculture pydSpction. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your			\neg				
### Total: \$874.15 #### Total: \$874.15 ###################################							
Total: \$874.15 ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is colusively for agriculture pydification. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your					Sales	Tax:	
ERMS AND CONDITIONS ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is calculatively for agriculture ps@action. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate you	dvisor:					etal: ±07	1 1 5
ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is columbers above, that renders any product tax exempt, implies its use is columbers. Thank you for choosing United Ag & Turf, we appreciate your					1	otal: \$874	1.15
ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is xclusively for agriculture production. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your							
ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is xclusively for agriculture production. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your							
ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is xclusively for agriculture production. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your							
ee numbers above for after hours service. The presentation of an agriculture exemption certificate, that renders any product tax exempt, implies its use is xclusively for agriculture production. Upon signing below I agree to the terms stated above. Thank you for choosing United Ag & Turf, we appreciate your							
1//							
	ee numbers above for agricult	r after hours service. Th	e presentation of an agric ning below I agree to the	ufture exemption certificate terms stated above, Thank	, that renders any product you for choosing United A	tax exempt, implies its g & Turf, we apprecial	use li

Invoice To Account No:	Deliver T	o:		SE	RVICE INVOICE
				Invoice Number:	11792393
				Invoice Date	11/23/2021
				Location: Work Order Number:	50 1073268
			i	Payment Type:	1070200
	11:				
Make/Model:	L	Meter	Serial Number:	Page:	1 of 2
JOHN DEERE CP690		1613	1N0C690PEJ4070393	1N0C690PEJ407039	
Service Reminders:		1010	114000301 E34010333	114000301 23401000	<u></u>
rip3 Retail					
COMPLAINT:					
1 Trip Fee for Service Truc	k 31-60 miles from close	st UAT locati	on		
CAUSE:					
CORRECTION		17			
CORRECTION:					
ob Total:					
en- Retail					
OMPLAINT:					
EF HEADER CODE					
AUSE:					
ad one time code for def po	imp not building pressure	e at start up.			
CORRECTION:					
had one stored code for del checked out the def system killed and restarted several customer said they would k	and found no issues with time to make the code go	h the def syst	em.	again.	
//liscellaneous Charges:				Ω	
SERVICE ACCESSORIE	S			Wing	\$7.0
bor: \$ Parts	: OL&	M: :	Misc:	Sub-Tota	al:
Customer PO No:				Job To	otal:
ax Exempt No:					
				Sales	ax: