

OK >>48

Hddl - entered after  
\$70K Credit

# SERVICE INVOICE

Invoice To Account No: 928220

Deliver To:

Invoice Number:

Invoice Date

09/15/2022

Location:

Work Order Number:

Payment Type:

Page:

1 of 5

Make/Model:

Meter

Serial Number:

EO Id:

Fleet No:

2014 JOHN DEERE 7760

1846

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

FTrip3 Retail

COMPLAINT:

01 Trip Fee for Service Truck 31-60 miles from closest UAT location  
closest location:  
parts location:  
tax region:

CAUSE:

CORRECTION:

Job Total: \$4,800.00

Gen- Retail

COMPLAINT:

02 motor work

CAUSE:

CORRECTION:

Went out to check the unit. Customer complained that it was white smoking at a idle and little low on power. Its also loosing coolant. I started the unit and found that it was white smoking. I pulled the elbow pipe off the egr cooler and had water coming out. I then pulled the pipe off before the egr cooler and found it had water coming out as well. I knew the water had to be coming from somewhere in the head. I ran a compression check on the unit and it checked good. I went ahead and started tearing everything down to get down to the head. I then pulled the head off the engine and took it back to the shop. I found that the injector cup on number three was cracked. Which explains why number three cylinder was full of coolant. All the injector tips were also rusted. I called the customer and talked to him on the phone. Don agreed to have the head worked over at the machine shop. He also agreed to put a set of injectors and the egr cooler on. I advised putting on a new turbo but the customer wanted to go ahead and put his back on. We also had to have new bearings and a floor belt kit as well. The belt was tore and coming apart so i had to cut it out. Once i got all the parts in we were able to go back out to the unit and put the engine back together. We went to put the head back on the first day and we got rained out. We then came back a couple days later and was able to get another couple hands to help knock it out. Once we got the engine back together. We changed the engine oil and fuel filters. We then tried starting the unit but the batteries were just shot. Customer brought us another set of batteries and we were able to get the unit running. We ran it for a while checking for leaks. No leaks were observed at this time. We finished putting together all the shields on the unit and i had to leave and head to waco. Richard was able to go out and finish putting the floor and the belt in and fix a hydraulic leak.

Richard

# SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number: 12194991

Invoice Date: 09/15/2022

Location:

Work Order Number:

Payment Type:

Page: 2 of 5

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2014 JOHN DEERE 7760

1846

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

8/1 Assisted Dylan in replacing head gasket and finishing engine job.

8/2 Assisted in reinstalling covers and engine accessories, diagnosed hydraulic issue to be check valve on rear of hydraulic reservoir.

8/3 Ordered parts at shop

8/11 Collected parts from shop and drove to location, drained hydraulic fluid from machine, took loose hoses from check valve and removed check valve, installed new check valve with new o-rings, filled hydraulic system with oil and started machine to check for leaks, found hose to rear axle to be leaking, drained oil from machine and removed hose from machine, cleaned tools and location, left location for paris store, made hydraulic hose and collected parts from paris store, returned to location, installed hose to rear axle, filled system with hydraulic oil, ran machine to check for leaks (no leaks found), brought machine to operating temp and checked for leaks again (no leaks found), cleaned tools and location, left location for home.

8/17 Collected parts from shop and drove to location, moved feeder belt rollers to tailboard of truck, attempted to use bearing puller to remove old bearings, used torch to cut off bearings from rollers, cleaned shafts and installed new bearings on rollers. Lifted rollers into machine and installed with new bolts, installed feeder belt and lace, tensioned belts to spec and tested operation, made adjustments to belt tracking, cleaned tools and location, left location for home.

8/23 Customer called and said hose was loose on top of engine, already on location for look at another machine, inspected machine for damage, found customers complaint to be true. removed covers from fan assembly, removed fan shroud, removed fan, climbed inside fan housing and connected trash cleaner hoses to Y-fitting. reinstalled fan, reinstalled all removed covers, tested operation of machine, all functions normal.

8/26 collected parts from shop and drove to location, customer complaints of accumulator auger constantly turning, as well as fuel codes, removed auger engagement solenoid and found o-rings to be blown out, inspected fuel codes and found pressure sensor behind filter housing to be broken. spoke with customer about findings, ordered parts and dropped off next time in the area.

Machine Model Number: CP7760

Machine Serial Number: 1N07760XKE0050290

Machine Hours as of 8/26: 3466 hrs

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
03M7191	BOLT	12.00				N
03M7192	BOLT	8.00				N
19M7913	SCREW	4.00				N
24H1228	WASHER	7.00				N
24M7101	WASHER	6.00				N
34H292	Spring Pin	2.00				N
34H336	SPRING PIN	4.00				N
A4730R	O-RING	2.00				N
AE37057	BALL BEARI	8.00				N

# SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number:

12194991

Invoice Date

09/15/2022

Location:

Work Order Number:

Payment Type:

Page:

3 of 5

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2014 JOHN DEERE 7760

1846

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

AKK21021	PACKAGE OF	1.00	N
AN373366	HYDRAULIC	1.00	N
AN374917	PRESSURE R	1.00	N
AT224862	SEAL KIT	2.00	N
DZ100375	GASKET	4.00	N
DZ10229	STUD	12.00	N
DZ105787	SPACER	12.00	N
DZ107052	ENGINE CYL	2.00	N
DZ112918	FILTER ELE	2.00	N
DZ114146	GUIDE	24.00	N
DZ120878	CAP SCREW	2.00	N
DZ122878	SENSOR	1.00	N
E63526	NUT	20.00	N
H161529	PRESSED FL	16.00	N
N275620	SCREW	9.00	N
N309233	O-RING	2.00	N
N374895	PLATE	4.00	N
N381576	CABLE	1.00	N
R114083	SCREW	12.00	N
R26375	O-RING	3.00	N
R29936	O-RING	5.00	N
R500318	O-RING	1.00	N
R515388	O-RING	1.00	N
R526831	GASKET	7.00	N
R526856	CAP SCREW	24.00	N
R528035	GASKET	1.00	N
R528254	Seal	2.00	N
R528478	GASKET	1.00	N
R528481	GASKET	1.00	N
R528512	SEAL	1.00	N
R528548	SEAL	24.00	N
R528578	CAP SCREW	15.00	N
R528611	SEALING RI	1.00	N
R528612	SEALING RI	5.00	N
R528620	GASKET	1.00	N
R528625	GASKET	2.00	N

# SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number:

12194991

Invoice Date:

09/15/2022

Location:

Work Order Number:

Payment Type:

Page:

4 of 5

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2014 JOHN DEERE 7760

1846

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

R529115	GASKET	1.00	N
R529465	GASKET	1.00	N
R529640	GASKET	1.00	N
R529889	GASKET	1.00	N
R530142	O-RING	4.00	N
R531285	GASKET	1.00	N
R531530	GASKET	1.00	N
R531581	GASKET	1.00	N
R531582	GASKET	1.00	N
R532008	BUSHING	4.00	N
R532009	O-RING	2.00	N
R532254	O-RING	1.00	N
R532305	O-RING	2.00	N
R532671	GASKET	1.00	N
R539762	FLANGE NUT	28.00	N
R541154	GASKET	1.00	N
R543352	STUD	4.00	N
R543924	WASHER	4.00	N
R545594	SPIDER	1.00	N
R551118	O-RING	1.00	N
R62976	O-RING	1.00	N
R63185	O-RING	4.00	N
RE25566	CLAMP	2.00	N
RE265844	CLAMP	1.00	N
RE538129	PRESSURE S	1.00	N
RE539465	FILTER ELE	1.00	N
RE540348	CLAMP	1.00	N
RE540355	GASKET	1.00	N
RE541291	GASKET	1.00	N
RE547863	ELECTRONIC	6.00	N
RE547863-CR	CORE for:Electronic Unit Injector	-6.00	N
RE547944	SLEEVE	4.00	N
RE548047	GASKET	6.00	N
RE548489	SLEEVE	6.00	N
RE553618	WIRING HAR	1.00	N
RE554015	THERMOSTAT	3.00	N

# SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number: 12194991

Invoice Date: 09/15/2022

Location:

Work Order Number:

Payment Type:

Page: 5 of 5

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2014 JOHN DEERE 7760

1846

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

RE560118	HEAT EXCHA	1.00				N
T76938	O-RING	1.00				N
T77857	O-RING	4.00				N
T77858	O-RING	1.00				N
T78612	O-RING	2.00				N
TY26576	COOL-GARD PRE-MIX, 2.5 GAL	7.00				N
U12547	O-RING	5.00				N
U13639	O-RING	2.00				N
X1JS43-8-8	HOSE FITTI	2.00				N
X387TC-8-RL	Bulk Hose	15.00				N

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
FREIGHT	FREIGHT	1.00				N
FREIGHT	FREIGHT	1.00				N
FREIGHT	FREIGHT	1.00				N

OL&M Charges:

Description  
head repair

Value

Miscellaneous Charges:

SERVICE ACCESSORIES

Sub-Total: \$43,846.24

## Finance Information

Customer PO No:

Tax Exempt No:

Advisor:

Type:

Mercha

Card No

Bill Coc

Credit F

Job Total:

Sales Tax:

Total: \$48,646.24

Received by: .....

Date: .....

Thank  
11/20/11

DR7748

Invoice To Account No: \_\_\_\_\_

Deliver To: \_\_\_\_\_

## SERVICE INVOICE

		Invoice Number:		
		Invoice Date:	10/26/2021	
		Location:		
		Work Order Number:		
		Payment Type:		
		Page:	1 of 2	
Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2014 JOHN DEERE 7760	3038	1N07760XKE0050290	ZN7760K050290Z	290

Service Reminders:

Trip3 Retail

COMPLAINT:

01 Trip Fee for Service Truck 31-60 miles from closest UAT location

CAUSE:

CORRECTION:

**PAID**  
*Farmplan*

Job Total: \$300.00

gen- Retail

COMPLAINT:

REPLACE FAN DRIVE // CUSTOMER HAS PARTS -- DOUBLE CHECK ELECTRICAL ISSUES FROM LAST TIME

CAUSE:

fan drive failure

CORRECTION:

- removed all guards and panels to access the fan drive.
- removed the fan.
- removed the fan drive assembly.
- installed the new fan drive assembly.
- installed new belt.
- reinstalled the fan.
- reinstalled all the panels and guards.
- test run and diag on the beater rollers.
- found the valve and solenoid for the beater rollers to be weak.
- ordered new valve and solenoid under the customers name on a counter ticket.
- customer will install the parts.

Miscellaneous Charges:

SERVICE ACCESSORIES

\$73.41

Sub-Total: \$1,704.66

## SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number: 11757769

Invoice Date: 10/26/2021

Location:

Work Order Number:

Payment Type:

Page: 2 of 2

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2014 JOHN DEERE 7760

3038

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

### Finance Information

Customer PO No:

Tax Exempt No:

Advisor:

Job Total:

Sales Tax:

Total: \$2,004.66

Invoice To Account No.: 928220

☐ Deliver To Account No.

## PARTS INVOICE

Invoice No: 11747686  
 Date: 10/20/2021  
 Page:  
 Payment Type:

Supplied Quantity	Back Order Quantity	Part Number	Part Description	Bin Loc	List Price	Net Price	Extended Price	Tax Ind
1.00	0.00	R300399	V-BELT	BLK32C				N
1.00	0.00	RE588578	FAN DRIVE	BLK28A	1			N
1.00	0.00	RE590285	FAN DRIVE	BLK25A				N

**Invoice Notes:**

FIELD TECH PICKED UP ON 10-20-2021 IS TECHS NAME

**Finance Information**

Customer PO No:  
 Tax Exempt No:  
 Salesperson:

**Parts:**

Misc:  
 Sales Tax:  
 Deposit:

Total: \$2,928.73



DK > > 48

Invoice To Account No: |

Deliver To:

# SERVICE INVOICE

Invoice Number: 11729302  
 Invoice Date: 10/06/2021  
 Location:  
 Work Order Number:  
 Payment Type:  
 Page: 1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2014 JOHN DEERE 7760	3025	1N07760XKE0050290	ZN7760K050290Z	290

Service Reminders:

Trip3 Retail

COMPLAINT:

01 Trip Fee for Service Truck 31-60 miles from closet UAT location

CAUSE:

CORRECTION:

**PAID**  
*Farmplan*

Job Total: \$1,200.00

gen- Retail

COMPLAINT:

02 BREAKS ARE LOCKED UP/DRIVE PUMP

CAUSE:

brake valve locked up on one side.

CORRECTION:

found the brake valve to be locked up.

-ordered a new brake valve.

-went to install new brake valve and found it to be an updated brake valve. had to order all new fittings.

-installed the new fitting into the new brake valve.

-installed the new brake valve and connected the line.

-tested the machine.

-machine now moves and has brakes.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
38H5017	ELBOW FITT	1.00				N
38H5208	ADAPTER FI	2.00				N
51M7041	O-RING	4.00				N
61M5026	ELBOW FITT	1.00				N
AKK14804	CONTROL VA	1.00	2			N
T77613	O-RING	4.00				N
T77857	O-RING	2.00				N

Invoice To Account No: -

Deliver To:

## SERVICE INVOICE

**Invoice Number:** 11729302  
**Invoice Date:** 10/06/2021  
**Location:**  
**Work Order Number:**  
**Payment Type:**

Page: 2 of 2

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2014 JOHN DEERE 7760

3025

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

Miscellaneous

Description

Quantity List Price Net Price Extended Price Taxed Ind

FREIGHT

1.00

N

### Miscellaneous Charges:

SERVICE ACCESSORIES

Labor: \$1,305.00

Parts: \$2,335.51

OL&M: \$0.00

Misc: \$214.51

Sub-Total: \$3,855.02

### Finance Information

**Job Total:** \$5,055.02

**Sales Tax:** \$0.00

**Total:** \$5,055.02

OK >>48

# SERVICE INVOICE

Invoice To Account No:

Deliver To:

Invoice Number: 11717373  
 Invoice Date: 09/29/2021  
 Location:  
 Work Order Number:  
 Payment Type:  
 Page: 1 of 2

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
2014 JOHN DEERE 7760	3025	1N07760XKE0050290	ZN7760K050290Z	290

Service Reminders:

Trip3 Retail

COMPLAINT:

01 Trip Fee for Service Truck 31-60 miles from closet UAT location

CAUSE:

CORRECTION:

**PAID**  
*Farmplan*

Job Total: \$600.00

gen- Retail

COMPLAINT:

BREAK ISSUES/ DRIVE PUMP NEED A SEAL REPLACE/ ELECTRICAL ISSUE

CAUSE:

seals in hydraulic motor on transmission out cause transmission to over fill  
 speed sensor on floor belt out

CORRECTION:

- removed panels to access the hydraulic motor.
- drained hydraulic fluid below site glass level.
- pulled vac on the hydraulic tank.
- disconnected and capped lines from the hydraulic motor.
- removed bolts from hydraulic motor.
- lowered the motor out using a transmission jack.
- removed the old seals from the motor and installed the new seals.
- installed the motor in reverse order.
- topped off hydraulic fluid.
- removed the bad speed sensor from the floor belt and installed the new one.
- test run the machine to check for leaks and codes.
- no leaks and no more active codes.

PartNumber	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
40M1873	SNAP RING	1.00				N

Invoice To Account No:

Deliver To:

**SERVICE INVOICE**

Invoice Number: **11717373**  
Invoice Date: 09/29/2021  
Location: ;  
Work Order Number: ;  
Payment Type: ;  
Page: 2 of 2

Make/Model:

Meter

Serial Number:

EQ Id:

Fleet No:

2014 JOHN DEERE 7760

3025

1N07760XKE0050290

ZN7760K050290Z

290

Service Reminders:

AH232278	SEAL	1.00	N
RE558874	WHEEL SPEE	1.00	N
T56238	O-RING	1.00	N
TY26101	CLEANING S	4.00	N

Miscellaneous Charges:

SERVICE ACCESSORIES

Sub-Total: \$1,607.85

## Finance Information

Job Total:	\$2,207.85
Sales Tax:	\$0.00
Total:	\$2,207.85