

Invoice: 1524

Date: 5/20/2022

Bill To
Panther Transport Logistics

P: (614) 5048085

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
2543	Net 30	6/19/2022	Mike		Strode, Ben	433

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Losing Coolant

Cause: Customer request

Labor Correction:

\$4,462.50

Engine / Cooling / Drained the engine oil and removed the oil pan, pressure tested the coolant system and found that coolant was leaking from the head and running down past cylinder's 2, 3, 4 and 5. Removed the head, removed the pistons and the liners. Inspected the crank shaft and it is fine, had the block counter bored, replaced the sleeves, pistons, main bearings and rod bearings. Removed the camshaft to install it in the new head and found that it was scared and needed to be replaced. Installed a new camshaft in the new head and installed the head with a new head gasket. Pressure tested the coolant system and verified no leaks, installed the oil pan, replaced the filters, found that the crankcase ventilation filter needed changed and changed it. Filled the engine with oil. After the engine was started verified that there were no leaks, no check engine lights and everything was working correctly. - 5/20/2022

Parts	Counter Bore	1.00000	
Parts	Camshaft, New	1.00000	
Parts	Freight	1.00000	
Parts	Sealant	1.00000	
Parts	Head, Cylinder	1.00000	
Parts	Kit, Classic	1.00000	
Parts	Seal, O Ring	1.00000	
Parts	Crankcase Filter	1.00000	
Parts	T3 CONVENTIONAL OIL	12.50000	
Parts	New, Head Bolt Kit	1.00000	
Parts	Remanufactured Fuel Injector	6.00000	
Parts	Freight	1.00000	
Parts	Fuel Filter	1.00000	
Parts	Fuel Filter	1.00000	
Parts	Oil Filter	1.00000	
Parts	Antifreeze Powergard ELC HD 50-50	11.00000	

Subtotal \$29,188.11

Item	Description	Quantity	Rate	Amount
Complaint: Steer Tires wearing unevenly				
Cause: Customer request				
Labor Correction:				
Chassis / Tire & Wheels / Removed the steer tires and inspected them and can turn them in as casings.				
Unit needs an alignment to prevent premature tire wear in the future. Took the unit for an alignment. -				
5/20/2022				
Parts	FS 295/75R22.5/G FS591 A/P	2.00000		
Parts	Front Axle Alignment	1.00000		

Complaint: Engine Won't Crank

Cause: Customer request

(Inspection)

Labor Correction:

Engine / Starting & Charging / Found one of the cables that jump from battery to battery on the ground posts was broken and one of the batteries was bad. Replaced the jumper cable and replaced the bad battery. - 5/20/2022

Parts	12V Dual Purpose Battery	1.00000		
Parts	Cable, Batt Stackable 2/0 7"	1.00000		

Unit: 433 (kw 828) **VIN:** 1XKYD49X9GJ456828
 2017 Kenworth T680
Chassis: 650,648 Miles

Total	\$31,296.66
Payments & Credits	\$0.00
Balance Due	\$31,296.66

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that US Diesel & Fab Inc makes no warranties of any kind unless expressed in writing.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that US Diesel & Fab Inc is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Invoice: 1957

Date: 12/30/2022

Bill To
Panther Transport Logistics

P: (614) 5048085

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
2996	Net 30	1/29/2023	Mike		Wessa, Mike	433

Item	Description	Quantity	Rate	Amount
Complaint: Needs new batteries				
Cause: Needs new batteries Type: Preventive maintenance				

Labor **Correction:**
Engine / Starting & Charging / battery replaced and truck started right up - Completed: 12/30/2022

Parts 12V Dual Purp Battery

4.00000 \$236.6415

Subtotal

Unit: 433 (kw 828) **VIN:** 1XKYD49X9GJ456828
2017 Kenworth T680
Chassis: 678,956 Miles

Labor

Parts

Shop Supplies

Pre-Charge Subtotal

City Sales Tax
(7.5000% of \$0.00)

Total

Payments & Credits

Balance Due

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that US Diesel & Fab Inc makes no warranties of any kind unless expressed in writing.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that US Diesel & Fab Inc is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Invoice: 1002

Date: 10/19/2021

Bill To

Panther Transport Logistics

P: (614) 5048085

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
2036	Net 30	11/18/2021	Mike		FAULKNER, MIKE	

Item	Description	Quantity
Complaint: Won't start without a jump start		
Cause: Customer request		
Labor	Correction: Chassis / Lighting & Electrical / Tested and found that the batteries were bad. Removed the old batteries and installed 4 new ones. Unit starts fine now. - 10/19/2021	
Parts	Battery, 950 CCA, 175 RC, 12MO Warranty	4.00000
Complaint: Secondary Air not building		
Cause: Customer request		
Labor	Correction: Chassis / Air Brake / Found that the air dryer was clogged and not allowing the air system to build. Removed the old air dryer and installed a new one. Air is building fine and working correctly at this time. - 10/19/2021	
Parts	Air Dryer	1.00000
Complaint: Check unit over		
Cause: Customer request		
Labor	Correction: Chassis / Chassis / Checked the unit over, topped off the windshield washer fluid and the coolant. Everything else is fine at this time. - 10/19/2021	
Parts	MAC HEAVY DUTY ANTIFREEZE 50/50	1.00000

Payments & Credits \$0.00

Balance Due \$1,513.89

Invoice: 1151

Date: 12/14/2021

Bill To
Panther Transport Logistics

P: (614) 5048085

Remit Payment To
US DIESEL & FAB, INC
775 ENTERPRISE AVE
COLUMBUS, OH 43228

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
2181	Net 30	1/13/2022	Mike		FAULKNER, MIKE	433

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: 'B' Full Wet Service (Lube, Oil & Filters)

Cause: Customer request

Labor Correction:

Engine / Lubrication / Changed the engine oil, oil filter, fuel filter and fuel/water separator. Checked for leaks and found that the front main seal and gear housing cover gasket were leaking and need to be replaced. Checked the fluid levels and the coolant was excessively low. Checked the tires and found that the rear 4 drive tires all need replaced. Checked and adjusted the brakes, greased all grease points. - 12/14/2021

Parts	T3 CONVENTIONAL OIL	11.50000		
Parts	Oil Filter	1.00000		
Parts	Fuel Filter	1.00000		
Parts	Luberfiner Fuel Filter	1.00000		

Complaint: Defect in engine oil level and/or condition

Cause: Found Gear housing cover and front main seal leaking **Type:** Other

(Procedure)

Labor Correction:

Engine / Lubrication / Removed the belt and dampener along with all other components attached to the gear case cover. Removed the gear case cover and replaced the gasket and front main crank seal. Reassembled all components and verified that there were no leaks from the front of the engine. - 12/14/2021

Parts	Element-BR	1.00000		
Parts	Seal-Rectangular	1.00000		
Parts	Seal-Oil	1.00000		
Parts	Belt-Poly	1.00000		

Complaint: Coolant Leak

Cause: Radiator leaking **Type:** Other

(Procedure)

Item	Description	Quantity	Rate	Amount
Labor	Correction: Engine / Cooling / Pressure tested the coolant system and found that the radiator was leaking and needed to be replaced. Drained the system and removed the radiator assy. Replaced the radiator core and reassembled the assembly. Installed the assembly back into the unit and refilled the coolant and checked for leaks and made sure that the engine wasn't overheating. Everything is good at this time. - 12/14/2021			
		1.00000		
Parts	Pacar W/Cummins Radiator			
		4.00000		
Parts	MAC HEAVY DUTY ANTIFREEZE 50/50			

Complaint: 3rd Axle drive tires need replaced

Cause: Customer request

(Inspection)

Labor **Correction:**

Chassis / Tire & Wheels / Removed the 4 tires and installed 4 new ones. 2 were able to be saved for spare tires on trailers and 2 were scrap. Made sure that they were inflated to 110 psi and put them on the unit. Lug nut torque needs checked in 50 miles. - 12/14/2021

Parts 295/75R22.5 M726 Cap

4.00000

Parts Tire disposal

2.00000

Complaint: Right Rear Shock Rusted off and Leaking

Cause: Customer request

(Inspection)

Labor **Correction:**

Chassis / Suspension / Removed the old shock and replaced with a new one. - 12/14/2021

Parts Meritor Shock

1.00000

Used295

Unit: 433 (kw 828) **VIN:** 1XKYD49X9GJ456828

2017 Kenworth T680

Chassis: 620,408 Miles

Balance Due \$3,369.62

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that US Diesel & Fab Inc makes no warranties of any kind unless expressed in writing.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that US Diesel & Fab Inc is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission

Invoice: 1153

Date: 12/15/2021

Bill To

Panther Transport Logistics

P: (614) 5048085

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
2184	Net 30	1/14/2022	Mike		FAULKNER, MIKE	433

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Top marker light out**Cause:** Customer request**Labor Correction:**

Chassis / Lighting & Electrical / Removed the light and installed the replacement light. - 12/15/2021

Parts Marker Light**Unit:** 433 (kw 828) **VIN:** 1XKYD49X9GJ456828

2017 Kenworth T680

Chassis: 620,408 Miles**Balance Due** \$119.52

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that US Diesel & Fab Inc makes no warranties of any kind unless expressed in writing.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that US Diesel & Fab Inc is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

Invoice: 1210

Date: 1/11/2022

Bill To
Panther Transport Logistics

P: (614) 5048085

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
2236	Net 30	2/10/2022	Mike		FAULKNER, MIKE	433

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Complaint: Right 1/4 Fender missing

Cause: Customer request

Labor Correction:

Chassis / Cab Hardware / Installed a new 1/4 fender on the right side of the unit. - 1/11/2022

Parts 1/4 Fender Right

Complaint: RFI and RFO Tires need replaced.

Cause: Customer request

Labor Correction:

Chassis / Tire & Wheels / Removed and replaced the tires on the RFI and RFO positions. Verified that pressure was set to 110 psi. Lug nut torque needs checked in 50 miles. The off Tires are good to be use spares. - 1/11/2022

Parts 295/75R22.5 M726 Cap

Complaint: Red Air line leaking, Blue Air line kinked

Cause: Customer request

Labor Correction:

Chassis / Air Brake / Removed the bad coiled plastic air lines and replaced with straight rubber ones. - 1/11/2022

Parts Red & Blue Straight Hose set 15'

Complaint: Check Fluids

Cause: Customer request

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

Labor Correction:

Chassis / Chassis / Checked all of the fluids. Topped off the washer fluid. - 1/11/2022

Complaint: Grease 5th wheel**Cause:** Customer request**Labor Correction:**

Chassis / Fifth Wheel / Greased the fifth wheel for the driver. - 1/11/2022

USED295 x2

Unit: 433 (kw 828) **VIN:** 1XKYD49X9GJ456828

2017 Kenworth T680

Chassis: 628,690 Miles**Balance Due** \$633.86

Any warranties on the parts and accessories sold hereby are made by the manufacturer. The undersigned purchaser understands and agrees that US Diesel & Fab Inc makes no warranties of any kind unless expressed in writing.

I hereby authorize the repair work herein set forth to be done along with the necessary material and agree that US Diesel & Fab Inc is not responsible for loss or damage to vehicle or articles left in the vehicle in case of fire, theft, or any other cause beyond control or for any delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you/or your employees permission to operate the vehicle herein described on streets, highways, or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.