

Invoice

Date

Invoice #

5/10/2021

Bill To

P.O. Number

MILEAGE

UNIT#

1035

Quantity	Item Code	Description	Price Each	Amount
1	91211	3/8 push connect tee		
1	44K.W12B	KW CAC K093-64 AIR TO AIR		
1	D1C29-4494	HOSE MOLDED		
1	HE8716	HUMP HOSE		
3	32853	CLAMP HOSE CONSTANT		
4	EXHAUST MOUNT	AIR TO AIR BUSHING		
240	3/8 HYD HOSE	3/8 HYD HOSE 2 WIRE		
3	6g-6mp	Fitting		
1	6g-6fp	Fitting		
2	8010-15	QUICK COUPLER		

Subtotal

Sales Tax ()

Total

PAYMENT/CREDIT

Balance Due

\$1,173.70

Phone #

Fax #

Invoice:

Date:

6/1/2021

Bill To

Service Order	Terms	Due Date	Authorizer	Customer PO	Service Writer	Unit #
		6/1/2021				1035

Item Description	Quantity	Rate	Amount
------------------	----------	------	--------

Inspection

Labor Inspection & Diag

Subtotal

Inspection

Labor TEST DRIVE

Subtotal

Complaint: STEER BAG, LEFT SIDE IS BLOWN.

Cause: Blown out

Labor Correction:

Chassis / Chassis / REPLACED DRIVERS SIDE STEER AIR BAG

Parts AIR BAG - ABH65790-002	1.00000		
------------------------------	---------	--	--

Parts SHIPPING - FREIGHT	1.00000		
--------------------------	---------	--	--

Subtotal

Complaint: REPLACE THE MUFFLER AND TURN OUT

Cause: Broke (Inspection)

Labor Correction:

Chassis / Chassis / Replaced muffler and turnout

Parts 5" FLAT BAND CLAMP - FBC500	2.00000		
-----------------------------------	---------	--	--

Parts Muffler 5x5x10 - 5x5x10 Muffler (SX22920) (M5510)(M-465)	1.00000		
--	---------	--	--

Parts 5" SADDLE CLAMP, U BOLT - SX35800	1.00000		
---	---------	--	--

Parts STACK CURVED 5"X36" OD CHR - K5-36SBC	1.00000		
---	---------	--	--

Parts 5" SADDLE CLAMP, U BOLT - SX35800	1.00000		
---	---------	--	--

Subtotal

Complaint: Oil leak noted

Cause: Oil pan gasket needs replaced, leaking in front corner of it. (Procedure)

Invoices

6/12/00

Item	Description	Quantity	Rate	Amount
Labor	Correction: Chassis / Chassis / Replaced oil pan gasket and oil filter, cleaned oil pan out, put in 11 gallons of oil. Test drove and looked over for leaks, no leaks were noticed.			
Parts	OIL & FUEL FILTER - BD50000	1.00000		
Parts	GASKET - 4026684	1.00000		
Parts	15W40 - BULK OIL 15W40	11.00000		

Subtotal

Unit: 1035 VIN: 2HSCEAPR87C340001
 2007 International L9227
 Chassis: 1,208,463 Miles

Labor

Parts

Shop Supplies

Pre Tax Total

LIVINGSTON COUNTY TAX (1.2500% of \$1,136.85)

MO STATE TAX (4.2250% of \$1,136.85)

Total

Payments & Credits

Balance Due \$2,424.00