

44136 3 C 6 U R 5 C J 2 E G 2 8 0 4 7 4

05/23/2023

2014 RAM 2500 ST WHITE

08:36

10:13

127323 127323 00/00/00 354NRG 00/00/00

05/31/23

(1) REPLACE CAM, AND FRONT FOUR LIFTERS ON LEFT SIDE.

| Labor                   |                  | T16 |
|-------------------------|------------------|-----|
| 5045517AC               | (CAMSHAFT)       | 1   |
| HS26568PT               | (GASKET SET)     | 1   |
| ES72200                 | (HEAD BOLT ST)   | 2   |
| 53021521AD              | (GASKET)         | 1   |
| 53021585AD              | (OIL SEAL)       | 1   |
| 4893353AA               | (OIL PAN GASKET) | 1   |
| 1-0-40-5QT              | (MOBIL 1 0W40)   | 1   |
| 1-0-40                  | (MOBIL 1 0W40)   | 2   |
| QFL25                   | (KIT - ELEMENT)  | 1   |
| 03309CD                 | (HARDWARE KIT)   | 2   |
| MS97083                 | (MANIFOLD SET)   | 1   |
| 03422                   | (MAN HARDWARE)   | 1   |
| Total Labor             |                  |     |
| Total Parts             |                  |     |
| Total Repair (Customer) |                  |     |

D

THANK YOU FOR YOUR BUSINESS..  
MOST FORD PARTS HAVE A 2 YEAR  
UNLIMITED MILE WARRANTY

Due: 2990.00

.00 Labor  
.00 Parts  
.00 Sublet  
.00 Shop Suppli  
.00 Oil/Grease  
.00 Sub Total  
.00 Tax  
.00 Total (Due) 2990.00

Page 1 of 1 Job 44136 Reprint (1)

44136

Customer Copy