

2006 GMC C7500
OK9572

R/O Open Date	R/O Number
09/27/22	
R/O Close Date	Status
12/02/22	
Mileage In	Mileage Out
	22205
Service Advisor / Tag #	

				Work Phone	Vehicle Identification Number	
				Home Phone	1GDJ7C1G56F415815	
					Delivery Date	In-Service Date
Year	Make	Model	Body		Color	License Number
2006	GMC	TC7500	REGULAR CAB			

DESCRIPTION OF SERVICE AND PARTS

#1 - ENG: ENGINE PERFORMANCE DIAGNOSIS (RUNNING ROUGH, OTHER)
TOWED TO SHOP- ENGINE HAD OVERHEATED--LOW ON COOLANT--FILLED WITH COOLANT--TRUCK STARTED SMOKING BADLY FROM EXHAUST. ALSO-TRUCK IS DEAD AND KEY WILL NOT COME OUT OF IGNITION

Caused by

d1-towed vehicle into shop, battery dead in vehicle. replaced battery and cranked over engine. motor seized up, found coolant in oil pan. drained fluids for inspection recommend replacing; engine assembly, cooler, hoses, heatshields, plugs wires, water pump, rear crank position sensor, exhaust manifold studs and nuts. removed exhaust and drained out oil and coolant mix. ignition key could not be removed from cylinder, recommend replacing key and ignition tumbler.

Tech:

Installed 15797871 :SL-N-HOSE (01173-CT)
Installed 15797887 :SL-N-HOSE (01159-CT)
Installed 12679800 :SL-N-SPARK PLUG (02270-CT)
Installed 19417609 :SL-*-N-WIRE KIT (02239-CT)
Installed 15768485 :SL-N-BELT (01066-CT)
Installed 12572718 :SL-N-TUBE (01516-CT)
Installed 12559597 :SL-N-GASKET (00423-CT)
Installed 89017539 :SL-N-GASKET KIT (03270-CT)
Installed 12567777 :SL-N-GASKET (01429-CT)

AMOUNT

LABOR

PARTS

DEDUCTIBLE

SUBLET

SHOP SUPPLIES

HAZARDOUS MATERIALS

SALES TAX OR TAX I.D.

SPECIAL ORDER DEPOSIT

DISCOUNTS

TOTAL DUE

Page 1

R/O Open Date	R/O Number
09/27/22	
R/O Close Date	Status
12/02/22	
Mileage In	Mileage Out
	22205
Service Advisor / Tag #	

			Work Phone	Vehicle Identification Number	
				1GDJ7C1G56F415815	
			Home Phone	Delivery Date	In-Service Date
Year	Make	Model	Body	Color	License Number
2006	GMC	TC7500	REGULAR CAB		

DESCRIPTION OF SERVICE AND PARTS

AMOUNT

Installed 13579648 :SL-N-SEAL (09222-BOPCKT)
 Installed 88861747 :78VPG
 Installed 15783576 :SL-N-CYLINDER KIT (02188-BCKT)
 Installed 23372321 :SL-N-KEY (02187-BOPCT)
 Installed 12571593 :SL-N-GASKET (01154-CT)
 Installed 12559575 :SL-N-THERMOSTAT (01246-CT)
 Installed 24577118 :SL-N-SEAL (01252-BOPCT)
 Installed 15021742 :SL-N-TENSIONER (01060-CT)
 Installed 15021741 :SL-N-PULLEY (03650-CT)
 Installed 15170285 :SL-N-SEAL (03611-CT)
 Installed 12558275 :SL-N-GASKET (03270-CT)
 Installed 11609296 :SL-N-STUD (03275-CT)
 Installed 11516076 :SL-N-NUT (08917-BOPCKT)
 Installed 11570082 :SL-N-BOLT (08900-BOPCKT)
 Installed 11515755 :SL-N-BOLT (08900-BOPCKT)
 Installed 44089 :WATER PUMP
 Installed REMANENGINE :L18 8.1L (496 CID)
 STK# 347820 PROD# 349119 / 8.1/496 V8 CHEV W/INTAK
 E
 Installed HDC010879PA :RADIATOR
 Installed 12346290 :N-COOLANT (08800-BOPCKT)
 Installed 12571614 :N-SHIELD (03602-CT) 12571
 Installed 11589264 :N-STUD (08981-BOPCKT)
 Installed 15709703 :N-NUT (08915-BOPCKT)
 Installed 15177423 :SL-N-HOUSING (00683-CT) 15177
 Installed 12575172 :SL-N-SENSOR (02383-CT)
 Installed 88983094 :N-HOUSING (03406-CT) 88983

LABOR

PARTS

DEDUCTIBLE

SUBLET

SHOP SUPPLIES

HAZARDOUS MATERIALS

SALES TAX OR TAX I.D.

SPECIAL ORDER DEPOSIT

DISCOUNTS

TOTAL DUE

Page 2

R/O Open Date	R/O Number
09/27/22	
R/O Close Date	Status
12/02/22	
Mileage In	Mileage Out
	22205
Service Advisor / Tag #	

				Work Phone	Vehicle Identification Number	
					1GDJ7C1G56F415815	
				Home Phone	Delivery Date	In-Service Date
Year	Make	Model	Body		Color	License Number
2006	GMC	TC7500	REGULAR CAB			

DESCRIPTION OF SERVICE AND PARTS

AMOUNT

Installed 15769220 :N-DUCT (03407-CT)
 Installed 88983093 :N-HOUSING (03406-CT)
 Installed 2824 :AIR FILTER
 Installed 88865638 :5W30 DEXOSO
 Installed 25324052 :SL-N-FILTER (01836-BOPCKT)
 Installed 702113 :HYDRAULIC FLUID
 s1- during engine removal had to pulled oil pan
 and lower engine oil shields to remove damaged
 internals to rotate engine for torque converter
 removal. found 2 bent rods with one missing the
 piston. remove cylinder head to remove bent rod
 and pistons out top. separated oil components and
 transferred over to new engine assembly.
 installed assembly, had time in broken exhaust
 manifold lower stud removal x3. topped off fluids
 and replaced ignition key and cylinder. ac system
 would not take a freon charge. will need to have
 serviced at later date. vehicle came into shop
 with no freon in ac system. test drove vehicle.
 no further issues found at this time.

Sub Total: 14411.85

Remanufactured
 Engine

Total Bill
 \$15,358.06

LABOR	
PARTS	
DEDUCTIBLE	
SUBLET	
SHOP SUPPLIES	
HAZARDOUS MATERIALS	
SALES TAX OR TAX I.D.	
SPECIAL ORDER DEPOSIT	
DISCOUNTS	
TOTAL DUE	\$ 15358.06

Remanufacturers of Quality Medium and Heavy Duty Drivetrain Components

Invoice#		LOC:		DLR CODE	
For Inquiries Contact:		Cust. Phone			
Date	Contact	Purchase Order No	Account Number	Terms	Salesman
4/25/2023					

Sold To

Ship To

Staging #

Invoice #

Part No.	Description	Qty	Unit Price	Core Charge	Ext. Total
98HF29WEL	SYNTHETIC ATF 5 GAL **CAUTION HEAVY**	1			
	OLD WELLER TAG 865625 2300PTS E015882	0			
	CUSTOMER WILL HAVE CORE READY	0			
2300PTSWEL (Tag 1433469)	Model: 2300PTS Series: P/N: E015882 CONV HSG: #3 W/MAN RPM/TID: CLOSE RATIO Torq Conv:210 Ser# N/A	1			

All Amounts
In USD

Parts Total:	
Labor Total:	
Non Taxable:	
Core Deposit:	
Freight:	
Sales Tax:	
PRE-PAID	\$3,431.42

Remanufactured
Transmission

Received By: (SIGN & PRINT)

Received Date:

