

Description	Quantity
Truck was towed in, check engine lights on and had a fire in the exhaust box, diagnose problem, make repairs, had some used parts to put on the outside of exhaust box, new washer fluid reservoir, start truck up and engine has a miss and is smoking bad, found #6 injector is over fueling, replace #6 injector, run overhead, start up, it is running good now, test drive, wash off engine, deliver back to schmidt.	
A22-77097-000 Washer fluid reservoir	1
A06-40827-000 Harness for washer pump	1
ELC Antifreeze	1
30980 Pink heat shrink butt splices	2
A6809950202 DPF V-band clamp	1
DD13 Diagnostics and repair	1
Tune-up with new valve cover gasket	1
subtotal	
tax	
shop supplies	
labor : 4	