

# INVOICE

Part Description / Number	Qty	Sale	Ext	Labor Description
NEW 342 RING AND PINION GEAR SET	1.00			CHECK OUT . FOUND PINION COULD MOVE DOWN , AND CARRIER BEARING NOISY ,
PTQ 742G730C				DOWN REAR DIFFERENTIAL PINION BEARING HAD SO
REAR DIFFERENTIAL BEARING KIT	1.00			PLAT WAS RUBBING ON CARRIER . REPLACE RING AND
PTQ 742G004A				N AND REPLACE ALL DIFFERENTIAL BEARINGS SET UP
REAR DRIVE SHAFT CENTER SUPPORT BEARING	1.00			DIFFERENTIAL AND REPLACE BOTH REAR WHEEL
HB4016A				INGS AND SEALS , AND REPLACE FLUID AND INSTALL
REAR WHEEL AXLE SEALS	2.00			TRAC ADDITIVE , REPLACE REAR DRIVE SHAFT CARRIER
4762N				ING ASSY AND RETEST .
POSI TRACK ADDITIVE	1.00			
BG				
NEW REAR WHEEL BEARINGS	2.00			
513067				
75W90 SYNTEC GEAR LUBE	3.00			
10047				
Shop Supplies				

1 yr

12000 mile warranty

10047  
Shop Supplies

3.00

120 e Warranty

Org. Estimate

Labor: \_\_\_\_\_  
Parts: \_\_\_\_\_  
  
SubTotal: \_\_\_\_\_  
Tax: \_\_\_\_\_  
Total: \_\_\_\_\_  
Bal Due: \$1,850.23  
Customer Number : 1814