

BUS:		YEAR		MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG
COLOR		07		GMC SIERRA 3500	1GDJJC34K77E591476		230799/230799	T124
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
24SEP07 DD			23:54 31MAY17			CHG	08MAY17	
R.O. OPENED		READY		OPTIONS: DLR:30200 ENG:6.0_Liter				

09:29 02MAY17 14:51 08MAY17
 LINE OPCODE TECH TYPE HOURS LIST NET TOTAL

A CUSTOMER STATES THE TRANSMISSION IS OVERHEATING AND WONT PULL ITSELF.
 THEY CAN TURN VEHICLE OFF AND LET IT COOL AND IT WIL DRIVE FINE
 UNTIL IT OVERHEATS AGAIN. CHECK AND ADVISE
 DR DRIVEABILITY

1687CPLD3
 1 19303195 REMANUFACTURED TRANSMISSION
 CORE CHARGE C
 12 88865601 FLUID
 -1 19303195 CORE RETURN

PARTS: LABOR: OTHER: TOTAL LINE A: 3982.36

230799 CHECKED CODES AND FOUND PRESSURE CODES, TEST DROVE AND IT
 SLIPS AND LOSES GEARS, GOT BACK TO THE SHOP AND CAN HEAR NOISE
 INTERNALLY. SPOKE WITH KEITH ABOUT EST. 1:58 5/3, REMOVED TRANSMISSION,
 FLUSHED COOLER LINES (4BFBE6), STARTED INSTALLING NEW TRANSMISSION,
 INSTALLED NEW TRANSMISSION, FILLED WITH FLUID, REPROGRAMMED TCM, TEST
 DROVE.

 B RECALL 15817 Front Passenger Airbag

CAUSE: PERFORM RECALL

9102125 Replace Front Passenger Air Bag Inflator
 Module

1687WGL43
 1 84255088 F-INFLATOR

PARTS: LABOR: OTHER: TOTAL LINE B:

230799 COMPLETED RECALL 15817, REPLACED AIR BAG CYLINDER, ID#
 ABEB59H1070897.

 C CERTIFIED SERVICE MULTI-POINT INSPECTION

GMMPI CERTIFIED SERVICE MULTI-POINT INSPECTION
 1687CPLD3

PARTS: LABOR: OTHER: TOTAL LINE C:

COMPLETED MULTI POINT INSP, COMPLETED INSP CHECKLIST, RH INNER TIE
 ROD LOOSE, LH LOW BEAM HEADLIGHT INOP.

STATEMENT OF DISCLAIMER		DESCRIPTION	TOTALS
		LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		MISC. CHARGES	
		TOTAL CHARGES	
		LESS INSURANCE	
		SALES TAX	
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)	CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT	

CUSTOMER COPY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/OUT	TAG
	07	GMC SIERRA 3500	1GDJ34K77E591476		230799/230799	T124
DEL DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT
24SEP07 DE			23:54 31MAY17			CHG
R.O. OPENED	READY	OPTIONS: DLR:30200 ENG:6.0 Liter				08MAY17

09:29 02MAY17 14:51 08MAY17

LINE OPCODE TECH TYPE HOURS

D** REPLACE RADIATOR LIST NET TOTAL

NWD NO WORK DONE AT THIS TIME
1687CPLD3

PARTS: LABOR: OTHER: TOTAL LINE D:
230799 DID RADIATOR FLUSH TEST. CHECKED GOOD, NO NEED TO REPLACE.

E** REPLACE THE R INNER TIE ROD

20 SUSPENSION

1687CPLD3

1 15295861 (S) ROD KIT

PARTS: LABOR: OTHER: TOTAL LINE E: 400.54

230799 REPLACED RH INNER TIE ROD END.

F** REPAIR LEFT LOW BEAM HEADLAMP

805 MISC ELECTRICAL

1687CPLD3

1 13586977 (S) BULB

PARTS: LABOR: OTHER: TOTAL LINE F: 114.17

230799 REPLACED LH LOW BEAM HEADLAMP.

G** ALIGN FRONT END LD

301 ALIGN FRONT END LD

1687CPLD3

PARTS: LABOR: OTHER: TOTAL LINE G: 109.95

230799 ALIGNED FRONT END.

SHOP SUPPLIES 200.66

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	5052.75

CUSTOMER COPY