T

Balance due \$4,818.27

SERVICED TRUCK, FIXED AIR LEAK, REPLACED BATTERIES, REMOVED PTOS AND INSTALLED PLATES, REMOVED CLUTCH INSTALLED NEW TRHOUGH SHAFT BUSHINGS, NEW INPUT SHAFT, NEW CLUTCH, PILOT BEARING, CLUTCH BRAKE, INSTALLED TRANSMISSION. PUT NEW DRAGLINK ON.

3-19-22

Print or save