

Sold Operations

JOB #1 CPDIAG PEFORM CUST PAY DIAGNOSTICS - RETAIL

COMPLAINT CHECK THE EXHAUST TUBE (GOING TO THE TURBO - OUTPUT) -
 CAUSE
 CORRECTION CUT OLD SECTION OUT AND ADDED NEW FLEX PIPE

QTY	ITEM	DESCRIPTION
	LABOR CPDIAG-RET	CHECK THE EXHAUST TUBE (GOING TO THE TURBO - 4
1	804X/562.U7130-10A	STRAIGHT TUBING 10FT
1	804X/562.U13621A	FLANG ADAPTER
1	FRT	FREIGHT
1	804N/320226C1	TUBE FLEX 26 IN
1	804N/FLTEC30PLA	CLAMP 3.0IN HD PRE-FORM ALUM
1	804N/2033978C1	CLAMP EXHAUST PIPE
1	804N/FLTEC35PLA	CLAMP 3.5IN HD PRE-FORM ALUM
1	804X/50TQ30042	EXH CLAMP

Prepay: \$0.00 Parts: \$644.37 Labor: \$300.00 Misc: \$175.00 Sublet: \$0.00 Job #1 Total: \$1,119.37

****INVOICE TOTAL ON FINAL PAGE****

JOB #2 QC COURTESY QUICK CHECK INSPECTION

COMPLAINT Courtesy Quick Check Inspection -
 CAUSE
 CORRECTION COMPLETED INSPECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE
	VMRS33	999-999-000	
	LABOR QC	Courtesy Quick Check Inspection	

Prepay: \$0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00

****INVOICE TOTAL ON FINAL PAGE****

JOB #3 DECISIV DECISIV DEFAULT JOB

COMPLAINT NEEDS NEW GLOW PLUGS -
 CAUSE
 CORRECTION INSTALLED NEW GLOW PLUGS

QTY	ITEM	DESCRIPTION	UNIT PRICE
	LABOR DECISIV	NEEDS NEW GLOW PLUGS	
8	804N/1820697C2	GLOWPLUG ASSY	
1	804N/2501107C1	CONNECTR,CONNECTOR INJ CTRL RE	41.25
			60.87

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	OIL LEAK ABOVE MOTOR
1	804N/1831666C1	GASKET FRONT OIL COOLER HEADER
2	804N/1807563C1	RING O
2	804N/1804414C1	RING O
1	804N/1815898C3	GASKET PUMP FLANGE
2	804N/1831665C2	GASKET, REAR OIL COOLER HEADER
7	804D/FLTAHVBC14KK	FLEET AER HIGH VOC BRAKE CLN 1
	LABOR 002398	Road test

Pt

****INVOICE TOTAL ON FINAL PAGE****

JOB #5 DECISIV DECISIV DEFAULT JOB

COMPLAINT OIL LEAK AROUND DIPSTICK -

CAUSE

CORRECTION installed new o rings on dip stick

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	OIL LEAK AROUND DIPSTICK
1	804N/1876743C1	SEAL O-RING

Prepay: \$0.00 Parts: \$3.77 Labor: \$0.00 Misc: \$0.00 Sublet:

****INVOICE TOTAL ON FINAL PAGE****

JOB #6 DECISIV DECISIV DEFAULT JOB

COMPLAINT NO DASH LIGHTS -

CAUSE

CORRECTION there was no voltage coming from dimmer switch installed new switch now working as supposed to

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	NO DASH LIGHTS
1	804N/1661480C3	CONTROL LIGHT PANEL DIMMER

Prepay: \$0.00 Parts: \$169.04 Labor: \$300.00 Misc: \$0.00 Sublet:

****INVOICE TOTAL ON FINAL PAGE****

JOB #7 DECISIV DECISIV DEFAULT JOB

COMPLAINT CHANGE OIL & OIL FILTERS (THERE'S OIL IN THE BACK OF THE TRUCK) -

CAUSE

CORRECTION changed oil and installed new fliters on vehicle

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	CHANGE OIL & OIL FILTERS (THERE'S OIL IN THE BAC)
1	804D/LF3630	L/O FLTR,LUBE/OIL FILTER
1	HAZ	HAZARDOUS WASTE

Prepay: \$0.00 Parts: \$36.54 Labor: \$200.00 Misc: \$14.50 Sublet:

****INVOICE TOTAL ON FINAL PAGE****

JOB #9 A01-RET FRAME / BUMPER - RETAIL

COMPLAINT Install dipstick on the power steering tank -
CAUSE FOUND THE DIPSTICK FOR THE POWER STEERING MISSING
CORRECTION RECOMMEND INSTALLING A NEW DIPSTICK

QTY	ITEM	DESCRIPTION
	LABOR A01-RET	Install dipstick on the power steering tank
1	804N/1695530C1	GAUGE,PWR STEER OIL LEVEL
1	804D/FLTPSF32KK	FLEETRITE POWER STEERING 32OZ

Prepay: \$0.00 Parts: \$83.88 Labor: \$37.50 Misc: \$0.00 Su

****INVOICE**

Sold Operations Totals

WE MAKE NO WARRANTY, expressed or implied, on the labor and materials necessary to repair this vehicle, and I acknowledge and understand that

	ESTIMATED	BILLED
LABOR		
PARTS		
MISC		
SUBLET		
PREPAY		
SUBTOTAL		
SHOP SUPPLIES		
MISC SUPPLIES		
TAX		
TOTAL		\$4,811.53