

Sales/Misc Items

Description	Qty	Unit Price	Tax	Amount
SHOP SUPPLIES				
MILEAGE				
FIELD LABOR & TRAVEL TIME				

**Invoice Memo**

WO 1218573  
CASE 621BS#JEE0056029  
HOURS 5302

#32

Complaint: Hydraulic leak underneath control lever in cab.

Cause: Blown pressure line on joystick control valve.

Correction: I drove to machine location. I then checked over machine. I removed cab skirt and checked for leaks. Oil is coming from inside cab. I then removed joystick covers and found pressure hose to be blown. I then removed key switch panel to properly remove hose. Once hose was removed customer went and had hose made. Once new hose arrived I slid into place and tightened. I then ran machine to check for leaks. There are no leaks at this time. I then put machine back together topped off hydraulic fluid. Machine is good to return to service. I took pictures loaded up tools and drove to shop.

Invoice Total      \$1,207.50