


QUANTITIES				BIN	PRICES	OFFICE USE
ORDERED	SHIPPED	B/O	✓			
				PART NUMBER	DESCRIPTION	
	1			MAKE: RE539764	MODEL: FUEL PUMP	
	1			MAKE: JD	MODEL: 672G	
				SHIPPING & HANDLING		
				Tax ID:		
				WE HAVE 24 HOUR EMERGENCY PARTS & SERVICE!!!		
				HOURS OF OPERATION 7AM - 6PM MON-FRI		
					
				THANK YOU FOR YOUR BUSINESS!!!		
						
				#10 P		

RECEIVED BY _____

PLEASE PAY THIS TOTAL ►

1155.94

DESCRIPTION	AMOUNT
CHECK A/C NOT WORKING	
COMPLAINT: THE A/C DOES NOT WORK.	
CAUSE: FOUND THAT A HOSE WAS LEAKING FROM COMPRESSOR TO ACCUMULATOR.	
CORRECTION: REPLACED HOSE FROM COMPRESSOR TO ACCUMULATOR AND CHARGED THE SYSTEM.	
1 N AT191102 CAB AIR FIL 1 N AT307501 CAB FILTER 1 N AT368580 REFRIGERANTXY 4 N R183411 O-RING CY 1 N AT162848 RECEIVER-D CY 2 N R183409 O-RING 12 N 6313 R134A R 1 N AT190809 PNEUMATIC * LABOR * 1 SHIPPING & HANDLING SHOP SUPPLIES (KC)	
>>- -> SEG# 01 PRT	

#10
Q

MAKE	MODEL	SERIAL NO.	EQUIP. NO.	METER	AUTHORIZED BY
JD	672G	1DW672GXJA0629482	672G MDT	2861	

DESCRIPTION	AMOUNT
-------------	--------

TRAVEL.***

* LABOR *

1 TRUCK #1007 SRV CALL 07/17/13

1 TRUCK #1007 SRV CALL 07/19/13

SHOP SUPPLIES (KC)

>>--> SEG# 02 PRT

REPLACE A/C COMPRESSOR

COMPLAINT:

A/C COMPRESSOR IS SETTING CODE FOR
SHORT TO GROUND.

CAUSE:

FOUND THE COMPRESSOR CLUTCH WAS MELTED.

CORRECTION:

REPLACED COMPRESSOR AND RAN.

1 N AT168543 COMPW/CLUTC

* LABOR *

1 CORE CHG/CR-DEERE

SHOP SUPPLIES (KC)

>>--> SEG# 03 PRT



RECEIVED BY _____

PLEASE PAY
THIS TOTAL ➡

3,301.20

Make/Model:	JOHN DEERE 672G
Meter Reading:	3517
Serial Number:	1DW672GXJA0629482
Equipment Number:	34423W

Gen- Retail
COMPLAINT:

diaganose machine will not go into gear

CAUSE:

FOUND THAT PARK BRAKE SOLENOID HAD FAILED.

CORRECTION:

CHECKED OUT PARK NEUTRAL REVERSE CONTROLLER AND GEAR SELECTOR CONTROLLER WIRING AND IT ALL CHECKED OUT GOOD. REPLACED PARKBRAKE SOLENOID THAT HAD FAILED AND RAN MACHINE.

Service Accessories

<u>Part Number</u>	<u>Description</u>
PARTS DELIVERY	PARTS DELIVERY
<i>Comments: KC to Fillmore exit</i>	
YZ107201	SOLENOID V

/Travel - 1 Retail

COMPLAINT:

Travel, to and from field service jobsite

CAUSE:

CORRECTION:

<u>Part Number</u>	<u>Description</u>
SVCTRUCK	MILEAGE CHARGE

672DG851036 Retail

COMPLAINT:

parkbrake solenoid replace

CORRECTION:

/Drive to Hub Retail

COMPLAINT:

Make/Model:	JOHN DEERE 672G
Meter Reading:	3517
Serial Number:	1DW672GXJA0629482
Equipment Number:	34423W

/Drive to Hub Retail
Drive to hub time

CAUSE:

CORRECTION:

Please remit payments to Murphy Tractor at the address shown on your monthly statement.

Total: \$1,406.87

Make/Model:	JOHN DEERE 672G
Meter Reading:	4179
Serial Number:	1DW672GXJA0629482
Equipment Number:	34423W

/Diagn - 1 Retail

COMPLAINT:

check out codes

ACTIVE CODES, MULTIPLE, INTERMITTENT.

\$409.50

CAUSE:

CHECK AND CLEAR CODES, CHECK OUT MACHINE, FOUND HARNESS, SHORTED UNDER FRONT SHROUD. REPAIRED, STILL HAVE ACTIVE CODE.

CORRECTION:

R&R FLC, PROGRAM AND PERFORM SOFTWARE UPDATES, CAL TRANS.

Service Accessories

<u>Part Number</u>	<u>Description</u>
AT346252	VEHICLE CO
FREIGHT	FREIGHT & SHIPPING

/Travel - 1 Retail

COMPLAINT:

Travel, to and from field service jobsite

CAUSE:

CORRECTION:

<u>Part Number</u>	<u>Description</u>
SVCTRUCK	MILEAGE CHARGE

#10 P

Make/Model:	JOHN DEERE 672G
Meter Reading:	4179
Serial Number:	1DW672GXJA0629482
Equipment Number:	34423W

/Drive to Hub Retail

COMPLAINT:

Drive to hub time

\$0.01

CAUSE:

CORRECTION:

Please remit payments to Murphy Tractor at the address shown on your monthly statement.

Total: \$2,093.21

Machine ID: 34423W	Make: JOHN DEERE	Model: 672G	PIN: 1DW672GXJA0629482	Hours: 5062
1.00	0.00	AT366546	HYDRAULIC	
1.00	0.00	FREIGHT	FREIGHT & SHIPPING	

Invoice Notes:
MIKE

Please remit payments to Murphy Tractor at the address shown on your monthly statement.

Total: \$1,061.24

Unit #10
P

4.00	0.00	T239757	INSERT	G10A2
2.00	0.00	T299164	INSERT	R5B3
1.00	0.00	FREIGHT	FREIGHT & SHIPPING	

Please remit payments to Murphy Tractor at the address shown on your monthly statement.

	Total:	\$871.38
--	---------------	-----------------

10

2

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G	6722	1DW672GXJA0629482	34423W	

/GOLD PNT INSPECTION Retail

COMPLAINT:

01 Gold Point Inspection

Full multi-point machine inspection performed by qualified technician.

For inspection details see attached inspection report.

CORRECTION:

Unit # 10
P

/Diagn - 3 Retail

COMPLAINT:

02 Machine doesn't have any power.

CORRECTION:

Removed hoses from turbo. Inspected turbo and found that the vanes are stuck causing the low power.

672GF999010 Retail

COMPLAINT:

03 TURBOCHARGER AND/OR GASKET, REPLACE

CAUSE:

Turbo has failed.

CORRECTION:

Replaced turbo and gaskets. Calibrated VGT actuator and ran machine to make sure there was no leaks and to make sure engine performed properly.

<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
--------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G	6722	1DW672GXJA0629482	34423W	

672GF999010 Retail
R520121 CAP SCREW
R521158 GASKET
R535094 GASKET
SE502429 Turbocharger Reman
SE502429-CR CORE for:Turbocharger Reman

Miscellaneous Charges:
Service Accessories

\$49.35

Please remit payments to Murphy Tractor at the address shown on your monthly statement.

*** DOCUMENT COPY ***

Grand Total: \$2,773.82

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G	6722	1DW672GXJA0629482	34423W	

672GF2101010 Retail

FREIGHT

FREIGHT & SHIPPING

INVOICE CONTAINS \$15.51 DISCOUNT

Miscellaneous Charges:

Service Accessories

\$200.00

Please remit payments to Murphy Tractor at the address shown on your monthly statement.

*** DOCUMENT COPY ***

Grand Total: \$6,969.53

Unit #10

make/model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G	6722	1DW672GXJA0629482	34423W	

672GF2101010 Retail

19M3190	CAP SCREW
51M7040	O-RING
PM38657	SEALANT
R131477	SEAL
R131478	SEAL
R135543	WASHER
R28782	O-RING
R76729	O-Ring
T158340	GASKET
T217291	HOSE
T233898	Gasket
T241241	ROD
T41677	O-RING
TY22028	HY-GARD QT
26779	3/16X14-3/16 T&B BLK TY-RAP
453816	M16 FW
87254	3" COARSE KB XL

Miscellaneous Description

Unit # 6

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G	6722	1DW672GXJA0629482	34423W	

/Drive to Hub Retail
CORRECTION:

unit # 10

/GOLD PNT INSPECTION Retail
COMPLAINT:
05 Gold Point Inspection

Full multi-point machine inspection performed by qualified technician.

For inspection details see attached inspection report.

CORRECTION:

672GF2101010 Retail

COMPLAINT:

06 There is a leak at the break to differential housing.

CORRECTION:

Pulled machine in shop and drained both tandems and differential. Removed both tandems and started removing the axle. Removed axle and washed it. Pulled right axle apart. Clean all of the parts. Replaced brake seal and resealed axle housing. Ran tap through all of the bolt holes to clean out the sealant. Put axle housing together with new hardware. Finish putting axle together and putting axle back in machine. Finish axle and put tandems back on machine. Filled tandems and axle with oil. Washed axle and tandems off and drove machine around to check for leaks.

Part Number	Description
T361909	SEAL
14M7398	NUT
19M7417	CAP SCREW
19M7488	16 X 40MM

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G	6722	1DW672GXJA0629482	34423W	

/Diagn - 1 Retail

COMPLAINT:

01 There is a leak at the tandem.

Unit # 10

CORRECTION:

Cleaned area and inspected machine. Found that the leak was between the break, and differential housing.

/Travel - 1 Retail

COMPLAINT:

02 Travel, to and from field service jobsite

CORRECTION:

Miscellaneous
SVCTRUCK

Description
MILEAGE CHARGE

/Diagn - 2 Retail

COMPLAINT:

03 Mold board is shifting back when it beginning of use.

CORRECTION:

Removed circle side shift cylinder end caps. Also removed shims to get tight. Put back together to specs. Greased pins and caps.

/Drive to Hub Retail

COMPLAINT:

04 Drive to hub time

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G		1DW672GXJA0629482	34423W	

/GOLD PNT INSPECTION Retail

COMPLAINT:

01 Gold Point Inspection

Full multi-point machine inspection performed by qualified technician.

For inspection details see attached inspection report.

unit # 10
D

/Diagn - 3 Retail

COMPLAINT:

02 When driving the machine it will kick into neutral and won't go back into gear unless the machine is shut off and restarted. Machine has a active code for inching pedal out of range.

CAUSE:

The inching pedal has failed.

CORRECTION:

Drove machine around and found transmission would go to neutral while driving it and a code for the inching pedal would become active in the monitor. Hooked up service advisor and went through the diagnostics procedures. Found the voltage coming out of the inching pedal switch was below spec. Machine needs a new inching pedal.

672GF1010472 Retail

COMPLAINT:

03 INCHING PEDAL (GP) , REPLACE

CAUSE:

install new inching pedal to due previous diagnosis

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 672G		1DW672GXJA0629482	34423W	

672GF1010472 Retail

CORRECTION:

Removed old inching pedal and cover. Installed new inching pedal and hook up harness. Reinstalled cover. Performed calibration and ran machine around yard to verify. No codes returned.

<u>Part Number</u>	<u>Description</u>
AT386338	PEDAL
<u>Miscellaneous</u>	<u>Description</u>
FREIGHT	FREIGHT & SHIPPING

Miscellaneous Charges:

Service Accessories

*** DOCUMENT COPY ***

Grand Total: \$1,741.66

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 672G	8988	1DW672GXJA0829482	34423W	

/GOLD PNT INSPECTION Retail

COMPLAINT:

01 Gold Point Inspection

Full multi-point machine inspection performed by qualified technician.

For inspection details see attached inspection report.

CAUSE:

CORRECTION:

672GF999639 Retail

COMPLAINT:

03 CAB WINDOW, REPLACE-R.H. DOOR

CAUSE:

CORRECTION:

customer said the right door glass was broke out
ordered in the correct glass for the door
went up to where the machine was located
removed the 4 bolts holding the door to the cab frame
laid the door frame down and removed the old glass and glue off door frame
installed new window glue on the frame
installed the new glass onto the door frame
installed new latch seal and door latch onto door glass
put weight on the glass to hold glass
let set for an hour and tested the set up
it was hard
installed door frame back on the cab frame
adjusted latch on the door

<u>PartNumber</u>	<u>Description</u>	<u>Quantity</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
-------------------	--------------------	-----------------	------------------	-----------------------	------------------

CONTINUED ON NEXT PAGE->

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 672G	8968	1DW672GXJA0629482	34423W	

T202653	WINDOWPANE
T204599	Gasket
T223734	Washer
T223734	Washer
T223735	Spacer
T223735	Spacer
U418	SEALER GLAS
<u>Miscellaneous</u>	<u>Description</u>
DISCOUNT	PARTS DISCOUNT ALLOWED
FREIGHT	FREIGHT & SHIPPING

Miscellaneous Charges:

Service Accessories

Total:	\$1,421.40
---------------	-------------------