

## SERVICE INVOICE

|          |           |                                   |       |            |  |
|----------|-----------|-----------------------------------|-------|------------|--|
| R/O      |           | VIN                               |       | DATE IN    |  |
|          |           | 1 F T 8 X 3 B T 3 G E B 7 8 8 1 4 |       | 07/12/2022 |  |
| YEAR     | MAKE      | MODEL                             | COLOR | TIME IN    |  |
| 2016     | FORD      | SUPER DUTY                        | O     | 15:04      |  |
| MILES IN | MILES OUT | FIRST USE                         | LISC. | CLOSED     |  |
| 95899    | 95899     | 00/00/00                          |       | 11:52      |  |
|          |           |                                   |       | 07/28/2022 |  |
| SEE ALSO |           |                                   |       |            |  |

1) REPLACE TRANSMISSION  
TRANSMISSION WOULD NOT GO INTO 2ND GEAR.  
REPLACED TRANSMISSION WITH 3YR 100K REMAN  
PROGRAMMED UNIT TO TRUCK AND TEST DROVE TO VR  
IFY REPAIR

|                         |               |   |
|-------------------------|---------------|---|
| Labor                   | T20           |   |
| MSL57151                | (FILTER)      | 1 |
| 72744                   | (GASKET)      | 1 |
| 6R140                   | (REMAN TRANS) | 1 |
| Total Labor             | .....         |   |
| Total Parts             | .....         |   |
| Total Repair (Customer) | .....         |   |

2) CS CHECK ENGINE LIGHT ON  
NOX SENSORS FRONT AND REAR HAVE FAILED AND VE  
HICLE WONT GO INTO REGEN MODE  
AFTER SENSOR AND MODULE REPLACEMENT SHORT CIR  
CUIT CODES STORED. CHECKED ALL CONNECTOR AND  
WIRING FOUND SOME WIRE DAMAGE AND CONNECTOR A  
DAMAGE. REPAIRED WIRING. VEHICLE OPERATES AS  
DESIGNED AT THIS TIME

|                         |            |   |
|-------------------------|------------|---|
| Labor                   | T20        |   |
| 01407                   | (TERMINAL) | 1 |
| DC3Z9D378D              | (SENSOR)   | 1 |
| DC3Z9D378C              | (SENSOR)   | 1 |
| DC3Z5K202D              | (MODULE)   | 1 |
| DC3Z5K202C              | (MODULE)   | 1 |
| DC3Z5K202C              | (MODULE)   | 1 |
| Total Labor             | .....      |   |
| Total Parts             | .....      |   |
| Total Repair (Customer) | .....      |   |

W/C

INT.

CUSTOMER

Labor  
Parts  
Sublet/Fees  
Shop Supplies  
Oil/Grease  
Sub Total  
Tax  
Total (Due)

7310.19