

MP9474	1612	Location: District 1-Topeka - Radio	ADAPTOR, PORTABLE RADIO, MOTOROLA, MDL. N2001A SN: 256CGM0308, NOT WORKING - SERVICEABLE, CRADLE ONLY - MISSING ALL OTHER PARTS
MP9474	1613	Location: District 1-Topeka - Radio	ADAPTOR, PORTABLE RADIO, MOTOROLA, MDL. N2001A SN: 256CGM0176, NOT WORKING - SERVICEABLE, CRADLE ONLY - MISSING ALL OTHER PARTS
MP9474	1614	Location: District 1-Topeka - Radio	TRAINER, DIGITAL DESIGN EXPERIMENTER, HEATHKIT, MDL. ET-3200 SN: 04720, NOT WORKING - SERVICEABLE
MP9474	1638	Location: District 1-Topeka - Radio	ADAPTOR, PORTABLE RADIO, MOTOROLA, MDL. N2001A SN: 256CGM0331, NOT WORKING - SERVICEABLE, CRADLE ONLY - MISSING ALL OTHER PARTS
MP9474	1639	Location: District 1-Topeka - Radio	CPU, HP, MDL. Z440 SN: 2UA5251RYS, Intel Xeon processor, 8 GB RAM, DVD, NO HARD DRIVE, NO OPERATING SYSTEM INSTALLED
MP9474	211-3010	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, MOTOROLA, MDL. R2670A, '94 SN: 496KUJ0020, FDMA digital communications system analyzer, NOT WORKING - SERVICEABLE
MP9474	211-3014	Location: District 1-Topeka - Radio	ANALYZER, SERVICE MONITOR, MOTOROLA, MDL. R2670A, '98 SN: 496KYN0040, FDMA digital communications system analyzer, NOT WORKING - SERVICEABLE
MP9474	511-3039	Location: District 1-Topeka - Radio	ANALYZER, BATTERY, CADEX, MDL. C7000, '00 SN: VGAF05661, BROKEN AND DEFECTIVE
MP9474	919030	Location: District 1-Topeka - Radio	CPU, HP, MDL. Z440, '15 SN: 2UA5251S07, Intel Xeon processor, 8 GB RAM, 128 GB hard drive, DVD, NO OPERATING SYSTEM INSTALLED
MP9474	919283	Location: District 1-Topeka - Radio	CPU, HP, MDL. Z440, '15 SN: 2UA5271NN4, Intel Xeon processor, 8 GB RAM, DVD, NO HARD DRIVE, NO OPERATING SYSTEM INSTALLED