

NP9505	312-1371	Location: District 3-Norton - Radio	ADAPTOR, PORTABLE RADIO, MOTOROLA, MDL. N1617A, '01 SN: 476ABL0202, NOT WORKING - SERVICEABLE
NP9505	312-1394	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0186, NOT WORKING - SERVICEABLE
NP9505	312-1395	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0187, NOT WORKING - SERVICEABLE
NP9505	312-1396	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0188, NOT WORKING - SERVICEABLE
NP9505	312-1399	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0191, NOT WORKING - SERVICEABLE
NP9505	312-1401	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0193, NOT WORKING - SERVICEABLE
NP9505	312-1402	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0194, NOT WORKING - SERVICEABLE
NP9505	312-1404	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0196, NOT WORKING - SERVICEABLE
NP9505	312-1408	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0200, NOT WORKING - SERVICEABLE
NP9505	312-1413	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0205, NOT WORKING - SERVICEABLE
NP9505	312-1414	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0206, NOT WORKING - SERVICEABLE
NP9505	312-1415	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0207, NOT WORKING - SERVICEABLE

NP9505	312-1416	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0208, NOT WORKING - SERVICEABLE
NP9505	312-1418	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0210, NOT WORKING - SERVICEABLE
NP9505	312-1421	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0213, NOT WORKING - SERVICEABLE
NP9505	312-1423	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0215, NOT WORKING - SERVICEABLE
NP9505	312-1429	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0221, NOT WORKING - SERVICEABLE
NP9505	312-1432	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0224, NOT WORKING - SERVICEABLE
NP9505	312-1435	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0227, NOT WORKING - SERVICEABLE
NP9505	312-1436	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0228, NOT WORKING - SERVICEABLE
NP9505	312-1437	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0229, NOT WORKING - SERVICEABLE
NP9505	312-1439	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '08 SN: 256CJP0231, NOT WORKING - SERVICEABLE
NP9505	312-1442	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CFL0040, NOT WORKING - SERVICEABLE
NP9505	312-1445	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0043, NOT WORKING - SERVICEABLE

NP9505	312-1449	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0047, NOT WORKING - SERVICEABLE
NP9505	312-1450	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0048, NOT WORKING - SERVICEABLE
NP9505	312-1453	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0051, NOT WORKING - SERVICEABLE
NP9505	312-1454	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0052, NOT WORKING - SERVICEABLE
NP9505	312-1455	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0053, NOT WORKING - SERVICEABLE
NP9505	312-1458	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0056, NOT WORKING - SERVICEABLE
NP9505	312-1459	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0057, NOT WORKING - SERVICEABLE
NP9505	312-1460	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0058, NOT WORKING - SERVICEABLE
NP9505	312-1461	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0059, NOT WORKING - SERVICEABLE
NP9505	312-1463	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0061, NOT WORKING - SERVICEABLE
NP9505	312-1465	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0063, NOT WORKING - SERVICEABLE
NP9505	312-1466	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0064, NOT WORKING - SERVICEABLE

NP9505	312-1467	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0065, NOT WORKING - SERVICEABLE
NP9505	312-1470	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0068, NOT WORKING - SERVICEABLE
NP9505	312-1471	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0069, NOT WORKING - SERVICEABLE
NP9505	312-1473	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0071, NOT WORKING - SERVICEABLE
NP9505	312-1478	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0076, NOT WORKING - SERVICEABLE
NP9505	312-1479	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0077, NOT WORKING - SERVICEABLE
NP9505	312-1480	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0078, NOT WORKING - SERVICEABLE
NP9505	312-1481	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0079, NOT WORKING - SERVICEABLE
NP9505	312-1482	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0080, NOT WORKING - SERVICEABLE
NP9505	312-1483	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0081, NOT WORKING - SERVICEABLE
NP9505	312-1484	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0082, NOT WORKING - SERVICEABLE
NP9505	312-1485	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0083, NOT WORKING - SERVICEABLE

NP9505	312-1486	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0084, NOT WORKING - SERVICEABLE
NP9505	312-1488	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0086, NOT WORKING - SERVICEABLE
NP9505	312-1489	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0087, NOT WORKING - SERVICEABLE
NP9505	312-1490	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0088, NOT WORKING - SERVICEABLE
NP9505	312-1493	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0091, NOT WORKING - SERVICEABLE
NP9505	312-1494	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0092, NOT WORKING - SERVICEABLE
NP9505	312-1495	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0093, NOT WORKING - SERVICEABLE
NP9505	312-1496	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0094, NOT WORKING - SERVICEABLE
NP9505	312-1497	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0095, NOT WORKING - SERVICEABLE
NP9505	312-1499	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0097, NOT WORKING - SERVICEABLE
NP9505	312-1500	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0098, NOT WORKING - SERVICEABLE
NP9505	312-1501	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0099, NOT WORKING - SERVICEABLE

NP9505	312-1507	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0105, NOT WORKING - SERVICEABLE
NP9505	312-1510	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0108, NOT WORKING - SERVICEABLE
NP9505	312-1511	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0109, NOT WORKING - SERVICEABLE
NP9505	312-1512	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0110, NOT WORKING - SERVICEABLE
NP9505	312-1513	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0111, NOT WORKING - SERVICEABLE
NP9505	312-1514	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0112, NOT WORKING - SERVICEABLE
NP9505	312-1515	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0113, NOT WORKING - SERVICEABLE
NP9505	312-1516	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0114, NOT WORKING - SERVICEABLE
NP9505	312-1519	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0117, NOT WORKING - SERVICEABLE
NP9505	312-1520	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0118, NOT WORKING - SERVICEABLE
NP9505	312-1521	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0119, NOT WORKING - SERVICEABLE
NP9505	312-1522	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0120, NOT WORKING - SERVICEABLE

NP9505	312-1523	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0121, NOT WORKING - SERVICEABLE
NP9505	312-1524	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0122, NOT WORKING - SERVICEABLE
NP9505	312-1526	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0124, NOT WORKING - SERVICEABLE
NP9505	312-1530	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0128, NOT WORKING - SERVICEABLE
NP9505	312-1531	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0129, NOT WORKING - SERVICEABLE
NP9505	312-1532	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLF0130, NOT WORKING - SERVICEABLE
NP9505	312-1535	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0011, NOT WORKING - SERVICEABLE
NP9505	312-1536	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0012, NOT WORKING - SERVICEABLE
NP9505	312-1537	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0013, NOT WORKING - SERVICEABLE
NP9505	312-1538	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0014, NOT WORKING - SERVICEABLE
NP9505	312-1539	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0015, NOT WORKING - SERVICEABLE

NP9505	312-1543	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0019, NOT WORKING - SERVICEABLE
NP9505	312-1545	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0021, NOT WORKING - SERVICEABLE
NP9505	312-1547	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0023, NOT WORKING - SERVICEABLE
NP9505	312-1550	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0026, NOT WORKING - SERVICEABLE
NP9505	312-1551	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0027, NOT WORKING - SERVICEABLE
NP9505	312-1552	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0028, NOT WORKING - SERVICEABLE
NP9505	312-1553	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0029, NOT WORKING - SERVICEABLE
NP9505	312-1554	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0030, NOT WORKING - SERVICEABLE
NP9505	312-1555	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0031, NOT WORKING - SERVICEABLE

NP9505	312-1556	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0032, NOT WORKING - SERVICEABLE
NP9505	312-1557	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0033, NOT WORKING - SERVICEABLE
NP9505	312-1558	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0034, NOT WORKING - SERVICEABLE
NP9505	312-1559	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0035, NOT WORKING - SERVICEABLE
NP9505	312-1560	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0036, NOT WORKING - SERVICEABLE
NP9505	312-1561	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0037, NOT WORKING - SERVICEABLE
NP9505	312-1562	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0038, NOT WORKING - SERVICEABLE
NP9505	312-1564	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0040, NOT WORKING - SERVICEABLE
NP9505	312-1565	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0041, NOT WORKING - SERVICEABLE

NP9505	312-1566	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0042, NOT WORKING - SERVICEABLE
NP9505	312-1567	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0043, NOT WORKING - SERVICEABLE
NP9505	312-1574	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0050, NOT WORKING - SERVICEABLE
NP9505	312-1575	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0051, NOT WORKING - SERVICEABLE
NP9505	312-1577	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0053, NOT WORKING - SERVICEABLE
NP9505	312-1578	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0054, NOT WORKING - SERVICEABLE
NP9505	312-1579	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0055, NOT WORKING - SERVICEABLE
NP9505	312-1581	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0057, NOT WORKING - SERVICEABLE
NP9505	312-1582	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0058, NOT WORKING - SERVICEABLE

NP9505	312-1583	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0059, NOT WORKING - SERVICEABLE
NP9505	312-1584	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0060, NOT WORKING - SERVICEABLE
NP9505	312-1585	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '10 SN: 256CLM0061, NOT WORKING - SERVICEABLE
NP9505	412-1399	Location: District 3-Norton - Radio	ADAPTER, PORTABLE RADIO, MOTOROLA, MDL. XTVA, '05 SN: 256CFR0637, NOT WORKING - SERVICEABLE