

NV9273	23021610	Location: District 2-Salina	BLOWER, LEAF, STIHL, MDL. BG56C SN: 275999412, NOT WORKING - SERVICEABLE, HARD TO START THEN DIES
NV9273	23021714	Location: District 2-Salina	TRIMMER, STRING, STIHL, MDL. FS250R SN: 279065234, NEEDS ROPE STARTER, MISSING BODY PARTS, RUNNING ISSUES
NV9273	23021715	Location: District 2-Salina	TRIMMER, STRING, STIHL, MDL. FS250R SN: 285064665, NEEDS EXHAUST FIXED, MISSING BODY PARTS, RUNNING ISSUES
NV9273	23031027	Location: District 2-Salina	SAW, POLE, STIHL, MDL. HT103 SN: 527592954, gas engine, CONDITION UNKNOWN – DAMAGED IN ACCIDENT
NV9273	23050531	Location: District 2-Salina	SAW, POLE, STIHL, MDL. HT131 SN: 296884314, extendable, 36.3 cc, 2 cycle engine, 11" bar, UNIT HAS A BENT SHAFT
NV9273	23050932	Location: District 2-Salina	SAW, CUT-N-BREAK, HUSQVARNA, MDL. K760 14" blade, NO BLADE, STARTING/RUNNING ISSUES