

ATSI

 1226 East 23rd Street
 Lawrence, KS. 66046

Phone: 785-843-7533 Fax: 785-856-2757

"TRANSMISSION CORRECTION AT A HIGHER LEVEL"

INVOICE

23446

INVOICE

Work Completed : 02/22/2019

Date: 02/25/2019

Quality Lawn Care - Corey Gaston

1185 N 900 Rd

Lawrence, KS 66047

Cellular 785-423-5877

2003 Ford - F450 Super Duty - 6L, V8 (363CI) VIN(P)

Lic #: 532694

Odometer In : 130259

Odometer Out : 130274

Hat #: 19

VIN #: 1FDXF47P3 3ED01758

Part Description	Qty	Sale	Ext	Labor Description	Ext
ATSI Rebuilt 5R100W Torque Shift	1.00	2,236.00	2,236.00	TRANSMISSION ASSEMBLY - Remove & Replace - Diesel,4WD	863.93
Transmission Oil Cooler Lines	1.00	198.30	198.30	Removed transmission assembly and prepped it for overhaul. Flushed transmission cooler through existing cooler lines. After cooler flush was completed, installed new OEM cooler lines and filter assembly. Installed a new filter in the housing. Completed transmission overhaul and installed unit. Filled with 18 qts of full synthetic ATF and test drove. Test drive was normal, double checked fluid levels. Engine drips some engine oil. Drag link is loose and one sway bar link is broken. Truck wanders when driving down the road.	
PREMIUM SYNTHETIC ATF	20.00	6.93	138.60	TRANSMISSION ASSEMBLY - Overhaul Removed - All Applicable Models - [Includes: Inspect and replace all necessary components, reassemble and adjust.]	1,064.00
Reprogramming Software	1.00	59.99	59.99	OIL COOLER LINES - Remove & Replace - Trans Mfr CD 5R110W	179.20
Cooler Filter	1.00	31.15	31.15	Fluid Capacity: Automatic Transmission Fluid - Volume: 17.50 QTS. (16.6L) - MOTORCRAFT Automatic Transmission Fluid MERCON LV; Trans Mfr CD 5R110W - TorqShift - (Note: FORD Special Service Message 21114: Vehicles equipped with TORQSHIFT Automatic Transmission should be serviced with MERCON LV ATF in place of MERCON SP. This includes top off as well as fluid replacement. Mixing MERCON LV and MERCON SP in the TORQSHIFT transmission is acceptable. Use MERCON LV ATF to service vehicles equipped with TORQSHIFT transmission. When adding or replacing ATF in vehicle equipped with TORQSHIFT Transmission, Use MERCON LV ATF.)	
Cooler Filter Assembly	1.00	450.21	450.21	TRANSMISSION CHECK OUT n/c	
SHOP SUPPLIES			23.93	Symptoms: Customer was pushing snow and the transmission kept overheating to max or almost max. They let it cool down multiple times. Customer was leaving our shop after setting up an appointment and it only had R and 1. ATSI test drove the vehicle and found that the truck has 1st, 2nd and reverse. When the codes are cleared the truck will try to make the 2-3 shift and it will tie up badly. Transmission codes stored: P0730 - gear ratio malfunction, P1783 - transmission over temp, P2704 - transmission friction element E apply time range or performance. There is a significant amount of engine codes stored. ATF is full and appears normal. Truck has multiple heavy engine oil leaks. 2nd gear is stuck on.	
				Flush Transmission Cooler	75.00
				Attach Hot Flush Machine to Transmission Cooler Lines and Hot Flush Transmission Cooler and Lines. Continue Flushing Until the Internal Filter in the Hot Flush Machine is Clear from Sediments from Cooler and Lines. Disconnect Hot Flush Machine From Vehicle Cooler Lines. Drain and refill transfer case with OE approved fluid (Where applicable)	
				REPROGRAMING PROCEDURE	99.99
				Reprogram all computer modules to latest OEM updates.	
				TRANSMISSION OIL FILTER - Remove & Replace - Line,Filter	n/c

ATSI1226 East 23rd Street
Lawrence, KS. 66046

Phone: 785-843-7533 Fax: 785-856-2757

"TRANSMISSION CORRECTION AT A HIGHER LEVEL"

INVOICE**23446****INVOICE**

Work Completed : 02/22/2019

Date: 02/25/2019

Quality Lawn Care - Corey Gaston

1185 N 900 Rd

Lawrence, KS 66047

Cellular 785-423-5877

2003 Ford - F450 Super Duty - 6L, V8 (363CI) VIN(P)

Lic # : 532694

Odometer In : 130259

Odometer Out : 130274

VIN # : 1FDXF47P3 3ED01758

Hat # : 19

Part Description	Qty	Sale	Ext	Labor Description	Ext
------------------	-----	------	-----	-------------------	-----

[Payments - Visa - \$5,910.84]

I authorize repair work to be done with the needed materials and grant you and/or your employees permission to operate the Vehicle as described on street, highways or elsewhere for testing and/or inspection. An express mechanic's lien on vehicle is hereby acknowledged to secure the amount of repairs. Warranty on new parts and labor is 3 yrs or 50,000 miles, whichever comes first. Warranty work must be performed in our shop & cannot exceed the original cost. If the customer is outside of town, customer must contact ATSI for repair authorization and instruction. No work will be performed or reimbursed without prior approval. Automatic Transmissions carry a 3 yrs or 100,000 miles Warranty, whichever comes first. Used components carry a 12 month, 12,000 mile warranty unless explicitly implied on the work order.

Labor:	2,282.12
Parts:	3,138.18
Sub:	5,420.30
Tax:	490.54
Total:	\$5,910.84
Bal Due:	\$0.00

Customer Number : 994

Vehicle Received: 2/22/2019

Signature _____

Date _____