

Date

11/8/2022

P.O. No.

Terms

Project

Net 10

Quantity

Description

Rate

Amount

Trailer V.I.N.: 1DA72G752YC015007

Removed and replaced rear axle brake lining, drums, s-cams, and s-cam bushings

Removed and replaced rear axle wheel seals and hub cap gaskets

Checked and inspected rear axle wheel bearings and races -OK-

Adjusted brakes on front axle

Removed both rear main cylinders

Removed all seized cylinder pins

Reinstalled new rear main cylinders (customer supplied)

Fabricated and installed all new rear main cylinder pins

Cleaned up and welded cracked grid section bracing

Installed grease zerks on new cylinders

Lubricated all cylinder pins

Checked operation of new cylinders -OK-

Checked all lights -OK-

Checked air system -OK-

Greased trailer

1 Mag1 Multiple Purpose Grease

1 Door Lube

2 MAG 1 Brake Cleaner

2 6-Hole Hubcap Gasket

2 Wheel Seal

Total

Date

11/8/2022

P.O. No.

Terms

Project

Net 10

Quantity

Description

Rate

Amount

8 1/4" Nylon Lock Nut
2 3/32 X 1" Cotter Pin
2 1/8" X 1-1/2" Cotter Pin
8 3/16" X 14 Cable Zip-Tie
4 Grease Zerk
2 Brake drum (12.25X8.0)
4 Reman shoe Dexter (12-1/2X7-1/2 PQ)
2 Brake kit (12.25 Dexter PQ)
2 Cam bushing kit
1 S-cam (Roadside)
1 S-cam (Curbside)
3 5/16X1-1/4 Grade 5 Bolt
1 Shop Supplies
Nebraska Sales Tax

Total

\$5,183.14

☐ ESTIMATE (VALID FOR 30 DAYS)

DATE _____

☐ SERVICE☐ WILL CALL☐ INSTALL☐ DELIVER

ADDRESS

MAKE

MODEL

SERIAL

ITEM TO BE SERVICED

[illegible]

DATE WANTED

DEPOSIT

RECEIVED BY

ESTIMATES ARE FOR LABOR ONLY, MATERIAL ADDITIONAL. WE WILL NOT BE RESPONSIBLE FOR LOSS OR DAMAGE CAUSED BY FIRE, THEFT, TESTING, OR ANY OTHER CAUSES BEYOND OUR CONTROL.