

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 620I	766	M0XUVGX017856	X017856	

CHECKOVER Retail

Gator 7856

CORRECTION:

TECH NAME: SAM P.

CHECK OVER FOR NEEDED REPAIRS, TORE DOWN UNIT TO FIGURE OUT THE PROBLEMS WITH UNIT.
 -WAS PUTTING WHEELS BACK ON AND NOTICED THAT DRIVE REAR WHEEL BEARING WAS OUT SO TOOK LOWER CONTROL ARM OFF AND WHEEL HUB OFF TO REPLACE WHEEL BEARING.
 -REASSEMBLED IN REVERSE ORDER THEN REINSTALLED WHEEL AND TORQUED TO 105 FT LBS.
 -REPLACED ROOF WITH A NEW ONE.

PartNumber	Description
AM148394	BALL BEARI

/SSGATORS Retail

CORRECTION:

SERVICE UNIT:
 CHANGE FUEL FILTER, WHEN REPLACING FUEL FILTER FUEL PUMP FITTING BROKE OFF. REPLACED FUEL PUMP WITH UPDATED KIT #BUC10543. (PUMP SOLD TO CUSTOMER AT COST PRICE). CHANGE ENGINE OIL/FILTER. CHANGE AIR CLEANER ELEMENT. CHECK AIR CLEANER DUST UNLOADING VALVE CLEANED. GREASE MACHINE. CHECK DRIVE BELT CONDITION REPLACED DRIVE BELT. REPLACED SECONDARY DRIVE CLUTCH. CHECK BRAKE OIL LEVEL. CLEAN PRIMARY DRIVE CLUTCH. INSPECT AND CLEAN BATTERY. CHECK BRAKE PAD WEAR (SEE OM FOR SPECS) CLEANED ALL FOUR WHEEL HUB AND REPLACED FRONT BRAKE PADS. CHECK AND TIGHTEN WHEEL BOLTS TO SPECS 105 FT LBS. REPLACE SPARK PLUG(S) GAPPED TO 30". CHECK AND TIGHTEN HARDWARE. TOPPED OF RADIATOR WITH COOLANT.

PartNumber	Description	Quantity	Net Price	Extended Price	Taxed Ind
19M7834	Screw				
24H1288	Washer				
24H1695	Washer				
AM141182	Brake Pad				
BUC10543	PUMP KIT				
LG261	Maintenance Kit				
M84972	NUT				
R115466	PLUG				
TY22000	LOW VIS HYDRAULIC OIL 1 GAL				

LG-03 Retail

CONTINUED ON NEXT PAGE->

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 620I	766	M0XUVGX017856	X017856	

CORRECTION:

CV JOINTS & REPLACE TOP:
 -DISASSEMBLED FRONT END -REMOVED FRONT DIFFERENTIAL AND CV SHAFTS -REMOVED FRONT STEERING SPINDLES -
 REPLACED WHEEL BEARINGS AND BALL JOINTS -REPLACED FRONT DIFFERENTIAL AND CV SHAFTS
 -INSTALLED NEW FRONT DIFFERENTIAL -REPLACED CV SHAFTS -INSTALLED NEW SIDE MIRRORS.

<u>PartNumber</u>	<u>Description</u>
11M7087	COTTER PIN
14M7396	LOCK NUT
	Sam
19M8319	Screw
	Sam
AM135249	Universal Driveshaft
AM135250	Universal Driveshaft
AUC14076	Drive
BM23063	Roof Kit
E59406	FLANGE NUT
HF620026167	Rear View Mirror
M122113	Washer
M155219	Sleeve
M155220	Sleeve
M156019	BALL BEAR
VG11506	BALL JOINT
<u>Miscellaneous</u>	<u>Description</u>
37501	PRT FREIGHT

LG-04 Retail

CORRECTION:

REPLACE BUSHINGS:
 -REMOVED SHOCK, UPPER AND LOWER REAR CONTROL ARMS TO REPLACED BUSINGS AND WASHERS.
 -PUNCHED OUT BUSHINGS FROM CONTROL ARMS AND REINSTALLED NEW ONES USED SOME BEARING MOUNT NEW
 BUSHINGS. -REPLACED WASHERS, O RINGS AND SEALS ON BUSHING MOUNTS. -REINSTALLED PART IN REVERSE ORDER.

<u>PartNumber</u>	<u>Description</u>
M156414	Bushing
M156696	Washer

CONTINUED ON NEXT PAGE->

JOHN DEERE 620I	Meter	Serial Number:	EQ Id:	Fleet No:
	766	M0XUVGX017856	X017856	

T16952 Washer
U11296 O-Ring

LG-05 Retail

CORRECTION:

REPAIR DRIVE LINE

-REMOVED BATTERY -REMOVED DRIVE LINE -TOOK PARK BRAKE ASSEMBLY OFF -SPLIT MFWD DRIVE HOUSING TO
REPLACED SHAFT SEAL -REBUILT DRIVE LINE REPLACED CARRIER BEARINGS AND DRIVE COUPLERS
-REPLACED PARK BRAKE ASSEMBLY WITH NEW ONE.

PartNumber	Description
AM136461	Drive Line Slip Sleeve
AM137954	Disk Brake Caliper Assy
AM143610	Bearing
AW25863	Seal
PM38657	SEALANT

LG-06 Retail

CORRECTION:

REPLACED CLUTCH BUTTONS:

-REMOVED BELT COVER -REMOVED SECONDARY CLUTCH AND BELT -TOOK CLUTCH APART TO REPLACE BUTTONS AND
FOUND CLUTCH RAMP GROVE AND WORE OUT SO ORDERED AND REPLACED WHOLE CLUTCH WITH NEW ONE.

PartNumber	Description
14M7397	LOCK NUT
AM138089	Clutch
M158267	Synchronous Belt

CONTINUED ON NEXT PAGE->

Make/Model:	Meter	Serial Number:	EQ Id:	Fleet No:
JOHN DEERE 620I	786	M0XUVGX017856	X017856	

Total: \$8,655.89