INVOICE

BILL TO

SHIP TO

INVOICE

DATE

06/19/2023

TERMS

DUE DATE

06/19/2023

DESCRIPTION QTY RATE AMOUNT

Job# 1017791292

Job Description: Fix wiring issue. Not running.

Wiring was cut and spliced. Couldn't use factory harness as a result. Made wiring to work the ignition and coil. Timing was 180 out and firing order was backwards. Reset distributor and changed firing order. Engine started and checked functions. Transmission wouldn't go into gear no pressure to torque converter. Tried flushing transmission and changed filter. Still won't engage. Pulled engine and removed torque converter. Removed transmission pump and found to be worn, installed new pump and had torque converter checked. Reinstalled engine and filled transmission with fluid. Started engine and transmission went into gear. Test drove and after a minute of driving it started slipping and lost fluid pressure at the converter again. Unit is being further inspected. After inspection it was found that the torque converter is and was sitting too far forward from the transmission. Tore apart and reset torque converter into position, Made spacers and installed new hardened bolts. Reassembled and test drove. Transmission works as it should. Throttle on engine is sticking closed. Removed mixer and cleaned. Removed engine governor and cleaned. Reinstalled and drove again. Everything is working good now but the entire wiring harness needs replaced in order for all the safety functions to work properly.

QBO Product UTF GALLONUNIVERSAL TRACTOR FLUID	6
QBO Product SY4620-PROBRAKE CLEANER	6
QBO Product HY1320018TRANSMISSION PUMP	1
Rebuilt Torque Converter	1
Shipping Charges	1
Labor	
Delivery	1
DARGAR A S NOVAS A S A DIMA	
	SUBTOTAL
	TAX
	TOTAL
	BALANCE DUE \$6,291.48

				Invoice
			Da	
			2/22/	2022
Bill To		Ship	To	
		Ship	10	
P.O. Number	Terms			
	Due on receipt			
177947203	Description	Our stille	Price Each	Amount
		Quantity	Finde Each	AHIOUH
		Quantity	Frice Each	Anount
BUILT 4.3 ENGINE		Quantity	1	Anoung
BUILT 4.3 ENGINE		Quantity		Allouik
EF: 30902 PARTS SO BUILT 4.3 ENGINE ORE CHARGE ipping Charges		Quantity	100	
BUILT 4.3 ENGINE DRE CHARGE ipping Charges		Cluamity	1	O Klift

