

Sold Operations

JOB #1 CPDIAG PEFORM CUST PAY DIAGNOSTICS - RETAIL

COMPLAINT CHECK THE EXHAUST TUBE (GOING TO THE TURBO - OUTPUT) -
 CAUSE
 CORRECTION CUT OLD SECTION OUT AND ADDED NEW FLEX PIPE

QTY	ITEM	DESCRIPTION
	LABOR CPDIAG-RET	CHECK THE EXHAUST TUBE (GOING TO THE TURBO - 4
1	804X/562.U7130-10A	STRAIGHT TUBING 10FT
1	804X/562.U13621A	FLANG ADAPTER
1	FRT	FREIGHT
1	804N/320226C1	TUBE FLEX 26 IN
1	804N/FLTEC30PLA	CLAMP 3.0IN HD PRE-FORM ALUM
1	804N/2033978C1	CLAMP EXHAUST PIPE
1	804N/FLTEC35PLA	CLAMP 3.5IN HD PRE-FORM ALUM
1	804X/50TQ30042	EXH CLAMP

Prepay: \$0.00 Parts: \$644.37 Labor: \$300.00 Misc: \$175.00 Sublet: \$0.00 Job #1 Total: \$1,119.37

****INVOICE TOTAL ON FINAL PAGE****

JOB #2 QC COURTESY QUICK CHECK INSPECTION

COMPLAINT Courtesy Quick Check Inspection -
 CAUSE
 CORRECTION COMPLETED INSPECTION

QTY	ITEM	DESCRIPTION	UNIT PRICE
	VMRS33	999-999-000	
	LABOR QC	Courtesy Quick Check Inspection	

Prepay: \$0.00 Parts: \$0.00 Labor: \$0.00 Misc: \$0.00 Sublet: \$0.00

****INVOICE TOTAL ON FINAL PAGE****

JOB #3 DECISIV DECISIV DEFAULT JOB

COMPLAINT NEEDS NEW GLOW PLUGS -
 CAUSE
 CORRECTION INSTALLED NEW GLOW PLUGS

QTY	ITEM	DESCRIPTION	UNIT PRICE
	LABOR DECISIV	NEEDS NEW GLOW PLUGS	
8	804N/1820697C2	GLOWPLUG ASSY	
1	804N/2501107C1	CONNECTR,CONNECTOR INJ CTRL RE	41.25
			60.87

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	OIL LEAK ABOVE MOTOR
1	804N/1831666C1	GASKET FRONT OIL COOLER HEADER
2	804N/1807563C1	RING O
2	804N/1804414C1	RING O
1	804N/1815898C3	GASKET PUMP FLANGE
2	804N/1831665C2	GASKET, REAR OIL COOLER HEADER
7	804D/FLTAHVBC14KK	FLEET AER HIGH VOC BRAKE CLN 1
	LABOR 002398	Road test

Pt

****INVOICE TOTAL ON FINAL PAGE****

JOB #5 DECISIV DECISIV DEFAULT JOB

COMPLAINT OIL LEAK AROUND DIPSTICK -
 CAUSE
 CORRECTION installed new o rings on dip stick

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	OIL LEAK AROUND DIPSTICK
1	804N/1876743C1	SEAL O-RING

Prepay: \$0.00 Parts: \$3.77 Labor: \$0.00 Misc: \$0.00 Sublet:

****INVOICE TOTAL ON FINAL PAGE****

JOB #6 DECISIV DECISIV DEFAULT JOB

COMPLAINT NO DASH LIGHTS -
 CAUSE
 CORRECTION there was no voltage coming from dimmer switch installed new switch now working as supposed to

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	NO DASH LIGHTS
1	804N/1661480C3	CONTROL LIGHT PANEL DIMMER

Prepay: \$0.00 Parts: \$169.04 Labor: \$300.00 Misc: \$0.00 Sublet:

****INVOICE TOTAL ON FINAL PAGE****

JOB #7 DECISIV DECISIV DEFAULT JOB

COMPLAINT CHANGE OIL & OIL FILTERS (THERE'S OIL IN THE BACK OF THE TRUCK) -
 CAUSE
 CORRECTION changed oil and installed new fliters on vehicle

QTY	ITEM	DESCRIPTION
	LABOR DECISIV	CHANGE OIL & OIL FILTERS (THERE'S OIL IN THE BAC)
1	804D/LF3630	L/O FLTR,LUBE/OIL FILTER
1	HAZ	HAZARDOUS WASTE

Prepay: \$0.00 Parts: \$36.54 Labor: \$200.00 Misc: \$14.50 Sublet:

****INVOICE TOTAL ON FINAL PAGE****

JOB #9 A01-RET FRAME / BUMPER - RETAIL

COMPLAINT Install dipstick on the power steering tank -
CAUSE FOUND THE DIPSTICK FOR THE POWER STEERING MISSING
CORRECTION RECOMMEND INSTALLING A NEW DIPSTICK

QTY	ITEM	DESCRIPTION
	LABOR A01-RET	Install dipstick on the power steering tank
1	804N/1695530C1	GAUGE,PWR STEER OIL LEVEL
1	804D/FLTPSF32KK	FLEETRITE POWER STEERING 32OZ

Prepay: \$0.00 Parts: \$83.88 Labor: \$37.50 Misc: \$0.00 Su

****INVOICE**

Sold Operations Totals

WE MAKE NO WARRANTY, expressed or implied, as to the condition, fitness, or suitability of materials or workmanship, and we do not accept any liability for damages of any kind arising from the use of the vehicle.

	ESTIMATED	BILLED
LABOR		
PARTS		
MISC		
SUBLET		
PREPAY		
SUBTOTAL		
SHOP SUPPLIES		
MISC SUPPLIES		
TAX		
TOTAL		\$4,811.53