

Invoice

Date	Invoice #
3/16/2022	

Customer

Unit Information
#10 2015 KW T680 VIN# 1XKYD49X9FJ424296 MILES: 851351 HRS: 19213 ISX 15 79799979

ME9558

Rep	Terms	Service Date	P.O. Number	Contact Info.
GLW	Due on Receipt	3/16/2022		
Quantity	Item Code	Description	Price Each	Amount
		LIKE GETS CAUGHT MIDWAY THRU SWITCH AND BLOWS BEHIND DASH. REMOVE DASH PANEL TO ACCESS ACTUATORS. CHECK HVAC ACTUATOR FOR SELECTOR, OK. CHECK DOORS, OK. COULD NOT GET TO ACT UP. DRIVER WILL MONITOR. REMOVE LEAKING PASS SIDE STEER AXLE HUB CAP. CLEAN AND REINSTALL HUB CAP WITH NEW GASKET. CHECK DRIVER SIDE HOOD MOUNT ON FIREWALL, CK OK. FOUND MOUNT ON HOOD MISSING 2 BOLTS AND 3RD BOLT LOOSE. REMOVE HOOD REST FROM HOOD. INSTALL FLANGE INSERTS. REINSTALL HOOD REST WITH NEW BOLTS. RUN UNIT AND CHECK FOR LEAKS AND BLEED AIR FROM COOLANT SYSTEM. CHECK OK. SALES TAX		

Total \$6,994.30

Payments/Credits

Balance Due

Invoice

Date

Invoice #

2/2/2022

PAID
02/10/2022

ME9558

P.O. No.

Terms

Description

Quantity

Rate

Amount

Airtank Clamp K2410576

Exhaust Clamp

Flex Pipe

5 pipe

elbow rubber

406 Clamps

4X6 Air Box

#10 Hose Clamp

Antifreeze

Shop Supplies

Labor

State Sales Tax

4

2

4

2

8

2

52

Total

\$40,775.92

18% interest will be applied if bill is past

Invoice

Date	Invoice #
3/16/2022	

Unit Information
#10 2015 KW T680 VIN# 1XKYD49X9FJ424296 MILES: 851351 HRS: 19213 ISX 15 79799979

ME9558

Rep	Terms	Service Date	P.O. Number	Contact Info.
GLW	Due on Receipt	3/16/2022		
Quantity	Item Code	Description	Price Each	Amount
1	NUT 1/4".	343804 GRADE 8		
4	WASHER 1/4".	373904 GRADE 8		
3	BOLT 1/4 X 1.	380408 GRADE 8		
1	SM 330-3024	HUB CAP GASKET		
1	CHEVRON 75...	CHEV SYN GL 75W90 XDM, PT		
3	85405	1/4-20 FLANGE INSERT		
15	GY 5526-075 IN.	3/4" BLUE SILICONE HEATER HOSE, IN		
1	26480	1 1/2 TUBE-3/8 HOLE CLAMP		
0.25	DIELECTRIC G...	80728 DIELECTRIC GREASE		
0.25	BATT CLEANER	7012 BATTERY TERMINAL CLEANER		
3	5" STAINLESS ...	X007785 STAINLESS LAP JOINT CLAMP		
1.1	5" STAINLESS ...	5" STAINLESS FLEXPipe, FT 16-500S TX 8888		
1	FUL 4305294	SHIFT TOWER GASKET		
1	MA 6306.	PILOT BEARING 306SZZNTN		
2	464808	#8 METRIC LOCK NUT		
4	WASHER 5/16".	373905 GRADE 8		
4	502612	#12 HD SIL HOSE CLAMP		
11	EXT LIFE 50/50	EXT LIFE RED ANTIFREEZE XLC 50/50		
11	USED ANTIFR...	DEIONIZED WATER, GAL		
1	17609	ANTIFREEZE DISPOSAL		
5	CLEANER.	2" STEEL BRUSH STEM CFX-3		
		CLEANER		

Total

Payments/Credits

Balance Due

Flywheel Housing

Invoice

Date	Invoice #
3/16/2022	

Unit Information
#10 2015 KW T680
VIN# 1XKYD49X9FJ424296
MILES: 851351 HRS: 19213
ISX 15 79799979

ME9558

Rep	Terms	Service Date	P.O. Number	Contact Info.
GLW	Due on Receipt	3/16/2022		
Quantity	Item Code	Description	Price Each	Amount
12	CHEV 15-40 SDE	CHEVRON DELO 400 SDE 15-40 CK-4, GAL		
1	P550949	OIL FILTER SUPERSEDE FROM P559000		
		PERFORM FULL SERVICE - CHANGE OIL AND		
		OIL FILTER. CHANGE FUEL FILTERS. CHECK AIR		
	TRACTOR	FILTERS. RAISE FRONT END, CK PARTS AND		
		GREASE TRUCK, CK ALL FLUIDS, BELTS,		
		COOLANT PROTECTION AND HOSES. LIGHTS,		
		BRAKE ADJUSTMENT AND AIR PRESSURE IN		
		TIRES.		
1	DBF6776	BLUE SPIN-ON SECONDARY FUEL FILTER		
1	P550851	FF5825-NN		
0.75	WO55	FUEL WATER SEPARATOR FILTER (FS19765)		
1	CHEV TUBE G...	WINDSHIELD WASHER FLUID, GAL		
1		CHEVRON ULTRA DUTY 14OZ TUBE GREASE GR		
1	P640110	EP2		
1	PARTS	PACCAR CAB AIR FILTER (4479) (X1987001)		
1	3678756	ETP-F37-1018 CABIN AIR FILTER		
1	4026684	SEAL O-RING		
1	4965569	ISX OIL PAN GASKET		
1	4393176	KIT SEAL REAR CRANKSHAFT		
1	PARTS	FLYWHEEL HOUSING GASKET		
		3103584 FLYWHEEL HOUSING		
	FREIGHT	FREIGHT		
1	PARTS	RESURFACE FLYWHEEL		
1	PARTS	1/4 X 1 DECK SCREW		

Total

Payments/Credits

Balance Due

Invoice

Date	Invoice #
4/22/2022	

Unit Information
#10 2015 KW T680 VIN# 1XKYD49X9FJ424296 MILES: 862704 HRS: 19549 ISX 15 79799979

ME 9558

Rep	Terms	Service Date	P.O. Number	Contact Info.
GLW	Due on Receipt	4/22/2022		
Quantity	Item Code	Description	Price Each	Amount
		RADIATOR, INSTALL NEW RADIATOR. RECONNECT ALL COOLANT HOSES. REINSTALL AIR TO AIR, COOLANT RESERVOIR, WASHER RESERVOIR, A/C CONDENSER AND AIR TO AIR PIPES. FILL WITH COOLANT REMOVED. REMOVE DRIVER SIDE STEPS. REATTACH BATTERY COVER WITH BOLT AND LOCK NUT. REINSTALL STEPS. RUN AND CHECK FOR AIR LEAKS, FOUND ONE FITTING WITH AUDIBLE LEAK ON TOP OF AIR TANK AND ONE FITTING WITH AUDIBLE AIR LEAK ON BOTTOM TANK. REMOVE AIR FITTINGS AND INSTALL NEW FITTINGS. AIR UNIT UP AT END OF THE DAY, NEXT MORNING STILL HAD 90PSI. START AND RUN, CHECK FLUID ON MONDAY MORNING, FULL. TOP OFF DRIVERS COOLANT JUG. SALES TAX		

Total \$1,601.87

Payments/Credits

Balance Due

New Radiator

Invoice

Date	Invoice #
4/22/2022	

Unit Information
#10 2015 KW T680 VIN# 1XKYD49X9FJ424296 MILES: 862704 HRS: 19549 ISX 15 79799979

ME 9658

Rep	Terms	Service Date	P.O. Number	Contact Info.
GLW	Due on Receipt	4/22/2022		
Quantity	Item Code	Description	Price Each	Amount
1	PARTS	25708 RADIATOR		
8	10322	3/8 X 1 1/4 FENDER WASHER		
1	LOCK NUT 1/4	344804 GRADE 8		
1	10325	1/4 X 1 1/4 FENDER WASHER		
1	WASHER 1/4"	373904 GRADE 8		
1	BOLT 1/4 X 3/4	580406 GRADE 8		
1	1469X8X8	1/2 - 1/2 MALE ELBOW		
1	1469X10	5/8 - 1/2 MALE ELBOW BRASS		
1	NC92810	12-10 FAST HEAT SHRINK 8-10 RING NARROW		
1	444804	8X1/2 SCREW		
9	7" CABLE TIE	6"-8" CABLE TIE 26680 26681		
1	EXT LIFE 50/50	EXT LIFE ANTIFREEZE XLC 50/50 DEIONIZED WATER, GAL; FILL JUG		
	SR	RADIATOR PREVIOUSLY DIAGNOSED LEAKING. REMOVE AIR TO AIR PIPING ON BOTH SIDES. REMOVE HOLD DOWNS FOR A/C CONDENSER. MOVE AIR CONDENSER OUT OF WAY ABOVE ENGINE. REMOVE AIR TO AIR AND WINDSHIELD WASHER RESERVOIR. DRAIN COOLANT. REMOVE COOLANT RESERVOIR. REMOVE ALL RADIATOR HOSES. REMOVE RADIATOR. REMOVE OLD RADIATOR FROM FRAMING. REMOVE GROUND WIRE FROM OLD RADIATOR. INSTALL GROUND WIRE ONTO NEW RADIATOR. INSTALL FRAME ONTO NEW		

Total

Payments/Credits

Balance Due

#10 2015 KW T680
VIN# 1XKYD49X9FJ424296
[REDACTED]
MILES: 851351 HRS: 19213
ISX 15 79799979

Total
Payments/Credits
Balance Due

Invoice

Engine Overhaul

Date

Invoice #

2/2/2022

PAID
02/10/2022

15 KW

VIN: 424296

ME9558

P.O. No.

Terms

Description

Quantity

Rate

Amount

#10 Miles 837475 Vin424296

Over Hall Kit

Cyl Head

head bolt

head bolts

20 th shims

Cut Counter Bores

Oil Pump

oil pump bolts

Inj

dampner

Front main seal

Fuel Screws

Adapter Gasket

Front Housing Gasket

gasket

acc seal roap

Turbo Cummins T6 Big

Manifold

cummins cam

Frost Plug 555-044

Water Plugs

Air Horn 3682674

clamp

water plate

Fuel Filter PF7755

Oil

276203 RSR Bearing

Bearing 27103127

Exh kit

Intake Plate

Cummins Diagnostic

muffler

Total

Invoice

Date	Invoice #
3/16/2022	

Unit Information

10 2015 KW T680
/IN# 1XKYD49X9FJ424296

MILES: 851351 HRS: 19213
SX 15 79799979

ME 9558

Rep	Terms	Service Date	P.O. Number	Contact Info.
	Due on Receipt	3/16/2022		
Quantity	Item Code	Description	Price Each	Amount
		TORQUE. WIRE HOLDER ON FRONT DRIVER SIDE CORNER BROKEN, INSTALL NEW CABLE CLAMP TO HOLD WIRE UP. REINSTALL TRANS AND CLUTCH AT WAS TAKEN OUT - LOOKED NEW. REATTACH ALL AIR AND ELECTRICAL LINES. HOSE FROM TRANS OIL COOLER TO BACK OF BLOCK RIPPED. INSTALL NEW HOSE AND CLAMPS FOR BOTH HOSES ONTO TRANS OIL COOLER. REINSTALL SHIFT TOWER WITH NEW GASKET. REATTACH AIRLINES. REINSTALL DRIVE SHAFTS AND GREASE. REINSTALL EXHAUST WITH NEW FLEX PIPE AND SEAL CLAMPS. CHECK TRANS FLUID, CK OK. REMOVE DRIVER SIDE STEP, FOUND COVER FOR BATTERIES IN STEP HAS ONE STUD BROKEN OFF AND MISSING 2 PRESS ON CLIPS. INSTALL NEW CLIPS. DRILL HOLE FOR BROKEN STUD AND ATTACH WITH SCREW. BATTERY CABLES CORRODED. CLEAN ALL BATTERY CABLES AND TERMINALS. RECONNECT CABLES AND COVER WITH DIELECTRIC GREASE. REINSTALL DRIVER SIDE STEPS. REMOVE PICKUP TUBE. REINSTALL TUBE WITH NEW O-RING. TORQUE BOLTS. DEFROST TO FLOOR NOT SWITCHING SOMETIMES AND ACTS		
			Total	
			Payments/Credits	
			Balance Due	