

WE THANK YOU FOR YOUR BUSINESS!
HOURS OF OPERATION: MON. - FRI. 5 A.M. - 11:30 P.M.

2/24/2023 8:27 AM

page 1

Invoice #

Day Phone
Eve Phone
Fax Number

-fold here -

Vehicle : 2016 Peterbilt 579 12.9 L 787 CID L6 Paccar MX Diesel
VIN : 1XPBDP9X1GD368176
Created : 7/6/2021 3:58:39 PM
Complete : 8/24/2021 3:17:44 PM
Invoiced : 8/24/2021 3:17:44 PM
Contact : KALEP (618-334-3996)
Srv Writer : 38

Color : Orange
Odometer In : 475157
Odometer Out : 475157

Labor/Notes

Code/Tech*	Reference	Description	Price
	DOT/INS	DOT/FHWA INSPECTION	
	LABOR	INSTALL TWO HYDRALIC SYSTEM	
		DRAIN TRANS FLUID TO INSTALL PTO REFILL CHECK FOR KICKING IN OK, INSTALLED HYDRALIC PUMP AND MAKE HOLDING BRACKET, RAN AIR LINE TO PTO, MAKE BRACKETS FOR HYDRALIC TANK TO SIT UP HIGHER, RAN LINES FROM TANK TO TO PUMP, PUMP TO TRAILER FITTING RETURN LINE HOOK TO TRAILER KICK IN WORKS BUT SHUT DOWN TRAILER HAS BAD LEAKS	
	LABOR	CHECK ENGINE MISS & EXHAUST LEAK	
		*ENGINE LIGHTS ON CHECK FOR CODES HAS CODES FOR # 6 INJECTOR, DID INJECTOR CUT OUT TEST #1 AND #6 WEAK PULLED VALVE COVER FOUND #1 VALVES LOOSE AND #6 VALVES TIGHT RAN OVER HEAD BUT BACK TOGETHER RAN TRUCK MISS IS GONE BUT STILL HAS A TICKING NOISE CHECK INTO FURTHER FOUND HIGH PRESSURE PUMP BAD NEEDS REPLACE	
	ENV	ENVIRONMENTAL	
	LABOR	R&R HP RAIL FUEL PUMPS & SUPPLY LINES	
		REPLACE BOTH RAIL PUMP ASSEMBLES AND FUEL LINE ASSEMBLY MISS IS GONE BUT HAD A TICKING NOISE NEEDS FURTHER DIAG	
	LABOR	CHECK INTO TICKING NOISE	
		CHECK INTO TICKING NOISE SOUND LIKE UNDER VALVE COVER STILL REPULLED VALVE COVER SOUND COMING FROM # 6 ROCKER PULLED OFF DIDNT SEE ANYTHING PULLED ANOTHER ONE OFF STILL DIDNT NOTHING RELOOK AT #6 VALVE AND FOUND ONE VALVE HIGHER THEN THE OTHER POSSIBLE VALVE SEAT COMING APART NEEDS HEAD PULLED	
	LABOR	R&R STEER SPRING PINS, BUSHINGS & HANGERS - REAR	
	ALN	3 AXLE ALN	
		*THIS COVERS THE FIRST 2.5 HOURS. ADDITIONAL TIME WILL BE CHARGED OUT. ANY PARTS NEEDED TO CORRECT ALIGNMENT WILL BE CHARGED OUT.	
	LABOR	REPLACE STEER TIRES - KEEP OLD ONES	
	LABOR	ADD OIL TO STEER HUBS	

WE THANK YOU FOR YOUR BUSINESS!
HOURS OF OPERATION: MON.- FRI. 5 A.M. - 11:30 P.M.

2/24/2023 8:27 AM

page 2

Invoice #102397

Vehicle : 2016 Peterbilt 579 12.9 L 787 CID L6 Paccar MX Diesel

Labor/Notes (continued)

Code/Tech*	Reference	Description
	LABOR	R&R CYLINDER HEAD

REMOVED HEAD CLEAN BLOCK CHECK COUNTER BORE WITH IN SPECS FOUND EXHAUST MANIFOLD BAD NEEDS
REPLACED ADVISED OK TO CHANGE, SENT HEAD OFF TO BE CHECK CAN'T BE REPAIR NEEDS NEW HEAD OK TO
CHANGE INSTALL PARTS BACK ON HEAD AND INSTALL HEAD ONTO BLOCK TORQUE DOWN FINISH INSTALLING
REMAINDER PARTS RUN OVERHEAD STARTED TRUCK NO NOISE.REPLACE OIL AND FILTER TOOK ON TEST DRIVE RUNS
GOOD.RECHECK FOR LEAKS OK

Parts

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
1	KELLER	DOTFORM	DOT STICKER W/FORM	New		
1	-	TG8SU680A1KX	MUNCIE PTO	New		
1	-	PL119C2BPBB	MUNCIE PUMP	New		
1	-	P050U2AAGXY	HYDRALIC OIL TANK	New		
1	-	PB10	BRACKET KIT	New		
40	-	NRG10346AW-55	NRG ISO A1W46 HYD. OIL	New		
1	-	1868X4	1/4" X 1/8" MPT Q/D FITTING	New		
1	-	1869X4S	FITTING,1/4TUBEX1/8MPT 90° QUICK CONN. SWIVEL	New		
3	-	451030	1/4" PLASTIC AIR LINE	New		
1	-	451060	HEAVY DUTY POGO STICK (METAL)	New		
1	-	032888406919	1" BLACK IRON COUPLING	New		
1	-	032888406902	3/4" BLACK IRON COUPLING	New		
1	GH	G251051212	HYD HOSE FITTING	New		
2	GH	G251001616	HYD HOSE FITTING	New		
1	GH	G251051616	HYD. HOSE FITTING	New		
16	-	70395	1" HYDRAULIC HOSE	New		
1	-	G251001612	HYD. HOSE FITTING	New		
1	-	XMVBVF125	1-1/4" BALL VALVE	New		
1	-	XMVBVF100	1" BALL VALVE	New		
2	-	YDXSTC15	1-1/4" PLATED KING NIPPLE	New		
10	-	WBIH036320BK-100	1 1/4 SUCTION HOSE	New		
2	-	KBC320	1-1/4" X CL BLACK PIPE NIPPLE	New		
2	-	YDXTBC188	T-BOLT CLAMP	New		
1	-	KBA320	1 1/4 STREET ELBOW 90 DEGREE	New		
1	-	KBA12016	1-1/4" x 1" HEX BUSHING	New		
1	-	KBA12412	1-1/2" x 3/4" HEX BUSHING	New		
1	-	KBA12420	1-1/2" x 1-1/4" HEX BUSHING	New		
1	-	XH8-62	EXTERNAL H COUPLER	New		
1	-	XH8-63	INTERNAL H COUPLER	New		
2	-	2102391PEX	RAIL PUMP ASSY. (FUEL PUMP)	Rebuilt		

CORE ITEM

WE THANK YOU FOR YOUR BUSINESS!
HOURS OF OPERATION: MON - FRI, 5 A.M. - 11:30 P.M.

2/24/2023 8:27 AM

page 3

Invoice #102397

Vehicle : 2016 Peterbilt 579 12.9 L 787 CID L6 Paccar MX Diesel

Parts (continued)

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
2	-	1930520PE	FUEL SUPPLY LINE ASSY.	New		
2	-	2104017PE	CLIP	New		
1	-	8397965	Q.D. O-RING STYLE FITTING	New		
6	-	2018671PE	O-RING	New		
4	-	1313122PE	FLANGE BOLT	New		
1	-	1857669PE	O-RING KIT	New		
0	-	B65-6008	THREADED SPRING PIN	New		
0	-	B13-1000	SPRING PIN BUSHING	New		
0	-	B11-1034-5	SPRING HANGER ASSY.	New		
0	-	B20-1007	SPRING SHACKLE	New		
4	-	327-544	SPRING PIN (AFTERMARKET)	New		
2	-	TB-77	BUSHING (AFTERMARKET)	New		
2	-	M1820	SPRING HANGER (AFTERMARKET)	New		
4	-	330-102	SPRING SHACKLE (AFTERMARKET)	New		
1	-	TWE52003	WHEEL 1" X 1" 80 GRIT FLAP	New		
2	-	TIRE	295/75R22.5 YOKAHOMA RY617			
1	-	2190203PEX	CYLINDER HEAD	Rebuilt		
1	-	2140884PE	HEAD GASKET SET	New		
26	-	1822166PE	HEAD BOLT	New		
7	-	1822941PE	HEAD BOLT	New		
1	-	2180879PE	THERMOSTAT	New		
1	-	2124041PE	THERMOSTAT	New		
2	-	1661278PE	O-RING	New		
1	-	2121080PE	EXHAUST MANIFOLD KIT	New		
			THE MANIFOLD BOLTS SHOULD COME IN THIS KIT			
18	-	2135209PE	BOLT	New		
			MAY OR MAY NOT BE IN MANIFOLD KIT			
0	-	1865847PE	INJECTOR O-RING	New		
0	-	1638270PE	INJECTOR O-RING	New		
0	-	2127551PE	INJECTOR O-RING	New		
6	-	1313120PE	INJECTOR HOLD DOWN BOLT	New		
1	-	2106210PE	TURBO MOUNT GASKET	New		
1	-	1893478PE	INTAKE MANIFOLD TEMP SENSOR	New		
2	-	TWE51530	2" SANDING DISK (FINE GRIT BLUE)	New		
1	-	TC2417	BRAKE CLEANER 14OZ	New		
4	-	RAA62032	CLAMP, 1-9/16 X 2-1/2 HOSE	New		
10	-	REDCOOL	RED ELC COOLANT	New		

WE THANK YOU FOR YOUR BUSINESS!
HOURS OF OPERATION: MON - FRI. 5 A.M. - 11:30 P.M.

2/24/2023 8:27 AM

page 4

Invoice #102397

Vehicle : 2016 Peterbilt 579 12.9 L 787 CID L6 Paccar MX Diesel

Parts (continued)

Qty	Code/Tech*	Reference	Description	Condition	Unit Price	Price
4	-	N000000001069	SEALING WASHER	New		
2	-	1863266PE	AIR HORN COUPLER	New		
2	-	2035973PE	GASKET	New		
2	-	N000000001068	SEALING RING	New		
4	-	1961490PE	ORING 12	New		
2	-	1858035PE	RING SEAL	New		
2	-	1982776PE	ORING 22X	New		
2	-	1960576PE	O-RING	New		
2	-	1977943PE	ORING 9.78	New		
2	-	0331328PE	COPPER SEAL	New		
1	-	1958374PE	VALVE COVER BOLT	New		
1	-	1923003PE	GASKET	New		
1	-	D42-1003	GASKET	New		
6	-	UCTT120R0K2	15 1/4" CABLE TIE	New		
1	GR	7370	OIL FILTER	New		
6	-	UCTT120R0K2	15 1/4" CABLE TIE	New		
1	-	3220X8X6	BRASS BUSHING 1/2" X 3/8"	New		
1	-	WH1880X8X8	1/2" Q.D. x 1/2" MPT FITTING 45 DEG.	New		
2	-	1862X8	UNION, 3/8X3/8 PUSH TO CONNECT	New		
1	-	451047	12.5" HOSE SPRING	New		
2	-	451031	3/8" PLASTIC AIR LINE	New		
10	-	001001000651-030	ROTELLA T 15W40 OIL	New		

Sublet/Misc.

Qty	Code/Tech*	Reference	Description	Unit Price	Price
0	-	CORE	Core Charge		
1	-	FREIGHT	FREIGHT		
0	-	CORE	Core Charge		

Labor

Parts

Sublet/Misc.

shop supplies

Charges

Sales Tax

Total Due \$27,803.45

Invoice#:		Technician:		Date:	01/13/22	Completed:	01/13/22
Company:				2016	Peterbilt		
Name:				Odometer:	486174	License:	
Address:				VIN:	368176		
Phone:				Tag#:			
				PO#:			

Hrs.	Labor Description	Total
1.00	Rerate engine and repair aftertreatment	

Wheel nuts must be retorqued after 100 miles.
30 Day Warranty on Labor. Parts Subject to OEM approval on Warranty.
All Custom or Converted Engines have NO Warranty.
Customer is required to arrange pickup of any major components that will not have a possible core within two weeks, examples being Engine or Transmission after two weeks the parts will be considered trash and disposed of.

Parts Total:

Labor Total:

Special Repairs Total:

Sub-Total:

Tax1:

Supply Charges:

Shipping:

Sub Total:	4,500.00	Discount:	
CC Fee:	0.00	Total:	4,500.00
		Paid:	4,500.00
On Acct:	0.00	Balance:	0.00

Authorized by Signature:

Accounts not paid within 30 days of the date of the invoice are subject to a 5% monthly finance charge. All accounts paid by credit card will incur a 3% processing fee.