

Repair Order Invoice

Page 1/2

Invoice Date	Invoice #	A/C	Customer PO	Payment Term	Customer Tax #
--------------	-----------	-----	-------------	--------------	----------------

Repair Oct 13, 2023

Unit 1083	VIN 1XP4D49X4FD290532	License	Last Cert.()
Peterbilt, 587, orange, high roof sleeper			
Make PETERBILT	Model 587 CONVENTIONAL	Year 2015	Engine

Activity Description	Part Number	Part Description	Quantity	Charge	Total
----------------------	-------------	------------------	----------	--------	-------

1. PM INS: Repair, Inspect, or Brief Assessment

DIAG.COMP	DIAGNOSTIC COMPUTER HOOK UP
E41401	14 Ga. Primary Wire, Black
E41405	14 Ga. Primary Wire, Yellow
E41403	14 Ga. Primary Wire, Blue
E41406	14 Ga. Primary Wire, Green
E22710	12-10 GA. NON INSULATED BUTT CONNECTOR
E22410	16-14 GA. NON INSULATED BUTT CONNECTOR
E52001	1/4" CLEAR PREMIUM SHRINK TUBE ES-1
G2NY043	7/16-14 NYLOCK NUT
6.5-70-18X	U JOINT STRAP KIT
P557004	FUEL FILTER K37-1004
FUL4305452	Gasket Housing Shift Tower XY
DPF 58031	DPF aftermarket filter 5295604
2880215CUM	GASKET-AMF DEVICE
21-CMS6337	DOC gasket

Activity Sub-Total: 8,279.09

Authorized

Repair Order Invoice

Page 1 / 1

Invoice Date	Invoice	A/C	Customer PO	Payment Term	Customer Tax #
Oct 24, 2019					

Repair Oct 21, 2019

Unit 1083	VIN 1XP4D49X4FD290532	License	Last Cert. ()
Peterbilt, 587, orange, high roof sleeper			
Make PETERBILT	Model 587 CONVENTIONAL	Year 2015	Engine
ODOMETER 451681 MI			

Activity Description	Part Number	Part Description	Quantity	Charge	Total
1. Sublet Repair, Pleasant Hill area					
10-21-19 MHC Kenworth, Des Moines, IA					
Replace clutch and related repairs.					
Check					
SUBLET T_NM		SUBLET REPAIR T_NM **20**			

Technician _____ Authorized _____

Invoice Total: \$ 8,019.77

Signature: _____