

Repair Order Invoice

Page 1 / 2

Invoice Date	Invoice #	A/C	Customer/PO	Payment Term	Customer Tax #
Dec 12, 2023	1W1028618	ICS		NET30	

Repair Nov 18, 2023

Unit 1088	VIN 1XP4D49X9GD351682	License	Last Cert.()
Peterbilt, 587, mocha, high roof sleeper			
Make PETERBILT	Model 587 CONVENTIONAL	Year 2016	Engine

Activity Description	Part Number	Part Description	Quantity	Charge	Total
----------------------	-------------	------------------	----------	--------	-------

1. PM INS: Repair, Inspect, or Brief Assessment

*disassemble clean , reseal and reassemble and reseal front gear case, bell housing, replace front and rear main seals.
sent out DPF for cleaning Replace oil pan gasket*

G8NY050	1/2-13 GR 8 NYLOCK NUT
N14B	14" CABLE TIE 50 LB
N14A	1/4" CABLE TIE 120 LB
DPF WATER CLEANING	water cleaning
213000KIT	CUMMINS PACCAR MX13 DPF DOC GASKET CLAMP KIT
4965569CUM	Kit, Seal, Rear Main
4965688	Gasket, Engine Misc (Cummins ISX)
4026684CUM	Gasket Oil Pan
3685173CUM	SEAL, OIL
3687007CUM	Seal, Rectangular Strip
5414049CUM	Gasket, Fuel Pump
4393089CUM	GASKET-GEAR HOUSING
3685556CUM	GASKET ADAPTER
5658175	Gasket, Gear Housing
4299124CUM	SEAL-O RING
4299125CUM	SEAL-REAR O RING
5719778	Gasket, Camshaft Cover
5440813CUM	Gasket, Acc Drive Support

Authorized

Repair Order Invoice

Page 2/2

Invoice Date	Invoice #	A/C	Customer PO	Payment Term	Customer Tax #
Dec 12, 2023					

Invoice Total: \$ 11,714.29

Signature: _____