

SC00510622-001 Replace - Joystick - Left

PARKING BRAKE WILL NOT DISENGAGE. ACTIVE CODE FOR LEFT JOYSTICK POSITION. LEFT JOYSTICK SHORTED. CHECKED FLUIDS, STARTED MACHINE AND VERIFIED THE COMPLAINT. HAD ACTIVE CODE. HOOKED UP TO ET AND FOUND ACTIVE CODE FOR THE LEFT JOYSTICK POSITION SENSOR. FOLLOWED TROUBLESHOOTING STEPS FOR THE CODE AND REPLACED. FOUND THE LEFT JOYSTICK TO BE BAD. REPLACED THE LEFT JOYSTICK BY REMOVING THE PANEL AROUND IT AND SWAPPING OVER THE JOYSTICK HANDLE. AFTER REPLACING IT, HOOKED UP TO ET AND CALIBRATED THE JOYSTICK. UPDATED THE MACHINE SOFTWARE FILE. CHECKED OPERATION.

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
176212	S10871	262C	MST05045	S10871	9,010
Quantity	Type	Part Number	Description		
1.00	Parts	4560169	Base As		
	Labor		Labor		

SC00510622-001 Replace - Joystick - Left

Parts	
Labor	
Misc	
Segment Subtotal:	1,292.64

Service Invoice

Invoice
Date
Call Number
Location
Page

Invoice Account
C010801

Payment
Cash On Delivery

Due Date
11/14/2023

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
176212	S10871	262C	MST05045	S10871	9,010.00

Summary

Parts 572.64

Sales Tax Summary

Misc 0.00

Parts, Labor and Misc

Flat Rate Total

Subtotal

Shop Supplies and
Environmental Fees

Subtotal 1,326.84

Total \$ 1,419.72

Invoice
Date
Account

SI000413338
11/14/2023
C010801

Amount Due:

\$1,419.72

Amount Enclosed: