

Vehicle Repair Log

Last modified: June 9, 2022

Year	2010
Make	Vermeer
Model	RTX750
Serial No.	1VR9060PXA1000140
License No.	

RTX750

Hours of use
 * 17 Hours in 2022 *
 * 1 Hour in 2023 *

Date	Description of Work
7/1/2010	Aluminum ramps
9/28/2010	replace ground drive creep & attachment controllers
10/7/2010	new actuator/idle up-down
11/17/2010	Remove bracket/lock down lever for backhoe attachment
11/18/2010	New 1" blade
1/6/2011	Repl Hydraulic hose to backhoe & repair backhoe locking lever & 7/8" Shackle
5/18/2011	Replace cracked hood
7/19/2011	100 hour check-up
10/3/2011	Replace cracked hood
4/23/2012	Replace hood with new re-design
11-16/20/12	Repair broken & missing bolts-hydro leak at backfill blade cylinder
4/11/2013	Backhoe Creep Control Switch-Chg oil-air & fuel filter-greased
9/25/2013	2 position switch
10/14/2014	Chg hydro-fuel-oil-air filter

11/20/2014	repair broken wire on throttle actuator-replace air minder & bolt through plow lift lock-tighten fitting on shaker box & ck o-ring
12/4/2015	misfire - remove trash in fuel filter-tighten bolts on lower pin for back hoe pivot-hood frame platform-place missing bolt in shield on shaker & tighten hose on shaker motor
1/27/2016	repl hydraulic boom cylinder hose & repl bushings in blade mount
3/24-31 & 4/1	chg oil & filters-installed new bolts & grease zerks-adjusted tracks
7/16/2016	welded/repair buckets for radiator overflow reservoir & fuel pump shutoff & turbo shield
9/16/2016	replaced hydraulic hose
10/16/2016	replace seat
10/24/2016	repl hydro hose for front push blade
12/22/2016	lock
6/17/2017	Chg oil/filter&greased - replace hydraulic hose for front push blade again
7/19/2017	repace battery
5/23/2018	pin
7/30/2018	new cable chute (shoe)#13880
10/31/2018	new cable chute (shoe)#296529816
11/30/2018	Chg oil/filter & greased-chg air & fuel filter-repair spool valve by seat
8/16/2019	rebuilt cyclinder on frt backhoe
10/12/2019	repair blade pivot (bushinas/bolts) arease zerks

11/15/2019	lost pin in rear swing cylinder - replaced		
11/19/2019	seal kit installed not shown on previous invoice		
12/13/2019	replace blown hyd hose onback of shacker		
10/22/2020	refasten air filter sensor		
0/21-26-30/202	repl PPU / retap mounting bolts & bracket for overflow jug		
3/29/2021	repair hydraulic leaks / replace oil/fuel/air/hydraulic filters		
3/18/2022	retighten hydraulic filter/replace seal for pump & transmission		
4/29/2022	hyd. Leak when using the plow steer / replace hose for blade pivot		
Total repair expenses:			\$28,633.08