

Invoice

Date 1/26/2024

Invoice # 1687

Bill To

P.O. No.

Terms

JD 6400

Due on receipt

Item	Qty	Description	Unit Price	Amount
Labor	8.5	1/16/2024-1/26/2024. John Deere 6400 Tractor PIN L06400P102267 with 4235 hours. *** The 540 PTO speed slips because of a broken spring pin in the shift collar for the 540 / 1000 PTO. * Drained the hydraulic oil and removed the rear PTO housing. Confirmed the PTO clutch was ok. * Replaced the PTO shift collar roll pin and reassembled the PTO. * Replaced the transmission and hydraulic oil filters.		
Parts	1	R129680 PTO Stub Shaft Snap Ring		
Parts	1	P47889 O-Ring		
Parts	1	I76193 Retaining Washer		
Parts	1	34M7074 Spring Pin		
Parts	1	L34383 Rubber Washer		
Parts	1	AL221066 Transmission Oil Filter		
Parts	1	AL233526 Hydraulic Oil Filter		
Parts	2	L62369 Shoulder Nut		
Parts	2	24M7113 Washer		
THF	3	Trans-Hydraulic Fluid, Gallon		
Shop Supplies		L76669 Gasket		

Thank you for your business.

Total

\$880.07