

Item	Description	Quantity	Rate	Amount
------	-------------	----------	------	--------

**Complaint:** PIECE OF 5TH WHEEL PLATE HANGING DOWN. FUEL LINES FROM TANK TO REEFER NEED REPLACED. PASSENGER REAR OUTSIDE TIRE IS FLAT. LATCH ON OVERHEAD DOOR IS LOOSE.

**Cause:** WEAR AND TEAR.

Labor

**Correction:**

Chassis / Chassis / DROPPED 5TH WHEEL PLATE FROM TRAILER TO CUT ADDED STRUCTURAL SUPPORT (1/4" FLAT METAL AND 1/4" ANGLE IRON). RE-INSTALLED 5TH WHEEL PLATE. REPLACED FUEL LINES FOR FUEL TANK TO REFER. REPAIRED PASSENGER REAR OUTSIDE TIRE (BEAD LEAKING. WIRE WHEELED BOTH BEADS). REPAIRED LATCH ON OVERHEAD DOOR (REPLACED HARDWARE AND ADDED BACKING PLATE TO SECURE LATCH). ONE BOTTLE OF BRAKE ANTIFREEZE. CHECKED ALL LIGHTS AFTER HOOKING EVERYTHING BACK UP (TOP FRONT MARKERS NOT WORKING. DRIVER STATED THAT THEY NEVER WORKED. AND WASN'T WORRIED ABOUT HAVING THEM REPAIRED. GREASED TRAILER. - Completed: 3/23/2023

Parts

1/4 x 4" FLAT

Parts

2X2X1/4 ANGLE IRON

Parts

3/8"-16X2.5" GRADE 8 BOLT

Parts

3/8"-16 NUT

Parts

CROSS MEMBER BOLT KIT

Parts

BULBEX LARGE FLANGE BLIND RIVET

Parts

1/2X3/8 45 DEGREE MALE ELBOW

Parts

1/4"-20x3.5" GRADE 8 BOLT

Parts

1/4" WASHER

Parts

1/4"-20 LOCK NUT

Parts

16-14 GAUGE BUTT CONNECTOR

ENVIRONMENTAL

Unit: 136 VIN: 1UYVS25374U135524  
2004 Utility Trailer Manufacturer Utility Trailer Manufacturer  
Chassis: 1 Miles

Total \$3,252.65