Invoice

Invoice No	88231
Invoice Date	7/29/23
Work Order No	38461
Date In	7/21/23

LE9010

Unit Information:

Make: G3 Miles/Hours: 21.5 Serial No: GEN90690B111

Motor1:

Make: YAMAHA Model: 90HP Serial No: 61PL1046740

Job No

Job Description

TOOK BOAT OUT WHEN FIRST GOT, RAN GOOD FOR FIRST 2 HOURS AND THEN THEN STARTED RUNNING ROUGH. AT FULL THROTTLE WOULD ONLY GO ABOUT 1/2 POWER. NOT SURE OF RPMS. CHANGED THE FUEL FILTER AND STILL HAS PROBLEMS. GOT BACK TO THE DOCK, MESSED WITH THE TROLLING MOTOR AND FOUND THAT IT NOT HOOKED UP. HOOKED UP AND NOW IT ALSO WILL BLOW A FUSE FOR THE TAXABLE PROBLEMS. A FUSE FOR THE TILT AND TRIM DURING THE RUNNING ISSUE.

Correction

#3 Injector is bad. Swapped with #2 Cylinder Injector. Needs water Pump serviced. Not pumping water.

Payable By Customer

Part No 67F-44352-00-00 67F-44311-01-00 67F-44322-00-00 688-44315-AC-90-6D8-13761-00-00 688-44324-AC-00 858068Q01	Make YAM YAM YAM YAM YAM YAM MERC	Dept P P P P P	Description IMPELLER HOUSING, WATER PUMP INSERT, CARTRIDGE TASKET WATER PUMP INJECTIOR ASSY GASKET, CARTRIDGE HI-PERF GEAR LUBE
		HERE B	

Descriptio Code R&R IMPELLER MO2810 **IMPELLER** R&R Fuel Inectors MO2810 FUEL INJEC

Job No.

Job Description

AERATOR IS NOT WORKING ON EITHER SIDE PLEASE CHECK

Correction

The wire is shorting under the dash and blowing the fuse. It was rubbing the radio brace. Tech cut and repaired

The livewell pump is bad and the fuse is missing at the fuse box. Need to replace aerator as well as the fuse.

Payable By Customer

Part No	Make	Dept	Description
38502	SOU	P	500 GPH 90 DEGREE

Description Tech Code MO2810 REPLACE AERATOR CARTRID AERATOR WIRING MO2810 REPAIR

Parts Total Invoice Summary Labor Total Shop Supplies Thank You For Your Business! Have a Great Day Sales Tax 1,718.19 Grand Total Amount Due By Customer Paid VISA Balance Due LE9010

Page:

2