

# Case W20C Wheel Loader EK4344

## Engine Overhaul Invoices

# Invoice

Invoice No.	
Customer No.	

To:

Ship To:

SO#		F.O.B		Shipping Terms	Payment Terms	Due Date	Salesperson		
R1319878		SHIPPING POINT		PPD	Credit Card	Mar/20/2023	WEB		
Ship Date		Order Date		Ordered By		PO #		Resale #	
Mar/16/2023		Mar/15/2023		BEN BARNETT					
Order Quantity	Shipped Quantity	Tax	Item Number			Warehouse	Unit Price	Tariff Surchg	Extended Price
			Description						
1.00	1.00		5A23544 Weight 1.20			Springfield			
			Cam Bearing Set						
6.00	6.00		5A43176 Weight 2.34			Springfield			Included in kit
			Rod Bearing-.020						RP925139
1.00	1.00		RP92320 Weight 2.98			Springfield			Included in kit
			Main Bearing Set-.020, less thrust washers						RP925139
1.00	1.00		5A189538 Weight 3.20			Springfield			Included in kit
			Conversion Gasket Set-with crank seals						RP925139
6.00	6.00		5A166134 Weight 99.00			Springfield			Included in kit
			Cylinder Kit						RP925139
1.00	1.00		5A151404 Weight 1.10			Springfield			Included in kit
			Head Gasket Set						RP925139
1.00	1.00		5A62573S Weight 0.36			Springfield			Included in kit
			Thrust Washer Set-.186						RP925139
			Old Item # 5A62573S-B						

Print Date	Mar/16/2023
Print Time	10:34:31 AM
Page #	1 of 2

Continued on next page . . .

# Invoice

Invoice No.	
Customer No.	

To:

Ship To:

SO#		F.O.B		Shipping Terms		Payment Terms		Due Date		Salesperson	
R1319878		SHIPPING POINT		PPD		Credit Card		Mar/20/2023		WEB	
Ship Date		Order Date		Ordered By				PO #		Resale #	
Mar/16/2023		Mar/15/2023		BEN BARNETT							
Order Quantity	Shipped Quantity	Tax	Item Number				Warehouse	Unit Price	Tariff Surchg	Extended Price	
			Description								
1.00	1.00		RP925139 Weight 113.00				Springfield				
			CFG0047915								
			Out-of-Frame Overhaul Kit								
			MainSetSz : KITHM1498S : Select Main Bearing Size								
			MainSetSz : RP92320 : Main Bearing Set-.020, less thrust washers								
			RodBrgSz : KITHR686-6 : Select Rod Bearing Size								
			RodBrgSz : 5A43176 : Rod Bearing-.020								
								</			

Print Date	Mar/16/2023
Print Time	10:34:32 AM
Page #	2 of 2

--	--

Product Subtotal \$	
Total Tariff Surchg \$	
Freight \$	
Sales Tax \$	
Discount Credit \$	
Invoice Total \$	1,499.67

1.5% Interest charged on all accounts not paid by invoice due date

Total Weight 110.18

All amounts in US dollars

# Invoice

Invoice No.	
Customer No.	

To:

Ship To:

SO#	F.O.B		Shipping Terms	Payment Terms	Due Date	Salesperson		
R1320371	SHIPPING POINT		PPD	Credit Card	Mar/26/2023	WEB		
Ship Date		Order Date	Ordered By		PO #		Resale #	
Mar/22/2023		Mar/21/2023	BEN BARNETT					
Order Quantity	Shipped Quantity	Tax	Item Number Description		Warehouse	Unit Price	Tariff Surchg	Extended Price
6.00	6.00		5A61241 Weight 1.50  Piston Pin Bushing		Springfield			
					CARRIER FedEx	SERVICE Ground		

Print Date	Mar/22/2023
Print Time	11:45:59 AM
Page #	1 of 1

--	--

Product Subtotal \$	
Total Tariff Surchg \$	
Freight \$	
Sales Tax \$	
Discount Credit \$	
Invoice Total \$	132.74

1.5% Interest charged on all accounts not paid by invoice due date

Total Weight 1.50

All amounts in US dollars

Repair Order #0004227

Date : 1/11/2023 Page 1 of 1

Orig Est #: Center : 1

Customer  
Address  
City  
Cell  
Work

Vehicle : 20 CASE LOADER W20C  
License : Colr :  
VIN :  
Fleet #:  
Engine : CASE 504BD, 6CYL CUSTM :  
Mileage : Sub :

Parts				Labor			
Quan	Part Number	Description	Price	Op	Tech	Description	Time Charge
9.00	140-7444	GUIDES		AM	0023	RECONDITION 3 HEADS	
12.00	122-1023	STEM SEAL-- O RING		AM	0033	SURFACE 3 HEADS	
				AM	0043	R & R GUIDES 3 INTAKE	
				AM	0053	R & R GUIDES 6 EXHAUST	
				AM	0223	REMOVE STUCK FUEL INJECTOR	

**DISCLAIMER OF WARRANTIES**

The Seller, hereby expressly disclaims all warranties, either express or implied including any implied warranty of merchantability or fitness for a particular purpose and neither assumes nor authorizes any other person to assume for it liability in connection with the sale of said products.

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft or any other cause beyond our control.

A 1.83% charge will be added to the bill if not paid in 30 days.

An express Mechanics Lien is hereby acknowledged on above car or truck to secure the amount of repairs there to.

Labor :  
Parts :  
Sublet :  
Other Fees :  
SHOP SUPPLY  
Subtotal :  
Sales Tax :  
  
Total : \$1,044.72

Signature X \_\_\_\_\_