

DATE 10/01/2020

VIN 275708

MI 475,912

Perform in-frame overhaul on Cummins ISM engine.

Parts for repair: engine overhaul kit, water pump, lower oil pan gasket set.

Parts for repair: Head.

Parts for repair: Oil, coolant, filters, AC line, freon, oaint, thermostat, gasket, seal, grease.

Parts for repair: Injector. (Replaced #1.)

AC machine fee.

Waste oil disposal fee.

Shop supplies.

Truck leaving with EGT fault. This is why truck is not running at optimal performance. Customer is aware of this.

PAYMENT

17,285.85

DATE 10/23/2020

10/23/2020

turbo for ism

BALANCE DUE

\$4,149.42