
Branch: Total Invoice: \$ 1,256.04 \*\*COD\*\*\* Page 1 of 3 IT Completion Date: 8/21/2019 Orig R/O: 0 houseaccount Make/Model: Peterbilt 359 stomer P/O: Model Year: 1979 Meter: 932617 Miles nit Number: 121144 VIN: XXXXXXXXXXXX121144 Department: 03-Service pe: Service DOT INSPECTION 40001 sk: 1 complaint: PERFORM MN DOT INSPECTION Extended orrection: PERFORMED MN DOT INSPECTION. Price Price Quantity U/M Description / Ref Number 1.0 Service Shop Supplies and Technology Part 1.0 Shop Sup1 MN DOT STICKER Parts: Task 1 Subtotals Shop Sup2 Labor Miscellaneous Task 1 Subtotals Department: 03-Service Correction: OPENED THE DASH AND FELT AROUND AND SPRAYED WITH SOAP WATER TO FIND THE LEAK, EVENTUALY FOUND THE PARK BRAKE AIR LEAK Extended VALVE LEAKING. Quantity U/M Description / Ref Number 1.0 Service Shop Supplies and Technology Part upp. Parts Task 2 Subtotals Shop Sup1 Labor Miscellaneous Task 2 Subtotals Department: 03-Service **EXHAUST LEAK** Complaint: DOT REPAIR FOR EXHAUST LEAK AFTER TURBO NEEDS FLEXPIPE Correction: REMOVED AND REPLACE THE FLEX PIPE UNDER THE CAB. Extend Price Quantity U/M Description / Ref Number 2.0 EA CLAMP-EXHAUST Part upp. EC50PLS BA 1.0 LOYALTY CARD: Y1904 YR DISC: 1 EA PIPE-EXHAUST FLEX 5"X24" 304 Service Shop Supplies and Technology EF5024S Parts: BA Task 3 Subtotals Shop Sup1 Labor Miscellaneous: Task 3 Subtotals Department: 03-Service CARRIER BEARING, MIDSHIP BEARING Correction: REMOVED DRIVESHAFT AND YOKE, REMOVED HANGER BEARING AND CLEANED SHAFT, INSTALLED NEW BEARING AND WENT TO INSTALL SHAFT, FOUND THE NEEDLE BEARINGS FELL OUT AND COULDN'T FIND THEM ALL, REMOVED U JOINT TO REPLACE AND FOUND THE YOKE TO BE WORN, PEENED TRANS OUTPUT YOKE AND REPLACED U JOINT, INSTALLED DRIVESHAFT AND GREASE

Invoice: 5103107251 Date / Hour: 8/21/2019 9:06:08PM

Repair Order: 107251 Customer:

Invoice: 5103107251 Date / Hour: 8/21/2019 9:06:08PM Repair Order: 107251 Customer Branch: Total Invoice: \$ 1,256.04 ...COD ... Page 2 of 3 hip To: Completion Date: 8/21/2019 Orig R/O: 0 Customer P/O: houseaccount jjohnson2 Extended Price Quantity U/M Supp. Part Description / Ref Number 1.0 EA HARDENED FLAT WASHER 1/2 SAE 39705 1.0 EA DA 5-280X KIT-U JOI 1.0 EA KIT-STRAP&BOLTS, 1/2 DA 6.5-70-18X 2.0 EA GR.8HXCAPSCREW3/8-24X1-1/2 CSG D39356 1.0 HANGER BEARING / 11506.00 XX HB88510 1.0 Service Shop Supplies and Technology Shop Sup1 Parts: Task 4 Subtotals Labor Miscellaneous Task 4 Subtotals Department: 03-Service DRIVE AXLE SUSPENSION 14004 Task: 5 Complaint: DOT REPAIR FOR SMALL U-BOLTS ON REAR SUSPENSION BEING LOOSE Correction: HEATED UP NUTS AND TIGHTENED UBOLTS Extended Price Price Quantity U/M Description / Ref Number 1.0 Supp. Part Service Shop Supplies and Technology Parts Shop Sup1 Task 5 Subtotals Labor Miscellaneous Task 5 Subtotals Department: 03-Service ADJUST BRAKES 17007 Task: 6 Complaint: DOT REPAIR FOR BRAKES OUT OF ADJUSTMENT Extended Correction: RELEASED BRAKES AND ADJUSTED. Price Quantity U/M Description / Ref Number Service Shop Supplies and Technology Part Supp. Parts: Shop Sup1 Task 6 Subtotals Labor: Miscellaneous: Task 6 Subtotals Department: 03-Service POWER STEERING 30002 Extended Correction: tightend the steer shaft pinch bolt Price Quantity U/M Description / Ref Number Service Shop Supplies and Technology Part Supp. **Parts** Shop Sup1 Task 7 Subtotals Labor Task 7 Subtotals Department: 03-Service **POWER STEERING** 30002 Complaint: DOT REPAIR FOR POWER STEERING LEAKING \*\* See I ast Page for Invoice Total \*



Customer: Branch: Total Invoice: \$ 3,507.44 \*\*\*\*Cash\*\*\* Page 1 of 4 Ship To: Bill T Completion Date: 05/22/2023 Open Date: 05/17/2023 Customer P/O: Salesperson: houseaccount Add User: ljacob Make/Model: Peterbilt 359 Model Year: 1979 Unit Number: 121144 Meter: 121415 Miles VIN: XXXXXXXXXXX121144 Type: Service Department: 03-Service **ENGINE OIL SAMPLE** Task: 1 10019 Extended Price Price Quantity U/M Description / Ref Number Part Supp. 1.0 S0S100 OIL SAMPLE KIT 1.0 Service Shop Supplies Shop Sup1 Parts: Task 1 Subtotals Labor: Task 1 Subtotals Department: 03-Service TRANSFER PUMP 2 Task: 34007 Complaint: replace the fuel transfer pump. Correction: REMOVE FUEL LINES FROM TRANSFER PUMP AND REMOVE TRANSFER PUMP SWAPED FITTINGS FROM OLD PUMP TO REMAN TRANFER PUMP INSTALLED WITH NEW MOUNTING ORING HOOKED UP FUEL LINES PRIMED FUEL SYSTEM, ALSO NOTICED FITTING LOOSE IN FRONT COVER FOR AIR COMPRESSOR OIL SUPPLY HOSE REMOVE FITTING AND CLEANED REINSTALLED WITH THREAD SEALANT HOOKED UP AIR COMPRESSOR OIL FEED LINE. RETURNED OLD TRANSFER PUMP TO PARTS DEPT FOR CORE Extended Price Price Quantity U/M Description / Ref Number Supp. Part EA PUMP G / 17604.00 0R3008 1.0 EA CORE / 17604.00 0R3008-C CT -1.0 EA CORE 0R3008-C CT Original Invoice: 5103119066 2.0 EA SEAL O RI / 17604.00 4J8997 CT NON-CHLORINATED QUICK DRY BRAKE CLEANEA 1.0 ETP-4520 1.0 Service Shop Supplies Shop Sup1 Parts: Task 2 Subtotals Core Chg: Core Ret: Labor: Miscellaneous: Task 2 Subtotals Department: 03-Service REAR AXLE DIFFERENTIAL 13010 Complaint: PERFORMED PLUG SWAP ON THE BOTH REAR ENDS Correction: REPLACED BOTH FRONT AND REAR DIF DRAIN PLUGS FOUND METAL SHAVINGS IN THE FRONT DRIVE DIFF PLUG Extended Price Price Quantity U/M Description / Ref Number 2.0 Supp. Part EA PLUG, MAGNETIC 3/4" PIPE 054254ETN EA 1.0 Waste Disposal (Tax Exempt)

Service Shop Supplies

Enviro EX

Shop Sup1

Invoice: 5103119066 Date / Hour: 5/23/2023 4:11:15PM

1.0

\*\* See Last Page for Invoice Total \*\*

Repair Order: 119066

Invoice: 5103119066 Date / Hour: 5/23/2023 4:11:15PM Repair Order: 119066 Customer: Branch: Total Invoice: \$ 3,507.44 \*\*\*\*Cash\*\*\* Page 2 of 4 p To: Completion Date: 05/22/2023 Open Date: 05/17/2023 ustomer P/O: Salesperson: houseaccount Parts: Add User Task 3 Subtotals Labor: Miscellaneous: Task 3 Subtotals Department: 03-Service SERVICE SPECIAL - OIL, FILTER, FUEL FILTER, GREASE 16002 Task: Complaint: CHECK ALL FLUID LEVELS. CHANGE OIL AND FILTER. CHANGE FUEL FILTER(S). GREASE CHASSIS. CHECK ALL GEAR BOXES. CHECK COOLANT CHEMICAL LEVEL. TORQUE ALL DRAIN PLUGS TO SPECS. Extended Price Price Correction: SERVICED TRUCK Quantity U/M Description / Ref Number 1.0 EA Supp Part FILTER 36.0 1R0716 EA CHV DELO 400 SDE 15W40CK-4 B CT1 1.0 222290-990 EA BC FILTER BF1259JAB BF 1.0 \*\*\*\*\* CAN USE FS1000 \*\*\*\*\*\* EA FILTER-FUEL SPIN ON 1.00-14 1.0 BF584JAB Waste Disposal (Tax Exempt) 1.0 Enviro EX Service Shop Supplies Parts: Task 4 Subtotals Shop Sup1 Labor: Miscellaneous: Task 4 Subtotals Department: 03-Service CAT 3406 TUNE-UP Correction: REMOVE INTAKE PIPING AND TURBO CROSSOVER PIPE TO PRECOOLER REMOVE VALVE COVERS AND JAKE SPACERS. 10030 Task: 5 SET VALVE BRIDGES, INTAKE VALVES, EXHAUST VALVES AND JAKE BRAKES TO SPEC. REASSEMBLED JAKE SPACERS. VALVE COVERS AND TURBO CROSSOVER PIPE WITH 2 GASKETS AT PRECOOLER CONNECTION INSTALLED INTAKE Extended

	VALVE COVERS AND TURB		U/M	Quantity	Price
		Description / Ref Number	EA	2.0	
Supp. Part		SEAL			
	- A10000	E SENDING GEORGE TO PICK UP GASKET	EA	2.0	
CT	7VV0688	E SENDING GEORGE TO PICK UP Service Shop Supplies		1.0	
PLEASE	LEAVE IN WILLCALL WE AR	Service Shop Supplies			
	Shop Sup1	Service Stick cabbuse	Task 5 Subtotals	Parts:	
	Such and		Idan o duality	Labor:	
				Miscellaneous:	

Task 5 Subtotals

\*\* See Last Page for Invoice Total \*\*

Price

Invoice: 5103119066 Date / Hour: 5/23/2023 4:11:15PM Repair Order: 119066 Customer: Branch: Total Invoice: \$ 3,507.44 \*\*\*Cash\*\*\* Page 3 of 4 Го Completion Date: 05/22/2023 Open Date: 05/17/2023 Salesperson: houseaccount

stomer P/O

Add User:

**ENGINE FAN HUB REBUILD** 

Department: 03-Service

Extended

Complaint: CHECK OVER FAILING BEARING NOISE COMING FROM POSSIBLEY THE FAN HUB WHEN BARRING OVER FOR THE TUNE

CORRECTION: REMOVE ALTERNATOR AND FAN BELTS CHECKED BEARINGS FOUND FAN HUB BEARINGS BAD INSTALLED BELTS AND PARKED TRUCK ORDRED FAN HUB KIT FOR MONDAY REMOVED THE UPPER RADIATOR MOUNTS. REMOVED THE ALTERNATOR. REMOVED THE FAN BLADES. REMOVED THE BELTS, REMOVED THE HUB ASSEMBLY, DISASSEMBLED THE

FAN HUB. CLEANED AND REASSEMBLED THE FAN HUB WITH THE REBUILD KIT. REINSTALLED THE FAN HUB ASSEMBLY. INSTALLED NEW FAN BELTS. SET THE BELT TENSION AND TORQUED THE MOUNTING BOLTS DOWN, INSTALLED THE FAN BLADES AND TORQUED THE MOUNTING BOLTS DOWN. REINSTALLED THE ALTERNATOR BELTS. REINSTALLED THE ALTERNATOR AND TORQUED THE MOUNTING BOLTS DOWN. SET THE ALTERNATOR BELT TENSION. REINSTALLED THE

UPPER RADIATOR SUPPORTS WITH NEW BUSHINGS. STARTED THE TRUCK AND TESTED THE FAN. FOUND THE FAN TO

WORK GOOD.

	WORK GOOD.	Clarify	U/M	Quantity	Price	Price
upp. P	art	Description / Ref Number	EA	2.0		
X	22607	belt / 17621.00 LOCK WASHER 3/8	EA	6.0		
SG	36727	LOCK WASHER 1/2	EA	2.0		
SG	36729	GR. C-NE8 NYL INS LOCK NUT 3	EA	4.0		
SG	39663 7500HP	COMPLETE REBUILD KIT	EA	1.0		
please	e ship speedee to winona.thanks	blet / 17621.00	EA	2.0		
×	9550	CABLE TIE BLACK 15" X 9/32"	EA	5.0		
SG	C24707	GR.8HXCAPSCREW3/8-24X3	EA	1.0		
SG	D39362	RADIATOR MOUNT (HARRIS) BUSHING	EA	4.0		
PVL	ETP-07-02552	Freight Charge - Parts Department		1.0		
	Freight 1	Service Shop Supplies		1.0		
	Shop Sup1	Task 6 Subt	otals	Parts: Labor: Miscellaneous: Task 6 Subtotals		
				Donartm	nent: 03-Sei	rvice

				Departme	ent: 03-Service
Task: 7	23002	WHEEL SEAL	U/M	Quantity	Price Price
Supp. Part	Shop Sup1	Description / Ref Number Service Shop Supplies	Task 7 Subtotals	1.0 Parts: Labor:	
-				Task 7 Subtotals	

Invoice: 5103119066 Date / Hour: 5/23/2023 4:11:15PM Repair Order: 119066 Customer: Branch: Total Invoice: \$ 3,507.44 Page 4 of 4 Bill Completion Date: 05/22/2023 Open Date: 05/17/2023 Salesperson: houseaccount Customer P/O: Total Parts: Add User: **Total Core Charge:** Detail Tax Info: Total Core Ret: Minnesota State Sales Tax Total Labor: Winona City Sales Tax Total Miscellaneous: Winona County Tax Invoice Subtotal: Total: **Total Tax:** \$3,507.44 Total Invoice: Due Date Terms Payment Method 6/10/2023 00-DUE NET 10TH \*\*\*Cash\*\*\* Remit To Bal Due: \$3,507.44 Amount Received: \$0.00 Paid With: Amount Due: \$3,507.44 Signature: oee Last Page for Invoice Total \*\*

\*\*\* Customer Review \*\*\*

6/23/2023 4:02:58PM Date / Time:

Repair Order: 119127

Customer: Branch:

Invoice Total: \$ 8,643.24

> \*\*\*\*Cash\*\*\* Page 1 of 5

Bill To:

Completion Date: Customer P/O: Make/Model: Peterbilt 359 Model Year: 1979 Unit Number: 121144 Meter: 121415 Miles VIN: XXXXXXXXXXXX121144 Type: Service Unit Components: Part Number Serial Number Manufacturer Model 7XC02780 CATERPILLAR 3406B 7FB22992

Task: 1 13009 FRONT AXLE DIFFERENTIAL Department: 03-Service

Complaint: REPLACE FRONT DIFF DUE TO FAILING

Correction: MOVED TRUCKS AROUND STARTED AIRED UP PULLED INTO 2ND BAY REMOVED ALL AXLE SHAFT NUTS ENDED UP SNAPPING A STUD OFF IN THE LEFT REAR DRIVE AXLE HUB REMOVED AXLE SHAFTS REMOVED FRONT DRIVE SHAFT WENT TO REMOVE REAR DRIVE SHAFT FOUND ALL OF THE BAND STRAP BOLTS WHERE SMACKED WITH A HAMMER AND HAD A LARGE FLAT SPOT POUNDED A SOCKET ON THEM REMOVED ALL OF THEM REMOVED SHAFT REMOVED FRONT DIFF NUTS INSTALLED GIUDE STUDS SLID DIFF OUT AND ON THE GROUND REMOVED FROM UNDER THE TRUCK REMOVED REAR DIFF NUTS AND BOLTS SLID DIFF OUT AND ON THE GROUND JACKED UP REAR AXLE REMOVED DIFF FROM UNDER TRUCK CLEANED UP TOOLS GRABBED FORKLIFT GRABBED PARTS OUT OF RO ROOM SET NEXT TO TRUCK CLEANED AND INSPECTED BOTH FRONT AND REAR DRIVE AXLE TUBES FOUND NO LARGE OR ANY DEBRIS IN THE AXLE TUBES CLEANED UP ALL AXLE SURFACES AND ALL DIFF SURFACES HEATED UP BOTH YOKE NUTS FOR BOTH DIFFS REMOVED NUTS USED YOKE PULLER REMOVED YOKES GRABBED NEW PALLET SET BOTH DIFFS ON PALLET SET NEXT TO PARTS GARAGE 6/17/2023 12:06:27 PM 11688 INSTALLED DIFFS ON JOB 2

								Extended
Supp.	Part		Description / Ref Number	A STATE OF THE PARTY OF THE PAR	U/M	Quantity	Price	Price
N 1	177	Enviro EX	Waste Disposal (Tax Exempt)	Misc		1.00		
		Shop Sup1	Service Shop Supplies	Misc		1.00		
EA		127592DAN	SEAL - RE	Part	EA	1.00		
EA		127539	BEARING-CUP	Part	EA	2.00		
EA		127540	BEARING	Part	EA	2.00		
BC		223030-783	CHV SYN-GEAR XDM 75W90(PAIL BY GAL)	Part	EA	5.00		
WEL		DS404355WEL	CARRIER-REMAN DS404 355 / 17636.00	Part	EA	1.00		
WEL		DS404355WEL-C	CORE / 17636.00	Inherent		1.00		
CSG		39704	HARDENED FLAT WASHER 7/16 SA	Part	EA	1.00		
CSG		39604	GR. 8 HEX NUT 7/16-14 ZY	Part	EA	1.00		
CX		3164067CUM	GASKET-RSL	Part	EA	2.00		
PVL		ETP-4520	*PROMO* 12.50Z PREM BRAKE CLEANER	Part	EA	4.00		
WEL		DS404355WEL-C	CORE	Part	EA	(1.00)		
				Task 1 Sul	ototals	Parts:		
						Core Charge: Core Ret:		
						Labor:		
						Miscellaneous:	-	

\*\*\* Customer Review \*\*\*

Date / Time: 6/23/2023 4:02:58PM

Repair Order: 119127

Customer: Branch:

Invoice Total: \$8,643.24

\*\*\*\*Cash\*\*\* Page 2 of 5

Bill To:

Completion Date: Customer P/O:

Task 1 Totals:

\$3,803.08

13010 Task: 2

REAR AXLE DIFFERENTIAL

Department: 03-Service

Complaint: REPLACE REAR DIFF DUE TO FAILING

Correction: 6/16/2023 11:18:31 AM 11688 GRABBED FORKLIFT LIFTED FRONT DIFF OFF PALLET SET ON GROUND HAD SOMEONE USE FORKLIFT WHILE UNDER TRUCK SETTING DIFF ON STUDS PUT A BEAD OF SILICONE ON HOUSING SLID DIFF ONTO STUDS PUT BLUE LOCTITE ON ALL BOLTS AND STUDS RAN DOWN ALL BOLTS AND EASY ACCESSABLE STUDS

WITH 1/2 INCH GUN TIL GUN STOPPED

6/16/2023 4:33:23 PM 11688 LIFTED REAR DIFF OFF PALET AND SET BY TRUCK PULLED DIFF UNDER TRUCK USED FORKLIFT SET DIFF ON GUIDE STUDS PUT A BEAD OF SILICONE ON SURFACE SLID IN PLACE PUT BLUE LOCTITE ON BOLTS AND NUTS TIGHTEND DOWN ALL BOLTS AND NUTS TILL 1/2 INCH GUN STOPPED PICKED UP PALLET SET OFF TO THE SIDE WENT INTO PARTS GRABBED AXLE GASKETS INSTALLED FRONT AXLES AND REAR RIGHT AXLE TIGHTEN DOWN ALL NUTS INSTALLED YOKES ON DIFFS RAN DOWN NUTS TILL 3/4 GUN STOPPED INSTALLED DRIVE SHAFTS WITH NEW BAND STRAPS AND GREASED UJOINTS PUT FORKLIFT AWAY AND CLEANED UP TOOLS

6/17/2023 12:05:11 PM 11688 FILLED DIFFS WITH OIL PULLED TRUCK OUT OF SHOP PRESSURE WASHED REAR DIFFS DROVE AROUND SHOP MULTIPLE TIMES PULLED BACK INTO SHOP TOPPED OFF DIFFS CHECKED OVER FOUND NO LEAKS PULLED BACK OUT OF SHOP PARKED TRUCK SWEPT AND PRESSURE WASHED FLOOR CLEANED UP MESS

Supp. Part	CUST	Description / Ref Number	RR	U/M	Quantity	Price	ended Price
опрр. Ган	Enviro EX	Waste Disposal (Tax Exempt)	Misc		1.00		
	Shop Sup1	Service Shop Supplies	Misc		1.00		
WEL	RS404355WEL	CARRIER-REMAN RS404 355 / 17636.00	Part	EA	1.00		
WEL	RS404355WEL-C	CORE / 17636.00	Inherent	13.250	1.00		
BC	223030-783	CHV SYN-GEAR XDM 75W90(PAIL BY GAL)	Part	EA	5.00		
04	6-4-8991-1X	YOKE ASSY-END 1710 2.024-39	Part	EA	1.00		
DA	03-01568	GASKET-AXLE SHAFT	Part	EA	4.00		
PB	6.5-70-18X	KIT-STRAP&BOLTS, 1/2	Part	EA	3.00		
DA	C24707	CABLE TIE BLACK 15" X 9/32"	Part	EA	5.00		
CSG	CTD6511	TIE-CABLE DUAL CLAMP BLK 19.2" 150LBS	Part	EA	1.00		
WEL	RS404355WEL-C	CORE	Part	EA	(1.00)		
			Task 2 Subt	otals	Parts:		
					Core Charge: Core Ret: Labor: Miscellaneous:		
					Task 2 Totals:	\$3,09	8.21

WHEEL SEAL Task: 3 23002 Complaint: REPAIR FOR LEFT REAR WHEEL SEAL LEAKING

\*\*\* Customer Review \*\*\*

Date / Time: 6/23/2023 4:02:58PM

Repair Order: 119127

Customer:

Branch: Invoice Total: \$ 8,643.24

> \*\*\*\*Cash\*\*\* Page 3 of 5

Bill To:

Customer P/O:

Completion Date:

Extended

Extended

Correction: JACKED UP TRUCK SET ON JACK ATTEMPTED TO CAGE REAR LEFT CHAMBER AND CAGING BOLT BROKE AIRED UP TRUCK BACKED OFF BRAKES REMOVED TIRES REMOVED DRUM REMOVED HUB INSPECTED FOUND WHEEL SEAL HAD FAILED REMOVED SPEEDY SLEEVE CLEANED UP HUB WENT INTO PARTS GOT A NEW HUB AND GOT A SPEEDY SLEEVE ORDERED FOR TOMORROW CLEANED UP SPINDLE REMOVED ABS SENSOR CLEANED UP SENSOR AND HOLE INSTALLED BACK IN REMOVED WHEEL SEAL OUT OF NEW HUB CLEANED UP SURFACE INSTALLED NEW REV MAX SEAL APPLIED LUBE AROUND SEAL PRELUBED BEARING INSTALLED ON HUB PUT LUBE ON SPINDLE INSTALLED HUB ON TRUCK FILLED HUB TIGHTENED DOWN BEARINGS FLIPPED OVER TABS INSTALLED NEW GASKET INSTALLED AXLE SHAFT AND NEW NUTS PRESSURE WASHED BRAKES AND DRUM INSTALLED BRAKES AND DRUM INSTALLED TIRES FILLED TRUCK WITH AIR ADJUSTED BRAKES JACKED UP TRUCK REMOVED JACK TORQUED WHEELS

Supp.	Part	The second secon	Description / Ref Number		U/M	Quantity	Price	Price
		Enviro EX	Waste Disposal (Tax Exempt)	Misc		1.00		
		Shop Sup1	Service Shop Supplies	Misc		1.00		
CM		CM10082217	HUB ASSY	Part	EA	1.00		
RHD		RM-D02	Rev Max Premium Drive Seal	Part	EA	1.00		
CSG		39667	GR. C-NE8 NYL INS LOCK NUT 5	Part	EA	8.00		
CSG		CUS	CABLE TIE BLACK 15"" X 9/32"	Part Task 3 Subt	EA	A.00 Parts: Labor: Miscellaneous: Task 3 Totals:	1	

Department: 03-Service ALTERNATOR BELT 28004 Task: 4

Complaint: INSTALL CUSTOMER SUPPLIED ALTERNATOR BELTS

Correction: LOOSENED THE ALTERNATOR. REMOVED THE BELTS. INSTALLED THE NEW BELTS. SET THE BELT TENSION WITH THE

ALTERNATOR. TORQUED THE ALTERNATOR MOUNTING BOLTS DOWN.

Supp.	Part	Description / Ref Number		U/M	Quantity	Price	Price
CSG CSG CSG	Shop Sup1 D39108 KP66131 39705	Service Shop Supplies GR.8HXCAPSCREW1/2-13X2 GR. C LOCK NUT 1/2-13 HARDENED FLAT WASHER 1/2 SAE	Misc Part Part Part	EA EA EA	1.00 1.00 2.00 2.00		
			Task 4 St	ubtotals	Parts: Labor: Miscellaneous:		
					Task 4 Totals:		

13011

\*\*\* Customer Review \*\*\* Date / Time: 6/23/2023 4:02:58PM Repair Order: 119127 Customer: Branch: Invoice Total: \$ 8,643.24 \*\*\*Cash\*\*\* Page 4 of 5

Completion Date:

Bill To:

Customer P/O:

Task: 6

Complaint: REPLACE FRONT DRIVE OUTPUT BEARINGS AND SEAL

REMOVED YOKE REMOVED SEAL AND INNER SNAP RING POPPED OUTER RACE OUT SLID WHOLE WORKS OUT. SPLIT THE BEARINGS CLEANED UP OUTPUT SHAFT INSTALLED BEARINGS PUNCHED OUT OLD INNER RACE CLEANED UP SEAL SURFACE FOUND IT TO HAVE PITTING ALL AROUND SEAL SURFACE, BRAKE CLEANED OUT HOLE INSTALLED INNER RACE WAITED TO INSTALL OUTPUT SHAFT UNTIL DIFF WAS INSTALLED INSTALLED OUTPUT SHAFT PUT BLUE LOCTITE AROUND NEW RACE POUNDED IN NEW RACE MADE SURE IT WAS SEATED INSTALLED SNAP RING PUT A SMALL FILM OF SILICONE ON SEAL SURFACE POUNDED IN NEW SEAL INSTALLED YOKE PUT BLUE LOCTITE ON YOKE

Supp. Part Description / Ref Number Extended Enviro EX U/M Quantity Price Price Waste Disposal (Tax Exempt) Misc Shop Sup1 1.00 Service Shop Supplies Misc 1.00 Task 5 Subtotals Parts:

Miscellaneous:

Labor:

Department: 03-Service

Task 5 Totals: 25008 AIR LEAK

Complaint: REPAIR FOR AN AIR LEAK AT THE AIR TANK

Correction: REMOVED AND REPLACED QUICK DRAIN ON LEFT REAR AIR TANK FILLED WITH AIR SPRAYED DOWN. FOUND NO

LEAKS WAS TOLD TO FIX CHAMBER ON AIR LEAK JOB RELEASED BRAKES REMOVED CHAMBER INSTALLED FITTINGS ON NEW CHAMBER INSTALLED CHAMBER ON TRUCK RELEASED BRAKES PRESSED BRAKES FOUND NO LEAKS PUT

CHAMBER IN SCRAP BIN

Extended Supp. Part Description / Ref Number U/M Quantity Price Price Shop Sup1 Service Shop Supplies Misc 1.00 DC VL2058 VALVE-DRAIN TRUCK BRS #4M Part EA 1.00 MG 3430008X P/B PLUS BULK KIT Part EA 1.00 Task 6 Subtotals Parts: Labor: Miscellaneous: Task 6 Totals:

Bill To:	Date / Time: 6/23/2023 4:02:58PM Repair Order: 119127 Customer: Branch: Invoice Total: \$ 8,643.24  ***Cash*** Page 5 of 5
Customer P/O:	
	Completion Date:
Payment Method Cash	Totals  Total Parts: Total Core Chg: Total Core Ret: Total EHC: Total Labor: Total Miscellaneous: Invoice Subtotal: Total Tax: Invoiced Total: \$8,643.24
Signature:	Invoiced Iotal: \$8,643.24

\*\* Reprint \*\* Invoice: 5103111282

Date / Hour: 11/20/2020 1:03:11PM

Repair Order: 111282 Customer:

Branch:

Total Invoice: \$ 6,540.76 \*\*\*Cash\*\*\*

Page 1 of 4

Bill

Ship To:

Customer P/O:

Open Date: 10/16/2020

Salesperson: houseaccount

Completion Date: 11/03/2020

Add User:

Make/Model: Peterbilt 359

Price

Extended

Price

Unit Number: 121144

Model Year: 1979

Meter: 24992 Miles

Type: Service

VIN: XXXXXXXXXXX121144

Task: 1 40010 DIAGNOSTIC / TROUBLESHOOTING

Department: 03-Service

Complaint: CHECK COMPLAINT OF TRUCK HAVING FUEL SPRAYING ON SIDE OF TRUCK AND TRUCK WILL NOT START

Correction: COMPLAINT OF FUEL ISSUE AND NOT STARTING. REMOVED AIR CLEANER PIPE, INTAKE PIPE AND TURBO PEANUT, BOTH VALVE COVERS, JAKES, JAKE HOUSINGS, FUEL LINES AND INJECTORS TESTED THE NOZZLES AND DID NOT FIND ONE THAT WOULD BE CAUSING THE ISSUE, MOTOR ROLLED OVER FINE BY HAND VALVE SETTINGS WERE GOOD NO FUEL IN THE OIL AND THE CYLINDERS HELD PRESSURE ORDERED NEW NOZZLES. INSTALLED 6 NEW NOZZLES AND INSTALLED FUEL JUMPER LINES WITH NEW ORINGS SET VALVE BRIDGES AND VALVES TO SPEC INSTALLED JAKES AND SET TO SPEC. INSTALLED JAKE AND VALVE COVERS INSTALLED TURBO CROSSOVER PIPE WITH NEW GASKET INSTALLED INTAKE PIPING STARTED ENGINE AND TOOK TRUCK FOR A TEST DRIVE ENGINE RUNS GOOD

Supp.	Part	Description / Ref Number	U/M	Quantity
CT	0R3421	NOZZLE A RE / 13611.00	EA	6.0
СТ	0R3421-C	CORE / 13611.00	EA	6.0
СТ	1H1023	RING / 13611.00	EA	8.0
СТ	0R3421-C	CORE SIGN	EA	-6.0
СТ	7W0688	GASKET / 13611.00	EA	2.0
	Labor CR 1	0R3421		-1.0
	Shop Sup1	Service Shop Supplies	はして	1.0
			Task 1 Subtotals	Parts:
				Core Chg:

Core Ret: Labor: Miscellaneous:

Task 1 Subtotals

DIAGNOSTIC / TROUBLESHOOTING

Department: 03-Service

Complaint: CHECK COMPLAINT OF TRUCK MAKING A POP SOUND AND DIE GOING DOWN THE ROAD

Correction: DRAINED COOLANT, REMOVED AIR COMPRESSOR, FUEL LINES AND FILTER BASE, REMOVED TIMING ADVANCE COVER AND REMOVED TIMING ADVANCE ASSEMBLY, REMOVED FUEL INJECTION PUMP FROM ENGINE AND DISASSEMBLED COMPLETELY AND CLEANED PARTS AND INSPECTED CAM AND PUMPS CHECKED OUT GOOD . FOUND GOVERNOR WEIGHTS AND TIMING ADVANCE WEIGHTS AND RACES WORN. INSTALLED CAM SHAFT .CAM FOLLOWERS AND RACK. LAPPED IN ALL 6 PUMPS AND INSTALLED IN INJECTION PUMP WITH NEW ORINGS INSTALLED NEW TACH SHAFT AND SEAL. INSTALLED NEW GOVERNOR WEIGHTS, PINS AND RACE. INSTALLED NEW THROTTLE SHAFT SEAL AND NEW SHUT OFF LEVER INSIDE OF GOVERNOR FOUND IT WAS BROKEN IN HALF, INSTALLED NEW SHUT OFF SHAFT SEAL AND REPLACED ALL ORINGS ON GOVERNOR HOUSING. RESEALED BACK SIDE OF INJECTION PUMP, INSTALLED GAUGE ON INJECTION PUMP AND SET FL STATIC FUEL SETTING TO 2.30 MM AND FT STATIC FUEL SETTING TO 3.30 SET AND SET STATIC A /F LEVER TO -1.25 MM INSTALLED . INSTALLED NEW SHUT OFF SOLENOID AND INSTALLED A REMAN TRANSFER PUMP. RETURNED OLD ONE TO PARTS DEPT FOR CORE. INSTALLED INJECTION PUMP ON ENGINE . INSTALLED NEW QUAD RINGS ON TIMING ADVANCE AND INSTALLED NEW WEIGHTS PINS AND RACE AND INSTALLED ON FUEL PUMP AND PIN TIMED. INSTALLED AIR COMPRESSOR FUEL LINES FILLED COOLING SYSTEM. HOOKED UP DIESEL ENGINE TIMING INDICATOR AND RAN ENGINE. CHECKED TIMING AND ADJUSTED START AND STOP TO SPEC AND RECORDED. REMOVED TIMING INDICATOR STEAMED OFF PUMP AND TOOK TRUCK FOR A TEST DRIVE CHECKED FOR LEAKS AND PAINTED INJECTION PUMP.

\*\* See Last Page for Invoice Total \*\*

Date / Hour: 11/20/2020 1:03:11PM Repair Order: 111282

Customer:
Branch:

Total Invoice: \$ 6,540.76

Page 2 of 4

P/O: ser: bkruse			Date: 10/16/2020 rson: houseaccount	Completion Date: 11/03/2020	
Part 0058160	Description / Ref Number SCREW / 13647.00	U/M	Quantity	Price	Extended
0R3008	PUMP G / 13647.00	EA	4.0		
0R3008-C	CORE / 13647.00	EA	1.0		
1255773	SOLENOID / 13647.00	EA	1.0		
1313719	SEAL-O-RING / 13647.00	EA	1.0		
1440478	GASKET / 13647.00	EA	6.0		
1440479	GASKET / 13647.00	EA	1.0		
1440480	GASKET / 13647.00	EA	1.0		
1440481	GASKET / 13647.00	EA	1.0		
1440482	THE RESERVE OF THE PARTY OF THE	EA	1.0		
1H9696	GASKET / 13647.00	EA	1.0		
1J9671	RING / 13647.00	EA	2.0		
	SEAL O RI / 13647.00	EA	2.0		
1J9671	SEAL O RI / 13647.00	EA	1.0		
150004	SEAL O RI / 13647.00	EA	1.0		
195440	DOWEL / 13647.00	EA	4.0		
1W5342	LEVER SHUT-OFF / 13654.00		1.0		
0R3008-C	CORE	EA	-1.0		
2W0459	GASKET / 13647.00	EA	1.0		
2W5447	GASKET / 13647.00	EA	1.0		
3170808	SEAL-O-RING / 13647.00	EA	1.0	Table 1	
3D8317	RING / 13647.00	EA	1.0	100	
3J1907	SEAL / 13647.00	EA	6.0		
3J7354	SEAL O RI / 13647.00	EA	2.0		
3L6768	RING / 13647.00	EA	1.0		
3P0009	INSULATOR / 13647.00	EA	1.0		
4589587	PAINT YELLOW	EA	1.0		
4D3107	SEAL-O-RING / 13647.00	EA	6.0		
4J7533	SEAL O RI / 13647.00	EA	1.0		
4J8997	SEAL O RI / 13647.00	EA	1.0		
4M8303	SEAL O RI / 13647.00	EA	1.0		
4N0260	SEAL / 13647.00	EA	1.0		
4N2927	RACE / 13647.00	EA	1.0		
4N2927	RACE / 13654.00	EA	1.0		

Invoice: **5103111282**Date / Hour: 11/20/2020 1:03:11PM

Repair Order: 111282

Customer: Branch:

10

Total Invoice: \$ 6,540.76 \*\*\*\*Cash\*\*\*\*

Page 3 of 4

Bil

	210			101101000	Constaller Date 44 100 100
Custome				te: 10/16/2020	Completion Date: 11/03/202
Add	User: bkruse 4N2953	LOCK-RING / 13647.00	Salesperso	n: houseaccount	
CT	4N9019		EA	1.0	
T	4W0435	DOWEL / 13647.00	EA	1.0	
		SEAL / 13647.00		1.0	
T	4W0436	SEAL / 13647.00	EA	1.0	
T	4W4616	SEAL / 13647.00	EA		
T	5F9144	SEAL / 13647.00	EA	1.0	
CT	5P5601	SEAL-O-RING / 13647.00	EA	1.0	
CT	5P6620	SEAL O RING / 13647.00	EA	1.0	
CT	5P9757	SEAL / 13647.00	EA	1.0	
CT	6F4718	SEAL / 13647.00	EA	1.0	
CT	6H9691	RING / 13647.00	EA	1.0	
CT	6V5029	SEAL / 13647.00	EA	1.0	
CT	7J0204	SEAL O RI / 13647.00	EA	2.0	
CT	7M7219	BEARING / 13647.00	EA	1.0	
CT	7N7264	WEIGHT / 13647.00	EA	4.0	
CT	7N7264	WEIGHT / 13647.00	EA	4.0	
CT	8J8343	SEAL / 13647.00	EA	1.0	
CT	8N2510	SHAFT / 13647.00	EA	1.0	
CT	8N3761	GASKET / 13647.00	EA	1.0	
СТ	8\$7803	RETAINER / 13647.00	EA	1.0	
СТ	8T2604	SEAL / 13647.00	EA	1.0	N 1000
CT	9M9647	SEAL O RING / 13647.00	EA	1.0	
СТ	9S8001	PLUG / 13647.00	EA	1.0	
CT	9Y7037	BOLT / 13647.00	EA	4.0	
CSG	D39054	GR.8HXCAPSCREW3/8-16X1	EA	2.0	
000	Comp Diag	Computer Diagnostic Charge		1.0	
	Freight 1	Freight Charge - Parts Department		1.0	
	Shop Sup1	Service Shop Supplies		1.0	
	Onop Cop i	Task 2 S	ubtotals	Part	
				Core Ch	The state of the s
				Core Re	
				Miscellaneou	
				Task 2 Subtota	

\*\* Reprint \*\*
Invoice: 5103111282
Date / Hour: 11/20/2020 1:03:11PM
Repair Order: 111282
Customer:
Branch:
Total Invoice: \$ 6,540.76

\*\*\*Cash\*\*\*
Page 4 of 4

Bill

Customer P/O:			Open Date: 10/16/2020	Completion Date: 11/03/2020
Add User: bkruse			Salesperson: houseaccount	55/11/5/15/15/15/2020
Detail Tax Info:	No. of the last of			
Minnesota State Sales Tax Winona City Sales Tax Winona County Tax	Total:	\$124.91 \$0.00 \$9.09 \$134.00	Total Parts: Total Core Charge: Total Core Ret: Total Labor: Total Miscellaneous:	
	To the second		Invoice Subtotal: Total Tax:	
	questions		Total Invoice:	\$6,540.76
Payment Method ***Cash***	Terms 00-DUE NET 10TH	<u>Due Date</u> 12/10/2020	7	
Remit To—		李		

Paid With:

Amount Due: \$6,540.76

Amount Received:\$0.00

Bal Due: \$6,540.76

A MOBILE DEVICE NO FLEET OWNER SHOULD BE WITHOUT

Signature: \_\_\_\_\_

HEH:

Invoice: 5103112411

Date / Hour: 7/7/2021 6:39:45PM

Repair Order: 112411

Customer: Branch:

Total Invoice: \$ 1,439.95

\*\*\*Cash\*\*\*

Page 1 of 3

Bill To

Ship To:

Customer

houseaccount

Orig R/O: 0

Completion Date: 07/06/2021

Unit Number: 121144 Type: Service

Model Year: 1979

Make/Model: Peterbilt 359

VIN: XXXXXXXXXXXX121144

Meter: 83152 Miles

Department: 03-Service

12010 YOKE

Complaint: REPAIR FOR TRANS OUTPUT YOKE BEING WORN OUT

Correction: PULLED TRUCK ONTO THE PIT. USED RATCHET STRAPS TO SUPPORT THE DRIVESHAFTS, REMOVED REAR SHAFT, REMOVED FRONT SHAFT, REMOVED YOKE NUT. PULLED SEAL HOUSING AND REMOVED SEAL, PUT HOUSING IN THE PARTS WASHER, INSTALLED NEW SEAL, CLEANED UP ALL GASKET AREAS, REINSTALLED HOUSING AND THE TONE RING, INSTALLED NEW YOKE, REMOVED UJOINT FROM THE DRIVE SHAFT AND INSTALLED NEW UJOINT, REINSTALLED DRIVE SHAFTS.

Supp.	Part	The state of the s	DERIVE SHAFTS.			Olivi
RI DA	17N4-6841X 5-280X	Description / Ref Number YOKE-END	U/M EA	Quantity 1.0	Price	Extended Price
DA FU	6.5-70-18X K2262	KIT-U JOI KIT-STRAP&BOLTS, 1/2	EA EA	1.0		
	Shop Sup1	K1T-OIL S Service Shop Supplies	EA	1.0		
			sk 1 Subtotals	1.0 Parts:		
Task: 2	2 36004 01/2			Labor: Miscellaneous: Task 1 Subtotals		

Task	2 36004	OVER TH	HE COUNTER PARTS		Task 1 Subtotals		
Supp.	Part				Departme	nt: 03-Ser	vice
PBA	P92-6972		Description / Ref Number HARNESS-SPEED SENSOR ADAPTER	U/M	Quantity	Price	Extended
PB	Q21-6005	4	SENSOR-SP	EA	1.0	11100	Price
	Shop Sup1	*1	Service Shop Supplies	EA	1.0		
			Task 2 Subt	otale	1.0		
			Man 2 Subt	otals	Parts:	-	
					Labor:		
Task:	3 16002	SERVICE	SPECIAL - OIL FILTED FUEL		Task 2 Subtotals		

SERVICE SPECIAL - OIL, FILTER, FUEL FILTER, GREASE

Department: 03-Service

Complaint: CHANGE OIL AND FILTERS ALSO TAKE OIL SAMPLE

GREASE CHASSIS. CHECK ALL FLUID LEVELS.

CHANGE OIL AND FILTER. CHANGE FUEL FILTERS. GREASE

CHASSIS. CHECK ALL GEAR BOXES. CHECK COOLANT CHEMICAL LEVEL TORQUE ALL DRAIN PLUGS TO SPECS.

Correction: SERVICED TRUCK AND PERFORMED OIL SAMPLE

Supp.	Part					
CT	1R0716	Description / Ref Number FILTER A	U/M	Quantity	Price	Extended Price
CT	1R0749		EA	1.0		, ,,,,
3C	222290-990	FILTER AS	EA	1.0		
		CHV DELO 400 SDE 15W40CK-4 B	EA	40.0		

Invoice: 5103112411
Date / Hour: 7/7/2021 6:39:45PM
Repair Order: 112411
Customer:
Branch:
Total Invoice: \$ 1,439.95
\*\*\*Cash\*\*\*
Page 2 of 3

Bill To

Custom	er P/O:	jjohnson2	houseaccount	Orig R/O	0	Completion Date: 7/6/2021
BF	BF1259JAB	FILTER		EA	1.0	
*****	* CAN USE FS1000 ****** Enviro EX	Waste Disposal (Tax Exempt)			1.0	
	Shop Sup1	Service Shop Supplies			1.0	
			Task 3 Subtotals		Par Lab	
					scellaneo	

Tools 4	40040	SCHEDULED OIL SAMPLE - SOS		Departme	ent: 03-Service
Task: 4	16018		U/M	Quantity	Price Price
Supp. Part		Description / Ref Number OIL SAMPLE KIT	EA	1.0	
CT	S0S100			1.0	
	Shop Sup1	Service Shop Supplies	Task 4 Subtotals	Parts: Labor: Task 4 Subtotals	

		Li La Nat Caused On Ser	vice Special	Departme	nt: 03-Servic	e
Task:	5 16028	Parts and Labor Not Covered On Ser	vice openial		Ex	tended
		Description / Ref Number	U/M	Quantity	Price	Price
-	Part	STABILIZER-OIL HD GAL	EA	1.0		
LU	10002LUC	GEAR LUBE SYN75/90	EA	1.0		
LU	10047LUC	COOLANT-ELC	EA	1.0		
CT	2388648	Service Shop Supplies		1.0		
	Shop Sup1	Service Study Supplies	Task 5 Subtotals	Parts: Labor:		
				Task 5 Subtotals	The state of the s	0.00

Detail Tax Info:		\$51.58
Minnesota State Sales Tax		\$0.00
Winona City Sales Tax		\$3.75
Winona County Tax	Total:	\$55.33

Total Parts:
Total Labor:

Total Miscellaneous:
Invoice Subtotal:
Total Tax:

Total Invoice: \$1,439.95

Payment Method Cash Terms 00-DUE NET 10TH Due Date 8/10/2021

INVOICE		INVOICE DATE	CUSTON	TER NUMBER	1	CUSTOMER ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE
LC0001	Andrews Minneson	11-05-19	10 10				36	T		4	2
PSO/WO N		DOC. DATE	PC	LC	MC	SHIP VIA	Deliver Constitution		CONTRACTOR OF THE PERSON NAMED IN	INV. SEO. I	NUMBER
LC0001	0	09-28-19	10	10	10			No. of Concession, Name of Street, or other party of the Concession, Name of Street, or other pa			1
MAKE	8.0	ODEL		SERIAL NUM	IBER	EQUIPMENT NUMBER	MET	ER READIN	-	MACH. I.D.	M MARKS
AA	3406B	073	C0278	0	1-140000		The second liverage and the second	2617.		MACH. 1.07	ACM BL-
QUANTITY	2002	ITEM	N/R	THE REAL PROPERTY.	DESC	PEPTION	UNIT PRICE	2017.	-	WARRION.	-
	TO STATE OF			PR/	The second second	INVOTOR	SHU FREE			TENSION	

CORRECTION: BROUGHT TRUCK INTO SHOP. ENGINE WAS RUNNING VERY ROUGH AND THERE WAS A GREENISH-GRAY OILY MIXTURE COMING FROM THE BLOWBY TUBE ON THE VALVE COVER. CUSTOMER STATED THE ENGINE COOLANT WAS FILLING THE CRANKCASE. HE WANTED US TO TROUBLESHOOT THE PROBLEM AND GIVE HIM OPTIONS ON WHAT TO DO AND COST OF EACH OPTION. STARTED BY DEALINING THE ENGINE OIL/COOLANT MIXTURE. ENGINE HAS A BRAKESAVER ON IT. THAT WAS DRAINED AND ALL THE BRAKESAVER RELATED COMPONENTS ATTACHED TO THE OIL PAN WERE REMOVED. REMOVED OIL PAN FROM ENGINE, ALL PICK UP TUBING, AND OIL PUMP. IMMEDIATELY I WAS ABLE TO SEE THE COOLANT O-RING FOR NUMBER 1 CYLINDER WAS LEAKING BADLY IN 2 SPOTS. THE CUSTOMER TOLD US THE TRUCK HAD BEEN SITTING FOR AN EXTENDED PERIOD OF TIME. MY DIAGNOSIS WAS THE COOLANT O-RING WAS ROTTED AWAY CAUSING THE LEAKING OF COOLANT INTO THE ENGINE OIL. ENGINE NEEDED TO BE COMPLETELY DISASSEMBLED. AT THE VERY MINIMUM, NUMBER 1 CYLINDER LINER NEEDED TO BE REPLACED. CUSTOMER GAVE US THE GREEN LIGHT TO TEAR DOWN THE ENGINE FURTHER TO REMOVE THE CYLINDER PACK AND EXAMINE THE ENGINE BLOCK TO SEE IF IT WAS SALVAGEABLE. DRAINED COOLANT FROM RADIATOR AND ENGINE BLOCK, REMOVED THE VALVE COVERS AND FOUND THAT ALL OF THE JAKE BRAKES AND VALVE TRAIN COMPONENTS WERE ALL RUSTED AND HAD BAD

* - NOT RETURNABLE	PLEASE PAY THIS AMOUNT	CONT'D
ARE BACKORDERED	AMOUNT CREDITED	. 10 10

CUSTOME	R NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

Sold To:

Ship To:

			Name and Address of	AND DESCRIPTION OF THE PERSON NAMED IN	CUSTOMER ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE
INVOICE NUMBER	INVOICE DATE	CUSTON	ER NUMBER		CUSTOMER ORDER HOUSE	36	T		INV. SEQ.	HIMBER
C00010	11-05-19	PC	I to I	MC	SHIP VIA				INV. SEG.	1
C00010	09-28-19	10	10	10	EQUIPMENT NUMBER		TER READI		MACH. I.O	NUMBER
MAKE	1000E	C027	SERIAL NUM	BER	THE RESERVE THE PERSON NAMED IN COLUMN 1	and an owner of	2617		EXTENSION	
AA 34061	ITEM T	N/R	The state of	DESC	PIPTION * * *	UNIT PRICE	100000			The later of

CONDENSATION ON THEM. REMOVED THE JAKE BRAKES, VALVE COVER BASES AND VALVE TRAIN. REMOVED THE ALTERNATOR, A/C COMPRESSOR, RADIATOR BRACKETS, FAN ALTERNATOR, A/C COMPRESSOR, RADIATOR BRACKETS, FAN HUB, WIRING HARNESS, AIR COMPRESSOR, AIR AND HUB, WIRING HARNESS, AIR COMPRESSOR, AIR AND COOLANT LINES AND TUBES, FUEL LINES, AIR INTAKE TUBING, AND TURBOCHARGER. MULTIPLE BOLTS AND NUTS WERE STRIPPED AND BROKEN DURING COMPONENT REMOVAL. 90% OF THE HARDWARE THAT WAS REMOVED HAD TO BE REPLACED. REMOVED CYLINDER HEAD, GASKETS, AND SPACER PLATE. AFTER CLOSER INSPECTION I NOTICED THAT NUMBER 3 EXHAUST VALVES HAD HIT THE TOP OF THE PISTON MULTIPLE TIMES ALSO. AT THAT POINT THE CYLINDER HEAD NEEDED TO BE REPLACED WITH A NEW OR REMAN. REMOVED THE CONNECTING ROD CAPS FOR NUMBER I AND 6 CYLINDER SO THOSE PACKS COULD BE REMOVED AND EXAMINED IF WE WERE GOING TO BE ABLE TO REUSE THE LINER OR HAVE TO GET ALL NEW ONES. AFTER THE PACKS WERE REMOVED IT WAS NOTICED THAT THEY HAD BAD CAVITATION PITTING IN THE LINER WALLS. I CLEANED THE BLOCK DECK, UPPER AND LOWER BORES FOR THE LINERS. THE LOWER BORES WERE STILL IN PRETTY GOOD SHAPE BUT THE UPPER BORES WERE STILL IN PRETTY GOOD SHAPE BUT THE UPPER BORES WERE NOT. UPPER BORES HAD A LOT OF PITTING AND WEAR ON THEM. THIS ENGINE WAS A REMAN ENGINE IN 1991 AND IT SHOWED AS IT HAD THE COUNTER BORES ALREADY CUT IN THE DECK. BUT SINCE THE UPPER BORES NEEDED WORK THE COUNTER BORES WOULD HAVE TO BE RE-CUT AS WELL. THE WATER

\* - NOT RETURNABLE ITEMS NOT SHOWN ARE BACKORDERED

PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

AND THE CUSTOMER NUMBER CUSTOMER ORDER NUMBER STORE DIV. SALESMAN TERMS PAGE  4 4  1 HAND THE DATE CUSTOMER NUMBER CUSTOMER ORDER NUMBER 36 T INV. SEQ. NUMBER 1	1
INVOICE M.IMSER	41
LC00010 09-28-19 SERIAL NUMBER 1932617.0  MAKE MODEL 07XC02780 DESCRIPTION UNIT PRICE EXTENSION  AA 3406B NR PROFORMA INVOICE * * *	

GROMMET AREAS ON THE BLOCK WERE DEEPLY PITTED AND UN-FIXABLE UNLESS THE BLOCK WAS DECKED. BUT AS UN-FIXABLE UNLESS THE BLOCK WAS DECKED. BUT AS THIS WAS A REMAN ENGINE IT WAS MORE THAN LIKELY THE BLOCK WAS ALREADY DECKED. IF THE BLOCK WAS TO BE TOTALLY MACHINED AGAIN THERE WOULD NOT BE ENOUGH MATERIAL LEFT TO HAVE IT BE A USABLE ENGINE ENOUGH MATERIAL LEFT TO HAVE IT BE A USABLE ENGINE CUSTOMER TO HAVE US TRY AND GET A LONG BLOCK CUSTOMER TO HAVE US TRY AND GET A LONG BLOCK OF THE SHORT BLOCK AND ASSEMBLE IT FROM THE GROUND UP. SHORT BLOCK AND ASSEMBLE IT FROM THE GROUND UP. SHORT BLOCK AND ASSEMBLE TO COME OUT OF TRUCK AND BE FURTHER DISASSEMBLED TO SEE WHAT PARTS WE COULD REUSE AND WHICH PARTS WE NEEDED TO GROEK. COULD REUSE AND WHICH PARTS WE NEEDED TO GIVE US REMOVED THE RADIATOR PACK FROM TRUCK TO GIVE US ALSO MORE ROOM TO REMOVE AND INSTALL ENGINE AND ALSO MORE ROOM TO REMOVE AND REMOVED THE FRONT WHEELS JACKED UP THE TRUCK ON CRIBBING TO GET IT A TOUCH AND SET THE TRUCK ON CRIBBING TO GET IT A TOUCH AND SET THE TRUCK ON CRIBBING TO GET IT A TOUCH AND SET THE TRUCK ON CRIBBING TO GET IT A TOUCH OWRE. TRIED TO LOOK UP AND ORDER A LONG BLOCK, WORK. TRIED TO LOOK UP AND ORDER A LONG BLOCK, BUT AFTER A DAY OR TWO OF LOOKING WE FOUND OUT SAME POWER RATING AND SPECS AS THE ORIGINAL. SO SAME POWER RATING AND SPECS AS THE ORIGINAL. SO SAME POWER RATING AND SPECS AS THE ORIGINAL. SO SAME POWER RATING AND SPECS AS THE ORIGINAL. SO THE SHORT BLOCK WAS OUR ONLY OPTION. WE WERE ABLE THE SHORT BLOCK WAS OUR ONLY OPTION. WE WERE ABLE MISSISSIPPI. BUT IT WAS GOING TO TAKE A COUPLE WEEKS TO GET ONE. SO IN THE MEAN TIME THE OLD

• - NOT RETURNABLE	PLEASE PAY THIS AMOUNT	CONT'D
ITEMS NOT SHOWN ARE BACKORDERED	AMOUNT CREDITED	

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

		THE PARTY OF THE P	STORE	DIV.	SALESMAN	I COMP
T TOTAL CONTE	CUSTOMER NUMBER CUST	TOMER ORDER NUMBER	36	T		4 1 3
	444		CONTRACTOR OF THE PARTY OF THE			INV. SEO. NUMBER
LC00010 11-05-19	TO LC MC	SHEVIA				1
DOC. DATE	10 10 10		-	TER READE	NG.	MACH, LD, NUMBER
LC00010 09-28-19	10 10 10 SEPIAL NUMBER	EQUIPMENT NUMBER		2617	-	
MOORI			200	1107		EXTENSION
AA 3406B 073	C02780	IOM	UNET PRICE			DOLLAR STATE OF THE PARTY OF TH
CONTRACT OF THE PARTY OF THE PA						
QUANTITY ITEM	* * * PROFORMA IN	MOTOR				

ENGINE BLOCK WAS COMPLETELY DISASSEMBLED AND ALL PARTS WERE EXAMINED FOR THEIR CONDITION TO BE REUSED OR NOT. I MADE A PARTS LIST OF EVERYTHING WE WOULD NEED TO ASSEMBLE THE ENGINE COMPLETELY ON THE GROUND AND THEN INSTALL IT IN THE TRUCK. THE CUSTOMER TOOK THE CLUTCH, FLYWHEEL, STARTER, RADIATOR AND ENGINE MOUNTS AND BOLTS AND SOME SENSORS AND SWITCHES THAT WERE NEEDED FROM THE TRUCK MANUFACTURE TO GET REPLACED OR RECONDITIONED. ONCE THE ENGINE BLOCK SHOWED UP WE STARTED INSTALLING COMPONENTS. THE FRONT AND REAR COVERS WERE CLEANED UP AND INSTALLED WITH NEW GASKETS, BOLTS, AND WASHERS. THE CAMBAFT AND GEAR WERE IN GOOD SHAPE AND WE WERE ABLE TO REUSE. CLEANED AND INSTALLED ALL THE GEAR TRAIN IN THE FRONT COVER AND TIMED ENGINE. INSTALLED OUTER FRONT COVER WITH NEW BOLTS, WASHERS, AND GASKET. INSTALLED NEW FRONT AND REAR MAIN CRANKSHAFT SEALS. DISASSEMBLED THE BRAKESAVER COMPLETELY, CLEANED EACH COMPONENT AND INSTALLED NEW MAIN SEALS, O-RINGS AND REGULAR SEALS. INSTALLED BRAKESAVER ON REAR ENGINE HOUSING WITH NEW BOLTS AND WASHERS. TINSTALLED BRAKESAVER ON REAR ENGINE HOUSING WITH NEW BOLTS AND WASHERS. INSTALLED OIL SEALS, TIN GASKET, SPACER PLATE AND TOP OIL SEALS ON CYLINDER BLOCK. CHECKED LINER PROJECTION AND EVERYTHING WAS IN CAT SPEC. CLEANED AND INSTALLED THE

- NOT RETURNABLE	PLEASE PAY THIS AMOUNT	CONT'D
ARE BACKORDERED	AMOUNT CREDITED	

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
INVOICE NUMBER LC00010 PLEASE PAY THIS AMOUNT AMOUNT	CONT'D
AMOUNT CREDITED	

	I INVOICE DATE	CUSTOMER NUMBER	CUSTOM	ER ORDER NUMBER	STORE	DIV.	SALESMAN	4 6
LC00010	11-05-19		MC	SHIP VIA	36			INV. SEO. NUMBER
The state of the s	09-28-19	10 10 SERIAL NUMB	10 ER	EQUIPMENT NUMBER		ER READIN	-	MACH. I.D. NUMBER
AA 3406E		02780	DESCRIPTION		UNIT PRICE	1		CTENSION
QUANTITY	11 676		FORMA INVOI	CE * * *				18 30 10 20 20 30 A

CAMSHAFT LIFTERS AS ALL OF THEM WERE ABLE TO BE REUSED WITH THE CAM. CLEANED NEW CYLINDER HEAD OF ANTI RUST INHIBITOR. CLEANED TOP OF SPACER PLATE AND INSTALLED CYLINDER HEAD ON ENGINE. AND TORQUED ALL HEAD BOLTS THAT DID NOT DEAL WITH THE JAKE BRAKES TO CAT SPEC. THE JAKE BRAKES WERE NOT ABLE TO CLEAN UP VERY WELL, DUE TO THE HEAVY RUST AND CORROSION ON THEM, AND WE RECOMMENDED GETTING NEW ONES. THE NEW JAKES CAME WITH NEW VALVE BASES AND EXHAUST VALVE BRIDGES. CLEANED OLD INTAKE VALVE BRIDGES AND INSTALLED THEM ON THE VALVES.

INSTALLED THE NEW EXHAUST VALVE BRIDGES AND SET INSTALLED THE NEW EXHAUST VALVE BRIDGES AND INSTALLED THE ROCKER ARM ASSEMBLIES AND FOUND 5 EXHAUST ROCKER ARMS TO BE UNUSABLE. ORDERED AND INSTALLED NEW ROCKER ARMS ON THE ROCKER ARM SHAFT. CLEANED AND INSTALLED THE ROCKER ARM ASSEMBLY ON THE CYLINDER HEAD. AND TORQUED THE LAST OF THE HEAD BOLTS TO CAT SPEC. WENT THROUGH AND RAN OVERHEAD ON ENGINE. CLEANED, PAINTED AND RESEALED THE LOWER VALVE COVER BASES AND TORQUED NEW BOLTS TO CAT SPEC. INSTALLED INSTALLED NEW INJECTOR NOZZLES WITH NEW SEALS AND INSTALLED NEW INJECTOR NOZZLES WITH NEW SEALS AND INSTALLED THE NEW JAKE BRAKES ON THE VALVE TRAIN AND TORQUED THEM TO SPEC. WENT THROUGH AND RAN OVERHEAD ON THE DAKE BRAKES ON THE VALVE TRAIN AND TORQUED THEM TO SPEC. WENT THROUGH AND RAN OVERHEAD ON THE JAKE BRAKE

\* - NOT RETURNABLE PLEASE PAY THIS AMOUNT CREDITED CONT ' D

CUSTOMER	R NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

	THE COOPER IN MAREN	STORE	DAA	SALESMAN	TEMMS	***
CUSTOMER NUMBER	MER ORDER NUMBER	36	T		4	-
HOVOICE MIMBER				AND DESCRIPTION OF THE PERSON	INV SEQ. N	JUMBER
LC00010 11-05-19 PC 1C MC	SHIP VIA	AND DESCRIPTION OF THE PARTY OF	100000000000000000000000000000000000000			1
DOC. DATE		- 40	TER READ	N/G	MACH LD	NUMBER
LC00010 09-28-19 10 10 10 LC00010 SERIAL NUMBER	EQUIPMENT NUMBER		12617	-		
MAKE MODEL 07YC02780		UNIT PRICE	1	the same of the sa	EXTENSION	
AA 3406B DIACOZIO	N	Ores Press	TO A STATE OF	NAME OF TAXABLE PARTY.		
	OICE * * *					ALCOHOLD STATE OF THE PARTY OF

RISERS ON THE LOWER VALVE COVER BASES AND TORQUED ALL NEW BOLTS AND WASHERS TO SPEC. INSTALLED JAKE BRAKE ACTUATOR WIRES AND CLEANED AND INSTALLED THE VALVE COVERS. RESEALED THE TIMING ADVANCE AND THE FUEL INJECTION PUMP AND INSTALLED THOSE ON THE FUEL LINES FROM THE PUMP TO THE HEAD WITH NEW CLIPS. DISASSEMBLED THE INTAKE MANIFOLD AND CLIPS. DISASSEMBLED THE INTAKE MANIFOLD AND CLIPS. DISASSEMBLED THE INTAKE MANIFOLD AND AFTERCOOLER. MULTIPLE BOLTS BROKE OFF INSIDE THE INTAKE MANIFOLD HOUSING THAT WE WERE NOT ABLE TO INTAKE MANIFOLD HOUSING THE HOUSING SEVERLY. AFTER FURTHER INSPECTION WE FOUND THE MANIFOLD HOUSING TO BE CRACKED ANYWAY. HAD TO ORDER NEW HOUSING ALONG WITH A NEW AFTERCOOLER AS WELL. ONCE THOSE PARTS ARRIVED WE ASSEMBLED THE WHOLE AFTERCOOLER AND MANIFOLD ASSEMBLY WITH NEW GASKETS AND O-RINGS. INSTALLED THE WHOLE ASSEMBLY ON THE CYLINDER HEAD WITH NEW BOLTS AND SPACERS. INSTALLED NEW WATER PUMP AND OIL COOLER ON RIGHT SIDE OF ENGINE. ALL ASSOCIATED COMPONENTS THAT WE WERE ABLE TO RE-USE WITH THE WATER PUMP, OIL COOLER AND AFTER COOLER LIKE TUBING AND FITTINGS WERE SANDBLASTED, BUFFED AND PAINTED BEFORE OR AFTER ASSEMBLY. THEY WERE THEN INSTALLED ON ENGINE BLOCK WITH NEW BOLTS, WASHERS, AND O-RINGS. INSTALLED ORIGINAL EXHAUST MANIFOLD ON CYLINDER HEAD WITH NEW STUDS, SPACERS, NUTS, AND GASKETS.

\* - NOT RETURNABLE PLEASE PAY
THIS AMOUNT CREDITED

\* - NOT RETURNABLE PLEASE PAY
THIS AMOUNT CREDITED

by us

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

INVOICE N	IMBER	INVOICE DA	TE	CUSTOMER NUMBER CUST			CUSTOM	R ORDER NUMBER		STORE	DIV.	SALESMAN	TERMS	PAGE
LC0001		11-05-								36	T	The state of the s	4	8
PSO/WO N	THE REAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN	DOC. DAT	-	PC	1.C	MC		SHIP VIA				CONTRACTOR DE	INV. SEQ. I	NUMBER
LC0001	The second second	09-28-		10	10	10					BANCON 100		Season Children	1
MAKE	THE RESERVE OF THE PERSON NAMED IN	DDEL		H CYCLONG	SERIAL NUN	ABER	NAME OF STREET	EQUIPMENT NUMI	BER		ER READIN	NAME AND ADDRESS OF TAXABLE PARTY.	MACH, I.D.	NUMBER
AA	3406B	SUPPLIES THE PROPERTY.	07X	C027	80					193	2617.			
QUANTITY	200	ITEM	they be	N/R	or a second	DES	CRIPTION	100000		UNIT PRICE			KTENSION	STATE OF THE PARTY.
COACTILITY		STATE OF THE		* * *	PR	OFORMA	INVO	CE * *	*					

INSTALLED NEW TURBOCHARGER ON EXHAUST MANIFOLD WITH NEW BOLTS, NUTS, AND GASKET. INSTALLED TURBO DRAIN LINE AND NEW SUPPLY LINE, ALL WITH NEW BOLTS AND WASHERS. PRE-LUBED THE TURBO BEFORE SUPPLY LINE WAS INSTALLED. ONCE THE CUSTOMER DROPPED OFF THE TRUCK OEM PARTS WE INSTALLED THE FLYWHEEL AND NEW CLUTCH WITH NEW BOLTS AND WASHERS AND TORQUED THEM TO GENERAL OEM TORQUE. LIFTED ENGINE OFF OF STAND AND INSTALLED NEW OIL PUMP WITH NEW BOLTS AND WASHERS. CLEANED AND INSTALLED BRAKESAVER TUBING, AND PICKUP TUBING WITH NEW BOLTS, WASHERS, AND O-RINGS. CLEANED AND INSTALLED OIL PAN, INSTALLED NEW GASKET AND INSTALLED OIL PAN ON ENGINE BLOCK WITH NEW BOLTS AND TORQUED EVERYTHING TO SPEC. CLEANED ALL EXTERNAL BRAKESAVER TUBING, VALVE AND COMPONENTS AND INSTALLED ON OIL PAN AND BRAKESAVER HOUSING WITH NEW BOLTS AND SEALS FOR EVERYTHING. GAVE THE ENGINE ONE LAST COAT OF PAINT FOR THE LARGER THINGS THAT WE DID NOT PAINT INDIVIDUALLY OR BEFORE WE INSTALLED THEM ON THE ENGINE. ONCE PAINT WAS DRY WE INSTALLED THEM ON THE ENGINE. ONCE PAINT WAS DRY WE INSTALLED THE AIR COMPRESSOR WITH ALL NEW LINES, AS THE OLD ONES WERE EITHER WEATHER CRACKED BADLY OR COMPLETELY UNUSABLE. INSTALLED CUSTOMERS NEW STARTER ON ENGINE WITH NEW BOLTS AND A GASKET. INSTALLED THE SPREADER BAR ON THE LIFT BRACKETS AND LIFTED ENGINE OVER TRUCK. INSTALLED A NEW CLUTCH BRAKE ON THE TRANSMISSION

+ - NOT RETURNABLE

ITEMS NOT SHOWN
ARE BACKORDERED

PLEASE PAY
THIS AMOUNT
AMOUNT
CREDITED

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

		CHETOM	ER NUMBER	-	USTOMER ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE
INVOICE NUMBER	10.0 1 (01.00.0. 10.1.1.2.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1	COSTOM	COSTOMERITY			36	T	PERMIT	4	9
LC00010	11-05-19				SHIP VIA		CONTRACTOR OF THE PERSON OF THE		INV. SEQ. NUMBER	
PSO/WO NUMBER	DOC. DATE	PC	LC	MC		A CONTRACTOR OF THE PARTY OF TH	No bests	117 (18 cm) (18 cm)	007109000	1
LC00010 09-28-19		10 10		10	The second second	METER READING		NG	MACH, LD. NUMBE	
	IODEL	EQUIPMENT NUMBER	1932617.0							
AA 34061		C027	80	OFFICE	PTION	UNIT PRICE	-	700 L	EXTENSION	
QUANTITY	ITEM	N/R	1000		INVOICE * * *					

INPUT SHAFT. IT TOOK AWHILE TO GET THE ANGLE OF
THE ENGINE JUST RIGHT TO SLIDE INTO THE ENGINE
MOUNTS AND THE TRANSMISSION INPUT SHAFT AT THE
SAME TIME. AFTER THE ENGINE WAS SITTING IN THE
TRUCK IT TOOK ABOUT 2 HOURS TO MOVE AND TWEAK THE
ENGINE TO GET ALL THE NEW MOUNTS, BOLTS, AND BOLT
HOLES TO LINE UP AND CINCH THE ENGINE DOWN INTO
PLACE. WE INSTALLED NEW BELL HOUSING BOLTS FOR THE
TRANSMISSION AND TORQUED EVERYTHING TO SPEC.
HOOKED UP THE WIRING HARNESS TO THE NEW SENSORS
CUSTOMER HAD GOTTEN, ALONG WITH ALL THE HOSES THE
BRAKESAVER, GAUGES IN THE CAB, FAN HUB.
ALTERNATOR, A/C COMPRESSOR, AIR COMPRESSOR,
STARTER WIRING, FUEL TRANSFER PUMP AND FUEL
INJECTION PUMP. INSTALLED FAN HUB ON ENGINE ALONG
WITH NEW BELTS AND ADJUSTED EVERYTHING TO SPEC.
INSTALLED THE NEW RADIATOR MOUNTS AND INSTALLED
THE RADIATOR PACK AND HOOKED UP ALL THE COOLANT
TUBES, HOSES AND LINES. FILLED THE COOLING SYSTEM
WITH BRAND NEW CAT ELC PER CUSTOMERS REQUEST.
CHANGED ALL FILTERS ON ENGINE, OIL AND FUEL.
REMOVED THE VALVE COVERS AND PRE-LUBED THE ENGINE
WITH 15W-40 ENGINE OIL. FILLED CRANKCASE TO SPEC
AND PRIMED THE FUEL SYSTEM. HOOKED UP THE
BATTERIES AND CRANKED ENGINE OVER A FEW DIFFERENT
TIMES TO GET THE OIL PRESSURE UP. BEFORE ENGINE
STARTED WE HAD 55 PSI OF OIL PRESSURE JUST FROM

DY U

NOT RETURNABLE

ITEMS NOT SHOWN

ARE BACKORDERED

PLEASE PAY
THIS AMOUNT
AMOUNT
CREDITED

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

INVOICE !	NUMBER	INVOICE DA	ATE	CUSTON	TER NUMBER		CUSTON	TER ORDER NUMBER		STORE	DIV.	TSALESMAN	TERMS	PAGE
LC0001	10	11-05-	19					ACCUSED BY THE REAL PROPERTY.		36	T	ar social rect	4	10
PSO/WO N	NUMBER	DOC. DAT		PC	LC	MC	A COLUMN	SHIP VIA	THE REAL PROPERTY.	W. W. Control of Control	SECULIAR STATE	The second second	INV. SEQ. I	Accessed to the latest
LC0001	.0	09-28-	19	10	10	10	101111111				1000000000		MY GEU.	1
MAKE	M	300			SERIAL NUM	MBER	7/(C) (S)(S)	EQUIPMENT NUM	REER	MET	ER READIN	0	MACH, LD.	MIMBER
AA	3406B		07X	C0278	0		~0700000				2617.		MACH, LD,	HUMBER
QUANTITY	Service Control	FTEM		NR		DES	CRIPTION		1000	UNIT PRICE		-	CTENSION	
					PR	OFORMA	INVO	ICE			NAME OF TAXABLE PARTY.	Miles and the later of the late	T. L.	

CRANKING. PRIMED THE FUEL SYSTEM THE REST OF THE WAY, CRACKING INJECTION LINES ON THE PUMP TO BLEED ALL AIR OUT. TRUCK FIRED RIGHT UP AND RAN WELL AND AS IT SHOULD. RAN ENGINE FOR ABOUT 5 MINUTES THEN OPERATED THE JAKE BRAKES AND THEY WORKED JUST LIKE THEY SHOULD ONCE THE AIR WAS BLED FROM THEIR OIL SYSTEM. RAN TRUCK FOR ABOUT ANOTHER 5 MINUTES WHILE CHECKING FOR LEAKS AND FOUND NONE. JACKED UP TRUCK AND INSTALLED THE FRONT WHEELS AND TIRES AND TORQUED THEM TO SPEC. CHECKED AND TOPPED OFF ALL OTHER FLUIDS. TRUCK WAS READY TO GET BACKED OUT OF THE SHOP BUT ONCE WE WENT TO MOVE IT THE CLUTCH BRAKE WOULD NOT SLOW DOWN OR STOP THE TRANSMISSION INPUT SHAFT SO WE COULD NOT GET TRUCK INTO GEAR. TRIED ADJUSTING THE CLUTCH IN BOTH DIRECTIONS AND NOTHING MADE A DIFFERENCE. THE CLUTCH WOULD NOT DISENGAGE AT ALL NOT MATTER ITS ADJUSTMENT POSITION. ENDED UP HAVING TO PULL THE TRANSMISSION BACK OUT OF TRUCK ALONG WITH THE

ADJUSTMENT POSITION. ENDED UP HAVING TO PULL THE TRANSMISSION BACK OUT OF TRUCK ALONG WITH THE DRIVESHAFTS, AND SHIFT TOWER. ONCE THE TRANSMISSION WAS OUT OF TRUCK WE REMOVED THE CLUTCH AND MADE SURE THAT IT WAS ASSEMBLED AND INSTALLED CORRECTLY WEICH IT WAS. AFTER LOOKING AT THE FLYWHEEL THERE WAS A DEEP GROOVE IN THE MACHINED FACE OF IT WHERE THE INTERNAL DISC SPRINGS AND LIPS HAD BEEN RIDING. AT THE TIME WE THOUGHT THE FLYWHEEL HAD BEEN MACHINED TOO FAR

\* - NOT RETURNABLE ITEMS NOT SHOWN ARE BACKORDERED

PLEASE PAY CONT'D THIS AMOUNT AMOUNT CREDITED

CUSTOME	R NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

					MER NUMBER	Town I al	CUSTOMER ORDER NUMBER			DIV.	SALESMAN	TERMS	PAGE
INVOICE N	UMBER	INVOICE DA		CUSTO	MER NUMBER					ula	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )	A	11
C0001	.0	11-05-	19	3					36	+		INV. SEO. NUMBE	
			LC	MC		SHIP VIA				INV. SECT HOMOEN			
GC0001	The second second	09-28-	19	10	10	10							1
COOLS OF THE PROPERTY AND ADDRESS OF THE PROPERTY ADDRESS OF THE PROPE		MBER.	BER EQUIPMENT NUMBER			TER READI		MACH, I.D. NUMBER					
AA	3406B 07XC02780								1932617.0				
UANTITY	The state of the s	ITEM	40 4 1	N/B	CONTRACTOR OF		CRIPTION		UNIT PRICE	_		XTENSION	
	Carried States				* PF	OFORM	A INVO	ICE * * *					

DOWN MAKING THE DISCS STAY ENGAGED ALL THE TIME.

WE ORDERED A NEW FLYWHEEL AND THAT CAME NEXT DAY
AIR. AFTER COMPARING THE FLYWHEELS THE NEWER ONE
HAD A LOT LARGER CENTER HOLE IN IT THAN THE
ORIGINAL DID, THE ORIGINAL FLYWHEEL DID NOT HAVE A
CENTER OPENING LARGE ENOUGH FOR THE STANDARD NEW
STYLE CLUTCH. WE INSTALLED THE NEW STYLE FLYWHEEL
ON THE CLUTCH AND WE HAD THE PROPER CLEARANCE FOR
THE CLUTCH NOW. INSTALLED THE NEW FLYWHEEL IN THE
BRAKESAVER AND TORQUED ALL THE BOLTS TO SPEC.
INSTALLED THE CLUTCH BACK ON THE FLYWHEEL AND
TORQUE THOSE BOLTS TO SPEC. WE INSTALLED THE
TRANSMISSION TO THE ENGINE AGAIN AND TORQUED ALL
THE THE MOUNTING BOLTS TO SPEC. INSTALLED THE
DRIVESHAFTS BACK IN TRUCK AND TORQUED BOLTS TO OEM
SPEC. DURING THE SHIFT TOWER INSTALLATION IT WAS
FOUND THAT THE TOP SECTION OF THE CASTING FOR THE
SHIFT TOWER WAS CRACKED ABOUT HALFWAY AROUND. WE
TRIED TO BE EXTREMELY CAREFUL DURING THE
INSTALLATION PROCESS TO NOT BREAK THE CASTING EVEN
FURTHER. BUT WHILE TRYING TO TIGHTEN THE MOUNTING
BOLTS DOWN THE TOP PART OF THE CASTING BROKE THE
REST OF THE WAY AND POPPED THE SHIFTING ROD OUT
OF THE TOWER. A NEW SHIFTING TOWER WAS ORDERED
PROM THE TRUCK MANUFACTURER WITH NEW GASKET. IN
ORDER TO REMOVE THE SHIFTER FROM THE CAB THE SEATS
HAD TO BE TAKKN OUT DUE TO THE LOCATION OF THE

* - NOT RETURNABLE	PLEASE PAY THIS AMOUNT	CONT'D
ARE BACKORDERED	AMOUNT CREDITED	

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

LC0001	0	11-05-		COSTOR	MER NUMBER		CUSTOMER ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE	
PSO/WO NO		DOC. DAT	THE RESERVE	PC	I LC	MC		36	T		4	12	
LC0001		09-28-	19	10	10	10	SHIP VIA		MEDICAL PROPERTY.		INV. SEQ. N	UMBER	
MAKE		DDEL	2	10000	SERIAL NUM	ASSESSMENT OF THE PARTY OF THE	Enturbalist Autonom			THE REAL PROPERTY.		1	
AA	3406B	A STATE OF THE PARTY OF THE PAR	07X	C0278			EQUIPMENT NUMBER	The state of the s			MACH, I.D. NUMBER		
QUANTITY	A GARLES IN	ITEM	gine	N/R	4.00	Dree		1932	2617.	0		TO THE LAND	
				* * *		FORMA	PTION * * *	UNIT PRICE	SECTION SECTION	EX	TENSION	No. of Contract	

TRIM PIECES THAT HAD TO BE TAKEN OUT TO GET TO THE SHIFTER BOOT AND MOUNTING RING IN THE FLOORBOARD. ONCE THE SIFTER AND ASSOCIATED PIECES WERE REMOVED FROM THE TRANSMISSION AND CAB WE ASSEMBLED ALL THE NEW PARTS AND COMPONENTS ON A TABLE THEN RE-INSTALLED THEM IN THE CAB AND ON THE TRANSMISSION. ASSEMBLED THE INTERIOR BACK TOGETHER AND ADJUSTED THE CLUTCH TO THE PROPER SETTING ALONG WITH THE CLUTCH LINKAGE. STARTED TRUCK AND MADE SURE THE CLUTCH WAS WORKING AS IT SHOULD AND IT WAS. AIRED UP TRUCK AND MADE SURE THE TRANSMISSION SPLITER WAS WORKING AS IT SHOULD AND IT WAS. BACKED TRUCK OUTSIDE AND SET IT AT HIGH IDLE. MADE SURE ALL GAUGES THAT WERE WORKING BEFORE THE REPAIR WERE STILL WORKING AS THEY SHOULD AND THEY WERE. RAN TRUCK AT HIGH IDLE FOR ABOUT AN HOUR AND A HALF. ENGINE TEMP GOT TO 205 DEGREES AND OPENED THE THERMOSTAT. CAME OUT EVERY TEN MINUTES OR SO TO CHECK FOR LEAKS AND TO LISTEN FOR ANY WEIRD NOISES. THERE WERE NONE OF EACH. ENGINE RAN GOOD AND SOUNDED GOOD. DROVE TRUCK BACK INTO SHOP AND LET IT SIT OVER NIGHT. THE NEXT MORNING I CHECKED ALL FLUID LEVELS AGAIN AND THEY WERE ALL GOOD. TOOK TRUCK FOR A TEST DRIVE AND MONITORED THE GAUGES. EVERYTHING ACTED FINE AND OPERATED AS IT SHOULD FOR A 40 YEAR OLD TRUCK. TRUCK IS READY FOR CUSTOMER PICKUP.

* - NOT RETURNABLE ITEMS NOT SHOWN	PLEASE PAY THIS AMOUNT	CONT'D
ARE BACKORDERED	AMOUNT CREDITED	French Committee

CUSTOME	R NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

INVOICE N	JMBER	INVOICE DAT	TE W	CHETOM	ED MIMBED	Control of the Control	CUSTOME	R ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE
LC0001	0	11-05-	19		2				36	T	N PROPERTY.	4	13
PSO/WO N	JMBER	DOC. DATE		PC	LC	MC		SHIP VIA	PART BARRIES	-	AND DESCRIPTION OF THE PERSON NAMED IN	INV. SEQ.	NUMBER
LC0001	0	09-28-	19	10	10	10				- 275	SHOWING IN		1
MAKE	M	ODEL			SERIAL NUM	BER	BER EQUIPMENT NUMBER			METER READING		MACH, I.D. NUMBER	
AA	3406B		07X	C027	80		THE REAL PROPERTY.		193	32617	.0		
QUANTITY	1900	ITEM	200	N/R		DES	CRIPTION		UNIT PRICE			XTENSION	
	1303 S. S. S.				PR	OFORMA	INVO	ICE * * *	·//	100000	N. D. Allenda		

CONTINGENT DAMAGE:
COMPLICATION: FINDING PARTS THAT WERE CORRECT FOR
A WATER AFTER COOLED 3406B MODEL WITH A BRAKE
SAVER WAS EXTRA CHALLENGING DUE TO THE FACT THAT
THERE WAS ONLY A SELECT NUMBER OF PARTS OUT THERE
FOR THESE AND WE HAD TO WAIT EXTRA TIME TO RECEIVE
THESE PARTS. ALMOST EVERY PART WE TOUCHED OR
TRIED TO TAKE OFF OF THE OLD ENGINE EITHER BROKE
OR BROKE THE BOLTS OFF IN THE ENGINE OR IN THE OLD
COMPONENT. SO WE SPENT TIME EITHER TRYING TO GET
BROKEN BOLTS OUT OF COMPONENTS OR SPENDING TIME
TRYING TO LOOK UP THE NEW COMPONENT AND SEEING IF
WE COULD EVEN GET THE PART OR THE COMPONENT. OF
COURSE THERE WAS WAIT TIME ON A LOT OF THESE PARTS
ALSO. THEN ONCE WE GOT THE ENGINE PUT TOCETHER
FINALLY AND IN THE TRUCK, THROUGH NO-FAULT-OF-OUR,
OR THE CUSTOMERS OWN, THE ORIGINAL FLYWHEEL DID
NOT MATCH UP TO THE MODERN DAY CLUTCHES. SO THERE
WAS EXTRA COST OF REMOVING THE TRANSMISSION A
SECOND TIME AND REMOVING THE TRANSMISSION A
SECOND TIME AND REMOVING THE CLUTCH AND OLD
FLYWHEEL TO INSTALLED THE NEW FLYWHEEL THAT
MATCHED THE NEW CLUTCH. ANOTHER COMPLICATION WAS
THE SHIFT TOWER BREAKING AND AFTER ALL SAID AND
DONE WE HAD TO RIP OUT HALF OF THE INTERIOR TO
CHANGE THE SHIFTER TOWER AFTER IT HAD BROKE ON THE
TRANSMISSION. WHAT ALSO TOOK A LOT OF TIME WAS
DUE TO THE FACT THAT EVERY PART WAS VERY RUSTY OR

- NOT RETURNABLE TEMS NOT SHOWN THE BACKORDERED	PLEASE PAY THIS AMOUNT	CONT'D
	AMOUNT CREDITED	

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

INVOICE		INVOICE DATE	CUSTON	MER NUMBER	1000000	CUSTOMER ORDER NUMBER	36	T DIV.	SALESMAN	TERMS 4	PAG 14
LC0001		11-05-19	9	1	***	SHIP VIA	130	1		INV. SEQ. I	_
PSO/WO N		DOC. DATE	PC PC	IC I	MC	SHIP VIA		Control of the last		MV. SEC.	7
LC0001	10	09-28-19	10	10	10	EQUIPMENT NUMBER	1	CO DEADIN	-	MACH, LD.	MIMBE
MAKE		ODEL		SERIAL NUM	MER	EQUIPMENT NUMBER		2617.		MACH, 1.D.	HOME
AA	3406B	073	XC0278	30				2011.	CONTRACTOR OF THE PARTY OF THE	XTENSION	
VITTANUE	2725 4	ITEM	N/R	A CONTRACTOR		INVOICE * * *	UNIT PRICE			ATUNSION	
SAND RUSTI SURFA 1 1 1 1 1 6 6 6 1 1 1 1 1 1 1 1 1 1 1	BLAST,		CAF CAF CAF CAF CAF CAF CAF COR FUL NOZ COR FUL	FO KEEP	O-RIN O-RIN IN.	OM	PLEA	SE PAY			
						- nor meromente		MOUNT	(	CONT'D	
					_		TITIO P		the same of the sa		
						ITEMS NOT SHOWN		CLINIT	COLUMN TO SERVICE AND ADDRESS OF THE PARTY O	A PERSONAL PROPERTY.	
					- 1	ARE BACKORDERED		OUNT	1		

CUSTOME	R NUMBER				
INVOICE NUMBER	INVOICE DATE				
LC00010	11-05-19				
PLEASE PAY THIS AMOUNT	CONT'D				
AMOUNT CREDITED					

PAGE STORE DIV. SALESMAN TERMS CUSTOMER ORDER NUMBER 15 4 CUSTOMER NUMBER 36 T INVOICE DATE INV. SEQ. NUMBER INVOICE NUMBER 11-05-19 SHIP VIA LC00010 DOC. DATE 09-28-19 METER READING 1932617.0 MACH, I.D. NUMBER PSO/WO NUMBER 10 10 **EQUIPMENT NUMBER** SERIAL NUMBER EXTENSION MODEL 07XC02780 UNIT PRICE MAKE DESCRIPTION 3406B AA PROFORMA INVOICE N/R ITEM QUANTITY CORE CHARGE FULL CORE PUMP GP OIL CORE CHARGE N 11112936 STORESTA OR-9697 FULL CORE CAP SCREW 0S-1585 0S-1587 0S-1588 0S-1590 CAP SCREW SCREW SCREW CAP SCREW 08-1594 08-1595 08-1608 SCREW 16462212 SCREW CAPSCREW 0T-0055 0T-0573 1A-2029 CAP SCREW CAPSCREW CAPSCREW 1A-2029 1A-5822 1A-5964 1B-8705 1B-9575 1D-4503 CAPSCREW KEY CAPSCREW 8 CAPSCREW BOLT NUT 1F-7958 1H-9696 1J-9671 421 RING SEAL O RING S NUT 1K-6872 1N-3523 1R-0716 N HOSE A S FILTER PLEASE PAY CONT'D \* - NOT RETURNABLE THIS AMOUNT ITEMS NOT SHOWN AMOUNT ARE BACKORDERED CREDITED

CATERPILLAR DEALER

\*\* Thank You For Your Business \*\*

by L

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

	NUMBER	INVOICE DATE	CUSTO	MER NUMBE	Re Part of C	USTOMER ORDER NUMBER	140 1415	STORE	DIV.	SALESMAN	TERMS	PAG
LC0001	The same of the sa	11-05-19					BI GAR	36	T	- CONTRACTOR OF THE PARTY OF TH	4	16
PSO/WO P		DOC. DATE	PC	1C	MG	SHIP VIA	100	The state of the last of the l		400	INV. SEO.	-
LC0001	-	09-28-19	10	10	10				A PERSONAL		mer. acu.	T
MAKE		DODEL		SERIAL NU	MBER	EQUIPMENT NUM	BER	MET	ER READIN	10	MACH. I.D.	PA SPACE
AA	3406B	THE R. LEWIS CO., LANSING, MICH.	KC0278	80			States a		2617.		MACH. I.D.	NUMBER
PYTITINAUC	10 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	ITEM SEE	N/R	1	DESCRI	MOTTO		UNIT PRICE			XTENSION	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1R-1712 1S-0004 1S-4290 1S-4290 1S-6595 1S-9544 1W-1898 1W-1898 1W-9168 1W-	12 22 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	GAS	SKET NG-SEAN RE A AMP LMP KET T T HER L O RI TING T K NUT MP	ING	S S S S S S S S S S S S S S S S S S S		DIEA	SE PAY			
						- NOT HETOMANDLE			MOUNT	(	CONT'D	
						ITEMS NOT SHOWN				-		
					100	ARE BACKORDERED		CREE	TAUC	MANAGE STATES		

CUSTOMER NUMBER								
INVOICE NUMBER	INVOICE DATE							
LC00010	11-05-19							
PLEASE PAY THIS AMOUNT	CONT'D							
AMOUNT CREDITED								

INVOICE N	UMBER	INVOICE DAT	E	CHSTOM	FR NUMBER	189.00 %	CUSTOMER ORDER NUMBER	-	STORE	DIV.	SALESMAN	TERMS	PAGE 17
LC0001		11-05-1		7	100				36	T		4	-
PSO/WO N	UMBER	DOC. DATE		PC	LC	MC	SHIP VI					INV. SEQ. I	T T
LC0001	0	09-28-1		10	10	10							1
MAKE.		ODEL	9568	4937960	SERIAL NUM	BER	EQUIPMENT NU	MBER		TER READI		MACH. I.D.	NUMBER
AA	3406E		07X	C0278	30	MATERIAL CO			THE RESERVE OF THE PARTY OF THE	2617			
QUANTITY	3403E	ПЕМ		N/R	PARAGE.		INVOICE *		UNIT PRICE			XTENSION	
40 11 11 18 61 12 46 82 18 21 11 11 22 14 21 11	2P-320: 2S-377: 2S-616 2W-045 3B-191 3B-474 3D-289 3J-735 3J-735 3J-735 3J-735 4F-738 4F-738 4J-858 4L-771 4M-836 4N-069 4N-09: 4N-11: 4N-11:	00 00 95 55 4 88 22 7 4 6 3 4 7 7 10 10 10 10 10 10 10 10 10 10 10 10 10		GAC BLC STEER STEE	ACER SHER SHER SKET OCKWASH IPPLE EAL O F EAL	EING EING EING RING RING RING RING		NAME .		PLEASE	PAY		
						NOT CIAL	- NOT RETUR	NABLE		THIS AN		CON	T'D
							ITEMS NOT SH	OWN					
							ARE BACKORD			CRED			

CUSTOMER	NUMBER			
INVOICE NUMBER	INVOICE DATE			
LC00010	11-05-19			
PLEASE PAY THIS AMOUNT	CONT'D			
AMOUNT				

NA POLOT N		INVOICE DATE	CUSTO	MER NUMBER	13000	CUSTOMER ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	18
INVOICE N		11-05-19	1	100	1		36	T		4	
C0001		DOC. DATE	PC	LC	MG	SHIP VIA				INV. SEQ. I	1 T
PSO/WO N		09-28-19	10	10	10						T
GC0001			-	SERIAL NUM	BER	EQUIPMENT NUMBER		ER READIN		MACH. I.D.	NUMBER
MAKE		DOEL 07X	C027				193	2617.			
AA	3406B	ITEM .	N/R		DESCR	TIPTION	UNIT PRICE		E	XTENSION	
11 11 11 11 11 11 11 11 11 11 11 11 11	4N-1292 4N-1797 4N-4188 4N-4688 4N-9008 4N-		AD GA BRO HOO GA SEE SEE SEE SEE SEE SEE SEE SEE SEE SE	CK APTER J SKET EATHER SE A SE SE SKET AL GP UD AL SKET AL G AL	NG K	INVOICE * * * *		ACE BA			
						+ - NOT RETURNABLE		ASE PA'		CONT'I	)
					100	ITEMS NOT SHOWN	100		100	-	TO THE PARTY
					- 8	ARE BACKORDERED	An	TAUON	THE RESERVE		

CUSTOMER NUMBER								
INVOICE NUMBER	INVOICE DATE							
LC00010	11-05-19							
PLEASE PAY THIS AMOUNT	CONT'D							
AMOUNT CREDITED								

INVOICE		INVOICE DATE	CUSTOM	ER NUMBER	C. C. Service C.	USTOMER ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE
LC0001	1.0	11-05-19		10.24			36	T		4	19
PSO/WO I		DOC. DATE	PC	LC	MC	SHIP VIA	A CONTRACTOR OF THE PARTY OF TH	The House	100000	INV. SEQ. N	-
LC0001	10	09-28-19	10	10	10	A STATE OF THE STA		100000000000000000000000000000000000000	THE RESERVE	33502000	1
MAKE	M	ODEL	160000	SERIAL NUM	BER	EQUIPMENT NUMBER		ER READIN		MACH. I.D.	NUMBER
AA	3406B		C0278	80				2617.		100000000000000000000000000000000000000	ESPERIT
QUANTITY	34, 23	пем при	N/R	2000	DESCRI	PTION	UNIT PRICE	1 2 2		CTENSION	15/2 1/2/2
35211112162111424221211122512	5P-8068 5P-8248 5F-4718 6F-6672 6I-3066 6J-2248 6L-7283 6L-7442 6L-9588 6V-8523 6V-8801 7C-0033 7F-881 7J-0206 7W-0688 7W-344 7W-573 7W-573 7W-7W-898 8M-439	5 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	WA SE SE SE SE SE SE SE SE SE SE SE SE SE	EAL OR EA	EAD ING ING ING						
					l.	* - NOT RETURNABLE		LEASE P	ACCOUNTS OF THE PARTY OF THE PA	CONT	·D
					- 1	ITEMS NOT SHOWN	TH	HIS AMO	UNI	COMI	D
						ARE BACKORDERED		AMOUN	IT		

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

LC000		11-05-19	100	MER NUMBER		CUSTOM	R ORDER NUMBER	STORE 36	DIV.	BALESMAN	TERMS	P/
LC0001		09-28-19	10	10	10	li l	SHIP VIA		4.36.36.	STOREST OF	INV. BEQ. I	2 NUMBE
MAKE AA	3406B	O7X	C0271	SERIAL NUI			EQUIPMENT NUMBER	193	ER READING	0	MACH. I.D.	NUMB
av-settit.		The second name of the second	N/R	DP	OFORMA	INVOI	CE · · ·	UNIT PRICE	SANS DESIGNATION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS	THE OWNER WHEN PERSONS NAMED IN	CTENSION	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	8M-4443 8M-4447 8M-4791 8M-8157 8M-8157 8M-8098 8S-9191 3T-4224 7F-8999 0G-6655 0H-6067 0H-8260 L-1557 L-1633 L-6643 L-6910 L-7712 L-9814 M-1974 M-2904 M-3786 M-4584 M-4584 M-4584 M-4582	Control of the contro	SEL WAS SEA SEA SEA VEE GAS NUT WASI CLAN SEAN SEAN SEAN SEAN SEAN SEAN SEAN SE	SHER SKET AL O RI SING- ST SHER OF SCREW MENT A L T SET KET L HER MP O RII NECTOR NECTOR O RII	ING	Zamanamazanzanzanamazanz						
						ITEMS	NOT SHOWN ACKORDERED	PLEAS THIS AI	TAUON	C	ONT'D	

CUSTOME	R NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT CREDITED	

LC0001	LO	11-05-1		ER NUMBER		COSTOME	R ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE
PSO/WO N	NUMBER	DOG, DATE		LC	MC	T	SHIP VIA	36	T		4	21
LC0001	0	09-28-1		10	10		300 Y 105		-		INV. SEQ. N	NUMBER
MAKE		DOEL		SERIAL NUM	-		EQUIPMENT NUMBER	-	TER READI	WO.	*****	1
AA	3406B	THE RESERVE AND ADDRESS OF THE PARTY OF THE	7XC0278	10				THE REAL PROPERTY.	32617		MACH. I.D.	NUMBER
ONVILLA	1	ITEM	N/M	alaska a		CRIPTION		UNIT PRICE		THE RESERVE AND ADDRESS OF THE PARTY OF THE	CTENSION	
1112121321411611121883111	9M-7002 9M-9647 9N-5253 9N-5279 9S-8752 9Y-6089 106-400 108-560 109-007 129-218 129-305 124-197 129-345 131-712 142-586 148-746 149-526 159-302 165-392 165-393 165-914 175-294 185-283	3 4 3 3 8 3 1 9 2 3 7 0 8 1 9 1 0 2 6 6 9	SEACON HOSE SEACON SEAC	AL O RAL O R	ING ING ING EGRL KIT CSHP ERLO HEA							
						ITI	- NOT RETURNABLE EMS NOT SHOWN RE BACKORDERED	TH	LEASE PA	UNT	CONT	D

CUSTOMER	NUMBER				
INVOICE NUMBER	INVOICE DATE				
LC00010	11-05-19				
PLEASE PAY THIS AMOUNT	CONT'D				
AMOUNT CREDITED					

Sold To:

Ship To:

INVOICE NUM	WBER	INVOICE DATE	CUSTOM	ER NUMBER	C	CUSTOMER OR	DER NUMBER	STORE	DIV.	SALESMAN	TERMS	PAGE
GC00010		11-05-19						36	T		4	23
PSO/WO NUM		DOC. DATE	PC	LC	MC		SHIP VIA		3.0		INV. SEQ. N	UMBER 1
C00010		09-28-19	10	10	10					-	*******	T
MAKE	MO	DEL		SERIAL NUN	MBER	EC	DUIPMENT NUMBER		2617		MACH. I.D.	HUMBEN
AA	3406B	07	XC0278	80					2011		er cure to the	
VITTABUC		ITEM	N/R	W	OFORMA	The second second	* * *	UNET PRICE		-	XTENSION	
1.00	RRANTY	PURCHASE	- 44	SEGM OPT F	ESC MISC C	TOTAL	SEG. 96					
APPLY D	ISCOUN	T										
1.00	_			OPT I	ESC							
1.00			11.770	TOTAL	MISC	CHGS	SEG. 97		7. T			
				TOTAL	Larre (			. ,			100	
		and and		SEG	MENT 97	TOTAL					599	
			La Carret					10 2 to				
									45066			_
			3 7						FAOF	av I		100-0
	100000000000000000000000000000000000000					* - NC	T RETURNABLE	CONTRACTOR DESCRIPTION OF THE PARTY OF THE P	EASE P	Contraction of the last of the	CONT'	D
						ITEMA	NOT SHOWN	THI	S AMOL	JIVI	201.1	
						ARE B	ACKORDERED	MINOR DESCRIPTION OF THE PARTY	AMOUN	Carlo State of the Control of the Co		

\*\* Thank You For Your Business \*\*

CUSTOMER	NUMBER
INVOICE NUMBER	INVOICE DATE
LC00010	11-05-19
PLEASE PAY THIS AMOUNT	CONT'D
AMOUNT	

AMOUNT CREDITED

INVOICE N	NUMBER	INVOICE DA	ne cu	STOMER NUMBER	4. 计设备的设	CUSTOMER	ORDER NUMBER	STORE	DIV.	SALESMAN	TERMS 4	PAGE 22
LC0001		11-05-	19					36	I		INV. SEQ. I	Accessed to the last of
PSO/WO N		DOC. DATE	E	PC LC	MC		SHIP VIA		Total Carlot		MY, SELL	1
LC0001		09-28-	19   1	0 10	10			-	TER READI	100	MACH, I.D.	NUMBER
MAKE	MC	DDEL	100	SERIAL NUI	MBER	-	EQUIPMENT NUMBER		2617		HOTOTT, T.O.	120
AA	3406B		07XC0					UNIT PRICE	2011		CLENSION	SEEDING
OUANTITY	Salvanii Yen	ITTEM	N/I		OFORMA	RIPTION	172 + + +	OTET PRICE	Mark Inches			5626580
111111111111111111111111111111111111111	191-794 191-794 191-794 191-794 191-794 20R-626 20R-626 238-864 247-713 305-684 352-020 428-880 456-856 458-958 103373 38364	2 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		OUTS	FUEL FUEL FUEL FUEL FUEL FOR FUEL FOR FUEL FUEL FUEL FUEL FUEL FUEL FUEL FUEL	SKAS TS TS IGHT	SEG. 01 F/R LBF					
17.0					BENEFIT OF STREET	-	The state of the s	P	LEASE F	YAY		
17.0				4 200		ITE	MOT RETURNABLE MIS NOT SHOWN E BACKONDERED	P. Co. L. Commission	AMOUN	TAUNT	CONT	''D

CUSTOMER	NUMBER			
INVOICE NUMBER	INVOICE DATE			
LC00010	11-05-19			
PLEASE PAY THIS AMOUNT	CONTID			
AMOUNT CREDITED				