| R/O Open Date | R/O Number | | | |
|-------------------------------|-----------------|--|--|--|
| 06/20/22 | 6030225/1 | | | |
| R/O Close Date | Status | | | |
| 06/24/22 | Pre-Invoice | | | |
| Mileage In | Mileage Out | | | |
| 123022 | 123022 | | | |
| Service Advisor / Tag # | | | | |
| | | | | |
| Vehicle Identification Number | | | | |
| 1GTV2MEC0GZ298663 | | | | |
| Delivery Date | In-Service Date | | | |
| 06/30/16 | 06/30/16 | | | |
| Color | License Number | | | |
| CTTTTPD | 1DVTT7142 | | | |

 Year
 Make
 Model
 Color
 License Number

 2016
 GMC
 SIERRA
 DOUBLE CA
 SILVER
 UNIT142

#1 - 021: TRANSMISSION C/S: CUST STATES AT HIGHWAY SPEEDS WHEN PASSING IT FEELS LIKE IT GOES INTO NATURAL Caused by went thru diag found codep0741 went thru diag found that the transmission has internal failure would reco a new replacement trans most likely cause of failure is torque converter and pump and clutches Tech: ARLAN GRIM (100)Installed 19431764 : R-REMANUFACTURED TRANSMISSION Installed 15035747 :SL-N-SEAL (03611-CT) Installed 15077362 :SL-N-SEAL (03611-CT) Installed 86816628 :SL-N-GASKET (04515-CT) Installed 23135703 :SL-N-SEAL (04128-BCKT) Installed SYNATF : SYNTHETIC R&R and replaced transmission and flushed cooler code bbdce16 new trans number is 17cka722123035 programmed transmission code 0syn116025119 performed test drive all okay at this time Sub Total: 5058.42 #2 - 031: WORLD CLASS INSPECTION MULTI-POINT INSPECTION (100)Tech: 2

Scheduled Start Date: Actual Start Date:

Expected Completion Date: Actual Completion Date:

Duration:

Repair Priority Class:

Status:

Issued By: Assigned to:

Vendor:

Labels:

Tue, Aug 29, 2023

Tue, Aug 29, 2023

Scheduled

Completed

VIN/SN: License Plate:

Operator:

Group:

1GTV2MEC0GZ298663

4235AFV

N/A

Truck Type:

*OUTSIDE PLANT

Odometer:

139,908mi

LINE ITEMS

Item




Battery Replacement Replaced old battery.

H7AGM (Part) Battery

DESCRIPTION

Total

\$245.37



| | duled Start Date: al Start Date: | Wed, Feb 28, 2024 | VIN/SN: License Plate: | 1GTV2MEC0GZ298663 4235AFV |
|----------------|---|--|------------------------------|------------------------------|
| | eted Completion Date: al Completion Date: ion: | Fri, Mar 1, 2024 2 days | Operator: Type: Group: | Truck *OUTSIDE PLANT |
| Repai | ir Priority Class: | N/A | Odometer: | 145,650mi |
| Statu | s: | Completed | | |
| Issue Assig | d By: ined to: | | | |
| Vend | or: | | | |
| Label | s: ITEMS | | | |
| Item | 1 | | | |
| * | Oil Leak Oil Leak Found Found Transmission lines 85585332 (Part) Trans cooler lines | leaking, replaced and test, ok at th | is time. | |
| 4 | Radiator Inspect has birds packed in grill. Ck | eaned out radiator. | | |
| 4 | dve and found condenser leak | ngaging. Found a/c system emp ing at welds, replaced condense lter to restore air flow in cab test a | r, Schrader valves | |
| | 2230129 (Part) Cabin Air filter | | | |
| | 801797 (Part) Schrader Valve Kit | | | |
| | 4283A (Part) condenser | | | |
| | | | | |

2016 GMC Sierra 1500

111,1 00 2, 2021

11:59 AM



10:09 AM Scheduled Start Date: Actual Start Date: Expected Completion Date: Actual Completion Date:

Mon, Jun 19, 20238:00 AM

Tue, Jun 20, 20231:30 PM 1 day 5 hrs 30 mins

Non-Scheduled

Completed

Status: Issued By: Assigned to:

Vendor: Labels:

Repair Priority Class:

Duration:

2016 GMC Sierra 1500

1GTV2MEC0GZ298663 VIN/SN: 4235AFV License Plate:

N/A Operator:

Truck Type:

*OUTSIDE PLANT Group:

Odometer: 139,417mi

LINE ITEMS

Item

Front Suspension Ball Joint Replacement Found upper and lower ball joints wom and have major play, Replaced ball Joints and upper control arms. Had aligned, test, ok at this time.

2601882 (Part) Lower Ball Joint

2608755 (Part) Lower ball joint

2608237 (Part) Upper Left Control Arm

2608236 (Part) Upper Right Control Arm



6205/55183

PO Number:

WORK ORDER DETAILS

Issue Date:

Wed, Jun 15, 2022

10:14 AM

5 days

Completed

N/A

142

2016 GMC Sierra 1500

Scheduled Start Date:

Actual Start Date:

Wed, Jun 15, 2022

VIN/SN:

1GTV2MEC0GZ298663

Expected Completion Date:

Actual Completion Date:

Repair Priority Class:

Mon, Jun 20, 2022

License Plate:

4235AFV

Operator:

Type:

Truck

Group:

*OUTSIDE PLANT

Odometer:

122,972mi

Status:

Duration:

Issued By:

Assigned to:

Vendor:

Labels:

LINE ITEMS

Item

Transmission Assembly Replacement

DESCRIPTION

Total

\$5,538.38

