

9/7/2023 2:00:49 PM CDT

Repair Order #26277

Page:1

Vehicle : 2005 Freightliner M2-106 8.8 L 538 CID L6 Caterpillar C9 Diesel

VIN : 1FVHCYDA55HU22855

Fleet #/Driver :

Created : 6/21/2023 3:56:03 PM CDT

Completed : 9/7/2023 2:00:17 PM

Service Writer : 3

Tag/State : /MO

Odometer In : 342069

Odometer Out : 342069

EN - RED SEP 18 2023

Labor/Notes

Technician
7

Description
labor

Price

TOWED IN, TRANS WONT MOVE WHEN HOT
Installed transmission and flushed cooler filled with new fluid and retested. Transmission shifts ok. Engine cuts out and misses on take from a stop. Worse hot. The speedometer is inaccurate reading slow. And repeat code in transmission module for service brake sensor signal staying on. Perform pinpoint test, found open circuit to speed sensor circuit, locate and repair broken wire, retest. fixed trans problems. check fuel pressure, losing pressure, replace fuel filters, check check valve in head, found fuel injectors bypassing to much fuel , replace all six fuel injectors, program to truck

Unable to change programming for speedometer.

Parts

| Qty | Code | Description | Condition | Unit Price | Price |
|-----|------|----------------------|-----------|------------|-------|
| 1 | | FUEL FILTER | | | |
| 1 | | FUEL FILTER | | | |
| 1 | | Allison Transmission | | | |
| 26 | | SYNTHIC FLUID | | | |
| 1 | | REGULATOR | | | |
| 1 | | ORING | | | |
| 6 | | INJECTOR | | | |

Labor

Parts

Shop Supplies

Sales Tax

Repair Total

PAYMENT

BALANCE DUE

\$16,299.38

Technician Code

Certification #

7

Approvals

Date & Time

Total Amount

Authorized By

Method

Employee

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.