

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG	
SILVER	17	CHEVROLET SILVERADO	3GCUKNEC7HG419207		88533/88533		
DEL. DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE

R.O. OPENED      READY      OPTIONS:      ENG: 5.3 LITER

9:47 17JUL24      08:55 01AUG24

ONE OPCODE TECH TYPE HOURS	LIST	NET	TOTAL
----------------------------	------	-----	-------

ENGINE WILL OVERHEAT ON HARD ACCEL--WORSE WHEN GOING 100+ TO CATCH UP TO ANOTHER VEHICLE

3200 ENGINE

905 C

- 1 12619770 1079CKT (S)GASKET
- 2 12346290 8800BOPCKT COOLANT
- 1 12674639 1073CT (S)OUTLET
- 2 12622325 0289CT (S)GASKET
- 15 11546959 0293CKT (S)BOLT
- 1 11611976 0293CKT (S)BOLT
- 2 12619787 0423CKT (S)GASKET
- 6 12626354 3270CT (S)GASKET
- 1 12677004 3163CT (S)PIPE
- 2 12657093 3270CKT (S)GASKET
- 1 15077342 3611CT (S)SEAL
- 1 15035747 3611CT (S)SEAL
- 1 12677002 3163CT (S)PIPE
- 8 88865698 8800BOPCK OIL
- 1 12737081 1836BOPCKT (S)FILTER
- 2 12346290 8800BOPCKT COOLANT
- 2 12699616 0269CT HEAD
- 2 19432442 3331CKT (S)SEAL KIT

BEARS MACHINE INV 18393

TEST DROVE, COULD ACCEL AND ENGINE WOULD HEAT UP TO 240 DEGREES AND ONCE BACK TO STEADY SPEED WOULD COOL QUICKLY. COOLING FANS WERE OK. VERIFIED NO DEBRIS IN RADIATOR OR CONDENSER. REMOVED WATER PUMP AND INSPECTED IMPELLER-OK. REPLACED THERMOSTAT DUE TO AFTERMARKET PART. TEST DROVE AGAIN, DIDN'T GET AS HOT BUT WOULD CHANGE QUICKLY WITH LOAD AND LOAD CHANGES. TESTED FOR COMBUSTION GAS IN COOLANT RESERVOIR--HAVE BUBBLES AND CHANGE IN COLOR TO BLOCK TESTER FLUID. REMOVED HEAD CYLINDER HEADS AND CRACK CHECKED AND MACHINE CYLINDER HEADS--OLD HEADS WERE CRACKED. REPLACED CYLINDER HEADS, FILLED COOLANT

WARRANTY STATEMENT PURSUANT TO KANSAS LAW, CONSUMERS HAVE SPECIFIC IMPLIED WARRANTY RIGHTS IN CONNECTION WITH CONSUMER TRANSACTIONS. ANY WARRANTIES BY A MANUFACTURER OR SUPPLIER OTHER THAN OUR DEALERSHIP, HOWEVER, ARE THEIRS, NOT OURS, AND ONLY SUCH MANUFACTURER OR SUPPLIER SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. NO EXPRESS WARRANTIES ARE GIVEN BY OUR DEALERSHIP. IF THIS REPAIR IS NOT PERFORMED IN CONNECTION WITH A CONSUMER TRANSACTION, THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR.

SHOP SUPPLY COSTS: We have added a charge equal to 10% of the total cost of labor, not to exceed \$40 to the Repair Order for shop supplies used in connection with this repair.

By signing below, you acknowledge that you were notified of and authorized the Dealership to perform the services/repairs itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as suggested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

DATE	CUSTOMER SIGNATURE	AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE	DESCRIPTION	TOTALS
			LABOR AMOUNT	
			PARTS AMOUNT	
			GAS, OIL, LUBE	
			SUBLET AMOUNT	
			MISC. CHARGES *	
			TOTAL CHARGES	
			COUPON / DISC.	
			SALES TAX	
			PLEASE PAY THIS AMOUNT	

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

CUSTOMER COPY

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN / OUT	TAG
VER	17	CHEVROLET SILVERADO	3GCUKNEC7HG419207		88533/88533	

R.O. OPENED      READY      OPTIONS:      ENG:5.3\_LITER

14:47 17JUL24 08:55 01AUG24

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

AND CHANGED OIL AND FILTER. Test drove, did many hard accels and EC highest was 230 degrees with 104 ambient temp and cooling fans only run at 60%, before they were running at 100%.

\*\*\*\*\*

**WARRANTY STATEMENT:** PURSUANT TO KANSAS LAW, CONSUMERS HAVE SPECIFIC IMPLIED WARRANTY RIGHTS IN CONNECTION WITH CONSUMER TRANSACTIONS. ANY WARRANTIES BY A MANUFACTURER OR SUPPLIER OTHER THAN OUR DEALERSHIP, HOWEVER, ARE THEIRS, NOT OURS, AND ONLY SUCH MANUFACTURER OR SUPPLIER SHALL BE LIABLE FOR PERFORMANCE UNDER SUCH WARRANTIES. NO EXPRESS WARRANTIES ARE GIVEN BY OUR DEALERSHIP. IF THIS REPAIR IS NOT COMPLETED IN CONNECTION WITH A CONSUMER TRANSACTION, THE DEALERSHIP HEREBY EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS AND IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, AND NEITHER ASSUMES NOR AUTHORIZES ANY OTHER PERSON TO ASSUME FOR IT ANY LIABILITY IN CONNECTION WITH THE SALE OF PARTS OR PRODUCTS OR THE REPAIR.

**\*SHOP SUPPLY COSTS:** We have added a charge equal to 10% of the total cost of labor, not to exceed \$40, to the labor order for shop supplies used in connection with this repair.

We, Agents Below, you acknowledge that you were notified of and authorized the Dealership to perform the repairs and services itemized in this invoice and that you received (or had the opportunity to inspect) any replaced parts as requested by you. The vehicle is being returned to you in exchange for your payment of the Amount Due.

\_\_\_\_\_  
CUSTOMER SIGNATURE

\_\_\_\_\_  
AUTHORIZED DEALERSHIP REPRESENTATIVE SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	—
PARTS AMOUNT	—
GAS, OIL, LUBE	—
SUBLET AMOUNT	—
MISC. CHARGES *	—
TOTAL CHARGES	—
COUPON / DISC.	—
SALES TAX	—
PLEASE PAY THIS AMOUNT	4777.46

ALL PARTS ARE NEW UNLESS OTHERWISE INDICATED.

# INVOICE

Let us service you!

Ref #:

Printed Date: 06/28/2024

Work Completed: 06/28/2024

2017 Chevrolet - Silverado 1500 LS - 5.3L V8 (323CI) VIN(C)  
 Lic # :  
 Unit # : 983  
 VIN # : 3GCUKNEC7 HG419207  
 Odometer In : 87849  
 Odometer Out : 87849

Part Description	Qty	Sale	Ext	Labor Description	Ext
New Radiator	1.00			Coolant leak please check and advise	
Engine coolant thermostat housing	1.00			Had to pressure test system for coolant leak found radiator leaking on the sides of tank on drivers side. Had to drain coolant and remove radiator and install new T-stat. Then filled cooling system with coolant and bleed all air out of system and looked for leaks no leaks found at this time.	
GM coolant straight concentrate	3.00				
AC Delco Dexos1 full synthetic motor oil Size: 1QT	8.00				
Baldwin oil filter	1.00			Customer states they are do for and oil change. Please change oil and check over vehicle	
Shop Supplies				Pulled vehicle in and change oil, filter and checked all fluid levels and topped off. Noticed we have been having to add about 1/2 gallon of coolant each oil change. Performed cooling system pressure test on system and found radiator leaking.	

Labor:

Parts:

SubTotal:

Tax:

Total: 992.59

Bal Due:

Vehicle Received: 6/28/2024

Customer Number : 552

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs there to. Warranty on parts per manufacturer. Labor warranty is 30 days. Warranty work has to be performed in our shop & cannot exceed the original cost of repair. IF PAYMENT IS NOT MADE WHEN VEHICLE IS PICKED UP THERE WILL BE 25% FEE ADDED TO BILL FOR PAST DUE PAYMENT.

Signature

Date

Visit us on the web: [www.4bserviceandmobilerepair.com](http://www.4bserviceandmobilerepair.com)

Email Address: [mobilerepair.4bservices@outlook.com](mailto:mobilerepair.4bservices@outlook.com)

## INVOICE

Printed Date: 09/03/2024 Work Completed: 08/31/2024

2017 Chevrolet - Silverado 1500 LS - 5.3L V8 (323CI) VIN(C)  
Lic # : Odometer In : 90291  
Unit # : 983 Odometer Out : 90309  
VIN # : 3GCUKNEC7 HG419207

Part Description	Qty	Sale	Ext	Labor Description	Ext
Fuel pump and module assembly Delphi carries 12 month 12,000 mile warranty on parts no Labor Shop Supplies	1.00			Customer states the truck dies and hesitates. Please check and advise Test drove vehicle and verified customers concern. Brought back to shop hooked up scanner and found codes for low fuel pressure, monitored live data and found fuel pressure about 11Psi from factory specs. Hooked up fuel pressure gauge and verified fuel pump was dropping out. Codes P018B, P0506, P2635. Emptied fuel tank out and then dropped fuel tank down removed faulty fuel pump then installed new fuel pump then re-installed fuel tank, filled back up with fuel. Cleared codes re-ran self test no codes present, went out and test drove vehicle, truck runs normal as it should.	

Org. Estimate 1,251.03 Revisions 0.00 Current Estimate 1,251.03

Labor:  
Parts:  
  
SubTotal: \_\_\_\_\_  
Tax: \_\_\_\_\_  
Total: \_\_\_\_\_  
Bal Due: \$1,251.03

Payments - 1

Date Received 8/31/2024

Customer Number : 552

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs there to. Warranty on parts per manufacturer. Labor warranty is 30 days. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.  
PAYMENT IS NOT MADE WHEN VEHICLE IS PICKED UP THERE WILL BE 25% FEE ADDED TO BILL FOR PAST DUE PAYMENT.

Signature \_\_\_\_\_ Date \_\_\_\_\_

Call us on the web: [www.4bserviceandmobilerepair.com](http://www.4bserviceandmobilerepair.com)Email Address: [mobilerepair.4bservices@outlook.com](mailto:mobilerepair.4bservices@outlook.com)