

Qty.	Part No.	Description	Price Ea.	Price
1	91-01-429	Starter		
		1/2 Price		
1	1023	coolant Reser		

(Starter Had Been
Replaced 1 1/2 years Earlier)

NAME

ADDRESS

DATE
4-18-23
A.M.
P.M.
PHONE?
YES
NO

YEAR 2013 MAKE 386 MODEL Pete COLOR LICENSE #05 SPEEDOMETER 849,063
MOTOR NO. ISX-15 SERIAL NO. ED 226632 HOURS

Oper. No.	Instructions	Labor
	Check Truck - Starter not cranking Engine - Short Solenoid & Hammer on Case - Cool Started - Take In Shop - Replace Starter with a Wilson Reman Unit Check Low Coolant Warning System Replace Level Sensor - still showing Low Coolant - Replace Reser Tank with float inside	

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

AUTHORIZED BY:

RECEIVED BY:

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

LEGENDS PRINTING

Gals. Gas @
Qts. Oil
Qts. Trans. Fld. @

TOTAL

F.S.	Total Labor
	Total Parts
	Sublet
	Env. Chg.
	Freight
	Gas Oil
	Trans. Fld.
	Sub Total
	Tax
	TOTAL

718 44

TOTAL PARTS @
SUBLET REPAIRS

TOTAL SUBLET REPAIR @

1 PAS652119 steering gear

57762

Cash Charge

DATE
5-1-23
A.M.
P.M.
PHONE?
YES
NOYEAR
14
MAKE
Pete
MODEL
386
COLOR
LICENSE
MOTOR NO.SERIAL NO.
ED226632SPEEDOMETER
845,723
HOURS

Oper. No.	Instructions	Labor
B 3.1	Replace steering gear Fill with 15-40 oil	

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

AUTHORIZED BY:

RECEIVED BY:

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

LEGENDS
PRINTING

Gals. Gas @

3 Qts. Oil 15-40 mobil

Qts. Trans. Fld. @ 1300 6 27

TOTAL 1831

F.S.

Total Labor

Total Parts

Sublet

Env. Chg.

Freight

Gas Oil

Trans. Fld.

Sub Total

Tax

TOTAL

TOTAL PARTS ≥

SUBLET REPAIRS

TOTAL SUBLET REPAIR ≥

1,57634

Qty.	Part No.	Description
2	5"	exh clamp
1	M15661	exh adapter
1	M4590515	— Elbow
1	209400	Pipe Plug
2 ft	273443	Fuel hose

58031

Cash Charge

✓

DATE 7-10-23 A.M.
P.M.
PHONE? YES
NO

YEAR 14 MAKE Pete MODEL 386 COLOR LICENSE #05 SPEEDOMETER 858,518
MOTOR NO. SERIAL NO. ED226632 HOURS

Oper. No.	Instructions	Labor
13	Replace exhaust pipe & flow out of 5.0 turbo	
	Had to cut & weld pipes together for correct lengths & bends	
	Blow out Radiator, air cooler & condenser	
	Replace vent in fuel tank & hose	

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

AUTHORIZED BY:

RECEIVED BY:

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

LEGENDS

Gals. Gas @

Qts. Oil

Qts. Trans. Fld. @

F.S.

Total Labor

Total Parts

Sublet

Saw. Chg.

Freight

Gas Oil

Trans. Fld.

Sub Total

Tax

625.00

TOTAL PARTS ≥

SUBLET REPAIRS

ROGUE

Qty. Part No. Description Price Ea.

1 1589001163 Legacy seat

58711

Cash Charge

✓

DATE 02-12-88 A.M.
PHONE? YES
NO

YEAR 14 MAKE Petz MODEL 386 COLOR LICENSE #05 SPEEDOMETER
MOTOR NO. SERIAL NO. HOURS

Oper. No.	Instructions	Labor
abe	Remove drivers seat & passenger seat	
1.0	Move drivers seat to passenger & install new drivers seat	

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

AUTHORIZED BY: _____

RECEIVED BY: _____

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

LEGENDS PRINTING

Gals. Gas @
Qts. Oil
Qts. Trans. Fid. @

TOTAL

F.S.

Total Labor

Total Parts

Sublet

Env. Chg.

Freight

Gas Oil

Trans. Fid.

Sub Total

Tax

TOTAL

1,335.99

TOTAL PARTS >

SUBLET REPAIRS

TOTAL SUBLET REPAIR >

Qty.	Part No.	Description	Price Ea.	Price
1	4952631	215° Thermostat		
1	440	Clutch Brake		
2	4473632	oil gasket		
2	EC3501	coolant		
1	LF9070	oil Filter		
2	675-011	Threaded stud		
2	215-013	nut		
36	111	Silicone base		
12	4965698	Exh Bolts		
1	4376196	oil cooler nut		
1	3682940	exh gasket		
4	496657	— —	2	
1	4965512	Exh spacer		
1	350-0107	Block heater		
1	4965487	oil cooler		
1	3689755	cooler hang gasket		
TOTAL PARTS ≥				
SUBLET REPAIRS				
TOTAL SUBLET REPAIR ≥				

58656

Cash Charge

DATE 12-19-23 A.M.
 PHONE? YES
 NO

YEAR 14 MAKE Pete MODEL 386 COLOR LICENSE #05 SPEEDOMETER 482,140
 MOTOR NO. SERIAL NO. ED226632 HOURS

Oper. No.	Instructions	Labor
B	Replace engine oil cooler & gaskets	
18.75	Replace oil thermostat with 215°	
	Replace block heater & cord	
	Remove exhaust manifold, drilled broken bolt, installed manifold with new gaskets & bolts	
	Drilled 2 broken bolts out of manifold where turbo mounted	
	Adjust clutch & replace broken clutch Brake	

I hereby authorize the above repair work to be done along with the necessary material, and herein grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

AUTHORIZED BY:

RECEIVED BY:

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

LEGENDS PRINTING

Gals. Gas @

4 Qts. Oil 15-40 motil
 Qts. Trans. Fld. @ 1300

TOTAL

F.S.

Total Labor

Total Parts

Sublet

Chg.

Freight
 Gas Oil
 Trans. Fld.

Sub Total

Tax

TOTAL 4,135.14

Qty.	Part No.	Description	Price Ea.	Price
3.8	16s 134a	Freon		
2oz	Pag 46	a/c oil		
1	LF9070	oil Filter		
1	9240901	Condenser		
1	040000	a/c line		

59225

Cash Charge

DATE 5-24-24 A.M.
 PHONE? YES
 NO

YEAR 14 MAKE Pete MODEL 386 COLOR LICENSE #OS SPEEDOMETER 703,695
 MOTOR NO. SERIAL NO. ED226632 HOURS

Oper. No.	Instructions	Labor
B	Replace a/c condensor & line	
1.75	Condensor to Filterdrier	
	drill out Broken bolt on radiator frame	
	tap & install new bolt to hold	
	a/c line	
	Vac & fill with oil, freon	
	(Put oil filter in cab)	

I hereby authorize the above repair work to be done along with the necessary material, and hereby grant you and/or your employees, permission to operate the car, truck or vehicle herein described on streets, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car, truck or vehicle to secure the amount of repairs thereto.

AUTHORIZED BY:

RECEIVED BY:

Not responsible for loss or damage to cars or articles left in cars in case of fire, theft, or any other cause beyond our control.

LEGENDS PRINTING

Gals. Gas @
 Qts. Oil
 Qts. Trans. Fld. @

TOTAL

F.S.

Total Labor

Total Parts

Sublet

Chg.

Freight

Gas Oil

Trans. Fld.

Sub Total

Tax

TOTAL

1,017.02

TOTAL PARTS ≥
 SUBLET REPAIRS

TOTAL SUBLET REPAIR ≥