2008 Volvo VNL Semi Truck NJ9612

Engine Overhaul & Other Major Repair Invoice

Invoice: 005-28337R

Date / Hour: 4/28/2021 9:28:16AM

Repair Order: 28337 Customer: 93060

Branch: 005

Page 1 of 3

Bill To

Customer P/O:

Add User: nblair

Unit Number: 108

Model Year: 2007

VIN: 4V4NC9GH58N460125

Make/Model:

Salesperson:

Open Date: 03/11/2021

Meter: 887954 Miles

Task: 1 ENGINE **ENGINE - OVERHAUL**

Department: Trk Svc

Completion Date: 04/15/2021

Complaint: ENGINE KNOCK

Type: CLASS 8 TRUCK

Correction: PULLED OIL PAN, STIFFENING PLATE AND NUMBER 3 AND 4 MAIN. FOUND CRANK IS BROKEN.

REMOVED ENGINE FROM TRUCK, STRIPPED DOWN EXHANGE ENGINE DOWN TO BARE BLOCK AND CRANK, REINSTALLED FRONT TIMING PLATE AND LOWER IDLER GEARS. CHECKED GEAR LASH AND RIGHT GEAR HAD .003 OF AN INCH AND THE LEFT ONE HAD .0025. SPEC IS .002 TO .007.

INSTALLED REAR HOUSING, INSTALLED NEW PISTON AND LINERS, LINER PROTRUSION RAN BETWEEN .006 AND .0065. INSTALLED NEW HEAD GASKET AND HEAD. INSTALLED RESURFACED FLYWHEEL AND TIMED CAM FROM OLD ENGINE AND SET GEAR LASH, LAST ON UPPER IDLER WAS .005 ON BOTH TOP AND BOTTOM.

PUT INJECTORS AND ROCKER SHAFT FROM OLD ENGINE IN AND ADJUSTED VALVES, INJECTORS AND ENGINE BRAKES. STARTED MOVING PARTS FROM OLD ENGINE TO NEW ENGINE . INSTALLED NEW OIL COOLER .

FINISHED ASSEMBLING ENGINE AND ISNTALLED INTO TRUCK. INSTALLED COOLING PACKAGE, TRANS, DRIVELINE, HOOD, BUMPERS AND GRILL GUARD, CLEARED FAULTS AND ROAD TESTED THE TRUCK.

Supp.	Part	Description / Ref Number	U/M	Quantity	
MIS	ZCB862-4	DOT UNION 1/4	EA	1.0	
VOL	20516147-C	TURBO CORE	EA	-1.0	
Speci	ial Order Part				
VOL	22397140-C	OIL PUMP CORE	EA	-1.0	
Speci	ial Order Part				
VOL	85000191-C	CYLINDER HEAD CORE	EA	-1.0	
Speci	ial Order Part				
VOL	85125020-C	ENGINE OVERHAUL KIT-Core	EA	-1.0	
Spec	ial Order Part				
VOL	20510082	GASKET 2222	EA	1.0	
VOL	20749399	OIL COOLER	EA	1.0	
DEX	251704	USED ENGINE	EA	1.0	
VOL	85125020	ENGINE OVERHAUL KIT	EA	1.0	
VOL	85125020-C	ENGINE OVERHAUL KIT-Core	EA	1.0	
Spec	ial Order Part				
VOL	85145873	INSTALL KIT	EA	1.0	
	FG FF5369W	FUEL FILTER 25 MICRON	EA	1.0	
VOL	23961779	V-RIBBED BELT	EA	1.0	
VOL	20733354	CLIPS	EA	4.0	

Invoice: **005-28337R** Date / Hour: 4/28/2021 9:28:16AM

Repair Order: 28337 Customer: 93060 Branch: 005

Page 2 of 3

Bill To:

Wor

	Wor				
Custome	er P/O:		Open Date: 0	3/11/2021	Completion Date: 04/15/202
Add	User: nblair		Salesperson:		
VOL	947281	GASKET 1512	EA	2.0	
VOL	983585	FLANGE SCREW	EA	4.0	
VOL	977581	STUD 1126	EA	2.0	
VOL	977639	NIPPLE	EA	1.0	
VOL	85116275	KIT	KT	1.0	
VOL	22397140	OIL PUMP	EA	1.0	
VOL	22397140-C	OIL PUMP CORE	EA	1.0	
Spe	cial Order Part				
VOL	1652986	BALL BEARING	EA	1.0	
اصر	20516147	TURBO	EA	1.0	
. JL	20516147-C	TURBO CORE	EA	1.0	
Spe	cial Order Part				
VOL	20712545	GASKET	EA	1.0	
VOL	8130185	GASKET 2629	EA	1.0	
VOL	21937327	COOLANT FILTER	EA	1.0	
VOL	21707132	OIL FILTER	EA	1.0	
VOL	21707133	OIL FILTER	EA	2.0	
VOL	23044511	FUEL FILTER	EA	1.0	
VOL	85103205	SPRAY PAINT	EA	2.0	
VOL	955984	O-RING 1514	EA	1.0	
VOL	21715813	AIR FILTER	EA	1.0	
VOL	176566	O-RING KIT A/C	EA	1.0	
VOL	8149182	THERMOSTAT 2627	EA	1.0	
VOL	8170514	GASKET 2629	EA	1.0	
VOL	85107600	SCREW 4519	EA	12.0	
VOL	20787384	SEALING RING 2652	EA	1.0	
VOL	20787386	SEALING RING 2652	EA	1.0	
VOL	471708	SEALING RING 2239	EA	2.0	
VOL	925094	O-RING 1514	EA	1.0	
VOL	22592094	O-RING	EA	1.0	
VOL	975675	O-RING 1514	EA	1.0	
RC	RC AFRNA053	NOAT RED EL GALLON 50/50	EA	2.0	
٠,	LOC82606	PERMATEX BRAKE CLEANER	EA	1.0	
MBL	MBL122492	OIL, MOBIL DELVAC SAE 15W40 (GAL)	EA	11.0	
	85000191	CYLINDER HEAD, EXCH	EA	1.0	

Invoice: **005-28337R** Date / Hour: 4/28/2021 9:28:16AM

Repair Order: 28337 Customer: 93060 Branch: 005

Page 3 of 3

Bill To:

Wo

Custome	er P/O:		Open Date: 03/	11/2021	Completion Date: 04/15/2021
Add	User: nblair		Salesperson:		
VOL	85000191-C	CYLINDER HEAD CORE	EA	1.0	
Spe	ecial Order Part				
Task: Comple	3 VEB aint: VEB IS INOP, R	ENGINE EXHAUST BRAKE RUN DOWN OPEN CIRCUIT		De	partment: Trk Svc
Correct		CLEANER AND VALVE COVER CHECKED VEB SOLENOID F WIRES, INSTALLED VALVE COVER AND AIR CLEANER DR			
Supp.	Part	Description / Ref Number	U/M_	Quantity	

Date_ Signature_

Invoice: 005-31274R

Date / Hour: 9/30/2022 7:39:39PM

Repair Order: 31274 Customer: 16241 Branch: 005

Total Invoice: \$ 6,172.12

COD

Page 1 of 3

Bill To:

Custon							
Unit	Number: 108	Model Year: 2007	Make/N	lodel:			
Type	: CLASS 8 TRUCK	VIN: 4V4NC9GH58N460125	Meter:	1100000	Miles		
ask:		PLACE ENGINE HARNESS D13			Depai	rtment: Trk Sv	/C
	plaint: REPLACE ENGINE HARNI						
Corre	CYL 1	R AND R ENGINE HARNESS, FOUND THE TRUCK IS S	TILL MISSIN	G AND HAS	AN OP	EN CIRCUT FAU	TFOR
upp.	Part	Description (Ref Number	U/M	Quantity	,	Price	Extended Price
OL.	983472	Description / Ref Number CABLE TIE 1162	EA	6.0			\$3.96
OL.	21514077	WIRING HARNESS	EA	1.0	-		\$1,195.69
OL	3964604	BUSHING 2119	EA	1.0			\$4.65
OC	LOC82606	PERMATEX BRAKE CLEANER	EA	1.0			\$7.37
00	20002000	Task 1 Subt			Parts:		\$1.31
		lask i Subt	Otais		abor:		
				Task 1 Sub			2.858.17
	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE	MISSION COOLER LINES 1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF SET AND FOUNDER A DREASSURE TEST AND CO	F THE TRAN	S ONTO THE	IE LINES	S. ALSO PUT THE	ETRUCK
Corre	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND CO	F THE TRAN IG COOLAN OANI LEAK S	IS ONTO TH I I TIGHTEN STOPPED.	IE LINES	S. ALSO PUT THE CLAMP AND CLE	E TRUCK EANED TH Extended
Corre	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND CO Description / Ref Number	F THE TRAN IG COOLAN' OANI LEAK S U/M	S ONTO THE IT I TIGHTEN STOPPED. Quantity	E LINES	S. ALSO PUT THE	ETRUCK EANED TH Extended Price
upp.	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING	F THE TRAN IG COOLAN' OANI LEAK S U/M EA	S ONTO THE TITIESTOPPED. Quantity 2.0	IE LINES	S. ALSO PUT THE CLAMP AND CLE	ETRUCK EANED TH Extended Price
Corre	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND CO Description / Ref Number	F THE TRAN IG COOLAN' OANI LEAK S U/M EA	S ONTO THE TITIESTOPPED. Quantity 2.0	E LINES ID THE	S. ALSO PUT THE CLAMP AND CLE	E TRUCK EANED TH Extended
upp.	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING	F THE TRAN IG COOLAN' OANI LEAK S U/M EA	S ONTO THE TITIESTOPPED. Quantity 2.0	Parts:	S. ALSO PUT THE CLAMP AND CLE	ETRUCK EANED TH Extended Pric \$10.30
Corre Supp.	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI Part 21866819	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TI OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subt	F THE TRAN IG COOLAN' OANI LEAK S U/M EA	S ONTO THE TITIESTOPPED. Quantity 2.0	Parts:	S. ALSO PUT THI CLAMP AND CLE Price	EXTRUCK EANED TH Extended Pric \$10.30
Supp. /OL	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI Part 21866819 : 3 BUS-B PM	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subt	F THE TRAN IG COOLAN' OANI LEAK S U/M EA	S ONTO THE TITIESTOPPED. Quantity 2.0	Parts:	S. ALSO PUT THE CLAMP AND CLE	EXTRUCK EANED TH Extended Pric \$10.30
Supp. /OL	ection: 9/23/2022 6:32:02 PM 880 UNIT IS SHOWING SIGNS UNDER A PREASSURE TE COOLANT OFF THE ENGI Part 21866819	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subte SERVICE	F THE TRAN IG COOLAN' OANI LEAK S U/M EA	S ONTO THE TITIESTOPPED. Quantity 2.0	Parts:	S. ALSO PUT THI CLAMP AND CLE Price	EXTRUCK EANED TH Extended Pric \$10.30
Supp. /OL Com	Part 21866819 BUS-B Paint: PM SERVICE - NO DAVCO dection: 9/23/2022 8:18:21 PM 880	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TI OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subtraction SERVICE FILTER 1 PREFORMED PM SERVICE	F THE TRAN IG COOLAN' OANI LEAK S U/M EA	S ONTO THE TITIESTOPPED. Quantity 2.0	Parts: .abor: ototals Depai	S. ALSO PUT THI CLAMP AND CLE Price	EXTENDENT Extended Price \$10.30 \$188.30
Supp. OL Com Corre	Part 21866819 BUS-B PM Plaint: PM SERVICE - NO DAVCO	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subte SERVICE	F THE TRAN IG COOLAN' OANI LEAK S U/M EA otals	IS ONTO THE TITIESTOPPED. Quantity 2.0 Task 2 Sub	Parts: Labor: ototals Depart	S. ALSO PUT THI CLAMP AND CLE Price rtment: Trk Sv	EXTENDENT Extended Price \$10.30 \$188.30
ask: Come	Part 21866819 BUS-B Plaint: PM SERVICE - NO DAVCO ection: 9/23/2022 8:18:21 PM 880 Part 22480372	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subte SERVICE DESCRIPTION / Ref Number Test 2 Subte Description / Ref Number FUEL FILTER	F THE TRAN IG COOLAN' OANI LEAK S U/M EA otals	S ONTO THE ITIGHTEN STOPPED. Quantity 2.0 Task 2 Sub	Parts: .abor: btotals Depart	S. ALSO PUT THI CLAMP AND CLE Price rtment: Trk Sv	EXTENDENT EXTENDED THE EXTENDED THE STORY
upp. OL Come	Part 21866819 BUS-B Part 21872022 8:18:21 PM 880 Part Part 21867819	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TILE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF ST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COODER OF THE PRESENT	F THE TRAN IG COOLAN' OANI LEAK S U/M EA otals	S ONTO THE TITIGHTEN STOPPED. Quantity 2.0 Task 2 Sub Quantity 1.0	Parts: .abor: btotals Depai	S. ALSO PUT THI CLAMP AND CLE Price rtment: Trk Sv	Extender Pric \$10.30 \$188.30 /C Extender Pric \$25.04
ask: Com Corre	Part 21866819 BUS-B Plaint: PM SERVICE - NO DAVCO ection: 9/23/2022 8:18:21 PM 880 Part 22480372 21707132	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subte SERVICE DESCRIPTION / Ref Number Test 2 Subte Description / Ref Number FUEL FILTER	F THE TRAN IG COOLAN' OANI LEAK S U/M EA otals U/M EA EA	Quantity Quantity Quantity 1.0	Parts: Labor: ototals Depail	S. ALSO PUT THI CLAMP AND CLE Price rtment: Trk Sv	Extended Price \$10.30 \$188.30 CExtended Price \$25.04 \$29.49 \$34.44
Corresion Corres	Part 21866819 BUS-B Plaint: PM SERVICE - NO DAVCO ection: 9/23/2022 8:18:21 PM 880 Part 22480372 21707132 23658092 MBL122492	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subte SERVICE DESCRIPTION / Ref Number FUEL FILTER OIL FILTER OIL FILTER	F THE TRAN IG COOLAN' OANI LEAK S U/M EA otals U/M EA EA EA	Quantity Quantity Quantity 1.0 Quantity 1.0 2.0	Parts: Labor: ototals Depail	S. ALSO PUT THI CLAMP AND CLE Price rtment: Trk Sv	Extended Price \$10.30 \$188.30 CExtended Price \$25.04 \$29.49 \$34.44
Corre Supp. /OL Com Corre Supp. /OL /OL	Part 21866819 BUS-B Plaint: PM SERVICE - NO DAVCO ection: 9/23/2022 8:18:21 PM 880 Part 22480372 21707132 23658092	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subte SERVICE DESCRIPTION / Ref Number FUEL FILTER OIL FILTER OIL FILTER	THE TRAN IG COOLAN' OANI LEAK S U/M EA otals U/M EA EA EA EA	Quantity 1.0 Quantity 2.0 Quantity 1.0 1.0 1.0	Parts: Labor: ototals Depail	S. ALSO PUT THI CLAMP AND CLE Price rtment: Trk Sv	Extended Pric \$10.30 \$188.30 CExtended Pric \$25.04 \$29.45 \$34.44
Supp. /OL	Part 21866819 BUS-B Plaint: PM SERVICE - NO DAVCO ection: 9/23/2022 8:18:21 PM 880 Part 22480372 21707132 23658092 MBL122492	1 PULLED UNIT INTO THE SHOP WENT UNDER THE TE OF REAR MAIN SEAL LEAKING AND DRAINING OUT OF EST AND FOUND UPPER RADIATOR HOSE WAS LEAKIN NE PUT IT BACK UNDER A PREASSURE TEST AND COO Description / Ref Number O-RING Task 2 Subte SERVICE DESCRIPTION / Ref Number FULL FILTER OIL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (GAL)	THE TRAN IG COOLAN' OANI LEAK S U/M EA otals U/M EA EA EA EA	Quantity 1.0 Quantity 1.0 1.0 1.0 1.0	Parts: .abor: btotals Depart	S. ALSO PUT THI CLAMP AND CLE Price rtment: Trk Sv	EXTENDED TH Extended Price \$10.30 \$188.30

044-10060.01 COMPLETE CONICAL KIT 6 PACK REPLACEMENT D12 D13

Correction: 9/30/2022 5:52:08 PM 2626 REMOVED AND REPLACED NUMBER 1 INJECTOR PROGRAMED TRIM CODE TEST DROVE WITHOUT ISSUES

Complaint: REPLACE FUEL INJECTOR #1

Department: Trk Svc

Invoice: 005-31274R

Date / Hour: 9/30/2022 7:39:39PM

Repair Order: 31274 Customer: 16241 Branch: 005

Total Invoice: \$ 6,172.12

Page 2 of 3

Bill To:

COD

COD

Custome	er P/O:		cdudley		Orig R	/O: 0	Completion Dat	e: 9/30/2022
	Part	Descrip	otion / Ref Number		U/M	Quantity	F	Extender
VOL	85022626-C	INJ CO	RE	[EA	-1.0		(\$399.00
Spe	ecial Order Part							
VOL	1677370	SEALIN	NG RING 2539	E	EA	2.0		\$9.3
/OL	21344774	FLANG	SE SCREW		EA	1.0		\$2.80
/OL	85022626	INJEC	TOR	E	EA	1.0		\$792.83
/OL	85022626-C	INJ CO	RE	E	EA	1.0		\$399.00
Spe	ecial Order Part							
/OL	3964604	BUSHI	NG 2119	E	EA	1.0		\$4.65
				Task 4 Subtotals		Part	ts:	-
						Core Ch	ig:	
						Core Re	et:	
						Labo	or:	
					7	ask 4 Subtota	als	\$1,610.66
Comple	5 033-10170. laint: REPLACE OIL PR tion: replaced oil pressi		SSURE SENSOR	D12		De	epartment: Trk	
Comple Correct	aint: REPLACE OIL PR tion: replaced oil presso Part	ESSURE SENSOR re sensor	SSURE SENSOR	1	U/M	Quantity		Extende
Comple Correct	aint: REPLACE OIL PR tion: replaced oil pressu	ESSURE SENSOR re sensor	otion / Ref Number	Į.	U/M EA	Quantity	F	Extende
Comple Correct	aint: REPLACE OIL PR tion: replaced oil presso Part	ESSURE SENSOR re sensor Descrip	otion / Ref Number	1		Quantity 1.0	F is:	Extende rice Pric
Comple Correct	aint: REPLACE OIL PR tion: replaced oil presso Part	ESSURE SENSOR re sensor Descrip	otion / Ref Number	Į.	EA	Quantity 1.0 Part	ts:	Extende Price Pric \$339.76
Comple Correct	aint: REPLACE OIL PR tion: replaced oil presso Part	ESSURE SENSOR re sensor Descrip	otion / Ref Number	Į.	EA	Quantity 1.0	ts:	Extende rice Pric
Comple Correct Supp. F	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681	ESSURE SENSOR re sensor Descrip	otion / Ref Number DR	Į.	EA 1	Quantity 1.0 Part	ts:	Extende Price Pric \$339.76
Comple Correct Supp. F /OL	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681 Tax Info: Gales Tax	ESSURE SENSOR re sensor Descrip	otion / Ref Number DR \$0.00	Task 5 Subtotals	EA T	Quantity 1.0 Part Labo ask 5 Subtota	ts: or: ols	Extende Price Pric \$339.76
Comple Correct Supp. F /OL	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681	ESSURE SENSOR re sensor Descrip	solution / Ref Number DR \$0.00 \$0.00	Task 5 Subtotals	Total C	Quantity 1.0 Part Labo ask 5 Subtota Total Parts ore Charge	ts: or: als	Extende Price Pric \$339.76
Comple Correct Supp. F /OL	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681 Tax Info: Gales Tax	ESSURE SENSOR re sensor Descrip	otion / Ref Number DR \$0.00	Task 5 Subtotals	Total Co	Quantity 1.0 Part Labo ask 5 Subtota Total Parts ore Charge al Core Re	s: or: ols	Extende Price Pric \$339.76
Comple Correct Supp. F /OL	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681 Tax Info: Gales Tax	ESSURE SENSOR re sensor Descrip	solution / Ref Number PR \$0.00 \$0.00	Task 5 Subtotals	Total Co	Quantity 1.0 Particle Laborates Total Parts ore Charge al Core Re	rs:	Extende Price Pric \$339.76
Supp. F /OL Detail 1 Local S	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681 Tax Info: Gales Tax	ESSURE SENSOR re sensor Descrip	solution / Ref Number PR \$0.00 \$0.00	Task 5 Subtotals	Total Co	Quantity 1.0 Part Labo ask 5 Subtota Total Parts ore Charge al Core Re	rs:	Extende Price Pric \$339.76
Comple Correct Supp. F /OL	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681 Tax Info: Gales Tax	ESSURE SENSOR re sensor Descrip	solution / Ref Number PR \$0.00 \$0.00	Task 5 Subtotals	Total Co Total	Quantity 1.0 Part Labo Task 5 Subtota Total Parts ore Charge al Core Re Total Labo SUPPLIES e Subtotal	ts: or: ols t: t: r: S:	Extende Price Pric \$339.76
Comple Correct Supp. F /OL	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681 Tax Info: Gales Tax	ESSURE SENSOR re sensor Descrip	solution / Ref Number PR \$0.00 \$0.00	Task 5 Subtotals	Total Co Total	Quantity 1.0 Part Labo ask 5 Subtota Total Parts ore Charge al Core Re Total Labo SUPPLIES	ts: or: ols t: t: r: S:	Extende Price Pric \$339.76
Comple Correct Supp. F /OL	laint: REPLACE OIL PR tion: replaced oil presso Part 23713681 Tax Info: Gales Tax	ESSURE SENSOR re sensor Descrip	solution / Ref Number PR \$0.00 \$0.00	Task 5 Subtotals	Total Co Total I SHOP	Quantity 1.0 Part Labo Task 5 Subtota Total Parts ore Charge al Core Re Total Labo SUPPLIES e Subtotal	s: or: ols t: r: s:	Extende Price Pric \$339.76

9/30/2022

Invoice: **005-31274R** Date / Hour: 9/30/2022 7:39:39PM

Repair Order: 31274 Customer: 16241 Branch: 005

Total Invoice: \$ 6,172.12 ****COD***

Page 3 of 3

Customer P/O:	cdudley	Orig R/O: 0	Completion Date: 9/30/2022

Signature_

Invoice: **005-31838R** Date / Hour: 12/19/2022 10:16:14AM

Repair Order: 31838 Customer: 16241 Branch: 005

Orig R/O: 0

Total Invoice: \$ 2,542.29 ***COD***

Page 1 of 2

Completion Date: 12/17/2022

Bill To:

Customer P/O:

Unit Number: 108

Unit	Number: 108	Model Year: 2007	Make/N	/lodel:		
Type	: CLASS 8 TRUCK	VIN: 4V4NC9GH58N460125	Meter:	1136134 Miles		
	plaint: DASH LIGHTS STAY ON W INSPECT STARTING SYST				nent: Trk Sv	С
COITE	REPAIRED WIRE	20 GOOLD NOT DOFFIGATE 1990E HOWEVER	0011011000101	MY VINCE HE WELLO	01.00110	
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
		Task	1 Subtotals	Parts:		_
				Labor: Task 1 Subtotals		\$356.00
Task:	: 2 032-10020.01 REF	PLACE STARTER D12 ISX		Departr	ment: Trk Sv	<u>. </u>
Com	plaint: LOAD TEST BATTERIES A REPLACE STARTER	ND CHECK CABLES FOR CORROSION OR BEIN 26 LOAD TESTED BATTS FOUND GOOD CLEAN				
orre	STARTER PER CUSTOME		NED CABLES AND E	DATT EUGS KEMIOVED	AND NEI BAGE	
Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Extended Price
DR	DR 8200291	STARTER 39MT	EA	1.0		\$512.38
		Task	2 Subtotals	Parts:		-
				Labor:		6000 00
				Task 2 Subtotals		\$690.38
			The second secon			
Task		TIME PM SERVICE DELVAC ALL VOLV	O ENGINES	Departi	nent: Trk Sv	С
Com	nplaint: PERFORM PM SERVICE		O ENGINES	Departs Quantity	ment: Trk Sv Price	Extended Price
		Description / Ref Number FUEL FILTER		•		Extended
Com Supp.	pplaint: PERFORM PM SERVICE Part	Description / Ref Number	U/M	Quantity		Extended Price
Supp.	Part 22480372	Description / Ref Number FUEL FILTER	U/M EA	Quantity 1.0		Extended Price \$25.04
Supp. VOL VOL	Part 22480372 21707132	Description / Ref Number FUEL FILTER OIL FILTER	U/M EA EA EA	Quantity 1.0 1.0		Extended Price \$25.04 \$29.49
Supp. VOL VOL VOL	Part 22480372 21707132 23658092	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER	U/M EA EA EA	Quantity 1.0 1.0 2.0 9.0		\$25.04 \$29.49 \$34.44
Supp. VOL VOL VOL	Part 22480372 21707132 23658092 MBL122492	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G	U/M EA EA EA	Quantity 1.0 1.0 2.0 9.0 Parts:		\$25.04 \$29.49 \$34.44
Supp. VOL VOL VOL	Part 22480372 21707132 23658092 MBL122492	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G	U/M EA EA EA AL) EA	Quantity 1.0 1.0 2.0 9.0 Parts: Labor:		Extended Price \$25.04 \$29.49 \$34.44 \$264.06
Supp. VOL VOL VOL	Part 22480372 21707132 23658092 MBL122492	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G	U/M EA EA EA AL) EA	Quantity 1.0 1.0 2.0 9.0 Parts: Labor: Task 3 Subtotals	Price	Extended Price \$25.04 \$29.49 \$34.44 \$264.06
Supp. VOL VOL VOL MBL	Part 22480372 21707132 23658092 MBL122492 Labor Quote: 196.97 24 047-10030.01 DO	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G Task	U/M EA EA EA AL) EA	Quantity 1.0 1.0 2.0 9.0 Parts: Labor: Task 3 Subtotals		Extended Price \$25.04 \$29.49 \$34.44 \$264.06
Supp. VOL VOL VOL MBL	Part 22480372 21707132 23658092 MBL122492 Labor Quote: 196.97 24 047-10030.01 DO eplaint: PERFORM DOT INSPECT ection: 12/16/2022 8:21:07 PM 88	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G Task	U/M EA EA EA AL) EA	Quantity 1.0 1.0 2.0 9.0 Parts: Labor: Task 3 Subtotals	Price	Extended Price \$25.04 \$29.49 \$34.44 \$264.06 \$550.00
Supp. VOL VOL VOL MBL	Part 22480372 21707132 23658092 MBL122492 Labor Quote: 196.97 24 047-10030.01 DO eplaint: PERFORM DOT INSPECT	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G. Task TINSPECTION TRUCK TION B01 PREFORMED DOT Description / Ref Number	U/M EA EA EA AL) EA V/M U/M	Quantity 1.0 1.0 2.0 9.0 Parts: Labor: Task 3 Subtotals Depart	Price	Extended Price \$25.04 \$29.49 \$34.44 \$264.06 \$550.00
Supp. VOL VOL VOL MBL	Part 22480372 21707132 23658092 MBL122492 Labor Quote: 196.97 24 047-10030.01 DO eplaint: PERFORM DOT INSPECT ection: 12/16/2022 8:21:07 PM 88	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G. Task TINSPECTION TRUCK TION B01 PREFORMED DOT Description / Ref Number	U/M EA EA EA AL) EA	Quantity 1.0 1.0 2.0 9.0 Parts: Labor: Task 3 Subtotals Depart	Price	Extended Price \$25.04 \$29.49 \$34.44 \$264.06 \$550.00
Supp. VOL VOL VOL MBL	Part 22480372 21707132 23658092 MBL122492 Labor Quote: 196.97 24 047-10030.01 DO eplaint: PERFORM DOT INSPECT ection: 12/16/2022 8:21:07 PM 88	Description / Ref Number FUEL FILTER OIL FILTER OIL FILTER OIL, MOBIL DELVAC SAE 15W40 (G. Task TINSPECTION TRUCK TION B01 PREFORMED DOT Description / Ref Number	U/M EA EA EA AL) EA V/M U/M	Quantity 1.0 1.0 2.0 9.0 Parts: Labor: Task 3 Subtotals Depart	Price	Extended Price \$25.04 \$29.49 \$34.44 \$264.06 \$550.00

zmcdonald

^{**} See Last Page for Invoice Total **

Invoice: **005-31838R** Date / Hour: 12/19/2022 10:16:14AM

Repair Order: 31838 Customer: 16241 Branch: 005

Total Invoice: \$ 2,542.29 ****COD****

Page 2 of 2

Customer P/O:		zmodonald		Orig	R/O: 0 Comp	letion Date: 12	/17/2022
Complaint: REPLAC	E L/F/D BRAKE CHAM	CE BRAKE CHAMBER EACH BER EPLACED BRAKE CHAMBER			Departm	ent: Trk Sv	С
Supp. Part	22 0.32.10 AM 0001 R	Description / Ref Number		U/M	Quantity	Price	Extended Price
VOL 8514582	24	BRAKE CHAMBER		EA	1.0		\$131.66
			Task 5 Subtotals		Parts:		
					Labor:		
					Task 5 Subtotals		\$398.66
Task: 6 002	-10390.01 REPL. \	WINDSHIELD			Departm	ent: Trk Sv	c
removed		placed windsheild on unit due to crack fa				nsheild seal wir	Extended
Supp. Part		Description / Ref Number		U/M	Quantity	Price	Price
MIS DW0		WINDSHIELD PRIOR TO 2019	1	EA	1.0	;	\$116.25
Special Order Pa	art				Doda:		
-			Task 6 Subtotals		Parts: Labor:		
					Task 6 Subtotals		\$472.25
Detail Tax Info:					Total Parts:		
Local Sales Tax		\$0.00			Total Labor:		
Missouri Sales Tax		\$0.00			Total Labor.		
		\$0.00		Invo	ice Subtotal:		
				IIIVC	Total Tax:		
				T	otal Invoice:	\$2,5	42.29
Payment Method	Terms	Due Date					
COD	COD	12/19/2022					

Signature	Date	
signature		

Invoice: 005-33838R

Date / Hour: 10/27/2023 6:21:37PM

Repair Order: 33838 Customer: 16241 Branch: 005

Total Invoice: \$ 3,077.52 ***COD***

Page 1 of 2

Bill To:

Customer	P/O:		Open Date:	10/20/2023	Completion Date: 1	0/27/2023
Add U	Jser: cdudley		Salesperson:			
Unit Nu	ımber: 108	Model Year: 2007	Make/I	Model:		
Type: 0	CLASS 8 TRUCK	VIN: 4V4NC9GH58N46	0125 Meter:	1208166 Mile	s	
Task:	1 097-10000.01 DIA	AGNOSTICS - VOLVO UPTIME (TR	RIAGE)	Dep	artment: Trk Sv	c
	int: FAN RUNS ALL THE TIME		D FAN OPERATION FOUR	D FAN OLLITOL 8	LUID DAD	
Correction	on: 10/20/2023 12:59:14 PM	3350 PULLED UNIT INTO SHOP. CHECKE	D FAN OPERATION. FOUN	ID FAN CLUTCH &	HUB BAD.	Extended
Supp. Pa	art	Description / Ref Number	U/M	Quantity	Price	Price
			Task 1 Subtotals	Parts:		
				Labor: Task 1 Subtotals		\$378.00
		ECTRICAL SYSTEM		Dep	artment: Trk Sv	С
	int: REPLACE HEADLIGHT St on: 10/20/2023 2:00:59 PM 3:	WITCH 350 R & R HEADLIGHT SWITCH.				
Contection	on torzorzozo z.oo.oo i m o.	oo Kaking a samon			P.I.	Extended
	art	Description / Ref Number	U/M	Quantity	Price	Price
VOL	20953575	SWITCH- HEADLIGHT	EA Task 2 Subtotals	1.0 Parts:		
			lask 2 Subtotals	Labor:		
				Task 2 Subtotals		\$269.87
Task:	3 007-10040.01 RE	PLACE FAN CLUTCH D12		Den	artment: Trk Sv	c
	int: REPLACE FAN CLUTCH			200		
Correcti	on: 10/27/2023 3:22:31 PM 8	10 R AND R FAN CLUTCH AND HUB.				
Supp. Pa	art	Description / Ref Number	U/M	Quantity	Price	Extended Price
VOL	85104756	FAN HUB	EA	1.0		\$743.09
VOL	85134489	FAN CLUTCH	EA	1.0		\$586.66
MIS	FREIGHT	FREIGHT		1.0		\$60.00
			Task 3 Subtotals	Parts:		
				Labor:		
				Task 3 Subtotals	\$.	2,334.75
Task:	4 047-10030.01 DC	T INSPECTION TRUCK		Dep	artment: Trk Sv	С
	int: DOT					
Correcti	on: 10/27/2023 4:52:18 PM 5/ REVERSE LIGHT INOP.	014 COMPLETED DOT INSPECTION ON I	UNII.			
	AUDIBLE LOW AIR ALAR	M INOP.				
	5TH WHEEL IS GOING TO	O NEED PINS/BUSHINGS SOON.				Extended
p. P	art	Description / Ref Number	U/M	Quantity	Price	Pric
			Task 4 Subtotals	Parts:		
				Labor: Task 4 Subtotals		\$75.00
				** See ast	Page for Invoice	"" ictol •

Invoice: 005-33838R

Date / Hour: 10/27/2023 6:21:37PM

Repair Order: 33838 Customer: 16241 Branch: 005 Total Invoice: \$ 3,077.52

Page 2 of 2

Bill To:

Customer P/O:			Open Date: 10/20/2023	Completion Date: 10/27/2023
Add User: cdudley			Salesperson:	
Detail Tax Info: Local Sales Tax Missouri Sales Tax		\$0.00 \$0.00 \$0.00	Total Parts: Total Labor: Total ENVIRONMENTAL CHARGE: Total SHOP SUPPLIES:	
			Invoice Subtotal: Total Tax: Total Invoice:	\$3,077.52
Payment Method COD***	Terms COD	<u>Due Date</u> 10/27/2023	Total invoice.	ψ3,077.32

Signature_____Date_____

** Reprint **

Invoice: 005-35749R

Date / Hour: 9/18/2024 11:23:24AN

Repair Order: 35749 Customer: 16241

Branch: 005 Total Invoice: \$ 3,629.07

COD

Page 1 of 3

Bill To:

Customer P/O:

Open Date: 09/06/2024

Salesperson:

Completion Date: 09/14/2024

Add-User: cdudley

Model Year: 2007

Make/Model:

Unit Number: 108 Type: CLASS 8 TRUCK

VIN: 4V4NC9GH58N460125

Meter: 1340779 Miles

004-10100.01 UPTIME PM SERVICE DELVAC ALL VOLVO ENGINES

Department: Trk Svc

Complaint: PM SERVICE. DO NOT CHANGE DAVCO. CUSTOMER SUPPLYING OIL. CHECK PASS FRT DRIVE FOR LEAK Correction: 9/6/2024 2:46:23 PM 8801 PREFORMED PM SERVICE AND INSPECTED WHEEL SEAL IT NEEDS ONE

9/7/2024 8:03:41 AM 5014 TEST DROVE UNIT, NO ISSUES.

Supp.	Part	Description / Ref Number		U/M	Quantity	Price	Extended Price
VOL	22480372	FUEL FILTER		ĒA	1.0		\$32.11
VOL	21707132	OIL FILTER		EΑ	1.0		\$39.71
\cap .	23658092	OIL FILTER		EΑ	2.0		\$47.20
			Task 1 Subtotals	1	Parts:		

Labor: Task 1 Subtotals

\$289.02

018-10060.01 REPL WHEEL SEAL W/OIL SOAKED SHOES/DRUMS PER WHEEL Department: Trk Svc

Complaint: REPLACE RIGHT FRONT DRIVE WHEEL SEAL, BRAKE SHOES

Correction: 9/6/2024 9:01:48 PM 8801 NNISHED PUTTING WHEEL SEAL IN AND TORQUED EVERYTHING TO SPEC ALL GOOD

Supp.	Part	Description / Ref Number	L	J/M	Quantity	Price	Extended Price
RC	RC BKE4707QRSD23-C	CORE	E	A	-1.0		\$(52.70)
Spe	cial Order Part						
VOL	20437531	SEAL 7736	- E	EΑ	1.0		\$64.01
MIS	HDV1601B	DRUM 16.5X7 - 20458891	E	A	1.0		\$120.13
RC	RC BKE4707QRSD23	ROAD CHOICE BRAKE SHOE	E	A	1.0		\$99.57
RC	RC BKE4707QRSD23-C	CORE	E	EA ,	1.0		\$52.70
Spe	cial Order Part						
			Task 2 Subtotals		Parts:		

Core Chg: Core Ret:

Labor:

Task 2 Subtotals

\$793.71

016-10020.01 REPLACE Z SPRING WITHOUT ALIGNMENT

Department: Trk Svc

Complaint: REPLACE Z SPRING, RADIOUS SPRING, U-BOLTS, NUTS, SHOCK, FRAME MOUNTING BRACKET AND HARDWARE ON RFD

Correction: 9/13/2024 4:02:22 PM 810 PULLED THE TRUCK IN THE SHOP, REMOVED ALL SPRINGS AND SPRING MOUNT.

9/13/2024 9:06:54 PM 4770 installed new radius and z spring, torqued components to spec, will need to retorque after 100 miles 9/14/2024 7:54:45 AM 9182 FINSIHED INSTALLING TIRES TORQUED WHEEL LUGS TO 450 FOOT POUNDS, REINSTALLED 1/4

FENDER

Description / Ref Number Supp. Part

Quantity U/M

Extended Price Price

** Reprint ** Invoice: 005-35749R

Date / Hour: 9/18/2024 11:23:24AM

Repair Order: 35749 Customer: 16241 Branch: 005 Total Invoice: \$ 3,629.07

> ***COD*** Page 2 of 3

Customer P/O:			Open Date: 09/06/2024		Completion Date: 09/14/202	
Add	User: cdudley		Salesperson:		,	
VOL	990962	FLANGE LOCK NUT	EA	2.0	\$14.32	
VOL	994522	FLANGE LOCK NUT	EA	8.0	\$45.84	
VOL	990952	FLANGE LOCK NUT	EA	2.0	\$4.80	
VOL	992342	FLANGE SCREW	EA	8.0	\$57.28	
VOL	990811	FLANGE SCREW	EA	2.0	\$5.26	
VOL	993910	HEXAGON SCREW	EA	1.0	\$11.59	
VOL	993913	HEXAGON SCREW	EA	1.0	\$14.63	
VOL	20703083	WEAR PLATE	EA	1.0	\$20.98	
VOL	21823706	WHEEL NUT	KT	4.0	\$61.36	
<u> </u>	23440291	BRACKET-RH	EA	1.0	\$366.83	
VUL	20551933	WASHER	EA	2.0	\$29.36	
VOL	8079890	SPRING STOP	EA	1.0	\$24.51	
VOL	20504754	U-BOLT 7233	EA	2.0	\$58.34	
VOL	21030460	SPRING LEAF	EA	1.0	\$342.45	
VOL	24608801	SPRING	EA	1.0	\$185.17	
VOL	24425357	CLEVIS PIN	EA	1.0	\$20.29	
VOL	20812234	STUD	EA	1.0	\$37.52	
VOL	21807998	WHEEL NUT	EA	1.0	\$10.81	
	FREIGHT	FREIGHT		1.0	\$45.00	
			Task 3 Subtotals	Parts:	4	
				Labor:		

Task: 4 050-10000.01 PERFORM 3 AXLE ALIGNMENT

Complaint: PERFORM 3 AXLE ALIGNMENT

HAND BRAKE IS LOOSE IN DASH - SECURE

Correction: 9/14/2024 9:35:50 AM 9182 PREFORMED ALIGHMNET, GOT ALL MEASURMENTS IN SPEC WITH COMPUTER, ROAD TESTED UNIT,

TRUCK DID NOT PULL AND DROVE STRIGHT, PULLED UNIT BACK INTO SHOP AND CENTERD STEERING WHEEL

Supp.	Part	Description / Ref Number	U/M	Quantity	Price Extended Price
			Task 4 Subtotals	Parts:	
				Labor:	7010100
				Task 4 Subtotals	\$340.00
ill Tax Info: Local Sales Tax Missouri Sales Tax		\$0.00 \$0.00 \$0.00		Total Parts: Core Charge: otal Core Ret: Total Labor:	\$1,870.00

^{**} See Last Page for Invoice Total *

Department: Trk Svc

** Reprint **
Invoice: 005-35749R
Date / Hour: 9/18/2024 11:23:24AM

Repair Order: 35749 Customer: 16241 Branch: 005

Total Invoice: \$ 3,629.07

Page 3 of 3

Customer P/O:			Open Date: 09/06/2024	Completion Date: 09/14/2024
Add User: cdudley			Salesperson:	
			Total Miscellaneous:	
			Invoice Subtotal: Total Tax:	
		1	Total Invoice:	\$3,629.07
Payment Method	Terms COD	Due Date 9/18/2024	·	

Date_ Signature_

Invoice: 005-34193R

Date / Hour: 12/18/2023 7:35:11PM

Repair Order: 34193 Customer: 16241 Branch: 005

Total Invoice: \$ 6,187.90 ***COD***

Page 1 of 2

Customer P/O:

Open Date: 12/15/2023

Completion Date: 12/16/2023

Extended

Add User: zmcdonald

Salesperson:

Unit Number: 108

Model Year: 2007

Make/Model:

Type: CLASS 8 TRUCK

VIN: 4V4NC9GH58N460125

Meter: 1232182 Miles

016-99999.01 MISCELLANEOUS REPAIR - SUSPENSION

Department: Trk Svc

Complaint: FRONT SPRINGS

Correction: 12/15/2023 3:06:58 PM 5690 HELP TEARDOWN FRONT SPRINGS, HAD TO TORCH OUT THE RIGHT FRONT SPRING PIN. 12/15/2023 8:56:07 PM 4770 REPLACED FRONT LEAF SPRINGS USING NEW HANGARS, SHACKLES, U BOLTS AND PINCH BOLTS AND PINS. ALIGNED ALL SPRING PINS. HAD TO REPLACE RIGHT SIDE MOUNT DUE TO PIN BREAKING IN AXLE. TORQUED U BOLTS TO SPEC. (375). INSTALLED GREASE FITTINGS AND GREASED ALL FRONT SPRING PINS. UNIT STILL NEEDS SPLASH SHIELDS PUT IN, DEER GUARD INSTALLED AND ALIGNMENT. ADVISED SERVICE

12/16/2023 10:22:44 AM 5014 ASSISTED 9113 WITH ALIGNMENT. TEST DROVE UNIT AND FOUND THAT STEERING WHEEL

NEEDED ADJUSTED. PARKED UNIT ONCE COMPLETE.

12/16/2023 10:24:01 AM 9113 INSTALLED SPLASHGAURDS AND BRUSH GAURD PERFORMED 3 AXLE ALIGNMENT ADJUSTED DRIVE AXLES TO SPEC AND SET TOE TO SPEC STRAIGHTENED STEERING WHEEL AFTER TEST DRIVE

Supp.	Part	Description / Ref Number	U/M	Quantity	Price	Price
VOL	914170	LUBRICATING NIPPLE	EA	6.0		\$25.02
VOL	990952	FLANGE LOCK NUT	EA	12.0		\$23.28
VOL	984818	FLANGE SCREW	EA	8.0		\$59.60
VOL	984819	FLANGE SCREW	EA	4.0		\$18.20
VOL	20548421	SHACKLE 7214	EA	4.0		\$247.48
VOL	21823706	WHEEL NUT	KT	8.0		\$119.20
VOL	20435532	WEDGE (28MM)	EA	1.0		\$67.18
VOL	23293635	ANCHORAGE	EA	2.0		\$390.62
VOL	20560239	U-BOLT 7214	EA	4.0		\$109.76
VOL	20548410	LEAF SPRING 7211	EA	2.0		\$1,342.04
VOL	1075723	BOLT 7213	EA	6.0		\$687.72
VOL	994884	WASHER	EA	8.0		\$76.24

Detail Tax Info:

Local Sales Tax \$0.00 Missouri Sales Tax \$0.00

\$0.00

Total Parts: Total Labor: Total ENVIRONMENTAL CHARGE: **Total SHOP SUPPLIES:** Total TECHNOLOGY FEE:

^{**} See Last Page for Invoice Total

Invoice: 005-34193R

Date / Hour: 12/18/2023 7:35:11PM

Repair Order: 34193 Customer: 16241 Branch: 005

Total Invoice: \$ 6,187.90

COD

Page 2 of 2

Customer P/O:			Open Date: 12/15/2023	Completion Date: 12/16/2023	
Add User: zmodona	ald		Salesperson:		
			Invoice Subtotal: Total Tax:		
_			Total Invoice:	\$6,187.90	
Payment Method ***COD***	Terms COD	<u>Due Date</u> 12/18/2023			

TERMS: Net due 30 days from invoice unless otherwise specified.

Any claims of shortage or deductions for erroneous charges must be made within 30 days after receipt of goods. Any tax imposed by any law on the sale of articles made or sold by this company shall be in addition to the sales price thereof, and shall be added to the amount to be paid thereon.

Gateway Truck & Refrigeration warrants its workmanship for 90 days after completion of services. Products sold are warranted exclusively by the manufacturer. Gateway Truck & Refrigeration expressly disclaims all other warranties, expressed or implied, including any implied warranty of merchantability or fitness for a particular purpose. IN NO EVENT SHALL GATEWAY TRUCK & REFRIGERATION BE LIABLE FOR ANY PUNITIVE, INDIRECT, INCIDENTAL, CONSEQUENTIAL, SPECIAL OR UNKNOWN DAMAGES, INCLUDING BUT NOT LIMITED TO, LOSS OF PROPERTY OR EQUIPMENT, LOSS OF DATA, LOSS OF USE, LOSS OF TIME, LOSS OF REVENUE, LOSS OF PROFIT, OR LOSS OF INCOME.

rns must be accompanied by this invoice and in the original, unopened box or packaging. A 15% restocking charge will be applied to all returned items. No returns on electrical items. No returns on special order items. No returns after 30 days from the date of invoice.

Signature	Date
9	

Work Order:

34193

Company: Year:

07

Technician: Odometer:

9113 1232182

Unit Number:

108

VIN:

460125

12/16/23 8:40 AM

Heavy Duty Vehicles: Volvo / VolvoGM / White[GMC]: Volvo VN,VT,VHD,VAH Series: Volvo Axles Total Alignment, 6 sensors





